



**VASTUKALA**  
Unlocking Excellence

www.vastukala.co.in

MSME Reg No: UDYAM-MH-18-0083617

An ISO 9001 : 2015 Certified Company

CIN: U74120MH2010PTC207869

## Vastukala Consultants (I) Pvt. Ltd.

Structural Stability Report / SVC / Kandivali East Branch/ Mrs. Samidha Rupesh Shinde (012433/2309100) Page 1 of 3

Vastu/Mumbai/11/2024/12433/2309100

18/02-185-BHV

Date: 18.11.2024

### Structural Stability Report

Structural Observation Report Residential Flat No. 503, 5<sup>th</sup> Floor, Building No. 4, Wing - A, "Himalaya", Om Jalaram Co-Op. Hsg. Soc. Ltd., Asha Nagar, Village - Poisar, Kandivali (East), Taluka - Borivali, District - Mumbai Suburban, Mumbai, PIN - 400 101, State - Maharashtra, India.

Name of Owner: **Mrs. Samidha Rupesh Shinde & Mr. Rupesh Raghunath Shinde**

This is to certify that on visual inspection, it appears that the structure at "Himalaya", Om Jalaram Co-Op. Hsg. Soc. Ltd. is in Normal condition and the future life can be reasonably taken under Normal condition and with proper periodic repairs & maintenance is about 25 years.

#### General Information:

A.	Introduction	
1	Name of Building	" Himalaya", Om Jalaram Co-Op. Hsg. Soc. Ltd
2	Property Address	Residential Flat No. 503, 5 <sup>th</sup> Floor, Building No. 4, Wing - A, "Himalaya", Om Jalaram Co-Op. Hsg. Soc. Ltd., Asha Nagar, Village - Poisar, Kandivali (East), Taluka - Borivali, District - Mumbai Suburban, Mumbai, PIN - 400 101, State - Maharashtra, India.
3	Type of Building	Residential
4	No. of Floors	Stilt + 7 Upper Floors
5	Whether stilt / podium / open parking provided	Stilt Parking
6	Type of Construction	R.C.C. Framed Structure
7	Type of Foundation	R.C.C. Footing
8	Thickness of the External Walls	9" thick brick walls both sides plastered
9	Type of Compound	Brick Masonry Walls
10	Year of Construction	1989 (As per occupancy certificate)
11	Present age of building	35 years
12	Residual age of the building	25 years Subject to proper, preventive periodic maintenance & structural repairs.
13	No. of flats (Per Floor)	5 <sup>th</sup> Floor is having 4 Flats
14	Methodology adopted	As per visual site inspection

B.	External Observation of the Building	
1	Plaster	Normal Condition
2	Chajjas	Normal Condition
3	Plumbing	Normal Condition
4	Cracks on the external walls	Found
5	Filling cracks on the external walls	Not Found
6	Cracks on columns & beams	Found
7	Vegetation	Yes



#### Our Pan India Presence at :

- Nanded
- Thane
- Ahmedabad
- Delhi NCR
- Mumbai
- Nashik
- Rajkot
- Raipur
- Aurangabad
- Pune
- Indore
- Jaipur

#### Regd. Office

BI-001, U/B Floor, BOOMERANG, Chandivali Farm Road, Powai, Andheri East, **Mumbai**: 400072, (M.S), India

+91 2247495919

mumbai@vastukala.co.in

www.vastukala.co.in

8	Leakages of water in the drainage pipes or water pipes	Yes
9	Dampness external in the wall due to leakages	Yes
10	Any other observation about the condition of external side of the building	Structural Stability Report from licensed structural engineers not provided for our verification.
<b>C Internal Observation of the common areas of the building and captioned premises</b>		
1	Beams (Cracks & Leakages)	Yes
2	Columns (Cracks & Leakages)	Not Found
3	Ceiling (Cracks & Leakages)	Not Found
4	Leakages inside the property	Not Found
5	Painting inside the property	Normal
6	Maintenance of staircase & cracks	Normal

<b>D</b>	<b>Common Observation</b>	
1	Structural Audit of the Building Under Bye – Laws No. 77 of the Model Bye Laws (Co-Operative Societies Act / Rules)	As per bye Laws No. 77 of Co-Op. Societies bye Laws under the Act the society shall conduct a Structural Audit of the building of the society as follows
2	Remark	<p>i) <b>At the time of site inspection, external condition of the building is normal, dampness not found, leakages are not found &amp; Cracks are not found.</b></p> <p>ii) <b>Structural Stability Report from licensed structural engineers not provided for our verification.</b></p>

<b>E</b>	<b>Conclusion</b>
<p>The captioned building is having Stilt + 7 Upper Floors which are constructed in year 1989 (As per occupancy certificate). Estimated future life under present circumstances is about 25 years subject to proper, preventive periodic maintenance &amp; structural repairs.</p> <p>The inspection dated 15.11.2024 of building. The building is well as the property is maintained in normal condition &amp; will stand future life subject to proper, preventive periodic maintenance &amp; normal structural repairs.</p> <p>Our Observations about the structure are given above.</p> <p>The above assessment is based on visual inspection only. Separate structural audit from licensed structural engineers is advised to assess exact balance life of structure.</p>	

For VASTUKALA CONSULTANTS (I) PVT. LTD.

**Sharadkumar  
B. Chalikwar**

Digitally signed by Sharadkumar B. Chalikwar  
DN: cn=Sharadkumar B. Chalikwar,  
o=Vastukala Consultants (I) Pvt. Ltd.,  
ou=CMD, email=cmd@vastukala.org, c=IN  
Date: 2024.11.18 10:15:58 +05'30'



**Director**

**Auth. Sign.**

**Sharadkumar B. Chalikwar**

Structural Engineer Licence No. STATE/R/2022/APL/01785

Govt. Reg. Valuer

Chartered Engineer (India)

Reg No. (N) CCIT/1-14/52/2008-09

SBI Empanelment No.: SME / TCC / 2021 – 22 / 85 / 13



Since 1989

**Vastukala Consultants (I) Pvt. Ltd.**

An ISO 9001 : 2015 Certified Company





## Actual site photographs

