

```
{
  "typeOfReport": {
    "value": "Land_and_Building",
    "label": "Land and Building"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64183a4e96b58848585f6d2c"
    },
    "firstName": "Sumit",
    "type": "CREDITOFFICER",
    "_id": "6581632265d49d78457d4583",
    "lastName": "Kumar",
    "mobileNo": "",
    "workMobileNo": "9926073036",
    "email": "sumit.kumar@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6450f43cba18c8062aad0215",
  "name": "Indore",
  "shortName": "Indore",
  "email": "indore@vastukala.org",
  "address": "106, 1st Floor, Gold Star Tower, 576, M G Road, Opp T1 Mall,
Indore-452001, Madhya Pradesh India",
  "city": "Indore"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "64183a4e96b58848585f6d2c",
  "name": "SME Khel Prashal Branch",
  "branchCode": "",
  "mobileNo": "99263 09091",
  "alternateMobileNo": "",
  "email": "nipun.tiwari@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "2nd Floor, 5, Y.N. Road, Indore, State - Madhya Pradesh, Country – India"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Industrial",
  "value": "Industrial"
},
"zone": {
  "_id": "641831ac96b58848585f5124",
  "zoneName": "Indore Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
```

```
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\
\profilePhoto_1622114310919_Manoj C.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\
\profilePhoto_1622114310919_Manoj C.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60016f965256c07aec8e6dd6",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Akhilesh",
"email": "akhilesh.yadav@vastukala.org",
"lastName": "Yadav",
"mobileNo": "9545753921",
"designation": "Processing Officer",
"workWithDocumentMaker": "6009222ca16fab0f2af9b0bf",
"profilePhoto": "users\\60016f965256c07aec8e6dd6\
\profilePhoto_1622371927126_Akhilesh Photo (2).jpg",
"shortName": "AY"
},
"maker": {
"type": "EMPLOYEE",
"_id": "60016f965256c07aec8e6dd6",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Akhilesh",
"email": "akhilesh.yadav@vastukala.org",
"lastName": "Yadav",
"mobileNo": "9545753921",
```

```
    "designation": "Processing Officer",
    "workWithDocumentMaker": "6009222ca16fab0f2af9b0bf",
    "profilePhoto": "users\\60016f965256c07aec8e6dd6\\
\\profilePhoto_1622371927126_Akhilesh Photo (2).jpg",
    "shortName": "AY"
  },
  "checker": {
    "type": "EMPLOYEE",
    "_id": "60016f965256c07aec8e6dd6",
    "role": "MAKER + RATE VERIFIER + CHEAKER",
    "firstName": "Akhilesh",
    "email": "akhilesh.yadav@vastukala.org",
    "lastName": "Yadav",
    "mobileNo": "9545753921",
    "designation": "Processing Officer",
    "workWithDocumentMaker": "6009222ca16fab0f2af9b0bf",
    "profilePhoto": "users\\60016f965256c07aec8e6dd6\\
\\profilePhoto_1622371927126_Akhilesh Photo (2).jpg",
    "shortName": "AY"
  },
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "IBBI/RV/07/2018/10366",
          "label": "Registered Valuer"
        }
      ],
      "type": "EMPLOYEE",
      "_id": "5ffe92d27737ca4d986b6453",
      "role": "VALUER",
      "firstName": "Manoj",
      "email": "manoj@vastukala.org",
      "lastName": "Chalikwar",
      "mobileNo": "9819597579",
      "designation": "Registered Valuer",
      "registrationNo": [
        {
          "title": {
            "label": "IBBI"
          },
          "_id": "60af80072ffdf65bcd658651",
          "number": "IBBI/RV/07/2018/10366"
        }
      ],
      "title": {
```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "22.72238890472884",
  "longitude": "75.87912522633874"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "12/12/2024 12:00 am"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "INdore",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Ground",
    "label": false
  }
}
```

```
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "INdore",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "INdore",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "INdore",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "17",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
```

```
"key": "buildingName",
"value": "",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
}
```



```
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "129/2/5",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
```

```
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
```

```
    "status": false,
    "name": "Suburb",
    "key": "suburb",
    "value": "",
    "label": false
  }
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
}
```

```
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": true,
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  }
}
```

```
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```



```
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
```

```
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "true",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": true,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "675abd7cbc26c2bda04ec00b",
"ownerName": "Vljaysingh S/O Aniruddhasinh Kushwah",
"ownerPhoneNo": "0000000000",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "0000000000",
"contactPersonName": "Vljaysingh S/O Aniruddhasinh Kushwah",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "Vljaysingh S/O Aniruddhasinh Kushwah",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "120224"
  }
],
"caseReferredBy": "5ffe92d27737ca4d986b6453",
"relationWithOwner": "self",
"fullAddress": "Industrial Land and Building No. Ground Floor, Plot No. 17, New/
Current Survey No. 129/2/5, Village - INdore, Taluka - INdore, District - INdore, INdore,
State - Maharashtra, India",
"remark": "",
"documents": [],
"isUrgent": "false",
"isExternal": "false",
```

```
"proposePurchaserName": "",
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"reralid": "",
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "013038",
"createdBy": "6006d4ce5080a310ac1fd2c",
"caseHistory": [
  {
    "id": "297417",
    "title": "Create Case",
    "description": "Create Case",
    "datetime": "Thu Dec 12 2024 10:39:56 GMT+0000 (Coordinated Universal Time)"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a1f79fc6108fdeef486bfc",
    "name": "externalImg_1738667933937_External_1.jpeg",
    "path": "cases/675abd7cbc26c2bda04ec00b/externalImg_1738667933937_External_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a1f79fc6108fdeef486bfd",
    "name": "externalImg_1738667933947_External_2.jpeg",
    "path": "cases/675abd7cbc26c2bda04ec00b/externalImg_1738667933947_External_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "67a1f79fc6108fdeef486bfe",
  "name": "externalimg_1738667933973_External_3.jpeg",
  "path": "cases/675abd7cbc26c2bda04ec00b/
externalimg_1738667933973_External_3.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a1f79fc6108fdeef486bff",
  "name": "externalimg_1738667934062_External_4.jpeg",
  "path": "cases/675abd7cbc26c2bda04ec00b/
externalimg_1738667934062_External_4.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a1f79fc6108fdeef486c00",
  "name": "externalimg_1738667934135_External_5.jpeg",
  "path": "cases/675abd7cbc26c2bda04ec00b/
externalimg_1738667934135_External_5.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a1f79fc6108fdeef486c01",
  "name": "externalimg_1738667934147_External_6.jpeg",
  "path": "cases/675abd7cbc26c2bda04ec00b/
externalimg_1738667934147_External_6.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a1f79fc6108fdeef486c02",
  "name": "externalimg_1738667934246_External_7.jpeg",
  "path": "cases/675abd7cbc26c2bda04ec00b/
externalimg_1738667934246_External_7.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "67a1f79fc6108fdeef486c03",
    "name": "externalimg_1738667934293_Ground_Floor_1.jpeg",
    "path": "cases/675abd7cbc26c2bda04ec00b/
externalimg_1738667934293_Ground_Floor_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a1f79fc6108fdeef486c04",
    "name": "externalimg_1738667934380_Ground_Floor_2.jpeg",
    "path": "cases/675abd7cbc26c2bda04ec00b/
externalimg_1738667934380_Ground_Floor_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a1f79fc6108fdeef486c05",
    "name": "externalimg_1738667934386_Ground_Floor_3.jpeg",
    "path": "cases/675abd7cbc26c2bda04ec00b/
externalimg_1738667934386_Ground_Floor_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a1f79fc6108fdeef486c06",
    "name": "externalimg_1738667934429_Ground_Floor_4.jpeg",
    "path": "cases/675abd7cbc26c2bda04ec00b/
externalimg_1738667934429_Ground_Floor_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a1f79fc6108fdeef486c07",
    "name": "externalimg_1738667934472_Ground_Floor_5.jpeg",
    "path": "cases/675abd7cbc26c2bda04ec00b/
externalimg_1738667934472_Ground_Floor_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a1f79fc6108fdeef486c08",
```

```
    "name": "externalImg_1738667934478_Ground_Floor_6.jpeg",
    "path": "cases/675abd7cbc26c2bda04ec00b/
externalImg_1738667934478_Ground_Floor_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a1f79fc6108fdeef486c09",
    "name": "externalImg_1738667934541_Ground_Floor_7.jpeg",
    "path": "cases/675abd7cbc26c2bda04ec00b/
externalImg_1738667934541_Ground_Floor_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a1f79fc6108fdeef486c0a",
    "name": "externalImg_1738667934548_Ground_Floor_8.jpeg",
    "path": "cases/675abd7cbc26c2bda04ec00b/
externalImg_1738667934548_Ground_Floor_8.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a1f79fc6108fdeef486c0b",
    "name": "externalImg_1738667934598_Ground_Floor_9.jpeg",
    "path": "cases/675abd7cbc26c2bda04ec00b/
externalImg_1738667934598_Ground_Floor_9.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a1f79fc6108fdeef486c0c",
    "name": "externalImg_1738667934605_Ground_Floor_10.jpeg",
    "path": "cases/675abd7cbc26c2bda04ec00b/
externalImg_1738667934605_Ground_Floor_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a1f79fc6108fdeef486c0d",
    "name": "externalImg_1738667934658_Ground_Floor_11.jpeg",
```

```
    "path": "cases/675abd7cbc26c2bda04ec00b/
externallmg_1738667934658_Ground_Floor_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a1f79fc6108fdeef486c0e",
    "name": "externallmg_1738667934663_Ground_Floor_12.jpeg",
    "path": "cases/675abd7cbc26c2bda04ec00b/
externallmg_1738667934663_Ground_Floor_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a1f79fc6108fdeef486c0f",
    "name": "externallmg_1738667934763_Ground_Floor_13.jpeg",
    "path": "cases/675abd7cbc26c2bda04ec00b/
externallmg_1738667934763_Ground_Floor_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a1f7b6a92c39df2abd3168",
    "name": "externallmg_1738667957383_Ground_Floor_14.jpeg",
    "path": "cases/675abd7cbc26c2bda04ec00b/
externallmg_1738667957383_Ground_Floor_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a1f7b6a92c39df2abd3169",
    "name": "externallmg_1738667957393_Ground_Floor_15.jpeg",
    "path": "cases/675abd7cbc26c2bda04ec00b/
externallmg_1738667957393_Ground_Floor_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a1f7b6a92c39df2abd316a",
    "name": "externallmg_1738667957398_Ground_Floor_16.jpeg",
    "path": "cases/675abd7cbc26c2bda04ec00b/
externallmg_1738667957398_Ground_Floor_16.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a1f7b6a92c39df2abd316b",
  "name": "externallmg_1738667957440_Ground_Floor_17.jpeg",
  "path": "cases/675abd7cbc26c2bda04ec00b/
externallmg_1738667957440_Ground_Floor_17.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a1f7b6a92c39df2abd316c",
  "name": "externallmg_1738667957445_Ground_Floor_18.jpeg",
  "path": "cases/675abd7cbc26c2bda04ec00b/
externallmg_1738667957445_Ground_Floor_18.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a1f7b6a92c39df2abd316d",
  "name": "externallmg_1738667957487_Ground_Floor_19.jpeg",
  "path": "cases/675abd7cbc26c2bda04ec00b/
externallmg_1738667957487_Ground_Floor_19.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a1f7b6a92c39df2abd316e",
  "name": "externallmg_1738667957490_Ground_Floor_20.jpeg",
  "path": "cases/675abd7cbc26c2bda04ec00b/
externallmg_1738667957490_Ground_Floor_20.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a1f7b6a92c39df2abd316f",
  "name": "externallmg_1738667957536_Ground_Floor_21.jpeg",
  "path": "cases/675abd7cbc26c2bda04ec00b/
externallmg_1738667957536_Ground_Floor_21.jpeg",
  "orientation": "portrait"
}
```



```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a1f7b6a92c39df2abd3170",
    "name": "externalImg_1738667957566_Mezzanine_Floor_1.jpeg",
    "path": "cases/675abd7cbc26c2bda04ec00b/
externalImg_1738667957566_Mezzanine_Floor_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a1f7b6a92c39df2abd3171",
    "name": "externalImg_1738667957572_Mezzanine_Floor_2.jpeg",
    "path": "cases/675abd7cbc26c2bda04ec00b/
externalImg_1738667957572_Mezzanine_Floor_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a1f7b6a92c39df2abd3172",
    "name": "externalImg_1738667957638_Mezzanine_Floor_3.jpeg",
    "path": "cases/675abd7cbc26c2bda04ec00b/
externalImg_1738667957638_Mezzanine_Floor_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a1f7b6a92c39df2abd3173",
    "name": "externalImg_1738667957665_Mezzanine_Floor_4.jpeg",
    "path": "cases/675abd7cbc26c2bda04ec00b/
externalImg_1738667957665_Mezzanine_Floor_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a1f7b6a92c39df2abd3174",
    "name": "externalImg_1738667957670_Mezzanine_Floor_5.jpeg",
    "path": "cases/675abd7cbc26c2bda04ec00b/
externalImg_1738667957670_Mezzanine_Floor_5.jpeg",
    "orientation": "landscape"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a1f7b6a92c39df2abd3175",
  "name": "externalImg_1738667957730_Mezzanine_Floor_6.jpeg",
  "path": "cases/675abd7cbc26c2bda04ec00b/
externalImg_1738667957730_Mezzanine_Floor_6.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a1f7b6a92c39df2abd3176",
  "name": "externalImg_1738667957736_Mezzanine_Floor_7.jpeg",
  "path": "cases/675abd7cbc26c2bda04ec00b/
externalImg_1738667957736_Mezzanine_Floor_7.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a1f7b6a92c39df2abd3177",
  "name": "externalImg_1738667957791_Servant_Room_1.jpeg",
  "path": "cases/675abd7cbc26c2bda04ec00b/
externalImg_1738667957791_Servant_Room_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a1f7b6a92c39df2abd3178",
  "name": "externalImg_1738667957801_Servant_Room_2.jpeg",
  "path": "cases/675abd7cbc26c2bda04ec00b/
externalImg_1738667957801_Servant_Room_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a1f7b6a92c39df2abd3179",
  "name": "externalImg_1738667957860_Servant_Room_3.jpeg",
  "path": "cases/675abd7cbc26c2bda04ec00b/
externalImg_1738667957860_Servant_Room_3.jpeg",
  "orientation": "landscape"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a1f7b6a92c39df2abd317a",
    "name": "externalImg_1738667957865_Servant_Room_4.jpeg",
    "path": "cases/675abd7cbc26c2bda04ec00b/
externalImg_1738667957865_Servant_Room_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a1f7b6a92c39df2abd317b",
    "name": "externalImg_1738667957906_Servant_Room_5.jpeg",
    "path": "cases/675abd7cbc26c2bda04ec00b/
externalImg_1738667957906_Servant_Room_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a1f7cca2b18adef0cca73d",
    "name": "externalImg_1738667979908_Servant_Room_4.jpeg",
    "path": "cases/675abd7cbc26c2bda04ec00b/
externalImg_1738667979908_Servant_Room_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a1f7cca2b18adef0cca73e",
    "name": "externalImg_1738667979912_Servant_Room_5.jpeg",
    "path": "cases/675abd7cbc26c2bda04ec00b/
externalImg_1738667979912_Servant_Room_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a1f7cca2b18adef0cca73f",
    "name": "externalImg_1738667979917_Servant_Room_6.jpeg",
    "path": "cases/675abd7cbc26c2bda04ec00b/
externalImg_1738667979917_Servant_Room_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "67a1f7cca2b18adef0cca740",
  "name": "externalImg_1738667979941_Servant_Room_7.jpeg",
  "path": "cases/675abd7cbc26c2bda04ec00b/
externalImg_1738667979941_Servant_Room_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a1f7cca2b18adef0cca741",
  "name": "externalImg_1738667979945_Servant_Room_8.jpeg",
  "path": "cases/675abd7cbc26c2bda04ec00b/
externalImg_1738667979945_Servant_Room_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a1f7cca2b18adef0cca742",
  "name": "externalImg_1738667979972_Servant_Room_9.jpeg",
  "path": "cases/675abd7cbc26c2bda04ec00b/
externalImg_1738667979972_Servant_Room_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a1f7cca2b18adef0cca743",
  "name": "externalImg_1738667979981_Servant_Room_10.jpeg",
  "path": "cases/675abd7cbc26c2bda04ec00b/
externalImg_1738667979981_Servant_Room_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a1f7cca2b18adef0cca744",
  "name": "externalImg_1738667980047_Servant_Room_11.jpeg",
  "path": "cases/675abd7cbc26c2bda04ec00b/
externalImg_1738667980047_Servant_Room_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "67a1f7cca2b18adef0cca745",
    "name": "externalImg_1738667980052_Servant_Room_12.jpeg",
    "path": "cases/675abd7cbc26c2bda04ec00b/
externalImg_1738667980052_Servant_Room_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a1f7cca2b18adef0cca746",
    "name": "externalImg_1738667980109_Servant_Room_13.jpeg",
    "path": "cases/675abd7cbc26c2bda04ec00b/
externalImg_1738667980109_Servant_Room_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a1f7cca2b18adef0cca747",
    "name": "externalImg_1738667980137_Servant_Room_14.jpeg",
    "path": "cases/675abd7cbc26c2bda04ec00b/
externalImg_1738667980137_Servant_Room_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a1f7cca2b18adef0cca748",
    "name": "externalImg_1738667980153_Servant_Room_15.jpeg",
    "path": "cases/675abd7cbc26c2bda04ec00b/
externalImg_1738667980153_Servant_Room_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a1f7cca2b18adef0cca749",
    "name": "externalImg_1738667980203_Servant_Room_16.jpeg",
    "path": "cases/675abd7cbc26c2bda04ec00b/
externalImg_1738667980203_Servant_Room_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a1f7cca2b18adef0cca74a",
```

```
    "name": "externallmg_1738667980208_Servant_Room_17.jpeg",
    "path": "cases/675abd7cbc26c2bda04ec00b/
externallmg_1738667980208_Servant_Room_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a1f7cca2b18adef0cca74b",
    "name": "externallmg_1738667980248_Servant_Room_18.jpeg",
    "path": "cases/675abd7cbc26c2bda04ec00b/
externallmg_1738667980248_Servant_Room_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a1f7cca2b18adef0cca74c",
    "name": "externallmg_1738667980257_Servant_Room_19.jpeg",
    "path": "cases/675abd7cbc26c2bda04ec00b/
externallmg_1738667980257_Servant_Room_19.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a1f7cca2b18adef0cca74d",
    "name": "externallmg_1738667980303_Servant_Room_20.jpeg",
    "path": "cases/675abd7cbc26c2bda04ec00b/
externallmg_1738667980303_Servant_Room_20.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a1f7cca2b18adef0cca74e",
    "name": "externallmg_1738667980318_Servant_Room_21.jpeg",
    "path": "cases/675abd7cbc26c2bda04ec00b/
externallmg_1738667980318_Servant_Room_21.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a1f7cca2b18adef0cca74f",
    "name": "externallmg_1738667980436_Servant_Room_22.jpeg",
```

```
"path": "cases/675abd7cbc26c2bda04ec00b/
externalImg_1738667980436_Servant_Room_22.jpeg",
"orientation": "landscape"
}
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-12-12T10:39:56.242Z",
"updatedAt": "2025-02-04T11:19:40.627Z",
"__v": 0,
"addressForMap": "",
"updatedBy": "6006d4ce5080a310ac1fdfc2"
}
```

Name	Length	Width	Total
Composition :			
Other			
Composition :			