

MSME Reg No: UDYAM-MH-18-0083617 An ISO 9001: 2015 Certified Company CIN: U74120MH2010PTC207869

Vastukala Consultants (I) Pvt. Ltd.

Structural Stability Report / SBI / RACPC Chinchpokli / Mr. Rohit Kumar (013367/2309825)

Vastu/Mumbai/12/2024/013367/2309825 27/18-523-SK Date: 27.12.2024

Structural Stability Report

Structural Observation Report of Residential Flat No. 101, 1st Floor, Building No 17, "Glenmark", Highland Residency 'D' Co - Op Hsg. Soc. Ltd., Dhokali Naka, Kolshet Road, Village - Dhokali, Thane (West), Taluka -Thane, District - Thane, PIN- 400607, State - Maharashtra, India.

Name of Owner: Mr. Vijay Jagannath Ahire & Mrs. Anuradha Vijay Ahire

Name of Proposed Purchaser: Mr. Rohit Kumar & Mrs. Neha Rohit Roy

This is to certify that on visual inspection, it appears that the structure of the at "Glenmark", is in good condition and the future life can be reasonably taken under good condition and with proper periodic repairs & maintenance is about 41 years.

General Information:

A.		Introduction
1	Name of Building	Glenmark
2	Property Address	Residential Flat No. 101, 1st Floor, Building No 17,
		"Glenmark", Highland Residency 'D' Co - Op Hsg. Soc.
		Ltd., Dhokali Naka, Kolshet Road, Village - Dhokali, Thane
		(West), Taluka - Thane, District - Thane, PIN- 400607, State
		- Maharashtra, India.
3	Type of Building	Residential used
4	No. of Floors	Ground + 7 th Upper Floors
5	Whether stilt / podium / open parking	Open Car Parking Space
	provided	
6	Type of Construction	R.C.C. Framed Structure
7	Type of Foundation	R.C.C. Footing
8	Thickness of the External Walls	9" thick brick walls both sides plastered
9	Type of Compound	Brick Masonry Walls
10	Year of Construction	2007 (As per site information)
11	Present age of building	17 years
12	Residual age of the building	43 years Subject to proper, preventive periodic
		maintenance & structural repairs.
13	No. of flats (Per Floor)	4 Flats on 1st Floor
14	Methodology adopted	As per visual site inspection

B.	External Observation of the Building		State of the state
1	Plaster	Not Found	Sal Landov's E.
2	Chajjas	Not Found	**************************************



Nanded Mumbai

Aurangabad

Thane Nashik Pune

PAhmedabad PDelhi NCR Rajkot

Raipur Jaipur

Regd. Office

B1-001, U/B Floor, BOOMERANG, Chandivali Farm Road, Powai, Andheri East, Mumbai: 400072, (M.S), India







Page	2	٠,	A
Page	7	Ωī	4

3	Plumbing	Not Found
4	Cracks on the external walls	Not Found
5	Filling cracks on the external walls	Not Found
6	Cracks on columns & beams	Not Found
7	Vegetation	Not Found
8	Leakages of water in the drainage pipes	Not Found
	or water pipes	
9	Dampness external in the wall due to	Not Found
	leakages	
10	Any other observation about the condition	Structural Stability Report from licensed structural
	of external side of the building	engineers not provided for our verification.
С	Internal Observation of the comm	on areas of the building and captioned premises
1	Beams (Cracks & Leakages)	Not Found
2	Columns (Cracks & Leakages)	Not Found
3	Ceiling (Cracks & Leakages)	Not Found
4	Leakages inside the property	Not Found
5	Painting inside the property	Not Found
6	Maintenance of staircase & cracks	Good

D	Common Observation	
1	Structural Audit of the Building Under Bye	As per bye Laws No. 77 of Co-Op. Societies bye Laws
	- Laws No. 77 of the Model Bye Laws (Co-	under the Act the society shall conduct a Structural Audit of
	Operative Societies Act / Rules)	the building of the society as follows
2	Remark	No Structural Audit Report is furnished for the perusal.

Ε Conclusion

The captioned building is having Ground + 7th Upper Floors which are constructed in year 2007 (As per site information) Estimated future life under present circumstances is about 43 years subject to proper, preventive periodic maintenance & structural repairs.

The inspection dated 16.12.2024 of building. The building is well as the property is maintained in good condition & will stand future life subject to proper, preventive periodic maintenance & Good structural repairs. Our Observations about the structure are given above.

The above assessment is based on visual inspection only. Separate structural audit from licensed structural engineers is advised to assess exact balance life of structure.

For VASTUKALA CONSULTANTS (I) PVT. LTD.

Sharadkumar

Digitally signed by Sharadkumar Chalikwar
DN: cn=Sharadkumar Chalikwar,
o=Vastukala Consultants (i) Pvt. Ltd.,
ou=CMD, email=cmdqwastukala org. c=IN
Date: 2024.12.27 17 S1:03 +05'30'

Auth. Sign.

Director

Sharadkumar B. Chalikwar

Structural Engineer Licence No. STATE/R/2022/APL/01785

Govt. Reg. Valuer

Chartered Engineer (India)

Reg No. (N) CCIT/1-14/52/2008-09

SBI Empanelment No.: SME / TCC / 2021 - 22 / 85 / 13



Since 1989



An ISO 9001: 2015 Certified Company



Actual site photographs
















Actual site photographs







