



VASTUKALA
Unlocking Excellence

Vastukala Consultants (I) Pvt. Ltd.

www.vastukala.co.in

Structural Stability Report Prepared for JSB / Bhayander (East) Branch / Mr. Soumen Sadhan Mukherjee (13451/2309915) Page 1 of 4

Vastu/Mumbai/01/2025/13451/2309915
03/13-34-JAVS
Date: 03.01.2025

Structural Stability Report

Structural Observation Report Residential Flat No. 206 & 207, 2nd Floor, Wing - A, "**Shivam Apartment**", Om Shivam Co-op. Hsg. Soc. Ltd., S. V. Road, Navghar Road, Village - Khari, Taluka - Thane, District - Thane, Bhayandar (East), PIN - 401 105, State - Maharashtra, Country - India.

Name of Client / Proposed Purchaser: **Mr. Soumen Sadhan Mukherjee & Mrs. Tiya Soumen Mukherjee**

Name of Owner: **Smt. Aruna Nawal Kishore Rungta**

This is to certify that on visual inspection, it appears that the structure at "**Om Shivam Co-op. Hsg. Soc. Ltd.**" is in average condition and the future life can be reasonably taken under good condition and with proper periodic repairs & maintenance is about 18 years.

General Information:

A.	Introduction	
1	Name of Building	" Om Shivam Co-op. Hsg. Soc. Ltd. "
2	Property Address	Residential Flat No. 206 & 207, 2nd Floor, Wing - A, " Shivam Apartment ", Om Shivam Co-op. Hsg. Soc. Ltd., S. V. Road, Navghar Road, Village - Khari, Taluka - Thane, District - Thane, Bhayandar (East), PIN - 401 105, State - Maharashtra, Country - India.
3	Type of Building	Residential
4	No. of Floors	Ground + 3 Upper Floors
5	Whether stilt / podium / open parking provided	No Parking Space available at site
6	Type of Construction	R.C.C. Framed Structure
7	Type of Foundation	R.C.C. Footing
8	Thickness of the External Walls	9" thick brick walls both sides plastered
9	Type of Compound	Brick Masonry Walls
10	Year of Construction	1983 (As per No Objection Certificate issued by Group Village Panchayat Navghar (Bhayandar East))
11	Present age of building	42 years
12	Residual age of the building	18 years Subject to proper, preventive periodic maintenance & structural repairs.
13	No. of flats (Per Floor)	2 nd Floor is having 7 Flats
14	Methodology adopted	As per visual site inspection

B.	External Observation of the Building	
1	Plaster	Normal Condition
2	Chajjas	Normal Condition
3	Plumbing	Normal Condition



Our Pan India Presence at :

- Nanded
- Thane
- Ahmedabad
- Delhi NCR
- Mumbai
- Nashik
- Rajkot
- Raipur
- Aurangabad
- Pune
- Indore
- Jaipur

Regd. Office

BI-001, U/B Floor, BOOMERANG, Chandivali Farm Road, Powai, Andheri East, **Mumbai**: 400072, (M.S.), India

+91 2247495919

mumbai@vastukala.co.in

www.vastukala.co.in



4	Cracks on the external walls	Minor Cracks Found
5	Filling cracks on the external walls	Not Found
6	Cracks on columns & beams	Not Found
7	Vegetation	Not Found
8	Leakages of water in the drainage pipes or water pipes	Not Found
9	Dampness external in the wall due to leakages	Not Found
10	Any other observation about the condition of external side of the building	Structural Stability Report from licensed structural engineers not provided for our verification.
C	Internal Observation of the common areas of the building and captioned premises	
1	Beams (Cracks & Leakages)	Not Found
2	Columns (Cracks & Leakages)	Not Found
3	Ceiling (Cracks & Leakages)	Not Found
4	Leakages inside the property	Not Found
5	Painting inside the property	Normal Condition
6	Maintenance of staircase & cracks	Normal

D	Common Observation	
1	Structural Audit of the Building Under Bye – Laws No. 77 of the Model Bye Laws (Co-Operative Societies Act / Rules)	As per bye Laws No. 77 of Co-Op. Societies bye Laws under the Act the society shall conduct a Structural Audit of the building of the society as follows
2	Remark	<p>i) At the time of site inspection, external condition of the building is average, dampness not found, leakages are not found & Cracks are not found.</p> <p>ii) Structural Stability Report from licensed structural engineers not provided for our verification.</p>

E	Conclusion
<p>The captioned building is having Ground + 3 Upper Floors which are constructed in year 1983 (As per No Objection Certificate issued by Group Village Panchayat Navghar (Bhayandar East). Estimated future life under present circumstances is about 18 years subject to proper, preventive periodic maintenance & structural repairs.</p> <p>The inspection dated 02.01.2025 of building. The building is well as the property is maintained in normal condition & will stand future life subject to proper, preventive periodic maintenance & Good structural repairs.</p> <p>Our Observations about the structure are given above.</p> <p>The above assessment is based on visual inspection only. Separate structural audit from licensed structural engineers is advised to assess exact balance life of structure.</p>	

For VASTUKALA CONSULTANTS (I) PVT. LTD.

Director

Auth. Sign.

Sharadkumar B. Chalikwar

Structural Engineer Licence No. STATE/R/2022/APL/01785

Govt. Reg. Valuer

Chartered Engineer (India)

Reg No. (N) CCIT/1-14/52/2008-09

SBI Panelment No.: SME / TCC / 2021 – 22 / 85 / 13






Since 1989

Vastukala Consultants (I) Pvt. Ltd.

An ISO 9001 : 2015 Certified Company



Actual site photographs



Actual site photographs

