

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And
Enforcement Of Security Interest Act, 2002",
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_
Enforcement_Of_Security_Interest_Act,_2002"
  },
  "masterTypeOfPurpose": {
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And
Enforcement Of Security Interest Act, 2002",
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_
Enforcement_Of_Security_Interest_Act,_2002"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7f7"
    },
    "firstName": "Uttam",
    "type": "CREDITOFFICER",
    "_id": "64cb5e480faf29427aca80c8",
    "lastName": "Sanap",
    "mobileNo": "02225009143",
    "workMobileNo": "7028022330",
    "email": "racpc.ghatkopar@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "0",
```

```
"discussWithPerson": "Uttam",
"expectedFees": null,
"quotedAmount": "2500"
},
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7f7",
  "branchCode": "000064",
  "type": "BRANCH",
  "name": "RACPC Ghatkopar (West)",
  "email": "racpcghatkopar.sanctions@sbi.co.in",
  "mobileNo": "022-25009143",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, 1st Floor, Ashok Silk Mills
Compound, LBS Marg, Ghatkopar (West), Mumbai - 400 086, State - Maharashtra,
Country - India.\r\n\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA - RACPC GHATKOPAR",
  "fax": "022-25009010",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
```

```
"_id": "60e03dac6576061dae462469",
"zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60b7177d2ffdf65bcd65882a",
    "role": "PICKUPPERSON",
    "firstName": "Saurabh",
    "email": "saurabhvelonde143@gmail.com",
    "lastName": "Velonde",
    "mobileNo": "8691048846",
    "shortName": "SSV",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1722582806298_image.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "648fcad91b499c2d52dc86f3",
    "role": "SITEENGINEER",
    "firstName": "Barkat",
    "email": "barkathodekar68@gmail.com",
    "lastName": "Hodekar",
    "mobileNo": "8879011615",
    "designation": "Site Engg",
    "shortName": "Barkat",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "64cde526dc9f3034f3fefa49",
    "role": "FRONTDESK",
    "firstName": "Rashmi",
    "email": "rashmijadhav14feb@gmail.com",
    "lastName": "Jadhav",
    "mobileNo": "7738144625",
    "designation": "Back Office Coordination",
    "shortName": "RJ",
    "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
    "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
  },
  "maker": {
```

```
"type": "EMPLOYEE",
"_id": "62fe044a48a26047e6552796",
"role": "MAKER",
"firstName": "Pradnya ",
"email": "pradnya@vastukala.org",
"lastName": "Rasam",
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "[N]C.C.I.T/I -14/52/2008-09",
"label": "Wealth Tax"
}
],
"type": "EMPLOYEE",
"_id": "6084131a13f01f158c6ea1f3",
"PANNo": "AEAPC7114Q",
"role": "VALUER",
"firstName": "Sharadkumar",
"fatherName": "Baburao",
"email": "cmd@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9422171100",
"designation": "CMD",
"registrationNo": [
{
"title": {
"value": "Wealth_Tax",
"label": "Wealth Tax"
},
}_id": "6084131a13f01f158c6ea1f4",
"number": "[N]C.C.I.T/I -14/52/2008-09"
}
],
"shortName": "SBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\6084131a13f01f158c6ea1f3\
\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
```

```
    }
  ]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.148373811931894",
  "longitude": "72.92629960924387"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.92629960924387,
    19.148373811931894
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2025-01-21",
      "remark": "NPA case "
    },
    {
      "status": "COMPLETED",
      "dateTime": "2025-01-20",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
```

```
"key": "state",
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "Country - India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Kanjur",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "6",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban ",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
}
```

```
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kurla",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Sainath Tower Co-Op. Hsg. Soc. Ltd. ",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Sai Vihar Marg",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
```

```
"value": "",
"label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
```



```
"status": true,
"name": "CTS No.",
"key": "CTSNo",
"value": "35/B & 35/C",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "601",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
```

```
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 078",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Bhandup (West)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Aluminium_Sliding_Windows_with_window_grills",
```

```

    "label": "Aluminium Sliding Windows with window grills"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement Plastering + POP Finish",
    "label": "Cement Plastering + POP Finish"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Slum_Rehabilitation_Authority",
    "label": "Slum Rehabilitation Authority"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Sai Vihar Marg",
    "west": "Slum Area",
    "south": "Wing -A",
    "east": "Shraddha Orchid Avenue Building "
  },
  "asPerDocumentAgreement": {
    "north": "Details not available ",
    "west": "Details not available ",
    "south": "Details not available ",
    "east": "Details not available "
  },
  "unitBoundaries": {

```

```
"asPerActual": {
  "north": "Flat No. 602",
  "east": "Passage ",
  "south": "Lift",
  "west": "Marginal Space "
},
"asPerDocument": {
  "north": "Details not available ",
  "east": "Details not available ",
  "south": "Details not available ",
  "west": "Details not available "
},
"isDisplay": false,
"title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Approved Building plans were not provided and not verified.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A.",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "0",
  "depreciationRatioOfBuilding": ""
```

```
"salvageValue": "",
"buildingServicesDepreciatedRate": "0",
"depreciatedCostOfConstruction": "20000.00",
"depreciatedBuildingRate": "3000"
},
"igrRate": {
"propertyName": "Residential Flat",
"rate": "125950",
"landRate": "60030",
"igrImage": "cases/678b8df5290edae64f1a3857/igr_1737437365378_Image.png",
"squareMeterGuideLineRate": "132248.00",
"squareFeetGuideLineRate": "12286.00"
},
"igrFinalRate": {
"floorRatePercentage": "5",
"depreciationPercentage": "0",
"rate": "125950.00",
"squareMeterGuideLineRate": "132248.00",
"squareFeetGuideLineRate": "12286.00"
},
"outgoingDetail": {
"areaStatusList": {
"value": "Medium",
"label": "Medium"
},
"propertyTypeOfUseList": {
"value": "Residential_Purpose",
"label": "Residential Purpose"
},
"propertyOccupiedByList": {
"value": "Owner_Occupied",
"label": "Owner Occupied"
},
"monthlyRent": "N.A",
"assessmentNo": "Details not available ",
"taxPaidHolderName": "Details not available ",
"taxAmount": "Details not available ",
"electricityServiceConnectionNo": "Details not available ",
"meterCardHolderName": "Details not available ",
"undividedAreaOfLandAsPerSaleDeed": "Details not available ",
"floorSpaceIndex": "As per SRA norms",
"tenantName": "",
"maintenanceOfFlat": "Good "
},
"marketability": {
"marketabilityList": {
```

```
"value": "Good",
"label": "Good"
},
"anyFavouringForExtraPotentialValue": "Located in developed area ",
"negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
"roof": {
"value": "rcc_Slab",
"label": "R. C. C. Slab"
},
"partitions": {
"value": "6\"_Thk._Brick_Masonry",
"label": "6\" Thk. Brick Masonery"
},
"waterTank": {
"value": "MunicipalWaterSupply",
"label": "Municipal Water Supply"
},
"pavementLaid": {
"value": "Yes",
"label": "Yes"
},
"carParking": "Stilt / Open Car Parking Space ",
"constructionWorkStatus": {
"value": "Completed",
"label": "Completed"
},
"asthetikLook": {
"value": "Plain_Looking",
"label": "Plain Looking"
},
"dateOfConstruction": {
"date": "1",
"month": "1",
"year": "2024",
"fullDate": "1/1/2024"
},
"planningArea": {
"value": "Residential",
"label": "Residential"
},
"typeOfStructure": {
"value": "R.C.C._Framed_Structure",
"label": "R.C.C. Framed Structure"
},
}
```

```
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenancelssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
```

```
"label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_site_information",
  "label": "As per site information"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "59",
"ageOfBuilding": "1",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "22",
"flatFloorNo": "6",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "8"
},
"finalPlinthArea": {
  "area": "321.20",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/678b8df5290edae64f1a3857/
routeMap_1737444803154_Image.png",
    "routeLat": "19.148317",
    "routeLng": "72.926621",
    "stationName": "Bhandup",
    "routeDistance": "1.9 Km. ",
    "routeStation": {
      "value": "Railway_Station",
```



```
    "label": "Railway Station"
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latlng": false,
  "finallatlng": false
},
"locationMapImg": [
  {
    "id": "41d1eg",
    "name": "41d1eg",
    "image": "cases/678b8df5290edae64f1a3857/
routeMap_1737444142485_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
```

```
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "5840000.00",
"distressValuePercentage": "70",
"realizableValuePercentage": "85",
"bookValue": "0",
"finalValue": "5840000.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
},
```

```
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
```

```
    "label": "Work Completed (%)",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": true,
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "3946263.00",
  "selectedBuildUpValue": "321.20",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "678f215a601c90e6962393ad",
      "name": "externallmg_1737433430941_1737433425228_image_4.jpeg",
      "path": "cases/678b8df5290edae64f1a3857/
externallmg_1737433430941_1737433425228_image_4.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "678f2132290edae64f1b3459",
      "name": "externallmg_1737433387046_1737433378457_image_6.jpeg",
      "path": "cases/678b8df5290edae64f1a3857/
externallmg_1737433387046_1737433378457_image_6.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "678f2132290edae64f1b345a",
      "name": "externallmg_1737433387438_1737433378457_image_7.jpeg",
      "path": "cases/678b8df5290edae64f1a3857/
externallmg_1737433387438_1737433378457_image_7.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "678f2132290edae64f1b3457",
      "name": "externallmg_1737433384258_1737433378457_image_4.jpeg",
      "path": "cases/678b8df5290edae64f1a3857/
externallmg_1737433384258_1737433378457_image_4.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "678f2132290edae64f1b345c",
    "name": "externallmg_1737433388666_1737433378457_image_9.jpeg",
    "path": "cases/678b8df5290edae64f1a3857/
externallmg_1737433388666_1737433378457_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "678f2132290edae64f1b345b",
    "name": "externallmg_1737433388284_1737433378457_image_8.jpeg",
    "path": "cases/678b8df5290edae64f1a3857/
externallmg_1737433388284_1737433378457_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "678f2132290edae64f1b345e",
    "name": "externallmg_1737433389507_1737433378457_image_11.jpeg",
    "path": "cases/678b8df5290edae64f1a3857/
externallmg_1737433389507_1737433378457_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "678f2132290edae64f1b3462",
    "name": "externallmg_1737433393082_1737433378457_image_15.jpeg",
    "path": "cases/678b8df5290edae64f1a3857/
externallmg_1737433393082_1737433378457_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "678f215a601c90e6962393af",
    "name": "externallmg_1737433432401_1737433425228_image_6.jpeg",
    "path": "cases/678b8df5290edae64f1a3857/
externallmg_1737433432401_1737433425228_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "678f4cb55a336ce64e571d73",
    "name": "externallmg_1737444526744_Picture1.jpg",
```

```
    "path": "cases/678b8df5290edae64f1a3857/
externallmg_1737444526744_Picture1.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "18620.00",
    "max": "22858.00"
  },
  "builtUpRateRange": {
    "min": "16927.00",
    "max": "20780.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```

```
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```



```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
{others": {
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
totalValues": {
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
taskStatus": {
"SITE_INSPECTION": true,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
createCase": "false",
type": "CASE",
leadType": {
"label": "Lead",
"value": "LEAD"
},
siteVisitType": "PARTIAL",
isExternalReport": false,
isSiteMeasurementAllowed": true,
finalValuationArea": "292.00",
empanelmentNo": [
"SME/TCC/2021-22/85/13"
```

```
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "678b8df5290edae64f1a3857",
"ownerName": "Mr. Rupesh Gangadhar Angane & Mrs. Rutuja Rupesh Angane ",
"ownerPhoneNo": "9870593203",
"appAddress": "Flat no. 601, 6th Floor, Sainath Tower, Wing - B, Bhandup West ",
"remark": "NPA case ",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "16/11/2021",
      "from": {
        "value": "Developers",
        "label": "Developers"
      },
      "Developers": "M/s. Sainath Developers ",
      "to": {
        "value": "Purchasers",
        "label": "Purchasers"
      },
      "Purchasers": "Mr. Rupesh Gangadhar Angane & Mrs. Rutuja Rupesh Angane ",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "20746 / 2021"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1737439407765_Agreement.pdf",
    "path": "cases/678b8df5290edae64f1a3857/
document_1737439407765_Agreement.pdf",
    "id": "613218",
    "uploadedBy": "62fe044a48a26047e6552796",
    "createdAt": "Tue Jan 21 2025 06:03:27 GMT+0000 (Coordinated Universal Time)"
  },
  {
```

```
"documentType": {
  "value": "60ae1247aa6d152c1801b2ea",
  "label": "Commencement Certificate"
},
"inputs": {
  "documentDate": "06/12/2019",
  "nameOfApprovingAuthority": {
    "value": "Slum_Rehabilitation_Authority_(SRA)",
    "label": "Slum Rehabilitation Authority (SRA)"
  },
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "S / PVT / 0137 / 20170601 / AP / R"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1737441617417_CC.pdf",
"path": "cases/678b8df5290edae64f1a3857/document_1737441617417_CC.pdf",
"id": "327553",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Tue Jan 21 2025 06:40:17 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "08/09/2021",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "P51800023902"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1737441697442_RERA.pdf",
  "path": "cases/678b8df5290edae64f1a3857/document_1737441697442_RERA.pdf",
  "id": "712558",
```

```
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Tue Jan 21 2025 06:41:37 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae1248aa6d152c1801b2ee",
    "label": "Previous Valuation Report"
  },
  "inputs": {
    "documentDate": "07/12/2021",
    "remark": " in the name of Mr. Rupesh Gangadhar Angane & Mrs. Rutuja Rupesh Angane issued by Vastukala Consultants Pvt. Ltd"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1737444719091_Previous_Report.pdf",
  "path": "cases/678b8df5290edae64f1a3857/
document_1737444719091_Previous_Report.pdf",
  "id": "569902",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Tue Jan 21 2025 07:31:59 GMT+0000 (Coordinated Universal Time)"
}
],
"caseNumber": "013754",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "961881",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Jan 18 2025 11:18:13 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Mr. Rupesh Gangadhar Angane & Mrs. Rutuja Rupesh Angane ",
    "phone": "9870593203",
    "ownershipShare": "",
    "email": "",
    "id": "270519"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
```

```
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "5",
"name": "Living Room",
"length": "13.75",
"length1": "13",
"length2": "9",
"width": "7.75",
"width1": "7",
"width2": "9",
"totalArea": "106.56",
"images": [],
"finalArea": "106.56",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Kitchen",
  "length": "7.75",
  "length1": "7",
  "length2": "9",
  "width": "5.67",
  "width1": "5",
  "width2": "8",
  "totalArea": "43.92",
  "images": [],
  "extraAreas": [],
  "finalArea": "43.92"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Passage",
  "length": "3.67",
  "length1": "3",
  "length2": "8",
  "width": "6.92",
```

```
"width1": "6",
"width2": "11",
"totalArea": "25.36",
"images": [],
"extraAreas": [],
"finalArea": "25.36"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Toilet",
  "length": "7.00",
  "length1": "7",
  "length2": "00",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "28.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "28.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bedroom",
  "length": "10.17",
  "length1": "10",
  "length2": "2",
  "width": "8.00",
  "width1": "8",
  "width2": "00",
  "totalArea": "81.33",
  "images": [],
  "extraAreas": [],
  "finalArea": "81.33"
}
],
"otherComposition": [],
"externalReport": [],
```

```
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "875168",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "292",
    "squareMeterArea": "27.13",
    "docFinalBuiltUp": "321.2",
    "docFinalBuiltUpSquareMeter": "29.843",
    "docBuiltupPercentage": "10",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "258.00",
      "squareMeterArea": "23.97",
      "expectedRate": "22081.40",
      "percentage": ""
    },
    "builtUpArea": {
      "area": "283.80",
      "squareMeterArea": "26.37",
      "expectedRate": "20074.00",
      "percentage": "10"
    },
    "saleableArea": {
      "area": "",
      "squareMeterArea": "0.00",
      "expectedRate": "0.00",
      "percentage": ""
    }
  },
  "printlnReport": true,
  "_id": "678f3124290edae64f1b50c1",
  "property": "Residential Flat",
```

```
"area": "258",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "https://www.99acres.com/",
"expectedPrice": "5697000",
"expectedRate": "22081.40",
"builtUpExpectedRate": "20074.00",
"image": "cases/678b8df5290edae64f1a3857/
indicator_1737437101822_Image.png",
"squareMeter": "23.97",
"id": "831372"
},
{
"carpetArea": {
"area": "350.00",
"squareMeterArea": "32.52",
"expectedRate": "22857.14",
"percentage": ""
},
"builtUpArea": {
"area": "385.00",
"squareMeterArea": "35.77",
"expectedRate": "20779.22",
"percentage": "10"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "678f3124290edae64f1b50c2",
"property": "Residential Flat",
"area": "350",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "https://www.99acres.com/",
"expectedPrice": "8000000",
"expectedRate": "22857.14",
```



```
"builtUpExpectedRate": "20779.22",
"image": "cases/678b8df5290edae64f1a3857/
indicator_1737437224453_Image.png",
"squareMeter": "32.52",
"id": "976620"
},
{
"carpetArea": {
"area": "354.00",
"squareMeterArea": "32.89",
"expectedRate": "19774.01",
"percentage": ""
},
"builtUpArea": {
"area": "389.40",
"squareMeterArea": "36.18",
"expectedRate": "17976.37",
"percentage": "10"
},
"saleableArea": {
"area": "0.00",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printInReport": true,
"_id": "678f3124290edae64f1b50c3",
"property": "Residential Flat",
"area": "354",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "7000000",
"expectedRate": "19774.01",
"builtUpExpectedRate": "17976.37",
"image": "cases/678b8df5290edae64f1a3857/
indicator_1737437251697_Image.png",
"squareMeter": "32.89",
"id": "230112"
},
{
"carpetArea": {
"area": "239.00",
```

```
    "squareMeterArea": "22.20",
    "expectedRate": "18619.25",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "262.90",
    "squareMeterArea": "24.42",
    "expectedRate": "16926.59",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "678f3124290edae64f1b50c4",
  "property": "Residential Flat",
  "area": "239",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "4450000",
  "expectedRate": "18619.25",
  "builtUpExpectedRate": "16926.59",
  "image": "cases/678b8df5290edae64f1a3857/
indicator_1737437283300_Image.png",
  "squareMeter": "22.20",
  "id": "192717"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678f2132290edae64f1b3453",
    "name": "externalImg_1737433381505_1737433378457_image_0.jpeg",
    "path": "cases/678b8df5290edae64f1a3857/
externalImg_1737433381505_1737433378457_image_0.jpeg",
    "orientation": "landscape"
  },
  {
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678f2132290edae64f1b3454",
    "name": "externallmg_1737433381983_1737433378457_image_1.jpeg",
    "path": "cases/678b8df5290edae64f1a3857/
externallmg_1737433381983_1737433378457_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678f2132290edae64f1b3455",
    "name": "externallmg_1737433382556_1737433378457_image_2.jpeg",
    "path": "cases/678b8df5290edae64f1a3857/
externallmg_1737433382556_1737433378457_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678f2132290edae64f1b3456",
    "name": "externallmg_1737433383630_1737433378457_image_3.jpeg",
    "path": "cases/678b8df5290edae64f1a3857/
externallmg_1737433383630_1737433378457_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678f2132290edae64f1b3457",
    "name": "externallmg_1737433384258_1737433378457_image_4.jpeg",
    "path": "cases/678b8df5290edae64f1a3857/
externallmg_1737433384258_1737433378457_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678f2132290edae64f1b3458",
    "name": "externallmg_1737433386521_1737433378457_image_5.jpeg",
    "path": "cases/678b8df5290edae64f1a3857/
externallmg_1737433386521_1737433378457_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "678f2132290edae64f1b3459",
  "name": "externallmg_1737433387046_1737433378457_image_6.jpeg",
  "path": "cases/678b8df5290edae64f1a3857/
externallmg_1737433387046_1737433378457_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "678f2132290edae64f1b345a",
  "name": "externallmg_1737433387438_1737433378457_image_7.jpeg",
  "path": "cases/678b8df5290edae64f1a3857/
externallmg_1737433387438_1737433378457_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "678f2132290edae64f1b345b",
  "name": "externallmg_1737433388284_1737433378457_image_8.jpeg",
  "path": "cases/678b8df5290edae64f1a3857/
externallmg_1737433388284_1737433378457_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "678f2132290edae64f1b345c",
  "name": "externallmg_1737433388666_1737433378457_image_9.jpeg",
  "path": "cases/678b8df5290edae64f1a3857/
externallmg_1737433388666_1737433378457_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "678f2132290edae64f1b345d",
  "name": "externallmg_1737433389143_1737433378457_image_10.jpeg",
  "path": "cases/678b8df5290edae64f1a3857/
externallmg_1737433389143_1737433378457_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "678f2132290edae64f1b345e",
    "name": "externallmg_1737433389507_1737433378457_image_11.jpeg",
    "path": "cases/678b8df5290edae64f1a3857/
externallmg_1737433389507_1737433378457_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678f2132290edae64f1b345f",
    "name": "externallmg_1737433389903_1737433378457_image_12.jpeg",
    "path": "cases/678b8df5290edae64f1a3857/
externallmg_1737433389903_1737433378457_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678f2132290edae64f1b3460",
    "name": "externallmg_1737433390261_1737433378457_image_13.jpeg",
    "path": "cases/678b8df5290edae64f1a3857/
externallmg_1737433390261_1737433378457_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678f2132290edae64f1b3461",
    "name": "externallmg_1737433391128_1737433378457_image_14.jpeg",
    "path": "cases/678b8df5290edae64f1a3857/
externallmg_1737433391128_1737433378457_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678f2132290edae64f1b3462",
    "name": "externallmg_1737433393082_1737433378457_image_15.jpeg",
    "path": "cases/678b8df5290edae64f1a3857/
externallmg_1737433393082_1737433378457_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678f2132290edae64f1b3463",
```

```
    "name": "externallmg_1737433393807_1737433378457_image_16.jpeg",
    "path": "cases/678b8df5290edae64f1a3857/
externallmg_1737433393807_1737433378457_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678f215a601c90e6962393a9",
    "name": "externallmg_1737433429491_1737433425228_image_0.jpeg",
    "path": "cases/678b8df5290edae64f1a3857/
externallmg_1737433429491_1737433425228_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678f215a601c90e6962393aa",
    "name": "externallmg_1737433430014_1737433425228_image_1.jpeg",
    "path": "cases/678b8df5290edae64f1a3857/
externallmg_1737433430014_1737433425228_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678f215a601c90e6962393ab",
    "name": "externallmg_1737433430216_1737433425228_image_2.jpeg",
    "path": "cases/678b8df5290edae64f1a3857/
externallmg_1737433430216_1737433425228_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678f215a601c90e6962393ac",
    "name": "externallmg_1737433430649_1737433425228_image_3.jpeg",
    "path": "cases/678b8df5290edae64f1a3857/
externallmg_1737433430649_1737433425228_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678f215a601c90e6962393ad",
    "name": "externallmg_1737433430941_1737433425228_image_4.jpeg",
```

```
    "path": "cases/678b8df5290edae64f1a3857/
externallmg_1737433430941_1737433425228_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678f215a601c90e6962393ae",
    "name": "externallmg_1737433431674_1737433425228_image_5.jpeg",
    "path": "cases/678b8df5290edae64f1a3857/
externallmg_1737433431674_1737433425228_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678f215a601c90e6962393af",
    "name": "externallmg_1737433432401_1737433425228_image_6.jpeg",
    "path": "cases/678b8df5290edae64f1a3857/
externallmg_1737433432401_1737433425228_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678f215a601c90e6962393b0",
    "name": "externallmg_1737433432578_1737433425228_image_7.jpeg",
    "path": "cases/678b8df5290edae64f1a3857/
externallmg_1737433432578_1737433425228_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678f215a601c90e6962393b1",
    "name": "externallmg_1737433433372_1737433425228_image_8.jpeg",
    "path": "cases/678b8df5290edae64f1a3857/
externallmg_1737433433372_1737433425228_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "678f20fd5a336ce64e56cded",
    "name": "externallmg_1737433341046_1737433281994_image_0.jpeg",
    "path": "cases/678b8df5290edae64f1a3857/
externallmg_1737433341046_1737433281994_image_0.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "678f20fd5a336ce64e56cdee",
  "name": "externallmg_1737433341119_1737433281994_image_1.jpeg",
  "path": "cases/678b8df5290edae64f1a3857/
externallmg_1737433341119_1737433281994_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "678f20fd5a336ce64e56cdef",
  "name": "externallmg_1737433341634_1737433281994_image_2.jpeg",
  "path": "cases/678b8df5290edae64f1a3857/
externallmg_1737433341634_1737433281994_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "678f4caf5a336ce64e571d30",
  "name": "externallmg_1737444526744_Picture1.jpg",
  "path": "cases/678b8df5290edae64f1a3857/
externallmg_1737444526744_Picture1.jpg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation Sheet NEW.xlsx",
    "filename": "1737437430130_Calculation_Sheet_NEW.xlsx",
    "path": "cases/678b8df5290edae64f1a3857/
processingDocuments/1737437430130_Calculation_Sheet_NEW.xlsx",
    "size": "1669991",
    "createdAt": "Tue Jan 21 2025 05:30:45 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  },
  {
    "originalname": "Rupesh Angane.doc",
    "filename": "1737437433433_Rupesh_Angane.doc",
    "path": "cases/678b8df5290edae64f1a3857/
processingDocuments/1737437433433_Rupesh_Angane.doc",
```



```
"size": "4848128",
"createdAt": "Tue Jan 21 2025 05:30:45 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "64cde526dc9f3034f3fefa49"
},
{
  "originalname": "Agreement.pdf",
  "filename": "1737444579751_Agreement.pdf",
  "path": "cases/678b8df5290edae64f1a3857/
processingDocuments/1737444579751_Agreement.pdf",
  "size": "705348",
  "createdAt": "Tue Jan 21 2025 07:29:40 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "62fe044a48a26047e6552796"
},
{
  "originalname": "CC.pdf",
  "filename": "1737444579770_CC.pdf",
  "path": "cases/678b8df5290edae64f1a3857/
processingDocuments/1737444579770_CC.pdf",
  "size": "139588",
  "createdAt": "Tue Jan 21 2025 07:29:40 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "62fe044a48a26047e6552796"
},
{
  "originalname": "Previous Report.pdf",
  "filename": "1737444579775_Previous_Report.pdf",
  "path": "cases/678b8df5290edae64f1a3857/
processingDocuments/1737444579775_Previous_Report.pdf",
  "size": "2174488",
  "createdAt": "Tue Jan 21 2025 07:29:40 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "62fe044a48a26047e6552796"
},
{
  "originalname": "RERA.pdf",
  "filename": "1737444579889_RERA.pdf",
  "path": "cases/678b8df5290edae64f1a3857/
processingDocuments/1737444579889_RERA.pdf",
  "size": "151852",
  "createdAt": "Tue Jan 21 2025 07:29:40 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "62fe044a48a26047e6552796"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-01-18T11:18:13.273Z",
"updatedAt": "2025-01-21T07:33:23.815Z",
```

```
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 601, 6th Floor, Wing - B, Sainath Tower Co-Op.
Hsg. Soc. Ltd. , Sai Vihar Marg, Village - Kanjur, Bhandup (West), Taluka - Kurla,
District - Mumbai Suburban , PIN - 400 078, State - Maharashtra, Country - India",
"updatedBy": "62fe044a48a26047e6552796",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Mr. Rupesh Gangadhar Angane",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "9870593203",
"relationWithOwner": "Owner ",
"rerald": "",
"siteVisitContactNo": "9870593203",
"buildingServicesRate": "3000",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 292.00",
"flatRate": "20000",
"landOtherRate": "17000",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"siteVisitDate": "2025-01-20",
"builtupPercentage": "10",
"carpetTotal": "285.17",
"extendOfSiteRemark": "\nAll the above areas are within 2% of the Agreement for Sale
Area. The above calculations and detailed measurements taken by us prove that the
Agreement for Sale area is not exorbitantly inflated. Hence, valuation is prepared based
on the Agreement for Sale area.",
"finalBuiltupArea": "313.69",
```

```

"finalCarpetArea": "285.17",
"finalSalableArea": "345.06",
"otherCarpetTotal": "0.00",
"salablePercentage": "10",
"siteMeasurementRemark": "\n",
"toBeAdded": "",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Passage + Toilet",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Tue Jan 21 2025 05:54:38 GMT+0000 (Coordinated
Universal Time)"
}

```

Name	Length	Width	Total
Composition :			
Living Room	13'9"	7'9"	106.56
Kitchen	7'9"	5'8"	43.92
Passage	3'8"	6'11"	25.36
Toilet	7'00"	4'00"	28.00
Bedroom	10'2"	8'00"	81.33
Other Composition :			