

```
{
  "typeOfReport": {
    "value": "Land",
    "label": "Land"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Market_Value",
    "label": "Market Value"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
    "name": "Mumbai",
    "shortName": "VCIPL/Mumbai",
    "email": "vastukalamumbai@vastukala.com",
    "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
    "city": "Mumbai"
  },
  "client": {
    "_id": "679721a82aadad0ced13aa08",
    "type": "PRIVATE_CLIENT",
  }
}
```

```
"name": "Mahanagar Gas Limited",
"displayName": "Mahanagar Gas Limited",
"initial": "M"
},
"branch": "",
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Commercial",
  "value": "Commercial"
},
"zone": "",
"staff": {
  "pickupPerson": null,
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "62691c48afd7d55eddecfda3",
    "role": "FRONTDESK",
    "firstName": "Bhavika",
    "email": "bhavikachavan0102@gmail.com",
    "lastName": "chavan",
    "mobileNo": "8390804382",
    "designation": "Site Engineer",
    "shortName": "BH",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
  },
  "rateVerifier": null,
  "maker": null,
  "checker": null,
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "IBBI/RV/07/2018/10366",
          "label": "Registered Valuer"
        }
      ]
    }
  ],
  "type": "EMPLOYEE",
  "_id": "5ffe92d27737ca4d986b6453",
  "role": "VALUER",
  "firstName": "Manoj",
  "email": "manoj@vastukala.org",
```

```
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
```

```
"value": "PRIVATE_CLIENT",
"label": "Private Clients"
},
"location": {
  "latitude": "17.969865888526016",
  "longitude": "73.84346709397843"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "27/01/2025 12:00 am",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  }
}
```

```
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Ekasar",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "NA",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
```

```
"key": "taluka",
"value": "Borivali",
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
}
```

```
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "1480/A",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
```

```
"value": "",
"label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
```



```
"status": false,
"name": "Gut No.",
"key": "GUTNo",
"value": "",
"label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Borivali West",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
```

```
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
}
```

```
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
```

```
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "0",
"selectedBuildUpValue": "0",
"selectedBuildUpMeasurementType": ""
},
"reportImages": {
"frontPageImages": [],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
"carpetRateRange": {
"min": "0.00",
"max": "0.00"
},
"builtUpRateRange": {
"min": "0.00",
"max": "0.00"
},
"saleableRateRange": {
"min": "0.00",
"max": "0.00"
}
```

```
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
    "title": "Interior Decorations",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
```

```
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "true",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "679721a82aadad0ced13aa0e",
"ownerName": "Mahanagar Gas Limited",
"ownerPhoneNo": "0000000000",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "8657944508",
"contactPersonName": "Mr Shashank",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "Mahanagar Gas Limited",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "494558"
  }
]
```



```
],
"caseReferredBy": "5ff3ead28cda966090eachbbe",
"relationWithOwner": "Contact Person",
"fullAddress": "Commercial Land No. NA Floor, CTS No. 1480/A, Village - Ekasar,
Borivali West, Taluka - Borivali, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae12b5aa6d152c1801b4e6",
      "label": "Development Plan Remark"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1737957621267_DP_Remarks.pdf",
    "path": "cases/679721a82aadad0ced13aa0e/
document_1737957621267_DP_Remarks.pdf",
    "id": "377825",
    "uploadedBy": "6006d4ce5080a310ac1fdcf2",
    "createdAt": "Mon Jan 27 2025 06:03:20 GMT+0000 (Coordinated Universal Time)"
  },
  {
    "documentType": {
      "value": "60ae124baa6d152c1801b2fd",
      "label": "Occupancy Certificate"
    },
    "inputs": {
      "documentDate": "25/08/2005",
      "nameOfApprovingAuthority": {
        "value": "BRIHANMUMBAI_MAHANAGARPALIKA",
        "label": "BRIHANMUMBAI MAHANAGARPALIKA"
      },
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "NO CHE/A-3254/BP(WS)AR"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1737957741299_OC.pdf",
    "path": "cases/679721a82aadad0ced13aa0e/document_1737957741299_OC.pdf",
    "id": "107457",
    "uploadedBy": "6006d4ce5080a310ac1fdcf2",
    "createdAt": "Mon Jan 27 2025 06:03:20 GMT+0000 (Coordinated Universal Time)"
  },
]
```

```
{
  "documentType": {
    "value": "60ae1249aa6d152c1801b2f4",
    "label": "Property Register Card"
  },
  "inputs": {
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "79531791092"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1737957798583_Property_Card_1480A.pdf",
  "path": "cases/679721a82aadad0ced13aa0e/
document_1737957798583_Property_Card_1480A.pdf",
  "id": "335649",
  "uploadedBy": "6006d4ce5080a310ac1fd2",
  "createdAt": "Mon Jan 27 2025 06:03:20 GMT+0000 (Coordinated Universal Time)"
}
],
"isUrgent": "false",
"isExternal": "false",
"proposePurchaserName": "",
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"rerald": "",
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "013947",
"createdBy": "6006d4ce5080a310ac1fd2",
"caseHistory": [
  {
    "id": "513361",
    "title": "Create Case",
    "description": "Create Case",
    "datetime": "Mon Jan 27 2025 06:03:20 GMT+0000 (Coordinated Universal Time)"
  }
]
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
```

```
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67986ed86258b1a576716f53",
    "name": "externallmg_1738042912239_1738042907839_image_0.jpeg",
    "path": "cases/679721a82aadad0ced13aa0e/
externallmg_1738042912239_1738042907839_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67986ed86258b1a576716f54",
    "name": "externallmg_1738042931827_1738042907839_image_1.jpeg",
    "path": "cases/679721a82aadad0ced13aa0e/
externallmg_1738042931827_1738042907839_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67986ed86258b1a576716f55",
    "name": "externallmg_1738042972803_1738042907839_image_2.jpeg",
    "path": "cases/679721a82aadad0ced13aa0e/
externallmg_1738042972803_1738042907839_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67986ed86258b1a576716f56",
    "name": "externallmg_1738042981510_1738042907839_image_3.jpeg",
    "path": "cases/679721a82aadad0ced13aa0e/
externallmg_1738042981510_1738042907839_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67986ed86258b1a576716f57",
    "name": "externallmg_1738042996192_1738042907839_image_4.jpeg",
    "path": "cases/679721a82aadad0ced13aa0e/
externallmg_1738042996192_1738042907839_image_4.jpeg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67986ed86258b1a576716f58",
  "name": "externallmg_1738043009223_1738042907839_image_5.jpeg",
  "path": "cases/679721a82aadad0ced13aa0e/
externallmg_1738043009223_1738042907839_image_5.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67986ed86258b1a576716f59",
  "name": "externallmg_1738043052723_1738042907839_image_6.jpeg",
  "path": "cases/679721a82aadad0ced13aa0e/
externallmg_1738043052723_1738042907839_image_6.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67986ed86258b1a576716f5a",
  "name": "externallmg_1738043081409_1738042907839_image_7.jpeg",
  "path": "cases/679721a82aadad0ced13aa0e/
externallmg_1738043081409_1738042907839_image_7.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67986ed86258b1a576716f5b",
  "name": "externallmg_1738043085785_1738042907839_image_8.jpeg",
  "path": "cases/679721a82aadad0ced13aa0e/
externallmg_1738043085785_1738042907839_image_8.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67986ed86258b1a576716f5c",
  "name": "externallmg_1738043090858_1738042907839_image_9.jpeg",
  "path": "cases/679721a82aadad0ced13aa0e/
externallmg_1738043090858_1738042907839_image_9.jpeg",
  "orientation": "landscape"
}
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67986ed86258b1a576716f5d",
    "name": "externallmg_1738043094963_1738042907839_image_10.jpeg",
    "path": "cases/679721a82aadad0ced13aa0e/
externallmg_1738043094963_1738042907839_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67986ee02f3738a577c884c6",
    "name": "externallmg_1738042895495_1738042878809_image_0.jpeg",
    "path": "cases/679721a82aadad0ced13aa0e/
externallmg_1738042895495_1738042878809_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67986ee02f3738a577c884c7",
    "name": "externallmg_1738042902478_1738042878810_image_1.jpeg",
    "path": "cases/679721a82aadad0ced13aa0e/
externallmg_1738042902478_1738042878810_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67986ee02f3738a577c884c8",
    "name": "externallmg_1738042915066_1738042878810_image_2.jpeg",
    "path": "cases/679721a82aadad0ced13aa0e/
externallmg_1738042915066_1738042878810_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67986ee02f3738a577c884c9",
    "name": "externallmg_1738042928960_1738042878810_image_3.jpeg",
    "path": "cases/679721a82aadad0ced13aa0e/
externallmg_1738042928960_1738042878810_image_3.jpeg",
    "orientation": "landscape"
  },
}
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67986ee02f3738a577c884ca",
  "name": "externallmg_1738042958545_1738042878810_image_4.jpeg",
  "path": "cases/679721a82aadad0ced13aa0e/
externallmg_1738042958545_1738042878810_image_4.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67986ee02f3738a577c884cb",
  "name": "externallmg_1738043014084_1738042878810_image_5.jpeg",
  "path": "cases/679721a82aadad0ced13aa0e/
externallmg_1738043014084_1738042878810_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67986ee02f3738a577c884cc",
  "name": "externallmg_1738043015240_1738042878810_image_6.jpeg",
  "path": "cases/679721a82aadad0ced13aa0e/
externallmg_1738043015240_1738042878810_image_6.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67986ee02f3738a577c884cd",
  "name": "externallmg_1738043029798_1738042878810_image_7.jpeg",
  "path": "cases/679721a82aadad0ced13aa0e/
externallmg_1738043029798_1738042878810_image_7.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67986ee02f3738a577c884ce",
  "name": "externallmg_1738043034809_1738042878810_image_8.jpeg",
  "path": "cases/679721a82aadad0ced13aa0e/
externallmg_1738043034809_1738042878810_image_8.jpeg",
  "orientation": "landscape"
},
{
```

```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67986ee02f3738a577c884cf",
    "name": "externallmg_1738043038242_1738042878810_image_9.jpeg",
    "path": "cases/679721a82aadad0ced13aa0e/
externallmg_1738043038242_1738042878810_image_9.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67986ee02f3738a577c884d0",
    "name": "externallmg_1738043040945_1738042878810_image_10.jpeg",
    "path": "cases/679721a82aadad0ced13aa0e/
externallmg_1738043040945_1738042878810_image_10.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67986ee02f3738a577c884d1",
    "name": "externallmg_1738043055267_1738042878810_image_11.jpeg",
    "path": "cases/679721a82aadad0ced13aa0e/
externallmg_1738043055267_1738042878810_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67986ee02f3738a577c884d2",
    "name": "externallmg_1738043062188_1738042878810_image_12.jpeg",
    "path": "cases/679721a82aadad0ced13aa0e/
externallmg_1738043062188_1738042878810_image_12.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67986ee02f3738a577c884d3",
    "name": "externallmg_1738043072564_1738042878810_image_13.jpeg",
    "path": "cases/679721a82aadad0ced13aa0e/
externallmg_1738043072564_1738042878810_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
```

```
    "status": false,
    "_id": "67986ee02f3738a577c884d4",
    "name": "externallmg_1738043076008_1738042878810_image_14.jpeg",
    "path": "cases/679721a82aadad0ced13aa0e/
externallmg_1738043076008_1738042878810_image_14.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67986ee02f3738a577c884d5",
    "name": "externallmg_1738043084130_1738042878810_image_15.jpeg",
    "path": "cases/679721a82aadad0ced13aa0e/
externallmg_1738043084130_1738042878810_image_15.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67986ee02f3738a577c884d6",
    "name": "externallmg_1738043090724_1738042878810_image_16.jpeg",
    "path": "cases/679721a82aadad0ced13aa0e/
externallmg_1738043090724_1738042878810_image_16.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67986ee02f3738a577c884d7",
    "name": "externallmg_1738043095961_1738042878810_image_17.jpeg",
    "path": "cases/679721a82aadad0ced13aa0e/
externallmg_1738043095961_1738042878810_image_17.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67986ee02f3738a577c884d8",
    "name": "externallmg_1738043096874_1738042878810_image_18.jpeg",
    "path": "cases/679721a82aadad0ced13aa0e/
externallmg_1738043096874_1738042878810_image_18.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
```



```

    "_id": "67986ee02f3738a577c884d9",
    "name": "externalimg_1738043099886_1738042878811_image_19.jpeg",
    "path": "cases/679721a82aadad0ced13aa0e/
externalimg_1738043099886_1738042878811_image_19.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-01-27T06:03:20.786Z",
"updatedAt": "2025-01-28T05:45:04.775Z",
"__v": 0,
"addressForMap": "",
"updatedBy": "62691c48afd7d55eddecfda3"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			