

Vastukala Consultants (I) Pvt. Ltd.

Structural Stability Report Prepared for JSB / Goregaon (West) Branch / Mr Gangaram K. Bhoir (14226/2310496) Page 1 of 3

www.vastukala.co.in

Vastu/Mumbai/02/2025/14226/2310496

11/05-146-SOV

Date: 11.02.2025

Structural Stability Report

Structural Observation Report of Residential Flat No. 305, 3rd Floor, Building No. 4, “**Shree Swami Samarth Co-Op. Hsg. Soc. Ltd.**”, M. G. Road, Sane Guruji Nagar, Teen Dongri, Village - Pahadi Goregaon, Goregaon (West), Taluka - Borivali, District - Mumbai Suburban, Mumbai, 400 104, State - Maharashtra, India.

Name of Owner: **Mr. Gangaram Keru Bhoir.**

This is to certify that on visual inspection, it appears that the structure of the at “**Shree Swami Samarth Co-Op. Hsg. Soc. Ltd.**”, is in Normal condition and the future life can be reasonably taken under Normal condition and with proper periodic repairs & maintenance is about 10 years.

General Information:

A.	Introduction	
1	Name of Building	“ Shree Swami Samarth Co-Op. Hsg. Soc. Ltd. ”
2	Property Address	Residential Flat No. 305, 3 rd Floor, Building No 4, “ Shree Swami Samarth Co-Op. Hsg. Soc. Ltd. ”, M. G. Road, Sane Guruji Nagar, Teen Dongri, Village - Pahadi Goregaon, Goregaon (West), Taluka - Borivali, District - Mumbai Suburban, Mumbai, 400 104, State - Maharashtra, India
3	Type of Building	Residential used
4	No. of Floors	Ground + 4 th Upper Floors
5	Whether stilt / podium / open parking provided	Open Car Parking Space
6	Type of Construction	R.C.C. Framed Structure
7	Type of Foundation	R.C.C. Footing
8	Thickness of the External Walls	9” thick brick walls both sides plastered
9	Type of Compound	Brick Masonry Walls
10	Year of Construction	1975 (As per site information)
11	Present age of building	50 years
12	Expected Balance life of the building	10 years Subject to proper, preventive periodic maintenance & structural repairs.
13	No. of flats (Per Floor)	08 Flats on 3 th Floor
14	Methodology adopted	As per visual site inspection

B.	External Observation of the Building	
1	Plaster	Normal Condition
2	Chajjas	Normal Condition
3	Plumbing	Normal Condition
4	Cracks on the external walls	Minor Cracks Found
5	Filling cracks on the external walls	Found
6	Cracks on columns & beams	Some Places



Our Pan India Presence at :

📍 Nanded 📍 Thane 📍 Ahmedabad 📍 Delhi NCR
📍 Mumbai 📍 Nashik 📍 Rajkot 📍 Raipur
📍 Aurangabad 📍 Pune 📍 Indore 📍 Jaipur

Regd. Office

B1-001, U/B Floor, BOOMERANG, Chandivali Farm Road, Powai, Andheri East, **Mumbai:** 400072, (M.S), India

+91 2247495919

mumbai@vastukala.co.in

www.vastukala.co.in

7	Vegetation	Found
8	Leakages of water in the drainage pipes or water pipes	Found
9	Dampness external in the wall due to leakages	Found
10	Any other observation about the condition of external side of the building	Structural Stability Report from licensed structural engineers not provided for our verification.
C	Internal Observation of the common areas of the building and captioned premises	
1	Beams (Cracks & Leakages)	Not Found
2	Columns (Cracks & Leakages)	Found
3	Ceiling (Cracks & Leakages)	Found
4	Leakages inside the property	Minor Leakages Found
5	Painting inside the property	Normal Condition
6	Maintenance of staircase & cracks	Minor Cracks Found

D	Common Observation	
1	Structural Audit of the Building Under Bye – Laws No. 77 of the Model Bye Laws (Co-Operative Societies Act / Rules)	As per bye Laws No. 77 of Co-Op. Societies bye Laws under the Act the society shall conduct a Structural Audit of the building of the society as follows
2	Remark	No Structural Audit Report is furnished for the perusal.

E	Conclusion
<p>The captioned building is having Ground + 4th Upper Floors which are constructed in year 1975 (As Per site information) Estimated future life under present circumstances is about 10 years subject to proper, preventive periodic maintenance & structural repairs.</p> <p>The inspection dated 08.02.2025 of building. The building is well as the property is maintained in normal condition & will stand future life subject to proper, preventive periodic maintenance & normal structural repairs. Our Observations about the structure are given above.</p> <p>The above assessment is based on visual inspection only. Separate structural audit from licensed structural engineers is advised to assess exact balance life of structure.</p>	

For VASTUKALA CONSULTANTS (I) PVT. LTD.

Manoj
Chalikwar

Director

Manoj Baburao Chalikwar

Structural Engineer Licence No. STATE/R/2025/APL/15680

Govt. Reg. Valuer

Chartered Engineer (India)

Reg. No. IBBI/RV/07/2018/10366

Janaseva Sahakari Bank (Borivali) LTD Empanelment No.: 36/ LOAN H.O./2016-17/232

Digitally signed by Manoj Chalikwar
DN: cn=Manoj Chalikwar, o=Vastukala
Consultants (I) Pvt. Ltd., ou=Mumbai,
email=manoj@vastukala.org, c=IN
Date: 2025.02.11 13:06:38 +05'30'



Auth. Sign.




Since 1989

Vastukala Consultants (I) Pvt. Ltd.

An ISO 9001 : 2015 Certified Company



Actual site photographs



Since 1989

Vastukala Consultants (I) Pvt. Ltd.

An ISO 9001 : 2015 Certified Company

