

```
{
  "typeOfReport": {
    "label": "Structural Report",
    "value": "Structural_Report"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "65efcb25857bdc098a9a168f"
    },
    "firstName": "Parmod",
    "type": "CREDITOFFICER",
    "_id": "65f13018857bdc098a9c0c7d",
    "lastName": "Kalyanour",
    "mobileNo": "",
    "workMobileNo": "8657004344",
    "email": "kallyanpurpm@svcbank.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "17625324",
    "discussWithPerson": "Parmod",
    "expectedFees": 8812.662,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d185c",
  "type": "BANK",
  "name": "SVC CO-OPERATIVE BANK LTD",
  "displayName": "SVC BANK",
  "initial": "SVC",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "65efcb25857bdc098a9a168f",
  "name": "Goregaon West Branch",
  "branchCode": "",
  "mobileNo": "8657004344",
  "alternateMobileNo": "8657004345",
  "email": "GoregaonOU@svcbank.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "12, Udyog Nagar,Time Star Building, S.V.Road, Goregaon(W), Mumbai -
400062"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60fbaf81d8cfc56a13fa8863",
  "zoneName": "PAN INDIA"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
    "_id": "60af6ae22ffdf65bcd65861d",
    "role": "PICKUPPERSON",
    "firstName": "Sunil",
    "email": "misalsunil87@gmail.com",
    "lastName": "Misal",
    "mobileNo": "8422982721",
    "shortName": "SM",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60af6ae22ffdf65bcd65861d\\
\\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "67776d60a5477d50e7dbc213",
    "role": "SITEENGINEER+MAKAR+CHECKER",
    "firstName": "AJAY",
    "email": "ajayrewale503@gmail.com",
    "lastName": "REWALE",
    "mobileNo": "9766640171",
    "designation": "",
    "shortName": "AJAY",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/67776d60a5477d50e7dbc213/
profilePhoto_1739252394344_image.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "60f915d3f3dd69653a592199",
    "role": "MAKER + RATE VERFIER + CHEAKER",
    "firstName": "Shobha",
    "email": "shobha@vastukala.org",
    "lastName": "Kuperkar",
    "mobileNo": "9004134140",
    "designation": "",
    "shortName": "SH",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
  },
  "maker": {
    "type": "EMPLOYEE",
    "_id": "60f91b6f344e052188ffd1fc",
    "role": "MAKER",
    "firstName": "Jayaraja",
    "email": "jayaraja@vastukala.org",
    "lastName": "Acharya",
```

```
"mobileNo": "9867664219",
"designation": "",
"shortName": "JA",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  "type": "EMPLOYEE",
  "_id": "5ffe92d27737ca4d986b6453",
  "role": "VALUER",
  "firstName": "Manoj",
  "email": "manoj@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9819597579",
  "designation": "Registered Valuer",
  "registrationNo": [
    {
      "title": {
        "label": "IBBI"
      },
      "_id": "60af80072ffdf65bcd658651",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  {
```

```
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.197485649390178",
  "longitude": "72.84402449941372"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.84402449941372,
    19.197485649390178
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "13/02/2025 12:00 am",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Malad South",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
```

```
"value": "11",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Borivali",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "1",
  "label": true
},
"buildingName": {
```

```
"status": true,
"name": "Building Name",
"key": "buildingName",
"value": "Rajendra Ratna Co-op. Hsg. Soc. Ltd.",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Mahesh Nagar",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "S. V. Road, Near MTNL Exchange",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
```



```
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "46 & 47(pt)",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "1384",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1102",
  "label": false
},
"municipalityWardNo": {
  "status": false,
```

```
"name": "Municipality Ward No.",
"key": "municipalityWardNo",
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 104",
  "label": false
}
```

```
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Goregaon (West), Mumbai",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
```

```
"routeMapImg": "",
"routeLat": "",
"routeLng": "",
"stationName": "",
"routeDistance": ""
},
"finalLatLng": {
  "coordinates": []
},
"locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
}
```

```
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
```

```
"title": "Wardrobes",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```



```
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": []
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
}
```

```
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67ada6aed716769af0d64ccc",
"ownerName": "Shri. Sureshkumar B. Maroo S/o. Shri. Benishankar S. Maroo",
"ownerPhoneNo": "9867286728",
"appAddress": "Flat no 1102 11th floor Rajendar Raten Co-op HSG Soc Ltd Plot no 1
Mahesh Nagar S.V Road Near MTNL Exchange Goregaon West Mumbai 400104",
"remark": "urgent Bank structural report kal ",
"documents": [
  {
    "documentType": {
      "label": "Previous Valuation Report",
      "value": "60ae1248aa6d152c1801b2ee"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/67ada6aed716769af0d64ccc/
document_1739433603215_1739433601025_CamScanner_02132025_1316.pdf",
    "fileName":
"document_1739433603215_1739433601025_CamScanner_02132025_1316.pdf",
    "id": "902512",
    "uploadedBy": "60af6ae22ffdf65bcd65861d",
    "createdAt": "Thu Feb 13 2025 08:00:46 GMT+0000 (Coordinated Universal Time)"
  }
],
"caseNumber": "014290",
```

```
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "892404",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Feb 13 2025 08:00:46 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Shri. Sureshkumar B. Maroo S/o. Shri. Benishankar S. Maroo",
    "phone": "9867286728",
    "ownershipShare": "",
    "email": "",
    "id": "157638"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67af2825dc5b7cb7d2f9bcc9",
    "name": "externalImg_1739532311694_1739532236895_image_0.jpeg",
    "path": "cases/67ada6aed716769af0d64ccc/externalImg_1739532311694_1739532236895_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67af2825dc5b7cb7d2f9bcc9",
    "name": "externalImg_1739532312285_1739532236895_image_1.jpeg",
    "path": "cases/67ada6aed716769af0d64ccc/externalImg_1739532312285_1739532236895_image_1.jpeg",
    "orientation": "portrait"
  },
  {

```

```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67af2825dc5b7cb7d2f9bccb",
    "name": "externallmg_1739532312880_1739532236895_image_2.jpeg",
    "path": "cases/67ada6aed716769af0d64ccc/
externallmg_1739532312880_1739532236895_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67af2825dc5b7cb7d2f9bcc",
    "name": "externallmg_1739532313638_1739532236895_image_3.jpeg",
    "path": "cases/67ada6aed716769af0d64ccc/
externallmg_1739532313638_1739532236895_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67af2825dc5b7cb7d2f9bccd",
    "name": "externallmg_1739532313869_1739532236895_image_4.jpeg",
    "path": "cases/67ada6aed716769af0d64ccc/
externallmg_1739532313869_1739532236895_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67af2825dc5b7cb7d2f9bcce",
    "name": "externallmg_1739532314435_1739532236895_image_5.jpeg",
    "path": "cases/67ada6aed716769af0d64ccc/
externallmg_1739532314435_1739532236895_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67af2825dc5b7cb7d2f9bccf",
    "name": "externallmg_1739532315220_1739532236895_image_6.jpeg",
    "path": "cases/67ada6aed716769af0d64ccc/
externallmg_1739532315220_1739532236895_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
```

```
    "status": false,
    "_id": "67af2825dc5b7cb7d2f9bcd0",
    "name": "externallmg_1739532316116_1739532236895_image_7.jpeg",
    "path": "cases/67ada6aed716769af0d64ccc/
externallmg_1739532316116_1739532236895_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67af2825dc5b7cb7d2f9bcd1",
    "name": "externallmg_1739532316746_1739532236895_image_8.jpeg",
    "path": "cases/67ada6aed716769af0d64ccc/
externallmg_1739532316746_1739532236895_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67af2825dc5b7cb7d2f9bcd2",
    "name": "externallmg_1739532317430_1739532236895_image_9.jpeg",
    "path": "cases/67ada6aed716769af0d64ccc/
externallmg_1739532317430_1739532236895_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67af2825dc5b7cb7d2f9bcd3",
    "name": "externallmg_1739532318525_1739532236895_image_10.jpeg",
    "path": "cases/67ada6aed716769af0d64ccc/
externallmg_1739532318525_1739532236895_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67af2825dc5b7cb7d2f9bcd4",
    "name": "externallmg_1739532318761_1739532236895_image_11.jpeg",
    "path": "cases/67ada6aed716769af0d64ccc/
externallmg_1739532318761_1739532236895_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
```

```
    "_id": "67af2825dc5b7cb7d2f9bcd5",
    "name": "externallmg_1739532319249_1739532236895_image_12.jpeg",
    "path": "cases/67ada6aed716769af0d64ccc/
externallmg_1739532319249_1739532236895_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67af2825dc5b7cb7d2f9bcd6",
    "name": "externallmg_1739532319859_1739532236895_image_13.jpeg",
    "path": "cases/67ada6aed716769af0d64ccc/
externallmg_1739532319859_1739532236895_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67af2825dc5b7cb7d2f9bcd7",
    "name": "externallmg_1739532320509_1739532236895_image_14.jpeg",
    "path": "cases/67ada6aed716769af0d64ccc/
externallmg_1739532320509_1739532236895_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67af2825dc5b7cb7d2f9bcd8",
    "name": "externallmg_1739532321245_1739532236895_image_15.jpeg",
    "path": "cases/67ada6aed716769af0d64ccc/
externallmg_1739532321245_1739532236895_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67af2825dc5b7cb7d2f9bcd9",
    "name": "externallmg_1739532322429_1739532236895_image_16.jpeg",
    "path": "cases/67ada6aed716769af0d64ccc/
externallmg_1739532322429_1739532236895_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67af2825dc5b7cb7d2f9bcda",
```

```
    "name": "externallmg_1739532323549_1739532236895_image_17.jpeg",
    "path": "cases/67ada6aed716769af0d64ccc/
externallmg_1739532323549_1739532236895_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67af282ee1b0fbb7b7ebacae",
    "name": "externallmg_1739532316130_1739532304918_image_0.jpeg",
    "path": "cases/67ada6aed716769af0d64ccc/
externallmg_1739532316130_1739532304918_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67af282ee1b0fbb7b7ebacaf",
    "name": "externallmg_1739532319781_1739532304918_image_1.jpeg",
    "path": "cases/67ada6aed716769af0d64ccc/
externallmg_1739532319781_1739532304918_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67af282ee1b0fbb7b7ebacb0",
    "name": "externallmg_1739532320941_1739532304918_image_2.jpeg",
    "path": "cases/67ada6aed716769af0d64ccc/
externallmg_1739532320941_1739532304918_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67af282ee1b0fbb7b7ebacb1",
    "name": "externallmg_1739532322110_1739532304918_image_3.jpeg",
    "path": "cases/67ada6aed716769af0d64ccc/
externallmg_1739532322110_1739532304918_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67af282ee1b0fbb7b7ebacb2",
    "name": "externallmg_1739532324156_1739532304918_image_4.jpeg",
```

```
    "path": "cases/67ada6aed716769af0d64ccc/  
externallmg_1739532324156_1739532304918_image_4.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "67af282ee1b0fbb7b7ebacb3",  
    "name": "externallmg_1739532324380_1739532304918_image_5.jpeg",  
    "path": "cases/67ada6aed716769af0d64ccc/  
externallmg_1739532324380_1739532304918_image_5.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "67af282ee1b0fbb7b7ebacb4",  
    "name": "externallmg_1739532324768_1739532304918_image_6.jpeg",  
    "path": "cases/67ada6aed716769af0d64ccc/  
externallmg_1739532324768_1739532304918_image_6.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "67af282ee1b0fbb7b7ebacb5",  
    "name": "externallmg_1739532324960_1739532304918_image_7.jpeg",  
    "path": "cases/67ada6aed716769af0d64ccc/  
externallmg_1739532324960_1739532304918_image_7.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "67af282ee1b0fbb7b7ebacb6",  
    "name": "externallmg_1739532325152_1739532304918_image_8.jpeg",  
    "path": "cases/67ada6aed716769af0d64ccc/  
externallmg_1739532325152_1739532304918_image_8.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "67af282ee1b0fbb7b7ebacb7",  
    "name": "externallmg_1739532325595_1739532304918_image_9.jpeg",  
    "path": "cases/67ada6aed716769af0d64ccc/  
externallmg_1739532325595_1739532304918_image_9.jpeg",
```



```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67af282ee1b0fbb7b7ebacb8",
    "name": "externallmg_1739532326471_1739532304918_image_10.jpeg",
    "path": "cases/67ada6aed716769af0d64ccc/
externallmg_1739532326471_1739532304918_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67af282ee1b0fbb7b7ebacb9",
    "name": "externallmg_1739532326875_1739532304918_image_11.jpeg",
    "path": "cases/67ada6aed716769af0d64ccc/
externallmg_1739532326875_1739532304918_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67af282ee1b0fbb7b7ebacba",
    "name": "externallmg_1739532329020_1739532304918_image_12.jpeg",
    "path": "cases/67ada6aed716769af0d64ccc/
externallmg_1739532329020_1739532304918_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67af282ee1b0fbb7b7ebacbb",
    "name": "externallmg_1739532329585_1739532304918_image_13.jpeg",
    "path": "cases/67ada6aed716769af0d64ccc/
externallmg_1739532329585_1739532304918_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67af282ee1b0fbb7b7ebacbc",
    "name": "externallmg_1739532330010_1739532304918_image_14.jpeg",
    "path": "cases/67ada6aed716769af0d64ccc/
externallmg_1739532330010_1739532304918_image_14.jpeg",
    "orientation": "portrait"
  }
}
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67af282ee1b0fbb7b7ebacbd",
    "name": "externallmg_1739532331245_1739532304918_image_15.jpeg",
    "path": "cases/67ada6aed716769af0d64ccc/
externallmg_1739532331245_1739532304918_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67af282ee1b0fbb7b7ebacbe",
    "name": "externallmg_1739532331605_1739532304918_image_16.jpeg",
    "path": "cases/67ada6aed716769af0d64ccc/
externallmg_1739532331605_1739532304918_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67af282ee1b0fbb7b7ebacbf",
    "name": "externallmg_1739532332155_1739532304918_image_17.jpeg",
    "path": "cases/67ada6aed716769af0d64ccc/
externallmg_1739532332155_1739532304918_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67af282ee1b0fbb7b7ebacc0",
    "name": "externallmg_1739532332690_1739532304918_image_18.jpeg",
    "path": "cases/67ada6aed716769af0d64ccc/
externallmg_1739532332690_1739532304918_image_18.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67af282ee1b0fbb7b7ebacc1",
    "name": "externallmg_1739532332955_1739532304918_image_19.jpeg",
    "path": "cases/67ada6aed716769af0d64ccc/
externallmg_1739532332955_1739532304918_image_19.jpeg",
    "orientation": "portrait"
  },
  },
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67af2863c594f0b7b65481b9",
  "name": "externallmg_1739532381804_1739532375957_image_0.jpeg",
  "path": "cases/67ada6aed716769af0d64ccc/
externallmg_1739532381804_1739532375957_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67af2863c594f0b7b65481ba",
  "name": "externallmg_1739532382789_1739532375957_image_1.jpeg",
  "path": "cases/67ada6aed716769af0d64ccc/
externallmg_1739532382789_1739532375957_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67af2863c594f0b7b65481bb",
  "name": "externallmg_1739532383587_1739532375957_image_2.jpeg",
  "path": "cases/67ada6aed716769af0d64ccc/
externallmg_1739532383587_1739532375957_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67af2863c594f0b7b65481bc",
  "name": "externallmg_1739532383783_1739532375957_image_3.jpeg",
  "path": "cases/67ada6aed716769af0d64ccc/
externallmg_1739532383783_1739532375957_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67af2863c594f0b7b65481bd",
  "name": "externallmg_1739532384249_1739532375957_image_4.jpeg",
  "path": "cases/67ada6aed716769af0d64ccc/
externallmg_1739532384249_1739532375957_image_4.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67af2863c594f0b7b65481be",
    "name": "externalImg_1739532384453_1739532375957_image_5.jpeg",
    "path": "cases/67ada6aed716769af0d64ccc/
externalImg_1739532384453_1739532375957_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67af2863c594f0b7b65481bf",
    "name": "externalImg_1739532385048_1739532375957_image_6.jpeg",
    "path": "cases/67ada6aed716769af0d64ccc/
externalImg_1739532385048_1739532375957_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67af2863c594f0b7b65481c0",
    "name": "externalImg_1739532385673_1739532375957_image_7.jpeg",
    "path": "cases/67ada6aed716769af0d64ccc/
externalImg_1739532385673_1739532375957_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67af2863c594f0b7b65481c1",
    "name": "externalImg_1739532386347_1739532375957_image_8.jpeg",
    "path": "cases/67ada6aed716769af0d64ccc/
externalImg_1739532386347_1739532375957_image_8.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-02-13T08:00:46.586Z",
"updatedAt": "2025-02-14T11:26:27.174Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
```

```

"label": "Retail"
},
"fullAddress": "Residential Structural Report No. 1102, 11th Floor, Rajendra Ratna Co-
op. Hsg. Soc. Ltd., Plot No. 1, New/Current Survey No. 46 & 47(pt), CTS No. 1384,
Mahesh Nagar, S. V. Road, Near MTNL Exchange, Village - Malad South, Goregaon
(West), Mumbai, Taluka - Borivali, District - Mumbai Suburban, PIN - 400 104, State -
Maharashtra, India",
"updatedBy": "67776d60a5477d50e7dbc213",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Shri. Sureshkumar B. Maroo S/o. Shri. Benishankar S. Maroo",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"rerald": "",
"siteVisitContactNo": "9867286728"
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			