

Vastukala Consultants (I) Pvt. Ltd.

Structural Stability Report Prepared for CB / Mulund (West) Branch/ Mrs. Rani Krishnat Kanse (014351/2310583) Page 1 of 3

www.vastukala.co.in

Vastu/Mumbai/02/2025/014351/2310583
15/12-233-PRRJ
Date: 15.02.2025

Structural Stability Report

Structural Observation Report of Residential Flat No. 45, 1st Floor, Building No B/3, "Mahavir Shikhar Co-Op. Hsg. Soc. Ltd.", L.B.S. Marg. Opp. Gabriel India Co., Mulund (West), Taluka - Kurla, Mumbai - 400 080, State - Maharashtra, Country - India.


Name of Owner: **Mrs. Rani Krishnat Kanse**

This is to certify that on visual inspection, it appears that the structure at "Mahavir Shikhar Co-Op. Hsg. Soc. Ltd." is in good condition and the future life can be reasonably taken under good condition and with proper periodic repairs & maintenance is about 18 years.

General Information:

A.	Introduction	
1	Name of Building	"Mahavir Shikhar Co-Op. Hsg. Soc. Ltd."
2	Property Address	Residential Flat No. 45, 1st Floor, Building No B/3, "Mahavir Shikhar Co-Op. Hsg. Soc. Ltd.", L.B.S. Marg. Opp. Gabriel India Co., Mulund (West), Taluka - Kurla, Mumbai - 400 080, State - Maharashtra, Country – India.
3	Type of Building	Residential
4	No. of Floors	Ground + 4 Upper Floors
5	Whether stilt / podium / open parking provided	Open Car Parking Space
6	Type of Construction	R.C.C. Framed Structure
7	Type of Foundation	R.C.C. Footing
8	Thickness of the External Walls	9" thick brick walls both sides plastered
9	Type of Compound	Brick Masonry Walls
10	Year of Construction	1983 (As per occupancy certificate)
11	Present age of building	42 years
12	Expected balance lift of the building	18 years Subject to proper, preventive periodic maintenance & structural repairs.
13	No. of flats (Per Floor)	1 st Floor is having 4 Flats
14	Methodology adopted	As per visual site inspection

B.	External Observation of the Building	
1	Plaster	Good Condition
2	Chajjas	Good Condition
3	Plumbing	Good Condition
4	Cracks on the external walls	Not Found
5	Filling cracks on the external walls	Found at some places
6	Cracks on columns & beams	Not Found
7	Vegetation	Not Found



Our Pan India Presence at :

- Nanded
- Thane
- Ahmedabad
- Delhi NCR
- Mumbai
- Nashik
- Rajkot
- Raipur
- Aurangabad
- Pune
- Indore
- Jaipur

Regd. Office

BI-001, U/B Floor, BOOMERANG, Chandivali Farm Road, Powai, Andheri East, Mumbai: 400072, (M.S.), India

+91 2247495919
mumbai@vastukala.co.in
www.vastukala.co.in



8	Leakages of water in the drainage pipes or water pipes	Not Found
9	Dampness external in the wall due to leakages	Not Found
10	Any other observation about the condition of external side of the building	Structural Stability Report from licensed structural engineers not provided for our verification.
C	Internal Observation of the common areas of the building and captioned premises	
1	Beams (Cracks & Leakages)	Not Found
2	Columns (Cracks & Leakages)	Not Found
3	Ceiling (Cracks & Leakages)	Not Found
4	Leakages inside the property	Not Found
5	Painting inside the property	Good Condition
6	Maintenance of staircase & cracks	Good

D	Common Observation	
1	Structural Audit of the Building Under Bye – Laws No. 77 of the Model Bye Laws (Co-Operative Societies Act / Rules)	As per bye Laws No. 77 of Co-Op. Societies bye Laws under the Act the society shall conduct a Structural Audit of the building of the society as follows
2	Remark	<ul style="list-style-type: none"> i) At the time of site inspection, external condition of the building is in good condition, dampness not found, leakages are not found & some filling cracks on external walls of the building was found. ii) Structural Stability Report from licensed structural engineers not provided for our verification.

E	Conclusion
<p>The captioned building is having Ground + 4 Upper Floors which are constructed in year 1983 (As per occupancy certificate). Estimated future life under present circumstances is about 18 years subject to proper, preventive periodic maintenance & structural repairs.</p> <p>The inspection dated 04.02.2025 of building. The building is well as the property is maintained in good condition & will stand future life subject to proper, preventive periodic maintenance & Good structural repairs.</p> <p>Our Observations about the structure are given above.</p> <p>The above assessment is based on visual inspection only. Separate structural audit from licensed structural engineers is advised to assess exact balance life of structure.</p>	

For VASTUKALA CONSULTANTS (I) PVT. LTD.

Director

Auth. Sign.

Manoj Chalikwar

Structural Engineer Licence No. STATE/R/2025/APL/15680

Govt. Reg. Valuer

Chartered Engineer (India)

Reg. No. IBBI/RV/07/2018/10366

State Bank of India Empanelment No.: SME/TCC/38/IBBI/3



Since 1989

Vastukala Consultants (I) Pvt. Ltd.

An ISO 9001 : 2015 Certified Company



Actual site photographs

