

```
{
  "typeOfReport": {
    "value": "Office",
    "label": "Office"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "MSME_Loan",
    "label": "MSME Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "67cacc6c7e0bb1d5cc311ecd"
    },
    "firstName": "Manesh ",
    "type": "CREDITOFFICER",
    "_id": "67cacc94021414d63cde8509",
    "email": "shenoym@svcbank.com",
    "lastName": "Shenoy",
    "mobileNo": "",
    "workMobileNo": "9869275960"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d185c",
  "type": "BANK",
  "name": "SVC CO-OPERATIVE BANK LTD",
  "displayName": "SVC BANK",
  "initial": "SVC",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "67cacc6c7e0bb1d5cc311ecd",
  "name": "Retail Sme Credit Branch Wagle estate",
  "branchCode": "",
  "mobileNo": "02271991000",
  "alternateMobileNo": "02271991451",
  "email": "shenoymys@svcbank.com",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "9th Floor, Dosti Pinnacle, Plot No E-7, Road No 22, Wagle Industrial
Estate, Thane West, 400604"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Commercial",
  "value": "Commercial"
},
"zone": {
  "_id": "60fbaf81d8cfc56a13fa8863",
  "zoneName": "PAN INDIA"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
```

```
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\
\profilePhoto_1622114310919_Manoj C.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "67776d60a5477d50e7dbc213",
"role": "SITEENGINEER+MAKAR+CHECKER",
"firstName": "AJAY",
"email": "ajayrewale503@gmail.com",
"lastName": "REWALE",
"mobileNo": "9766640171",
"designation": "",
"shortName": "AJAY",
"workWithDocumentMaker": "",
"profilePhoto": "users/67776d60a5477d50e7dbc213/
profilePhoto_1739252394344_image.jpeg"
},
"rateVerifier": null,
"maker": null,
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
]
},
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
```

```
    "label": "IBBI"
  },
  "_id": "60af80072ffdf65bcd658651",
  "number": "IBBI/RV/07/2018/10366"
},
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.122362263082056",
  "longitude": " 72.86674190737662"
```

```
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "7/03/2025 12:00 am",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Mulgaon",
```

```
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "2",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
```

```
"name": "Plot No.",
"key": "plotNo",
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Lodha SUPremes",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
}
```

```
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
```



```
"key": "selectNo",
"value": "203",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
}
```

```
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400093",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Andheri East",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
}
```

```
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
```

```
"title": "Electricity deposits / electrical fittings, etc",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": []
},
"taskStatus": {
  "SITE_INSPECTION": false,
```



```
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "true",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67caf83b7e0bb1d5cc316590",
"ownerName": "SBS Health Care Service",
"ownerPhoneNo": "0000000000",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "0000000000",
"contactPersonName": "SBS Health Care Service",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "SBS Health Care Service",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "526378"
  }
],
"caseReferredBy": "5ffe92d27737ca4d986b6453",
```

```
"relationWithOwner": "self",
"fullAddress": "Commercial Office No. 203, 2nd Floor, Lodha SUpremes, Village -
Mulgaon, Andheri East, Mumbai, 400093, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Other",
      "value": "60ae124eaa6d152c1801b30b"
    },
    "attachConfig": {
      "fromPage": 0,
      "toPage": 0
    },
    "attachInReport": false,
    "isHardCopy": false,
    "displayStatus": false,
    "fileName":
"document_1741355047527_20220818Full_OC_Letter3BGr1st_to_6th_flr.pdf",
    "path": "cases/67caf83b7e0bb1d5cc316590/
document_1741355047527_20220818Full_OC_Letter3BGr1st_to_6th_flr.pdf",
    "id": "902942",
    "uploadedBy": "5ffe92d27737ca4d986b6453",
    "createdAt": "Fri Mar 07 2025 13:44:26 GMT+0000 (Coordinated Universal Time)"
  },
  {
    "documentType": {
      "label": "Other",
      "value": "60ae124eaa6d152c1801b30b"
    },
    "attachConfig": {
      "fromPage": 0,
      "toPage": 0
    },
    "attachInReport": false,
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1741355060903_AGREEMENT_LODHA_SUPREMUS.pdf",
    "path": "cases/67caf83b7e0bb1d5cc316590/
document_1741355060903_AGREEMENT_LODHA_SUPREMUS.pdf",
    "id": "847986",
    "uploadedBy": "5ffe92d27737ca4d986b6453",
    "createdAt": "Fri Mar 07 2025 13:44:26 GMT+0000 (Coordinated Universal Time)"
  }
],
"isUrgent": "false",
```

```
"isExternal": "false",
"proposePurchaserName": "",
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"reralid": "",
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "014765",
"createdBy": "5ffe92d27737ca4d986b6453",
"caseHistory": [
  {
    "id": "240587",
    "title": "Create Case",
    "description": "Create Case",
    "datetime": "Fri Mar 07 2025 13:44:27 GMT+0000 (Coordinated Universal Time)"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67cb449b8037ced5d24204bb",
    "name": "externalImg_1741374565717_1741374547524_image_0.jpeg",
    "path": "cases/67caf83b7e0bb1d5cc316590/externalImg_1741374565717_1741374547524_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67cb449b8037ced5d24204bc",
    "name": "externalImg_1741374567705_1741374547524_image_1.jpeg",
    "path": "cases/67caf83b7e0bb1d5cc316590/externalImg_1741374567705_1741374547524_image_1.jpeg",
    "orientation": "portrait"
  }
]
```

```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67cb449b8037ced5d24204bd",
    "name": "externallmg_1741374568566_1741374547524_image_2.jpeg",
    "path": "cases/67caf83b7e0bb1d5cc316590/
externallmg_1741374568566_1741374547524_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67cb449b8037ced5d24204be",
    "name": "externallmg_1741374568839_1741374547524_image_3.jpeg",
    "path": "cases/67caf83b7e0bb1d5cc316590/
externallmg_1741374568839_1741374547524_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67cb449b8037ced5d24204bf",
    "name": "externallmg_1741374569723_1741374547524_image_4.jpeg",
    "path": "cases/67caf83b7e0bb1d5cc316590/
externallmg_1741374569723_1741374547524_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67cb449b8037ced5d24204c0",
    "name": "externallmg_1741374570741_1741374547524_image_5.jpeg",
    "path": "cases/67caf83b7e0bb1d5cc316590/
externallmg_1741374570741_1741374547524_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67cb449b8037ced5d24204c1",
    "name": "externallmg_1741374571829_1741374547524_image_6.jpeg",
    "path": "cases/67caf83b7e0bb1d5cc316590/
externallmg_1741374571829_1741374547524_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
```

```
    "status": false,
    "_id": "67cb449b8037ced5d24204c2",
    "name": "externallmg_1741374572785_1741374547524_image_7.jpeg",
    "path": "cases/67caf83b7e0bb1d5cc316590/
externallmg_1741374572785_1741374547524_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67cb449b8037ced5d24204c3",
    "name": "externallmg_1741374578258_1741374547524_image_8.jpeg",
    "path": "cases/67caf83b7e0bb1d5cc316590/
externallmg_1741374578258_1741374547524_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67cb449b8037ced5d24204c4",
    "name": "externallmg_1741374584216_1741374547524_image_9.jpeg",
    "path": "cases/67caf83b7e0bb1d5cc316590/
externallmg_1741374584216_1741374547524_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67cb449b8037ced5d24204c5",
    "name": "externallmg_1741374584847_1741374547524_image_10.jpeg",
    "path": "cases/67caf83b7e0bb1d5cc316590/
externallmg_1741374584847_1741374547524_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67cb449b8037ced5d24204c6",
    "name": "externallmg_1741374588232_1741374547524_image_11.jpeg",
    "path": "cases/67caf83b7e0bb1d5cc316590/
externallmg_1741374588232_1741374547524_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
```

```
    "_id": "67cb449b8037ced5d24204c7",
    "name": "externallmg_1741374594411_1741374547524_image_12.jpeg",
    "path": "cases/67caf83b7e0bb1d5cc316590/
externallmg_1741374594411_1741374547524_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67cb449b8037ced5d24204c8",
    "name": "externallmg_1741374600163_1741374547524_image_13.jpeg",
    "path": "cases/67caf83b7e0bb1d5cc316590/
externallmg_1741374600163_1741374547524_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67cb449b8037ced5d24204c9",
    "name": "externallmg_1741374604123_1741374547524_image_14.jpeg",
    "path": "cases/67caf83b7e0bb1d5cc316590/
externallmg_1741374604123_1741374547524_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67cb449b8037ced5d24204ca",
    "name": "externallmg_1741374607798_1741374547524_image_15.jpeg",
    "path": "cases/67caf83b7e0bb1d5cc316590/
externallmg_1741374607798_1741374547524_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67cb449b8037ced5d24204cb",
    "name": "externallmg_1741374617345_1741374547524_image_16.jpeg",
    "path": "cases/67caf83b7e0bb1d5cc316590/
externallmg_1741374617345_1741374547524_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67cb449b8037ced5d24204cc",
```

```
    "name": "externallmg_1741374617766_1741374547524_image_17.jpeg",
    "path": "cases/67caf83b7e0bb1d5cc316590/
externallmg_1741374617766_1741374547524_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67cb449b8037ced5d24204cd",
    "name": "externallmg_1741374618178_1741374547524_image_18.jpeg",
    "path": "cases/67caf83b7e0bb1d5cc316590/
externallmg_1741374618178_1741374547524_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67cb44bb8037ced5d2420519",
    "name": "externallmg_1741374639740_1741374637683_image_0.jpeg",
    "path": "cases/67caf83b7e0bb1d5cc316590/
externallmg_1741374639740_1741374637683_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67cb44bb8037ced5d242051a",
    "name": "externallmg_1741374641615_1741374620318_image_0.jpeg",
    "path": "cases/67caf83b7e0bb1d5cc316590/
externallmg_1741374641615_1741374620318_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67cb44bb8037ced5d242051b",
    "name": "externallmg_1741374643043_1741374620318_image_1.jpeg",
    "path": "cases/67caf83b7e0bb1d5cc316590/
externallmg_1741374643043_1741374620318_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67cb44bb8037ced5d242051c",
    "name": "externallmg_1741374644023_1741374620318_image_2.jpeg",
```

```
    "path": "cases/67caf83b7e0bb1d5cc316590/
externallmg_1741374644023_1741374620318_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67cb44bb8037ced5d242051d",
    "name": "externallmg_1741374644230_1741374620318_image_3.jpeg",
    "path": "cases/67caf83b7e0bb1d5cc316590/
externallmg_1741374644230_1741374620318_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67cb44bb8037ced5d242051e",
    "name": "externallmg_1741374644846_1741374620318_image_4.jpeg",
    "path": "cases/67caf83b7e0bb1d5cc316590/
externallmg_1741374644846_1741374620318_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67cb44bb8037ced5d242051f",
    "name": "externallmg_1741374645327_1741374620318_image_5.jpeg",
    "path": "cases/67caf83b7e0bb1d5cc316590/
externallmg_1741374645327_1741374620318_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67cb44bb8037ced5d2420520",
    "name": "externallmg_1741374645620_1741374620318_image_6.jpeg",
    "path": "cases/67caf83b7e0bb1d5cc316590/
externallmg_1741374645620_1741374620318_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67cb44bb8037ced5d2420521",
    "name": "externallmg_1741374646069_1741374620318_image_7.jpeg",
    "path": "cases/67caf83b7e0bb1d5cc316590/
externallmg_1741374646069_1741374620318_image_7.jpeg",
```



```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67cb44bb8037ced5d2420522",
  "name": "externallmg_1741374646309_1741374620318_image_8.jpeg",
  "path": "cases/67caf83b7e0bb1d5cc316590/
externallmg_1741374646309_1741374620318_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67cb44bb8037ced5d2420523",
  "name": "externallmg_1741374646598_1741374620318_image_9.jpeg",
  "path": "cases/67caf83b7e0bb1d5cc316590/
externallmg_1741374646598_1741374620318_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67cb44bb8037ced5d2420524",
  "name": "externallmg_1741374646986_1741374620319_image_10.jpeg",
  "path": "cases/67caf83b7e0bb1d5cc316590/
externallmg_1741374646986_1741374620319_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67cb44bb8037ced5d2420525",
  "name": "externallmg_1741374647246_1741374620319_image_11.jpeg",
  "path": "cases/67caf83b7e0bb1d5cc316590/
externallmg_1741374647246_1741374620319_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67cb44bb8037ced5d2420526",
  "name": "externallmg_1741374647380_1741374620319_image_12.jpeg",
  "path": "cases/67caf83b7e0bb1d5cc316590/
externallmg_1741374647380_1741374620319_image_12.jpeg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67cb44bb8037ced5d2420527",
      "name": "externallmg_1741374648151_1741374620319_image_13.jpeg",
      "path": "cases/67caf83b7e0bb1d5cc316590/
externallmg_1741374648151_1741374620319_image_13.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67cb44bb8037ced5d2420528",
      "name": "externallmg_1741374648939_1741374620319_image_14.jpeg",
      "path": "cases/67caf83b7e0bb1d5cc316590/
externallmg_1741374648939_1741374620319_image_14.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67cb44bb8037ced5d2420529",
      "name": "externallmg_1741374649019_1741374620319_image_15.jpeg",
      "path": "cases/67caf83b7e0bb1d5cc316590/
externallmg_1741374649019_1741374620319_image_15.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67cb44bb8037ced5d242052a",
      "name": "externallmg_1741374649326_1741374620319_image_16.jpeg",
      "path": "cases/67caf83b7e0bb1d5cc316590/
externallmg_1741374649326_1741374620319_image_16.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67cb44bb8037ced5d242052b",
      "name": "externallmg_1741374649812_1741374620319_image_17.jpeg",
      "path": "cases/67caf83b7e0bb1d5cc316590/
externallmg_1741374649812_1741374620319_image_17.jpeg",
      "orientation": "portrait"
    },
  },
}
```

```

{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67cb44bb8037ced5d242052c",
  "name": "externalImg_1741374650007_1741374620319_image_18.jpeg",
  "path": "cases/67caf83b7e0bb1d5cc316590/
externalImg_1741374650007_1741374620319_image_18.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67cb44bb8037ced5d242052d",
  "name": "externalImg_1741374650466_1741374620319_image_19.jpeg",
  "path": "cases/67caf83b7e0bb1d5cc316590/
externalImg_1741374650466_1741374620319_image_19.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-03-07T13:44:27.219Z",
"updatedAt": "2025-03-07T19:10:51.970Z",
"__v": 0,
"addressForMap": "",
"updatedBy": "67776d60a5477d50e7dbc213"
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			