

## PROFORMA INVOICE

<b>Vastukala Consultants (I) Pvt Ltd</b> Ackruti Star, 1st Floor, 121, Central Road, MIDC, Andheri (E), Mumbai - 400 093 GSTIN/UIN: 27AADCV4303R1ZX State Name : Maharashtra, Code : 27 E-Mail : accounts@vastukala.org	Invoice No. <b>PG-317(A)/23-24</b>	Dated <b>27-Apr-23</b>
Buyer (Bill to)  <b>STATE BANK OF INDIA</b> RACPC BORIVALI BRANCH MTNL BUILDING, DEVIDAS ROAD BORIVALI (W), MUMBAI GSTIN/UIN : 27AAACS8577K2ZO State Name : Maharashtra, Code : 27	Delivery Note	Mode/Terms of Payment <b>AGAINST REPORT</b>
	Reference No. & Date.	Other References
	Buyer's Order No.	Dated
	Dispatch Doc No. <b>31097 / 2300322</b>	Delivery Note Date
	Dispatched through	Destination
	Terms of Delivery	

SI No.	Particulars	HSN/SAC	GST Rate	Amount
1	<b>STRUCTURAL REPORT FEE</b> <i>(Technical Inspection and Certification Services)</i>	997224	18 %	1,500.00
	<b>CGST</b>			135.00
	<b>SGST</b>			135.00
	<b>Total</b>			<b>₹ 1,770.00</b>

Amount Chargeable (in words)

E. & O.E

**Indian Rupee One Thousand Seven Hundred Seventy Only**

HSN/SAC	Taxable Value	Central Tax		State Tax		Total Tax Amount
		Rate	Amount	Rate	Amount	
997224	1,500.00	9%	135.00	9%	135.00	270.00
<b>Total</b>	<b>1,500.00</b>		<b>135.00</b>		<b>135.00</b>	<b>270.00</b>

Tax Amount (in words) : **Indian Rupee Two Hundred Seventy Only**

**Remarks:**

"Smt. Shubhalakshmi Vilas Deshpande - residential Flat No. 5, 2nd Floor, Wing - D, ""Pranam Co-op. Hsg. Soc. Ltd.""", Plot No. 513, Chikuwadi, Village - Eksar, Borivali (West), Taluka - Borivali, District - Mumbai , Pincode-400 092, State - Maharashtra, India"

Company's PAN : **AADCV4303R**

**Declaration**

NOTE - AS PER MSME RULES INVOICE NEED TO BE CLEARED WITHIN 45 DAYS OR INTEREST CHARGES APPLICABLE AS PER THE RULE.  
 MSME Registration No. - 27222201137

**Company's Bank Details**

Bank Name : **State Bank of India**  
 A/c No. : **32632562114**  
 Branch & IFS Code : **MIDC Andheri (E) & SBIN0007074**



UPI Virtual ID : vastukala@icici

**for Vastukala Consultants (I) Pvt Ltd**

*Authorised Signatory*

This is a Computer Generated Invoice



**Vastukala Consultants (I) Pvt. Ltd.**

An ISO 9001:2015 Certified Company

www.vastukala.org



Structural Stability Report Prepared For: SBI / RACPC Borivali (West) Branch / Ms. Shubhalakshmi Vilas Deshpande (31097/2300322) Page 1 of 3

Vastu/Mumbai/04/2023/31097/2300322  
27/11-315-AHSH  
Date: 27.04.2023

## Structural Stability Report

Structural Observation Report of Residential Flat No. 5, 2<sup>nd</sup> Floor, Wing - D, "Pranam Co-op. Hsg. Soc. Ltd.", Plot No. 513, Chikuwadi, Village - Eksar, Borivali (West), Mumbai - 400 092, State – Maharashtra, Country – India.

Name of Owners: **Ms. Shubhalakshmi Vilas Deshpande**

This is to certify that on visual inspection, it appears that the structure of the at "Pranam Co-op. Hsg. Soc. Ltd.", is in good condition and the future life can be reasonably takes under good condition and with proper periodic repairs & maintenance is about 35 years.

### General Information:

A.	Introduction	
1	Name of Building	" Pranam Co-op. Hsg. Soc. Ltd.",
2	Property Address	Residential Flat No. 5, 2 <sup>nd</sup> Floor, Wing - D, "Pranam Co-op. Hsg. Soc. Ltd.", Plot No. 513, Chikuwadi, Village - Eksar, Borivali (West), Mumbai - 400 092, State – Maharashtra, Country – India.
3	Type of Building	Residential used
4	No. of Floors	Stilt + 7 Upper Floors
5	Whether stilt / podium / open parking provided	Stilt + Open Car Parking
6	Type of Construction	R.C.C. Framed Structure
7	Type of Foundation	R.C.C. Footing
8	Thickness of the External Walls	9" thick brick walls both sides plastered
9	Type of Compound	Brick Masonry Walls
10	Year of Construction	1998 (As per occupancy certificate)
11	Present age of building	25 years
12	Residual age of the building	35 years Subject to proper, preventive periodic maintenance & structural repairs.
13	No. of flats (Per Floor)	2 Flats on 2 <sup>nd</sup> Floor
14	Methodology adopted	As per visual site inspection



www.vastukala.org

### Our Pan India Presence at :

Mumbai Aurangabad Pune Rajkot  
Thane Nanded Indore Raipur  
Delhi NCR Nashik Ahmedabad Jaipur



Regd. Office : 121, 1st Floor, Akruti Star,  
Central Road, MIDC, Andheri (E),  
Mumbai - 400 093, (M.S.), INDIA  
TeleFax : +91 22 28371325/24  
mumbai@vastukala.org

<b>B.</b>	<b>External Observation of the Building</b>	
1	Plaster	Good Condition
2	Chajjas	Good Condition
3	Plumbing	Good Condition
4	Cracks on the external walls	Not found
5	Filling cracks on the external walls	Not found
6	Cracks on columns & beams	Not found
7	Vegetation	Not found
8	Leakages of water in the drainage pipes or water pipes	Not found
9	Dampness external in the wall due to leakages	Not found
10	Any other observation about the condition of external side of the building	The external condition of the building is in good condition
<b>C</b>	<b>Internal Observation of the common areas of the building and captioned premises</b>	
1	Beams (Cracks & Leakages)	Good Condition
2	Columns (Cracks & Leakages)	Good Condition
3	Ceiling (Cracks & Leakages)	Good Condition
4	Leakages inside the property	Not found
5	Painting inside the property	Normal
6	Maintenance of staircase & cracks	Good

<b>D</b>	<b>Common Observation</b>	
1	Structural Audit of the Building Under Bye – Laws No. 77 of the Model Bye Laws (Co-Operative Societies Act / Rules)	As per bye Laws No. 77 of Co-Op. Societies bye Laws under the Act the society shall conduct a Structural Audit of the building of the society as follows
2	Remark	No Structural Audit Report is furnished for the perusal

<b>E</b>	<b>Conclusion</b>
	<p>The captioned building is having Stilt + 7 Upper Floors which are constructed in year 1998 as per occupancy certificate. Estimated future life under present circumstances is about 35 years subject to proper, preventive periodic maintenance &amp; structural repairs.</p> <p>The inspection dated 24.04.2023 reveals no structural damage or deterioration to the building. The building as well as the property is maintained in good condition &amp; will stand future life subject to proper, preventive periodic maintenance &amp; Good structural repairs.</p> <p>Our Observations about the structure are given above.</p> <p>The above assessment is based on visual inspection only.</p>

For VASTUKALA CONSULTANTS (I) PVT. LTD.

Sharadkumar  
B. Chalikwar

Director

Digitally signed by Sharadkumar B. Chalikwar  
DN: cn=Sharadkumar B. Chalikwar, o=Vastukala Consultants (I) Pvt. Ltd., ou=CMD, email=cmd@vastukala.org, c=IN  
Date: 2023.04.28 10:54:00 +05'30'

Auth. Sign.

Sharadkumar B. Chalikwar

Govt. Reg. Valuer

Chartered Engineer (India)

Reg. No. (N) CCIT/1-14/52/2008-09

SBI Empanelment No.: SME/TCC/2021-22/85/13



Vastukala Consultants (I) Pvt. Ltd.

An ISO 9001:2015 Certified Company

www.vastukala.org





## Actual Site Photographs

