

```
{
  "typeOfReport": {
    "label": "APF",
    "value": "APF"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63b26652191f7b344b008cac"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f66be948726cc141b8f",
    "email": "sbi.04380@sbi.co.in",
    "firstName": "NITIN ",
    "mobileNo": "",
    "workMobileNo": "9969814381",
    "lastName": "SARGAN"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "10000000",
    "discussWithPerson": "NITIN ",
    "expectedFees": 5000,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
    "name": "VCIPL Mumbai",
    "shortName": "VCIPLM",
    "email": "vastukalamumbai@vastukala.com",
    "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
```

```
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63b26652191f7b344b008cac",
  "name": "HLST BKC",
  "branchCode": "",
  "mobileNo": "022-26445021",
  "alternateMobileNo": "",
  "email": "sbi.04380@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "HLST Synergy Building, 1st floor, C – 6, G Block\nBandra Kurla
Complex, Bandra (East),\nMumbai – 400 051."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential_cum_commercial",
  "label": "Residential cum Commercial"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "62723addafd7d55eddeddfe4",
    "role": "PICKUPPERSON",
    "firstName": "Ramkrishna ",
    "email": "rampatakar1991@gmail.com",
    "lastName": "Patkar",
    "mobileNo": "7045746060",
```

```
    "shortName": "RP",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "63fc4680ce84bf289ba9c7fc",
    "role": "SITEENGINEER",
    "firstName": "Nikhil ",
    "email": "valtechnical2022@gmail.com",
    "lastName": "Sonawane",
    "mobileNo": "9819470709",
    "designation": "",
    "shortName": "NS",
    "workWithDocumentMaker": "6006d4ce5080a310ac1fdfc2",
    "profilePhoto": "users/63fc4680ce84bf289ba9c7fc/
profilePhoto_1681380664371_WhatsApp_Image_20230413_at_33801_PM.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "60f9147bf3dd69653a591e8c",
    "role": "MAKER + RATE VERFIER + CHEAKER",
    "firstName": "Vinita",
    "email": "vinita.surve@vastukala.org",
    "lastName": "Surve",
    "mobileNo": "9820652818",
    "designation": "",
    "shortName": "V",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
  },
  "maker": {
    "type": "EMPLOYEE",
    "_id": "60f9147bf3dd69653a591e8c",
    "role": "MAKER + RATE VERFIER + CHEAKER",
    "firstName": "Vinita",
    "email": "vinita.surve@vastukala.org",
    "lastName": "Surve",
    "mobileNo": "9820652818",
    "designation": "",
    "shortName": "V",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
```

```
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f9147bf3dd69653a591e8c",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Vinita",
  "email": "vinita.surve@vastukala.org",
  "lastName": "Surve",
  "mobileNo": "9820652818",
  "designation": "",
  "shortName": "V",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
        "number": "CAT-I-F-1763"
      }
    ]
  }
]
```

```
    },
    {
      "title": {
        "value": "Chartered_Engineer",
        "label": "Chartered Engineer"
      },
      "_id": "60af80072ffdf65bcd658653",
      "number": "AM161706-3"
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.25587052785202",
  "longitude": "73.09133286004534"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.09133286004534,
    19.25587052785202
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
}
```

```
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft."
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Gove",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Basement",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": false,
```

```
"name": "District",
"key": "district",
"value": "",
"label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
}
```

```
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "HOH Kalyan Oak wood Bridge Wood, Greenwood",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
```



```
"key": "newSurveyNumber",
"value": "",
"label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
}
```

```
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"outgoingDetail": {
  "monthlyRent": ""
},
}
```

```
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
```

```
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
{others": {
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
totalValues": {
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
taskStatus": {
"SITE_INSPECTION": false,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
createCase": "false",
type": "CASE",
leadType": {
"label": "Lead",
"value": "LEAD"
},
siteVisitType": "FULL",
isSiteMeasurementAllowed": true,
finalValuationArea": "0",
empanelmentNo": [],
```



```
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"_id": "64b26eb35e3c942514e7f27f",
"ownerName": "HOH Kalyan Oak wood Bridge Wood, Greenwood",
"ownerPhoneNo": "9769303709",
"appAddress": "Bhiwandi ",
"remark": "contact - Gautam Jain ",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "path": "cases/64b26eb35e3c942514e7f27f/
document_1689415311419_apf__HOH_KALYAN__OAKWOOD.pdf",
    "fileName": "document_1689415311419_apf__HOH_KALYAN__OAKWOOD.pdf",
    "displayStatus": false,
    "id": "372254",
    "uploadedBy": "62723addafd7d55eddeddfe4",
    "createdAt": "Sat Jul 15 2023 15:32:05 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "002598",
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
  {
    "id": "979959",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Jul 15 2023 15:32:27 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "HOH Kalyan Oak wood Bridge Wood, Greenwood",
    "phone": "9769303709",
    "ownershipShare": "",
    "email": "",
    "id": "840834"
  }
],
"siteInspection": [],
"composition": [],
"otherComposition": [],
```

```
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64b67c80f76ce54e5d433061",
    "name":
"externallmg_1689681024092_WhatsApp_Image_20230718_at_51249_PM_6.jpeg",
    "path": "cases/64b26eb35e3c942514e7f27f/
externallmg_1689681024092_WhatsApp_Image_20230718_at_51249_PM_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64b67c80f76ce54e5d433062",
    "name":
"externallmg_1689681024097_WhatsApp_Image_20230718_at_51249_PM_7.jpeg",
    "path": "cases/64b26eb35e3c942514e7f27f/
externallmg_1689681024097_WhatsApp_Image_20230718_at_51249_PM_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64b67c80f76ce54e5d433063",
    "name":
"externallmg_1689681024102_WhatsApp_Image_20230718_at_51249_PM_8.jpeg",
    "path": "cases/64b26eb35e3c942514e7f27f/
externallmg_1689681024102_WhatsApp_Image_20230718_at_51249_PM_8.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64b67c80f76ce54e5d433064",
    "name":
"externallmg_1689681024109_WhatsApp_Image_20230718_at_51249_PM_9.jpeg",
    "path": "cases/64b26eb35e3c942514e7f27f/
externallmg_1689681024109_WhatsApp_Image_20230718_at_51249_PM_9.jpeg",
    "orientation": "landscape"
  },
  {

```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64b67c80f76ce54e5d433065",
    "name":
"externallmg_1689681024113_WhatsApp_Image_20230718_at_51249_PM_10.jpeg",
    "path": "cases/64b26eb35e3c942514e7f27f/
externallmg_1689681024113_WhatsApp_Image_20230718_at_51249_PM_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64b67c9df76ce54e5d4330d4",
    "name":
"externallmg_1689681053391_WhatsApp_Image_20230718_at_51249_PM_6.jpeg",
    "path": "cases/64b26eb35e3c942514e7f27f/
externallmg_1689681053391_WhatsApp_Image_20230718_at_51249_PM_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64b67c9df76ce54e5d4330d5",
    "name":
"externallmg_1689681053396_WhatsApp_Image_20230718_at_51249_PM_7.jpeg",
    "path": "cases/64b26eb35e3c942514e7f27f/
externallmg_1689681053396_WhatsApp_Image_20230718_at_51249_PM_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64b67c9df76ce54e5d4330d6",
    "name":
"externallmg_1689681053401_WhatsApp_Image_20230718_at_51249_PM_8.jpeg",
    "path": "cases/64b26eb35e3c942514e7f27f/
externallmg_1689681053401_WhatsApp_Image_20230718_at_51249_PM_8.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64b67c9df76ce54e5d4330d7",
    "name":
"externallmg_1689681053406_WhatsApp_Image_20230718_at_51249_PM_9.jpeg",
    "path": "cases/64b26eb35e3c942514e7f27f/
externallmg_1689681053406_WhatsApp_Image_20230718_at_51249_PM_9.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64b67c9df76ce54e5d4330d8",
    "name":
"externallmg_1689681053410_WhatsApp_Image_20230718_at_51249_PM_10.jpeg",
    "path": "cases/64b26eb35e3c942514e7f27f/
externallmg_1689681053410_WhatsApp_Image_20230718_at_51249_PM_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64b67c9df76ce54e5d4330d9",
    "name":
"externallmg_1689681053414_WhatsApp_Image_20230718_at_51249_PM_11.jpeg",
    "path": "cases/64b26eb35e3c942514e7f27f/
externallmg_1689681053414_WhatsApp_Image_20230718_at_51249_PM_11.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64b67c9df76ce54e5d4330da",
    "name":
"externallmg_1689681053419_WhatsApp_Image_20230718_at_51249_PM_12.jpeg",
    "path": "cases/64b26eb35e3c942514e7f27f/
externallmg_1689681053419_WhatsApp_Image_20230718_at_51249_PM_12.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64b67c9df76ce54e5d4330db",
    "name":
"externallmg_1689681053426_WhatsApp_Image_20230718_at_51249_PM_13.jpeg",
    "path": "cases/64b26eb35e3c942514e7f27f/
externallmg_1689681053426_WhatsApp_Image_20230718_at_51249_PM_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64b67c9df76ce54e5d4330dc",
```

```
    "name":
"externallmg_1689681053431_WhatsApp_Image_20230718_at_51249_PM_14.jpeg",
  "path": "cases/64b26eb35e3c942514e7f27f/
externallmg_1689681053431_WhatsApp_Image_20230718_at_51249_PM_14.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64b67c9df76ce54e5d4330dd",
  "name":
"externallmg_1689681053435_WhatsApp_Image_20230718_at_51249_PM_15.jpeg",
  "path": "cases/64b26eb35e3c942514e7f27f/
externallmg_1689681053435_WhatsApp_Image_20230718_at_51249_PM_15.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64b67c9df76ce54e5d4330de",
  "name":
"externallmg_1689681053438_WhatsApp_Image_20230718_at_51249_PM_16.jpeg",
  "path": "cases/64b26eb35e3c942514e7f27f/
externallmg_1689681053438_WhatsApp_Image_20230718_at_51249_PM_16.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64b67c9df76ce54e5d4330df",
  "name":
"externallmg_1689681053441_WhatsApp_Image_20230718_at_51249_PM_17.jpeg",
  "path": "cases/64b26eb35e3c942514e7f27f/
externallmg_1689681053441_WhatsApp_Image_20230718_at_51249_PM_17.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64b67c9df76ce54e5d4330e0",
  "name":
"externallmg_1689681053445_WhatsApp_Image_20230718_at_51249_PM.jpeg",
  "path": "cases/64b26eb35e3c942514e7f27f/
externallmg_1689681053445_WhatsApp_Image_20230718_at_51249_PM.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64b67c9df76ce54e5d4330e1",
  "name":
"externallmg_1689681053447_WhatsApp_Image_20230718_at_51250_PM_1.jpeg",
  "path": "cases/64b26eb35e3c942514e7f27f/
externallmg_1689681053447_WhatsApp_Image_20230718_at_51250_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64b67c9df76ce54e5d4330e2",
  "name":
"externallmg_1689681053450_WhatsApp_Image_20230718_at_51250_PM_2.jpeg",
  "path": "cases/64b26eb35e3c942514e7f27f/
externallmg_1689681053450_WhatsApp_Image_20230718_at_51250_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64b67c9df76ce54e5d4330e3",
  "name":
"externallmg_1689681053451_WhatsApp_Image_20230718_at_51250_PM_3.jpeg",
  "path": "cases/64b26eb35e3c942514e7f27f/
externallmg_1689681053451_WhatsApp_Image_20230718_at_51250_PM_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64b67c9df76ce54e5d4330e4",
  "name":
"externallmg_1689681053453_WhatsApp_Image_20230718_at_51250_PM.jpeg",
  "path": "cases/64b26eb35e3c942514e7f27f/
externallmg_1689681053453_WhatsApp_Image_20230718_at_51250_PM.jpeg",
  "orientation": "landscape"
}
],
"externalDocuments": [],
"createdAt": "2023-07-15T10:02:27.049Z",
"updatedAt": "2023-07-18T11:50:53.527Z",
"__v": 0,
"invoiceId": "64b26eb35e3c942514e7f285",
```

"fullAddress": " APF No. Basement Floor, HOH Kalyan Oak wood Bridge Wood, Greenwood, Village - Gove, State - Maharashtra, India",
"updatedBy": "6006d4ce5080a310ac1fdcf2",
"addressForMap": "",
"caseReferredBy": "62723addafd7d55eddeddfe4",
"contactPersonName": "HOH Kalyan Oak wood Bridge Wood, Greenwood",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9769303709"

}

Name	Length	Width	Total
-------------	---------------	--------------	--------------

Composition :

Other

Composition :
