

PROFORMA INVOICE

Vastukala Consultants (I) Pvt Ltd B1-001,U/B FLOOR, BOOMERANG,CHANDIVALI FARM ROAD, ANDHERI-EAST 400072 GSTIN/UIN: 27AADCV4303R1ZX State Name : Maharashtra, Code : 27 E-Mail : accounts@vastukala.org	Invoice No. PG-1983/23-24	Dated 14-Aug-23
Buyer (Bill to) Cosmos Bank-Fort Branch Fort Branch 229/231, Perin Nariman Street, Bazar Gate, Fort 400001 GSTIN/UIN : 27AAAAT0742K1ZH State Name : Maharashtra, Code : 27	Delivery Note	Mode/Terms of Payment AGAINST REPORT
	Reference No. & Date.	Other References
	Buyer's Order No.	Dated
	Dispatch Doc No. 003092 / 2302043	Delivery Note Date
	Dispatched through	Destination
	Terms of Delivery	

SI No.	Particulars	HSN/SAC	GST Rate	Amount
1	STRUCTURAL REPORT FEE <i>(Technical Inspection and Certification Services)</i>	997224	18 %	2,000.00
	CGST			180.00
	SGST			180.00
	Total			2,360.00

Amount Chargeable (in words) E. & O.E

Indian Rupee Two Thousand Three Hundred Sixty Only

HSN/SAC	Taxable Value	Central Tax		State Tax		Total Tax Amount
		Rate	Amount	Rate	Amount	
997224	2,000.00	9%	180.00	9%	180.00	360.00
Total	2,000.00		180.00		180.00	360.00

Tax Amount (in words) : **Indian Rupee Three Hundred Sixty Only**

Remarks:
 Mr. Jamaluddin Usman Shaikh, Mr. Firoz Usman Shaikh, Shaikh Usman Mohammad Ibrahim & Mrs. Zulekhabi Usman Shaikh - Residential Flat No. 304, 3rd Floor, Wing - D, "Shree Sai Park D Wing Co-op. Hsg. Soc. Ltd.", Azad Nagar No. 2, Near Castle Mill, Village - Panchpakhadi, Thane (West), PIN Code - 400 601, State - Maharashtra, Country - India

Company's PAN : **AADCV4303R**

Declaration
 NOTE - AS PER MSME RULES INVOICE NEED TO BE CLEARED WITHIN 45 DAYS OR INTEREST CHARGES APPLICABLE AS PER THE RULE.
 MSME Registration No. - 27222201137

Company's Bank Details
 Bank Name : **The Cosmos Co-Operative Bank Ltd**
 A/c No. : **0171001022668**
 Branch & IFS Code : **Vileparle & COSB0000017**



UPI Virtual ID : **Vastukala@icici**

for **Vastukala Consultants (I) Pvt Ltd**

R. D. D.
 Authorised Signatory

This is a Computer Generated Invoice



Vastukala Consultants (I) Pvt. Ltd.
 An ISO 9001:2015 Certified Company www.vastukala.org



Structural Stability Report

Structural Observation Report of Residential Flat No. 304, 3rd Floor, Wing – D, "Shree Sai Park D Wing Co-op. Hsg. Soc. Ltd.", Azad Nagar No. 2, Near Castle Mill, Village – Panchpakhadi, Thane (West), PIN Code – 400 601, State – Maharashtra, Country – India.

Name of Owner: Mr. Jamaluddin Usman Shaikh, Mr. Firoz Usman Shaikh, Shaikh Usman Mohammad Ibrahim & Mrs. Zulekhabi Usman Shaikh

This is to certify that on visual inspection, it appears that the structure of the building "Shree Sai Park D Wing Co-op. Hsg. Soc. Ltd." is in normal condition and the future life can be reasonably taken under good working condition and with proper periodic repairs & maintenance is about 45 years.

General Information:

A.	Introduction	
1	Name of Building	"Shree Sai Park D Wing Co-op. Hsg. Soc. Ltd."
2	Property Address	Residential Flat No. 304, 3 rd Floor, Wing – D, "Shree Sai Park D Wing Co-op. Hsg. Soc. Ltd.", Azad Nagar No. 2, Near Castle Mill, Village – Panchpakhadi, Thane (West), PIN Code – 400 601, State – Maharashtra, Country – India
3	Type of Building	Residential use
4	No. of Floors	Ground + 8 Upper Floors
5	Whether stilt / podium / open parking provided	Open Car Parking Space
6	Type of Construction	R.C.C. Framed Structure
7	Type of Foundation	R.C.C. Footing
8	Thickness of the External Walls	9" thick brick walls both side plastered
9	Type of Compound	Brick Masonry Walls
10	Year of Construction	2008 (Approx.)
11	Present age of building	15 Years
12	Residual age of the building	45 years Subject to proper, preventive periodic maintenance & structural repairs.
13	No. of flats (Per Floor)	4 Flats
14	Methodology adopted	As per visual site inspection



Our Pan India Presence at :

Mumbai Aurangabad Pune Rajkot
Thane Nanded Indore Raipur
Delhi NCR Nashik Ahmedabad Jaipur

Regd. Office : B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Andheri (East), Mumbai - 400 072, (M.S.), INDIA
TeleFax : +91 22 28371325/24
mumbai@vastukala.org

B.	External Observation of the Building	
1	Plaster	Normal Condition
2	Chajjas	Normal Condition
3	Plumbing	Normal Condition
4	Cracks on the external walls	Found
5	Filling cracks on the external walls	Found
6	Cracks on columns & beams	Not Found
7	Vegetation	Found
8	Leakages of water in the drainage pipes or water pipes	Not Found
9	Dampness external in the wall due to leakages	Found
10	Any other observation about the condition of external side of the building	The external condition is Normal
C	Internal Observation of the common areas of the building and captioned premises	
1	Beams (Cracks & Leakages)	Good Condition
2	Columns (Cracks & Leakages)	Good Condition
3	Ceiling (Cracks & Leakages)	Normal Condition
4	Leakages inside the property	Not Found
5	Painting inside the property	Good
6	Maintenance of staircase & cracks	Normal

D	Common Observation	
1	Structural Audit of the Building Under Bye – Laws No. 77 of the Model Bye Laws (Co-Operative Societies Act / Rules)	As per Bye Laws No. 77 of Co-Op. Societies Bye Laws under the Act the society shall conduct a Structural Audit of the building of the society as follows
2	Remark	No Structural Audit Report is furnished for the perusal

E	Conclusion
	<p>The captioned building is having Ground + 8 upper floors which is constructed in year 2008 (Approx.). Estimated future life under present circumstances is about 45 years subject to proper, preventive periodic maintenance & structural repairs.</p> <p>The inspection dated 24.07.2023 reveals no structural damage to the building. The building as well as the property is maintained normally and will stand future life subject to proper, preventive periodic maintenance & structural repairs.</p> <p>Our Observations about the structure are given as above.</p> <p>The above assessment is based on visual inspection only.</p>

For VASTUKALA CONSULTANTS (I) PVT. LTD.

Sharadkumar
B. ChalikwarDigitally signed by Sharadkumar B.
Chalikwar
DN: cn=Sharadkumar B. Chalikwar,
o=Vastukala Consultants (I) Pvt. Ltd.,
ou=CMD, email=cmd@vastukala.org, c=IN
Date: 2023.08.14 11:11:11 +05'30'

C.M.D.

Auth. Sign

Sharadkumar B. Chalikwar

Govt. Reg. Valuer

Chartered Engineer (India)

Reg. No. (N) CCIT/1-14/52/2008-09

SBI Empanelment No.: SME / TCC / 2016-17 / 156 / Sr. No. - 193



Vastukala Consultants (I) Pvt. Ltd.

An ISO 9001:2015 Certified Company

www.vastukala.org



Actual Site Photographs

