CIN: U74120MH2010PTC207869 MSME Reg. No.: UDYAM-MH-18-0083617 An ISO 9001:2015 Certified Company





Structural Stability Report Prepared For: BOB / Regional Office Branch / Shri. Yuvraj Bhimrao Shriwant (3093/2302022) Page 1 of 3

Vastu/Nashik/08/2023/3093 / 23012022 11/09-168-CHSH

Date: 11.08.2023

Structural Stability Report

Residential Flat No. F-3, Building No. F-8, Ground Floor, "Kailasji Co. Op. Hsg. Soc. Ltd. Nashikroad ",Survey No.125/1B, Front of Central Jail, Bhim Nagar, Jail Road, Nashik Road, Village - Deolali, Taluka & District - Nashik, PIN Code - 422 401, State - Maharashtra, Country - India belongs to Kailasji Co. Op. Hsg. Soc. Ltd. Nashikroad, Through Member Smt. Vimalbai Bhaidas Wadile Name of Proposed Purchaser: Shri. Yuvraj Bhimrao Shriwant & Sau. Maya Yuvraj Shriwant.

This is to certify that on visual inspection, it appears that the structure of "Kailasji Co. Op. Hsg. Soc. Ltd. Nashikroad " is in normal condition and the future life can be reasonably takes under good condition and with proper periodic repairs & maintenance is about 38 years.

General Information:

A.		Introduction
1	Name of Building	" Kailasji Co. Op. Hsg. Soc. Ltd. Nashikroad "
2	Property Address	Residential Flat No. F-3, Building No. F-8, Ground Floor, "
		Kailasji Co. Op. Hsg. Soc. Ltd. Nashikroad", Survey
		No.125/1B, Front of Central Jail, Bhim Nagar, Jail Road,
		Nashik Road, Village - Deolali, Taluka & District - Nashik,
		PIN Code – 422 401, State – Maharashtra, Country – India
3	Type of Building	Flat No.F-3
4	No. of Floors	Ground + 3 Upper Floors
5	Whether stilt / podium / open parking	Open Car Parking
	provided	
6	Type of Construction	R.C.C. Framed Structure
7	Type of Foundation	R.C.C. Footing
8	Thickness of the External Walls	6' thick brick walls both sides plastered
9	Type of Compound	Brick Masonry Walls
10	Year of Construction	2001 (As per Part Occupancy Certificate)
11	Present age of building	22 years
12	Residual age of the building	38 years Subject to proper, preventive periodic
		maintenance & structural repairs.
13	No. of Flats	4 Flats on Ground Floor
14	Methodology adopted	As per visual site inspection
		Wolana V Spaning



Nashik: 4, 1st Floor, Madhusha Elite, Vrundavan Nagar, Jatra-Nandur Naka Link Road, Adgaon, Nashik - 422 003, (M.S.) E-mail: nashik@vastukala.org, Tel.: +91 253 4068262 / 9890380564



Mumbai Aurangabad Thane 💡 Nanded **?** Nashik Delhi NCR

Pune 🕈 Ahmedabad 💡 Jaipur

🦞 Rajkot **♀** Raipur Regd. Office: B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Andheri (East), Mumbai - 400 072, (M.S.), INDIA

TeleFax: +91 22 28371325/24

B.	External Observation of the Building		
1	Plaster	Normal Condition	
2	Chajjas	Normal Condition	
3	Plumbing	Good Condition	
4	Cracks on the external walls	Found	
5	Filling cracks on the external walls	Not Found	
6	Cracks on columns & beams	Not Found	
7	Vegetation	Not Found	
8	Leakages of water in the drainage pipes	Not Found	
	or water pipes		
9	Dampness external in the wall due to	Found	
	leakages		
10	Any other observation about the condition	The external condition of the structure is in normal condition	
	of external side of the building		
С	Internal Observation of the common areas of the building and captioned premises		
1	Beams (Cracks & Leakages)	Not found	
2	Columns (Cracks & Leakages)	Not found	
3	Ceiling (Cracks & Leakages)	Not found	
4	Leakages inside the property	Not Found	
5	Painting inside the property	External Wall Plaster and Painting Condition is normal	
6	Maintenance of staircase & cracks	Average	

D	Con	nmon Observation
1	Structural Audit of the Building Under Bye	As per bye Laws No. 77 of Co-Op. Societies bye Laws
	- Laws No. 77 of the Model Bye Laws (Co-	under the Act the society shall conduct a Structural Audit of
	Operative Societies Act / Rules)	the building of the society as follows
2	Remark	- /

E Conclusion

The captioned Flat is having Ground Floor which are constructed in year 2001 (As per Part Occupancy Certificate). Estimated future life under present circumstances is about 38 years' subject to proper, preventive periodic maintenance & structural repairs.

The inspection dated 02.08.2023 reveals no structural damage or deterioration to the building. The building as well as the property is maintained in Average condition & will stand future life subject to proper, preventive periodic maintenance & Average structural repairs.

Our Observations about the structure are given above.

The above assessment is based on visual inspection only.

For VASTUKALA CONSULTANTS (I) PVT. LTD.

C.M.D. Auth. Sign

Sharadkumar B. Chalikwar

Govt. Reg. Valuer Chartered Engineer (India)

Reg. No. (N) CCIT/1-14/52/2008-09

Encl: Valuation report.



Actual site photographs













