

```
{
  "typeOfReport": {
    "value": "Residential",
    "label": "Residential"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64ddb919ccaf1e7b7f650a1e"
    },
    "type": "CREDITOFFICER",
    "_id": "64ddb919ccaf1e7b7f650a20",
    "firstName": "Nitin ",
    "lastName": "Gupta",
    "mobileNo": "",
    "workMobileNo": "8191099787",
    "email": "ubin0562335@unionbankofindia.bank"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "6418456a96b58848585f8cb2",
"name": "Thane",
"email": "thane@vastukala.com",
"phone": "1234567890",
"address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
"city": "Thane",
"shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "64ddb919ccaf1e7b7f650a1e",
  "name": "Vartak Nagar Branch",
  "branchCode": "",
  "mobileNo": "022 25855050",
  "alternateMobileNo": "",
  "email": "ubin0562335@unionbankofindia.bank",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Ground Floor, Jagdale Amizra, Kores Road, Near Aai Mata Temple,
Vartak Nagar, Thane West - 400606"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60f93be845132d6a6bdda676",
  "zoneName": "MUMBAI SOUTH"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "64abdb2806d6ec174986d16b",
"role": "PICKUPPERSON",
"firstName": "Sahadu",
"email": "thoratsahadu8679@gmail.com",
"lastName": "Thorat",
"mobileNo": "9422389642",
"shortName": "ST",
"workWithDocumentMaker": ""
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "62ea09ea4e679b264caf07d7",
"role": "SITEENGINEER",
"firstName": "Suraj",
"email": "suraj@vastukala.org",
"lastName": "Zore",
"mobileNo": "8652448654",
"designation": "",
"shortName": "SZ",
"workWithDocumentMaker": "60092304a16fab0f2af9b0c2",
"profilePhoto": "users/62ea09ea4e679b264caf07d7/
profilePhoto_1685629394240_image.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"maker": {
"type": "EMPLOYEE",
"_id": "627222afafd7d55eddeddd82",
"role": "MAKER",
"firstName": "Pratibha",
"email": "shilvanta_pratibha@yahoo.co.in",
"lastName": "Shilvantha",
"mobileNo": "9821518537",
"designation": ""
}
```

```
"shortName": "PS",
"workWithDocumentMaker": "",
"profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": "",
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
"value": "FIIV",
"label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
"title": {
"value": "Chartered_Engineer",
"label": "Chartered Engineer"
},
"_id": "60af80072ffdf65bcd658653",
"number": "AM161706-3"
},
}
```

```
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
},
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.203884034271002",
  "longitude": " 72.96838053558186"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-08-17",
      "remark": ""
    }
  ]
},
"schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
}
```

```
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Panchpakhadi",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "3",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
```

```
"value": "Thane",
"label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Dev Corpora",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
```

```
"status": false,
"name": "Street 1",
"key": "street1",
"value": "",
"label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Pokharan Rd Number 1, J K Gram, Thane West",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
```



```
"label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "306",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
```

```
"name": "Mouza",
"key": "mouza",
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
}
```

```
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
}
```

```
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
```

```
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```

```
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
{others": {
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
totalValues": {
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
taskStatus": {
"SITE_INSPECTION": true,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
createCase": "false",
type": "CASE",
leadType": {
"label": "Lead",
"value": "LEAD"
},
siteVisitType": "PARTIAL",
isSiteMeasurementAllowed": true,
finalValuationArea": "0",
empanelmentNo": [],
isAdvanceInvoice": false,
status": true,
```



```
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"_id": "64ddc097ccaf1e7b7f651cb2",
"ownerName": "Mr. Chinmay Padmakar Bhoir",
"ownerPhoneNo": "8879739354",
"fullAddress": "Residential Flat No. 306, 3rd Floor, Wing - A, Dev Corpora, Pokharan
Rd Number 1, J K Gram, Thane West, Village - Panchpakhadi, District - Thane, State -
Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "10/07/2023",
      "from": {
        "value": "Vendor",
        "label": "Vendor"
      },
      "Vendor": "Mr. Balkrishna Liladhar Mahajan & Mrs. Shailaja Balkrishna Mahajan",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      },
      "purchaser": "Mr. Chinmay Padmakar Bhior"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1692254325297_Sale_Deed_Chinmay_Bhoir.pdf",
    "path": "cases/64ddc097ccaf1e7b7f651cb2/
document_1692254325297_Sale_Deed_Chinmay_Bhoir.pdf",
    "id": "219014",
    "uploadedBy": "6430f74691d7c62df11f3f15",
    "createdAt": "Thu Aug 17 2023 12:08:53 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124baa6d152c1801b2fd",
      "label": "Occupancy Certificate"
    },
    "inputs": {
      "documentDate": "30/12/2016",
      "nameOfApprovingAuthority": {
        "value": "Thane_Municipal_Corporation",
        "label": "Thane Municipal Corporation"
      }
    }
  }
]
```

```
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "1613 / TMC / TDD / 159 "
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1692768131918_164771.pdf",
  "path": "cases/64ddc097ccaf1e7b7f651cb2/
document_1692768131918_164771.pdf",
  "id": "582398",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Wed Aug 23 2023 11:01:06 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124daa6d152c1801b306",
    "label": "Property Tax"
  },
  "inputs": {
    "documentDate": "01/04/2023",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "TMC232412803579"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1692768269058_263318.pdf",
  "path": "cases/64ddc097ccaf1e7b7f651cb2/
document_1692768269058_263318.pdf",
  "id": "543914",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Wed Aug 23 2023 11:01:06 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1258aa6d152c1801b33a",
    "label": "No Objection Certificate "
  },
  "inputs": {
    "documentDate": "22/08/2023",
    "nameOfApprovingAuthority": {
```

```
    "value": "SOCIETY",
    "label": "SOCIETY"
  },
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "NA"
},
"isHardCopy": false,
"displayStatus": true,
"fileName":
"document_1692768354942_Chinmay_Bhoir__Society_NOC__306A.pdf",
  "path": "cases/64ddc097ccaf1e7b7f651cb2/
document_1692768354942_Chinmay_Bhoir__Society_NOC__306A.pdf",
  "id": "670370",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Wed Aug 23 2023 11:01:06 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae12b1aa6d152c1801b4d6",
    "label": "Title Report"
  },
  "inputs": {
    "documentDate": "02/08/2023",
    "remark": "issued by R. R. Singh (Advocate)",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "NA"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1692768514030_Title_Report.pdf",
  "path": "cases/64ddc097ccaf1e7b7f651cb2/
document_1692768514030_Title_Report.pdf",
  "id": "144583",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Wed Aug 23 2023 11:01:06 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae12b1aa6d152c1801b4d6",
    "label": "Title Report"
  }
}
```

```
    },
    "inputs": {
      "documentDate": "05/10/2015",
      "remark": "issued by Umesh G. Deshpande (Advocate)"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1692768665671_Title_Investigation_Report____306.pdf",
    "path": "cases/64ddc097ccaf1e7b7f651cb2/
document_1692768665671_Title_Investigation_Report____306.pdf",
    "id": "822832",
    "uploadedBy": "627222afafd7d55eddeddd82",
    "createdAt": "Wed Aug 23 2023 11:01:06 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "003158",
"createdBy": "6430f74691d7c62df11f3f15",
"caseHistory": [
  {
    "id": "565542",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Aug 17 2023 12:09:19 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Chinmay Padmakar Bhoir",
    "phone": "8879739354",
    "ownershipShare": "",
    "email": "",
    "id": "909081"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
  }
]
```

```
    "_id": "64dde784ccaf1e7b7f656fcc",
    "name": "externallmg_r_1692264288789_1692264088183_image_1.jpg",
    "path": "cases/64ddc097ccaf1e7b7f651cb2/
externallmg_r_1692264288789_1692264088183_image_1.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64dde784ccaf1e7b7f656fcd",
    "name": "externallmg_r_1692264286063_1692264088183_image_0.jpg",
    "path": "cases/64ddc097ccaf1e7b7f651cb2/
externallmg_r_1692264286063_1692264088183_image_0.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64dde784ccaf1e7b7f656fce",
    "name": "externallmg_r_1692264290075_1692264088183_image_2.jpg",
    "path": "cases/64ddc097ccaf1e7b7f651cb2/
externallmg_r_1692264290075_1692264088183_image_2.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64dde784ccaf1e7b7f656fcf",
    "name": "externallmg_r_1692264290751_1692264088183_image_3.jpg",
    "path": "cases/64ddc097ccaf1e7b7f651cb2/
externallmg_r_1692264290751_1692264088183_image_3.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64dde784ccaf1e7b7f656fd0",
    "name": "externallmg_r_1692264291483_1692264088183_image_4.jpg",
    "path": "cases/64ddc097ccaf1e7b7f651cb2/
externallmg_r_1692264291483_1692264088183_image_4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64dde784ccaf1e7b7f656fd1",
```

```
    "name": "externallmg_r_1692264294534_1692264088183_image_6.jpg",
    "path": "cases/64ddc097ccaf1e7b7f651cb2/
externallmg_r_1692264294534_1692264088183_image_6.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64dde784ccaf1e7b7f656fd2",
    "name": "externallmg_r_1692264296618_1692264088183_image_7.jpg",
    "path": "cases/64ddc097ccaf1e7b7f651cb2/
externallmg_r_1692264296618_1692264088183_image_7.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64dde784ccaf1e7b7f656fd3",
    "name": "externallmg_r_1692264292991_1692264088183_image_5.jpg",
    "path": "cases/64ddc097ccaf1e7b7f651cb2/
externallmg_r_1692264292991_1692264088183_image_5.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64dde784ccaf1e7b7f656fd4",
    "name": "externallmg_r_1692264298736_1692264088183_image_8.jpg",
    "path": "cases/64ddc097ccaf1e7b7f651cb2/
externallmg_r_1692264298736_1692264088183_image_8.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64dde784ccaf1e7b7f656fd5",
    "name": "externallmg_r_1692264300618_1692264088183_image_9.jpg",
    "path": "cases/64ddc097ccaf1e7b7f651cb2/
externallmg_r_1692264300618_1692264088183_image_9.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64dde784ccaf1e7b7f656fd6",
    "name": "externallmg_r_1692264302366_1692264088183_image_10.jpg",
```

```
    "path": "cases/64ddc097ccaf1e7b7f651cb2/
externallmg_r_1692264302366_1692264088183_image_10.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64dde784ccaf1e7b7f656fd7",
    "name": "externallmg_r_1692264303780_1692264088183_image_11.jpg",
    "path": "cases/64ddc097ccaf1e7b7f651cb2/
externallmg_r_1692264303780_1692264088183_image_11.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64dde784ccaf1e7b7f656fd8",
    "name": "externallmg_r_1692264305622_1692264088183_image_12.jpg",
    "path": "cases/64ddc097ccaf1e7b7f651cb2/
externallmg_r_1692264305622_1692264088183_image_12.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64dde784ccaf1e7b7f656fd9",
    "name": "externallmg_r_1692264309716_1692264088183_image_14.jpg",
    "path": "cases/64ddc097ccaf1e7b7f651cb2/
externallmg_r_1692264309716_1692264088183_image_14.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64dde784ccaf1e7b7f656fda",
    "name": "externallmg_r_1692264307751_1692264088183_image_13.jpg",
    "path": "cases/64ddc097ccaf1e7b7f651cb2/
externallmg_r_1692264307751_1692264088183_image_13.jpg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64dde784ccaf1e7b7f656fdb",
    "name": "externallmg_r_1692264265966_1692264063747_image_2.png",
    "path": "cases/64ddc097ccaf1e7b7f651cb2/
externallmg_r_1692264265966_1692264063747_image_2.png",
```

```

    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64dde784ccaf1e7b7f656fdc",
    "name": "externalImg_r_1692264263034_1692264063747_image_0.jpg",
    "path": "cases/64ddc097ccaf1e7b7f651cb2/
externalImg_r_1692264263034_1692264063747_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64dde784ccaf1e7b7f656fdd",
    "name": "externalImg_r_1692264264878_1692264063747_image_1.jpg",
    "path": "cases/64ddc097ccaf1e7b7f651cb2/
externalImg_r_1692264264878_1692264063747_image_1.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"createdAt": "2023-08-17T06:39:19.994Z",
"updatedAt": "2023-08-23T05:31:06.579Z",
"__v": 0,
"invoiceId": "64ddc098ccaf1e7b7f651cc1",
"updatedBy": "627222afafd7d55eddeddd82",
"addressForMap": "",
"caseReferredBy": "64abdb2806d6ec174986d16b",
"contactPersonName": "Mr. Chinmay Padmakar Bhoir",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "8879739354"
}

```

Name	Length	Width	Total
Composition :			



Other  
Composition :

---