

```
{
  "typeOfReport": {
    "value": "Residential",
    "label": "Residential"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64e5c4d71452884516b3d53a"
    },
    "type": "CREDITOFFICER",
    "_id": "64e5c4d71452884516b3d53c",
    "firstName": "AKshay",
    "lastName": "Patil",
    "mobileNo": "",
    "workMobileNo": "9421212673",
    "email": "bmmsro3506@centralbank.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "6418456a96b58848585f8cb2",
"name": "Thane",
"email": "thane@vastukala.com",
"phone": "1234567890",
"address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
"city": "Thane",
"shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17fa",
  "type": "BANK",
  "name": "Central Bank of India",
  "displayName": "Central Bank of India",
  "initial": "CBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "64e5c4d71452884516b3d53a",
  "name": "Bhandup West Branch",
  "branchCode": "",
  "mobileNo": "02225961416",
  "alternateMobileNo": "",
  "email": "bmmsro3506@centralbank.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Shop no 28-29, Mayursh Srishti, Opp Asian Paints, L B S Road, Bhanup
West Mumbai 400078"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60f917e0f3dd69653a592221",
  "zoneName": "South Mumbai Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
  "_id": "62720e52afd7d55eddedc887",
  "role": "PICKUPPERSON",
  "firstName": "Harshad",
  "email": "harshad@vastukala.org",
  "lastName": "Panchal",
  "mobileNo": "9029575553",
  "shortName": "HP",
  "workWithDocumentMaker": ""
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62ea09ea4e679b264caf07d7",
  "role": "SITEENGINEER",
  "firstName": "Suraj",
  "email": "suraj@vastukala.org",
  "lastName": "Zore",
  "mobileNo": "8652448654",
  "designation": "",
  "shortName": "SZ",
  "workWithDocumentMaker": "60092304a16fab0f2af9b0c2",
  "profilePhoto": "users/62ea09ea4e679b264caf07d7/
profilePhoto_1685629394240_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "627221f4afd7d55eddeddcb4",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Prajakta",
  "email": "prajakta@vastukala.org",
  "lastName": "Patil",
  "mobileNo": "9769797568",
  "designation": "",
  "shortName": "P",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "MAKER",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
  "designation": ""
```

```
"shortName": "PS",
"workWithDocumentMaker": "",
"profilePhoto": "users/627222afafd7d55eddedd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "627221f4afd7d55eddeddcb4",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Prajakta",
"email": "prajakta@vastukala.org",
"lastName": "Patil",
"mobileNo": "9769797568",
"designation": "",
"shortName": "P",
"workWithDocumentMaker": "",
"profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
"value": "FIIV",
```

```
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.13629315961642",
  "longitude": "72.93004113558186"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
}
},
```

```
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-08-24",
      "remark": ""
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Kanjurmarg",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "18",
```

```
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
```

```
"name": "Building Name",
"key": "buildingName",
"value": "Gundecha Altura",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "L B S Marg Kanjurmarg west ",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
}
```



```
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1802",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
```

```
"key": "municipalityWardNo",
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": " 400078",
  "label": false
},
}
```

```
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
```

```
"label": "Full Building Rcc",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
```

```
"title": "Wardrobes",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
}
```



```
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"_id": "64e5cfe01452884516b3e845",
"ownerName": "Mr. Tushar Y Savdavkar",
"ownerPhoneNo": "7506345042",
"fullAddress": "Residential Flat No. 1802, 18th Floor, Gundecha Altura, L B S Marg
Kanjurmarg west , Village - Kanjurmarg, Mumbai, 400078, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "13/06/2017",
      "from": {
        "value": "Transferor",
        "label": "Transferor"
      },
      "Transferor": "Mr. Mukund Kisan Adak ",
      "to": {
        "value": "transferee",
        "label": "transferee"
      },
      "transferee": "Mrs. Hemangini Tushar Savdavkar & Mr. Tushar Yashwant Savdavkar"
    }
  },
  {
    "isHardCopy": false,
    "displayStatus": true,
    "path": "cases/64e5cfe01452884516b3e845/
document_1692951043926_DocScanner_23Aug2023_2326.pdf",
    "fileName": "document_1692951043926_DocScanner_23Aug2023_2326.pdf",
    "id": "785389",
```

```
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Fri Aug 25 2023 13:46:10 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "05/10/2011",
    "nameOfApprovingAuthority": {
      "value": "BRIHANMUMBAI_MAHANAGARPALIKA",
      "label": "BRIHANMUMBAI MAHANAGARPALIKA"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "CE / 1113 / BPES / AS"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1692951302032_141269.pdf",
"path": "cases/64e5cfe01452884516b3e845/
document_1692951302032_141269.pdf",
"id": "687485",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Fri Aug 25 2023 13:46:10 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "15/01/2010",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_Of_Greater_Mumbai",
      "label": "Municipal Corporation Of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "CE / 11 / 3 / BPES / AS"
},
}
```

```
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1692951370057_110433.pdf",
    "path": "cases/64e5cfe01452884516b3e845/
document_1692951370057_110433.pdf",
    "id": "746973",
    "uploadedBy": "627222afafd7d55eddeddd82",
    "createdAt": "Fri Aug 25 2023 13:46:10 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "003328",
"createdBy": "6430f74691d7c62df11f3f15",
"caseHistory": [
  {
    "id": "429552",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Aug 23 2023 14:52:40 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Tushar Y Savdavkar",
    "phone": "7506345042",
    "ownershipShare": "",
    "email": "",
    "id": "767524"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e7355c1452884516b6cef7",
    "name": "externalimg_r_1692874031562_1692873899376_image_0.jpg",
    "path": "cases/64e5cfe01452884516b3e845/
externalimg_r_1692874031562_1692873899376_image_0.jpg",
    "orientation": "portrait"
  }
]
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "64e7355c1452884516b6cef8",
      "name": "externallmg_r_1692874034880_1692873899376_image_3.jpg",
      "path": "cases/64e5cfe01452884516b3e845/
externallmg_r_1692874034880_1692873899376_image_3.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "64e7355c1452884516b6cef9",
      "name": "externallmg_r_1692874032808_1692873899376_image_1.jpg",
      "path": "cases/64e5cfe01452884516b3e845/
externallmg_r_1692874032808_1692873899376_image_1.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "64e7355c1452884516b6cefa",
      "name": "externallmg_r_1692874033654_1692873899376_image_2.jpg",
      "path": "cases/64e5cfe01452884516b3e845/
externallmg_r_1692874033654_1692873899376_image_2.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "64e7355c1452884516b6cefb",
      "name": "externallmg_r_1692874036495_1692873899376_image_5.jpg",
      "path": "cases/64e5cfe01452884516b3e845/
externallmg_r_1692874036495_1692873899376_image_5.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "64e7355c1452884516b6cefc",
      "name": "externallmg_r_1692874040171_1692873899376_image_7.jpg",
      "path": "cases/64e5cfe01452884516b3e845/
externallmg_r_1692874040171_1692873899376_image_7.jpg",
      "orientation": "portrait"
    },
  ],
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e7355c1452884516b6cefd",
  "name": "externallmg_r_1692874035668_1692873899376_image_4.jpg",
  "path": "cases/64e5cfe01452884516b3e845/
externallmg_r_1692874035668_1692873899376_image_4.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e7355c1452884516b6cefe",
  "name": "externallmg_r_1692874038148_1692873899376_image_6.jpg",
  "path": "cases/64e5cfe01452884516b3e845/
externallmg_r_1692874038148_1692873899376_image_6.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e7355c1452884516b6ceff",
  "name": "externallmg_r_1692874043992_1692873899376_image_9.jpg",
  "path": "cases/64e5cfe01452884516b3e845/
externallmg_r_1692874043992_1692873899376_image_9.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e7355c1452884516b6cf00",
  "name": "externallmg_r_1692874041862_1692873899376_image_8.jpg",
  "path": "cases/64e5cfe01452884516b3e845/
externallmg_r_1692874041862_1692873899376_image_8.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e7355c1452884516b6cf01",
  "name": "externallmg_r_1692874045453_1692873899376_image_10.jpg",
  "path": "cases/64e5cfe01452884516b3e845/
externallmg_r_1692874045453_1692873899376_image_10.jpg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e7355c1452884516b6cf02",
    "name": "externallmg_r_1692874050225_1692873899376_image_11.jpg",
    "path": "cases/64e5cfe01452884516b3e845/
externallmg_r_1692874050225_1692873899376_image_11.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e7355c1452884516b6cf03",
    "name": "externallmg_r_1692874051212_1692873899376_image_12.jpg",
    "path": "cases/64e5cfe01452884516b3e845/
externallmg_r_1692874051212_1692873899376_image_12.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e7355c1452884516b6cf04",
    "name": "externallmg_r_1692874054259_1692873899376_image_14.jpg",
    "path": "cases/64e5cfe01452884516b3e845/
externallmg_r_1692874054259_1692873899376_image_14.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e7355c1452884516b6cf05",
    "name": "externallmg_r_1692874055935_1692873899376_image_15.jpg",
    "path": "cases/64e5cfe01452884516b3e845/
externallmg_r_1692874055935_1692873899376_image_15.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e7355c1452884516b6cf06",
    "name": "externallmg_r_1692874052075_1692873899376_image_13.jpg",
    "path": "cases/64e5cfe01452884516b3e845/
externallmg_r_1692874052075_1692873899376_image_13.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "64e7355c1452884516b6cf07",
    "name": "externalimg_r_1692874057750_1692873899376_image_16.jpg",
    "path": "cases/64e5cfe01452884516b3e845/
externalimg_r_1692874057750_1692873899376_image_16.jpg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64e7355c1452884516b6cf08",
    "name": "externalimg_r_1692873999798_1692873867088_image_2.png",
    "path": "cases/64e5cfe01452884516b3e845/
externalimg_r_1692873999798_1692873867088_image_2.png",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64e7355c1452884516b6cf09",
    "name": "externalimg_r_1692873998859_1692873867088_image_1.jpg",
    "path": "cases/64e5cfe01452884516b3e845/
externalimg_r_1692873998859_1692873867088_image_1.jpg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64e7355c1452884516b6cf0a",
    "name": "externalimg_r_1692873990071_1692873867087_image_0.jpg",
    "path": "cases/64e5cfe01452884516b3e845/
externalimg_r_1692873990071_1692873867087_image_0.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "3228.xlsx",
    "filename": "1692940836999_3228.xlsx",
    "path": "cases/64e5cfe01452884516b3e845/
processingDocuments/1692940836999_3228.xlsx",
    "size": "1518707",
    "createdAt": "Fri Aug 25 2023 10:50:37 GMT+0530 (India Standard Time)",
    "uploadedBy": "627221f4afd7d55eddeddb4"
  }
]
```

```
],
"createdAt": "2023-08-23T09:22:40.853Z",
"updatedAt": "2023-08-25T08:16:10.163Z",
"__v": 0,
"updatedBy": "627222afafd7d55eddedd82",
"addressForMap": "",
"caseReferredBy": "62720e52afd7d55eddedc887",
"contactPersonName": "Mr. Tushar Y Savdavkar",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "7506345042",
"siteVisitDate": "2023-08-24"
}
```

Name	Length	Width	Total
Composition :			
Other			
Composition :			