

```
{
  "typeOfReport": {
    "value": "Residential",
    "label": "Residential"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6437bc198989760c1fb616df"
    },
    "type": "CREDITOFFICER",
    "_id": "6437bc198989760c1fb616e1",
    "firstName": "Nilesh",
    "lastName": "Sir",
    "mobileNo": "",
    "workMobileNo": "9881298896",
    "email": "bom1582@mahabank.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "6418456a96b58848585f8cb2",
"name": "Thane",
"email": "thane@vastukala.com",
"phone": "1234567890",
"address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
"city": "Thane",
"shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180e",
  "type": "BANK",
  "name": "Bank Of Maharashtra",
  "displayName": "Bank Of Maharashtra",
  "initial": "BOM",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6437bc198989760c1fb616df",
  "name": "Kasarwadavli Branch\t",
  "branchCode": "",
  "mobileNo": "02225976011\t",
  "alternateMobileNo": "",
  "email": "bom1582@mahabank.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Shop No 19.20.21, Sai Pushpa Bldg, Opp Vedant Hospital, S no 50, H
No 6 Kasarwadavali Thane west\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "63abe77f4e30460e90087d32",
  "zoneName": "Mumbai City Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "64abdb2806d6ec174986d16b",
"role": "PICKUPPERSON",
"firstName": "Sahadu",
"email": "thoratsahadu8679@gmail.com",
"lastName": "Thorat",
"mobileNo": "9422389642",
"shortName": "ST",
"workWithDocumentMaker": ""
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62ea09ea4e679b264caf07d7",
  "role": "SITEENGINEER",
  "firstName": "Suraj",
  "email": "suraj@vastukala.org",
  "lastName": "Zore",
  "mobileNo": "8652448654",
  "designation": "",
  "shortName": "SZ",
  "workWithDocumentMaker": "60092304a16fab0f2af9b0c2",
  "profilePhoto": "users/62ea09ea4e679b264caf07d7/
profilePhoto_1685629394240_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "MAKER",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
  "designation": ""
```

```
"shortName": "PS",
"workWithDocumentMaker": "",
"profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": "",
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
"value": "FIIV",
"label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
"title": {
"value": "Chartered_Engineer",
"label": "Chartered Engineer"
},
"_id": "60af80072ffdf65bcd658653",
"number": "AM161706-3"
},
}
```

```
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
},
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.267186331378966",
  "longitude": "73.08189285303777"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-08-25",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-08-25",
      "remark": ""
    }
  ]
}
```

```
],
"schedule": [],
},
"marketAnalysisAndRemark": {
"audioNotes": []
},
"externalReportDetails": {
"finalAreaType": "Built_Up",
"finalMeasurementType": "Sq. Ft.",
"underConstruction": false
},
"address": {
"state": {
"status": true,
"name": "State",
"key": "state",
"value": "Maharashtra",
"label": true
},
"country": {
"status": true,
"name": "Country",
"key": "country",
"value": "India",
"label": false
},
"village": {
"status": true,
"name": "Village",
"key": "village",
"value": "Ranjnoli",
"label": true
},
"floorNo": {
"status": true,
"name": "Floor No",
"key": "floorNo",
"value": "19",
"label": false
},
"buildingNo": {
"status": false,
"name": "Building No",
"key": "buildingNo",
"value": "",
"label": true
}
```

```
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Bhiwandi",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Aamantra Complex Phase II",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
```

```
"key": "selectArea",
"value": "",
"label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Phase II ",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
}
```



```
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "J-191",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
```

```
"value": "",
"label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "421 302",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
```

```
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
```

```
    "percentage": "0.00",
    "isHideFloor": true,
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
```

```
"title": "Showcases",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
```



```
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"_id": "64e8595e1452884516b8eedd",
"ownerName": "Mr. Rajiv Kumar Shrivastava & Mr. Avinash Shrivastava",
"ownerPhoneNo": "8591082841",
"fullAddress": " Flat No. J-191, 19th Floor, Aamantra Complex Phase II, Phase II ,
Village - Ranjnoli, Taluka - Bhiwandi, District - Thane, 421 302",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "30/12/2020",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "Eco Homes Townships LLP & Tata Housing Development Company
Limited ",
      "to": {
        "value": "Allottee",
        "label": "Allottee"
      },
      "Allottee": "Mr. Rajive Kumar Shrivastava & Mr. Avinash Srivastava"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "422035",
    "path": "cases/64e8595e1452884516b8eedd/
document_1692948787863_Document_21.pdf",
    "fileName": "document_1692948787863_Document_21.pdf"
  },
  {
    "documentType": {
      "value": "60ae1247aa6d152c1801b2ea",
      "label": "Commencement Certificate"
    },
    "inputs": {
      "documentDate": "26/06/2015",
```

```
"nameOfApprovingAuthority": {
  "value": "Mumbai_Metropolitan_Region_Development_Authority",
  "label": "Mumbai Metropolitan Region Development Authority"
},
"number": {
  "value": "No",
  "label": "No"
},
"No": "SROT / BSNA / 2501 / BP / Amended / Ranjanoli – 02 / 347 / 2015"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1693302644378_CC.pdf",
"path": "cases/64e8595e1452884516b8eedd/document_1693302644378_CC.pdf",
"id": "903282",
"uploadedBy": "627222afafd7d55eddedd82",
"createdAt": "Tue Aug 29 2023 15:22:06 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "12/03/2018",
    "nameOfApprovingAuthority": {
      "value": "Mumbai_Metropolitan_Region_Development_Authority",
      "label": "Mumbai Metropolitan Region Development Authority"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "SROT / BSNA / 2501 / Occupancy Certificate / Ranjanoli – 02 / 354 / 2018"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1693302681894_OC.pdf",
"path": "cases/64e8595e1452884516b8eedd/document_1693302681894_OC.pdf",
"id": "994891",
"uploadedBy": "627222afafd7d55eddedd82",
"createdAt": "Tue Aug 29 2023 15:22:06 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
```

```
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "15/07/2017",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "P51700000308 "
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1693302726802_P51700000308.pdf",
  "path": "cases/64e8595e1452884516b8eedd/
document_1693302726802_P51700000308.pdf",
  "id": "572145",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Tue Aug 29 2023 15:22:06 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "003375",
"createdBy": "6430f74691d7c62df11f3f15",
"caseHistory": [
  {
    "id": "666081",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Aug 25 2023 13:03:50 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Rajiv Kumar Shrivastava & Mr. Avinash Shrivastava",
    "phone": "8591082841",
    "ownershipShare": "",
    "email": "",
    "id": "445586"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
```

```
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e8badb1452884516ba2ec4",
    "name": "externalImg_r_1692973748861_1692973609300_image_2.jpg",
    "path": "cases/64e8595e1452884516b8eedd/
externalImg_r_1692973748861_1692973609300_image_2.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e8badb1452884516ba2ec5",
    "name": "externalImg_r_1692973745241_1692973609300_image_0.jpg",
    "path": "cases/64e8595e1452884516b8eedd/
externalImg_r_1692973745241_1692973609300_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e8badb1452884516ba2ec6",
    "name": "externalImg_r_1692973749755_1692973609300_image_3.jpg",
    "path": "cases/64e8595e1452884516b8eedd/
externalImg_r_1692973749755_1692973609300_image_3.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e8badb1452884516ba2ec7",
    "name": "externalImg_r_1692973747034_1692973609300_image_1.jpg",
    "path": "cases/64e8595e1452884516b8eedd/
externalImg_r_1692973747034_1692973609300_image_1.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e8badb1452884516ba2ec8",
```

```
    "name": "externallmg_r_1692973750700_1692973609300_image_4.jpg",
    "path": "cases/64e8595e1452884516b8eedd/
externallmg_r_1692973750700_1692973609300_image_4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e8badb1452884516ba2ec9",
    "name": "externallmg_r_1692973752372_1692973609300_image_6.jpg",
    "path": "cases/64e8595e1452884516b8eedd/
externallmg_r_1692973752372_1692973609300_image_6.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e8badb1452884516ba2eca",
    "name": "externallmg_r_1692973751541_1692973609300_image_5.jpg",
    "path": "cases/64e8595e1452884516b8eedd/
externallmg_r_1692973751541_1692973609300_image_5.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e8badb1452884516ba2ecb",
    "name": "externallmg_r_1692973754377_1692973609300_image_7.jpg",
    "path": "cases/64e8595e1452884516b8eedd/
externallmg_r_1692973754377_1692973609300_image_7.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e8badb1452884516ba2ecc",
    "name": "externallmg_r_1692973756592_1692973609300_image_8.jpg",
    "path": "cases/64e8595e1452884516b8eedd/
externallmg_r_1692973756592_1692973609300_image_8.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e8badb1452884516ba2ecd",
    "name": "externallmg_r_1692973760453_1692973609300_image_10.jpg",
```

```
    "path": "cases/64e8595e1452884516b8eedd/
externallmg_r_1692973760453_1692973609300_image_10.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e8badb1452884516ba2ece",
    "name": "externallmg_r_1692973758086_1692973609300_image_9.jpg",
    "path": "cases/64e8595e1452884516b8eedd/
externallmg_r_1692973758086_1692973609300_image_9.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e8badb1452884516ba2ecf",
    "name": "externallmg_r_1692973762216_1692973609300_image_11.jpg",
    "path": "cases/64e8595e1452884516b8eedd/
externallmg_r_1692973762216_1692973609300_image_11.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e8badb1452884516ba2ed0",
    "name": "externallmg_r_1692973766808_1692973609300_image_13.jpg",
    "path": "cases/64e8595e1452884516b8eedd/
externallmg_r_1692973766808_1692973609300_image_13.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e8badb1452884516ba2ed1",
    "name": "externallmg_r_1692973768754_1692973609300_image_14.jpg",
    "path": "cases/64e8595e1452884516b8eedd/
externallmg_r_1692973768754_1692973609300_image_14.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e8badb1452884516ba2ed2",
    "name": "externallmg_r_1692973765181_1692973609300_image_12.jpg",
    "path": "cases/64e8595e1452884516b8eedd/
externallmg_r_1692973765181_1692973609300_image_12.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e8badb1452884516ba2ed3",
  "name": "externallmg_r_1692973770400_1692973609300_image_15.jpg",
  "path": "cases/64e8595e1452884516b8eedd/
externallmg_r_1692973770400_1692973609300_image_15.jpg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "64e8badb1452884516ba2ed4",
  "name": "externallmg_r_1692973708763_1692973583969_image_2.png",
  "path": "cases/64e8595e1452884516b8eedd/
externallmg_r_1692973708763_1692973583969_image_2.png",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "64e8bb311452884516ba2ef9",
  "name": "externallmg_r_1692973865004_1692973739261_image_0.jpg",
  "path": "cases/64e8595e1452884516b8eedd/
externallmg_r_1692973865004_1692973739261_image_0.jpg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "64e8bb311452884516ba2efa",
  "name": "externallmg_r_1692973865269_1692973739261_image_1.jpg",
  "path": "cases/64e8595e1452884516b8eedd/
externallmg_r_1692973865269_1692973739261_image_1.jpg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "64e8bb311452884516ba2efb",
  "name": "externallmg_r_1692973866476_1692973742640_image_0.jpg",
  "path": "cases/64e8595e1452884516b8eedd/
externallmg_r_1692973866476_1692973742640_image_0.jpg",
  "orientation": "portrait"
}
```

```

    }
  ],
  "externalDocuments": [],
  "processingDocuments": [
    {
      "originalname": "Calculation.xlsx",
      "filename": "1693035670824_Calculation.xlsx",
      "path": "cases/64e8595e1452884516b8eedd/
processingDocuments/1693035670824_Calculation.xlsx",
      "size": "1487422",
      "createdAt": "Sat Aug 26 2023 13:11:10 GMT+0530 (India Standard Time)",
      "uploadedBy": "60f915d3f3dd69653a592199"
    }
  ],
  "createdAt": "2023-08-25T07:33:50.347Z",
  "updatedAt": "2023-08-29T09:52:06.997Z",
  "__v": 0,
  "invoiceId": "64e8595e1452884516b8eef1",
  "updatedBy": "627222afafd7d55eddedd82",
  "addressForMap": "",
  "caseReferredBy": "64abdb2806d6ec174986d16b",
  "contactPersonName": "Mr. Rajiv Kumar Shrivastava & Mr. Avinash Shrivastava",
  "email": "",
  "isExternal": "false",
  "isUrgent": "false",
  "ownershipShare": "",
  "purchaseValueAsPerDocument": "",
  "relationWithOwner": "self",
  "siteVisitContactNo": "8591082841",
  "remarks": []
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			