

```
{
  "typeOfReport": {
    "value": "Residential_Bungalow_",
    "label": "Residential Bungalow "
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002",
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002"
  },
  "masterTypeOfPurpose": {
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002",
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6503f61fa8e9b70221e57e31"
    },
    "type": "CREDITOFFICER",
    "_id": "6503f61fa8e9b70221e57e33",
    "firstName": "Rahul waghmare",
    "lastName": "Sir",
    "mobileNo": "9850860792",
    "workMobileNo": "9850860792",
    "email": "ubin0559695@unionbankofindia.bank"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": ""
  }
}
```

```
"expectedFees": null,
"quotedAmount": "3540"
},
"organization": {
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Mashusha Elite, Vrundavan Naka Link Road, Adgaon, ",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6503f61fa8e9b70221e57e31",
  "name": "Panchavati Branch, Nashik",
  "branchCode": "559695",
  "mobileNo": "2532629306",
  "alternateMobileNo": "8104604059",
  "email": "ubin0559695@unionbankofindia.bank",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "SHOP NO 1,2 3 RUPASHRI APPARTMENT OPP TAXI STAND DINDORI
RD PANCHVATI,NASIK,422003"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "63fda9ecce84bf289baadd43",
  "zoneName": "Nashik Zone"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "63f9ed37ce84bf289ba991ac",
  "role": "FRONTDESK",
  "firstName": "Rushikesh",
  "email": "rushingle2201@gmail.com",
  "lastName": "Pingle",
  "mobileNo": "8788210361",
  "shortName": "RUP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "63f9f4adce84bf289ba9956e",
  "role": "FRONTDESK + ENGINEER",
  "firstName": "Swapnil",
  "email": "waghswapnil309@gmail.com",
  "lastName": "Wagh",
  "mobileNo": "8237116625",
  "designation": "",
  "shortName": "SW",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/63f9f4adce84bf289ba9956e/
profilePhoto_1688707461551_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "636a1ad14d42487767af3f91",
  "role": "MAKER + RATE VERFIER",
  "firstName": "Chintamani",
  "email": "chintamanichaudhari099@gmail.com",
  "lastName": "Chaudhari",
  "mobileNo": "8007230780",
  "designation": "",
  "shortName": "Chintamani",
  "workWithDocumentMaker": "62724142afd7d55eddede405",
  "profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "636a1ad14d42487767af3f91",
  "role": "MAKER + RATE VERFIER",
  "firstName": "Chintamani",
```

```
"email": "chintamanichaudhari099@gmail.com",
"lastName": "Chaudhari",
"mobileNo": "8007230780",
"designation": "",
"shortName": "Chintamani",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f9147bf3dd69653a591e8c",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Vinita",
  "email": "vinita.surve@vastukala.org",
  "lastName": "Surve",
  "mobileNo": "9820652818",
  "designation": "",
  "shortName": "V",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
},
"valuers": []
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "20.051869473347754",
  "longitude": "73.80889530960297"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
```

```
"audioNotes": [],
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Mhasrul",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Upper Ground",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
```

```
"key": "district",
"value": "Nashik",
"label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "177 + 178",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
}
```

```
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Warvandi Link Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Behind Dalvi Farm ",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
```

```
"value": "4,5,7 to 10,281 & 282 ",
"label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
```



```
"status": false,
"name": "Mouza",
"key": "mouza",
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422004",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
```

```
"isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
}
```

```
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
{others": {
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
totalValues": {
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
taskStatus": {
"SITE_INSPECTION": false,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
createCase": "false",
type": "CASE",
leadType": {
"label": "Lead",
"value": "LEAD"
},
siteVisitType": "FULL",
isSiteMeasurementAllowed": true,
finalValuationArea": "0",
empanelmentNo": [],
isAdvanceInvoice": false,
```

```
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"_id": "6503f88ea8e9b70221e584e3",
"ownerName": "Nita Sangle",
"ownerPhoneNo": "8208723278",
"fullAddress": " Residential Bungalow No. Upper Ground Floor, Behind Dalvi Farm ,
Plot No. 177 + 178, New/Current Survey No. 4,5,7 to 10,281 & 282 , Warvandi Link
Road, Village - Mhasrul, Taluka - Nashik, District - Nashik, Nashik, 422004",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName":
"document_1694758681541_20230905_GroundFloorPlan__Mita_Rajesh_Sangle.pdf",
    "path": "cases/6503f88ea8e9b70221e584e3/
document_1694758681541_20230905_GroundFloorPlan__Mita_Rajesh_Sangle.pdf",
    "id": "565096",
    "uploadedBy": "63f9ed37ce84bf289ba991ac",
    "createdAt": "Fri Sep 15 2023 11:53:40 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae1249aa6d152c1801b2f5",
      "label": "Quantity Estimate"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1694758694257_Estimate.pdf",
    "path": "cases/6503f88ea8e9b70221e584e3/
document_1694758694257_Estimate.pdf",
    "id": "388662",
    "uploadedBy": "63f9ed37ce84bf289ba991ac",
    "createdAt": "Fri Sep 15 2023 11:53:40 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
    "displayStatus": false,
```



```
    "fileName": "document_1694758701977_Rajesh_Patil_Agreement.pdf",
    "path": "cases/6503f88ea8e9b70221e584e3/
document_1694758701977_Rajesh_Patil_Agreement.pdf",
    "id": "661331",
    "uploadedBy": "63f9ed37ce84bf289ba991ac",
    "createdAt": "Fri Sep 15 2023 11:53:40 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1694758710172_Rajesh_Patil_Layout_02.pdf",
    "path": "cases/6503f88ea8e9b70221e584e3/
document_1694758710172_Rajesh_Patil_Layout_02.pdf",
    "id": "573827",
    "uploadedBy": "63f9ed37ce84bf289ba991ac",
    "createdAt": "Fri Sep 15 2023 11:53:40 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1694758721880_Rajesh_Patil_Layout_03_B.pdf",
    "path": "cases/6503f88ea8e9b70221e584e3/
document_1694758721880_Rajesh_Patil_Layout_03_B.pdf",
    "id": "929195",
    "uploadedBy": "63f9ed37ce84bf289ba991ac",
    "createdAt": "Fri Sep 15 2023 11:53:40 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1694758736462_Rajesh_Patil_Layout_03.pdf",
    "path": "cases/6503f88ea8e9b70221e584e3/
document_1694758736462_Rajesh_Patil_Layout_03.pdf",
    "id": "405064",
```

```
"uploadedBy": "63f9ed37ce84bf289ba991ac",
"createdAt": "Fri Sep 15 2023 11:53:40 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1694758837484_Rajesh_Patil_Plot_Layout.pdf",
  "path": "cases/6503f88ea8e9b70221e584e3/
document_1694758837484_Rajesh_Patil_Plot_Layout.pdf",
  "id": "444310",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Fri Sep 15 2023 11:53:40 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "003824",
"createdBy": "63f9ed37ce84bf289ba991ac",
"caseHistory": [
  {
    "id": "345575",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Sep 15 2023 11:54:14 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Nita Sangle",
    "phone": "8208723278",
    "ownershipShare": "",
    "email": "",
    "id": "813311"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externallImages": [
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6503fa13a8e9b70221e58b01",
  "name":
"externallmg_1694759441937_WhatsApp_Image_20230907_at_44810_PM.jpeg",
  "path": "cases/6503f88ea8e9b70221e584e3/
externallmg_1694759441937_WhatsApp_Image_20230907_at_44810_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6503fa13a8e9b70221e58b02",
  "name":
"externallmg_1694759441996_WhatsApp_Image_20230907_at_44811_PM.jpeg",
  "path": "cases/6503f88ea8e9b70221e584e3/
externallmg_1694759441996_WhatsApp_Image_20230907_at_44811_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6503fa13a8e9b70221e58b03",
  "name":
"externallmg_1694759442045_WhatsApp_Image_20230907_at_44812_PM_1.jpeg",
  "path": "cases/6503f88ea8e9b70221e584e3/
externallmg_1694759442045_WhatsApp_Image_20230907_at_44812_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6503fa13a8e9b70221e58b04",
  "name":
"externallmg_1694759442121_WhatsApp_Image_20230907_at_44812_PM.jpeg",
  "path": "cases/6503f88ea8e9b70221e584e3/
externallmg_1694759442121_WhatsApp_Image_20230907_at_44812_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6503fa13a8e9b70221e58b05",
  "name":
"externallmg_1694759442170_WhatsApp_Image_20230907_at_44813_PM_1.jpeg",
```

```
    "path": "cases/6503f88ea8e9b70221e584e3/
externallmg_1694759442170_WhatsApp_Image_20230907_at_44813_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6503fa13a8e9b70221e58b06",
    "name":
"externallmg_1694759442262_WhatsApp_Image_20230907_at_44813_PM_2.jpeg",
    "path": "cases/6503f88ea8e9b70221e584e3/
externallmg_1694759442262_WhatsApp_Image_20230907_at_44813_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6503fa13a8e9b70221e58b07",
    "name":
"externallmg_1694759442412_WhatsApp_Image_20230907_at_44813_PM.jpeg",
    "path": "cases/6503f88ea8e9b70221e584e3/
externallmg_1694759442412_WhatsApp_Image_20230907_at_44813_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6503fa13a8e9b70221e58b08",
    "name":
"externallmg_1694759442481_WhatsApp_Image_20230907_at_44814_PM.jpeg",
    "path": "cases/6503f88ea8e9b70221e584e3/
externallmg_1694759442481_WhatsApp_Image_20230907_at_44814_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6503fa13a8e9b70221e58b09",
    "name":
"externallmg_1694759442571_WhatsApp_Image_20230915_at_95654_AM_1.jpeg",
    "path": "cases/6503f88ea8e9b70221e584e3/
externallmg_1694759442571_WhatsApp_Image_20230915_at_95654_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```

    "status": false,
    "_id": "6503fa13a8e9b70221e58b0a",
    "name":
"externalImg_1694759442980_WhatsApp_Image_20230915_at_95654_AM.jpeg",
    "path": "cases/6503f88ea8e9b70221e584e3/
externalImg_1694759442980_WhatsApp_Image_20230915_at_95654_AM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-09-15T06:24:15.032Z",
"updatedAt": "2023-09-15T06:30:43.135Z",
"__v": 0,
"invoiceId": "6503f891a8e9b70221e58509",
"updatedBy": "63f9ed37ce84bf289ba991ac",
"addressForMap": "",
"caseReferredBy": "63f9f4adce84bf289ba9956e",
"contactPersonName": "Nita Sangle",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "8208723278"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			