

PROFORMA INVOICE

Vastukala Consultants (I) Pvt Ltd B1-001,U/B FLOOR, BOOMERANG,CHANDIVALI FARM ROAD, ANDHERI-EAST 400072 GSTIN/UIN: 27AADCV4303R1ZX State Name : Maharashtra, Code : 27 E-Mail : accounts@vastukala.org	Invoice No.	Dated
	PG-2681/23-24	29-Sep-23
	Delivery Note	Mode/Terms of Payment
	Reference No. & Date.	Other References
Buyer (Bill to) STATE BANK OF INDIA- RASMECCC Panvel RASMECCC Panvel Sharda Terrace,Shop No 5,Ground Floor, Plot No 65,Sector-11,CBD Belapur GSTIN/UIN : 27AAACS8577K2ZO State Name : Maharashtra, Code : 27	Buyer's Order No.	Dated
	Dispatch Doc No.	Delivery Note Date
	4096 /2302765	
	Dispatched through	Destination
	Terms of Delivery	

SI No.	Particulars	HSN/SAC	GST Rate	Amount
1	STRUCTURAL REPORT FEE <i>(Technical Inspection and Certification Services)</i>	997224	18 %	2,500.00
	CGST			225.00
	SGST			225.00
Total				₹ 2,950.00

Amount Chargeable (in words) E & O.E

Indian Rupee Two Thousand Nine Hundred Fifty Only

HSN/SAC	Taxable Value	Central Tax		State Tax		Total Tax Amount
		Rate	Amount	Rate	Amount	
997224	2,500.00	9%	225.00	9%	225.00	450.00
Total			225.00		225.00	450.00

Tax Amount (in words) **Indian Rupee Four Hundred Fifty Only**

Company's Bank Details
 Bank Name **State Bank of India**
 A/c No. : **32632562114**
 Branch & IFS Code: **MIDC Andheri (E) & SBIN0007074**

Remarks:
 Mr. Dilip Ramchandra Pawar - of Residential Flat No.
 201, 2nd Floor, Building No. C/5, "Greenland", Yogi
 Dham, Behind Anupam Gholap Nagar, Kalyan Murbad
 Road, Village - Gaunipada, Taluka - Kalyan, District -
 Thane, Kalyan (West), PIN - 421 306, State -
 Maharashtra, India



Company's PAN **AADCV4303R**

UPI Virtual ID : vastukala@icici

Declaration
 NOTE - AS PER MSME RULES INVOICE NEED TO BE
 CLEARED WITHIN 45 DAYS OR INTEREST CHARGES
 APPLICABLE AS PER THE RULE
 MSME Registration No. - 27222201137

for Vastukala Consultants (I) Pvt Ltd

Authorised Signatory

This is a Computer Generated Invoice



Vastukala Consultants (I) Pvt. Ltd.

An ISO 9001:2015 Certified Company www.vastukala.org





Structural Stability Report

Structural Observation Report of Residential Flat No. 201, 2nd Floor, Building No. C/5, "Greenland", Yogi Dham, Behind Anupam Gholap Nagar, Kalyan Murbad Road, Village - Gauripada, Taluka - Kalyan, District - Thane, Kalyan (West), PIN - 421 306, State - Maharashtra, India.

Name of Owner: **Mr. Dilip Ramchandra Pawar.**

This is to certify that on visual inspection, it appears that the structure of the Building No. C/5 at "Greenland", Yogi Dham, is in normal condition and the future life can be reasonably takes under good condition and with proper periodic repairs & maintenance is about 37 years.

General Information:

A.	Introduction	
1	Name of Building	"Greenland", Yogi Dham
2	Property Address	Residential Flat No. 201, 2 nd Floor, Building No. C/5, "Greenland", Yogi Dham, Behind Anupam Gholap Nagar, Kalyan Murbad Road, Village - Gauripada, Taluka - Kalyan, District - Thane, Kalyan (West), PIN - 421 306, State - Maharashtra, India.
3	Type of Building	Residential used
4	No. of Floors	Ground + 7 Upper Floor
5	Whether still / podium / open parking provided	Open Car Parking
6	Type of Construction	R.C.C. Framed Structure
7	Type of Foundation	R.C.C. Footing
8	Thickness of the External Walls	9" thick brick walls both sides plastered
9	Type of Compound	Brick Masonry Walls
10	Year of Construction	2000 (As per Building Completion Certificate)
11	Present age of building	23 years
12	Residual age of the building	37 years Subject to proper, preventive periodic maintenance & structural repairs.
13	No. of flats (Per Floor)	6 Flats on 2 nd Floor
14	Methodology adopted	As per visual site inspection



Our Pan India Presence at :

Mumbai Aurangabad Pune Rajkot
Thane Nanded Indore Raipur
Delhi NCR Nashik Ahmedabad Jaipur

Regd. Office : B1-001, U/B Floor, Boomerang,
Chandivali Farm Road, Andheri (East),
Mumbai - 400 072, (M.S.), INDIA
TeleFax : +91 22 28371325/24
mumbai@vastukala.org

B. External Observation of the Building		
1	Plaster	Good Condition
2	Chajjas	Good Condition
3	Plumbing	Gppd Condition
4	Cracks on the external walls	Not found
5	Filling cracks on the external walls	Found
6	Cracks on columns & beams	Not found
7	Vegetation	Not found
8	Leakages of water in the drainage pipes or water pipes	Not found
9	Dampness external in the wall due to leakages	Found
10	Any other observation about the condition of external side of the building	The external condition of the building is in normal condition
C Internal Observation of the common areas of the building and captioned premises		
1	Beams (Cracks & Leakages)	Good Condition
2	Columns (Cracks & Leakages)	Good Condition
3	Ceiling (Cracks & Leakages)	Good Condition
4	Leakages inside the property	Not found
5	Painting inside the property	Good
6	Maintenance of staircase & cracks	Normal

D Common Observation		
1	Structural Audit of the Building Under Bye – Laws No. 77 of the Model Bye Laws (Co-Operative Societies Act / Rules)	As per bye Laws No. 77 of Co-Op. Societies bye Laws under the Act the society shall conduct a Structural Audit of the building of the society as follows
2	Remark	No Structural Audit Report is furnished for the perusal

E Conclusion	
<p>The captioned building is having Ground + 7 Upper Floors which are constructed in year 2000 as per Building Completion Certificate. Estimated future life under present circumstances is about 37 years subject to proper, preventive periodic maintenance & structural repairs.</p> <p>The inspection dated 25.09.2023 reveals no structural damage or deterioration to the building. The building as well as the property is maintained in normal condition & will stand future life subject to proper, preventive periodic maintenance & Good structural repairs.</p> <p>Our Observations about the structure are given above.</p> <p>The above assessment is based on visual inspection only.</p>	

For VASTUKALA CONSULTANTS (I) PVT. LTD.

Sharadkumar
B. Chalikwar

Digitally signed by Sharadkumar B. Chalikwar
DN: cn=Sharadkumar B. Chalikwar,
o=Vastukala Consultants (I) Pvt. Ltd.,
ou=CMD, email=cmd@vastukala.org, c=IN
Date: 2023.09.29 13:11:42 +05'30'

Auth. Sign.

Director

Sharadkumar B. Chalikwar

Govt. Reg. Valuer

Chartered Engineer (India)

Reg. No. (N) CCIT/1-14/52/2008-09

SBI Empanelment No.: SME/TCC/2021-22/85/13



Vastukala Consultants (I) Pvt. Ltd.

An ISO 9001:2015 Certified Company

www.vastukala.org



Actual Site Photographs

