### PROFORMA INVOICE

Invoice No. Dated Vastukala Consultants (I) Pvt Ltd B1-001,U/B FLOOR, 5-Oct-23 PG-2766/23-24 BOOMERANG, CHANDIVALI FARM ROAD. **Delivery Note** Mode/Terms of Payment ANDHERI-EAST 400072 AGAINST REPORT GSTIN/UIN: 27AADCV4303R1ZX Reference No. & Date. Other References State Name: Maharashtra, Code: 27 E-Mail: accounts@vastukala.org Buyer's Order No. Dated Buyer (Bill to) STATE BANK OF INDIA Dispatch Doc No. Delivery Note Date RACPC SION BRANCH B-603 & 604, Kohinoor City, Commercial-1 6th Floor, Kirol 004182/2302852 Road, Off L.B.S. Marg, Kurla (West), Mumbai - 400070 Dispatched through Destination State - Maharashtra, Country - India GSTIN/UIN : 27AAACS8577K2ZO Terms of Delivery State Name : Maharashtra, Code : 27

SI No.	Particulars		HSN/SAC	GST Rate	Amount
1	STRUCTURAL REPORT FEE (Technical Inspection and Certification Services)		997224	18 %	2,500.00
		CGST			225.00
		SGST			225.00
	3.0				
	. 1)		į.		
	3		//		
		Total	/		2,950.00

Amount Chargeable (in words)

E. & O.E

## Indian Rupee Two Thousand Nine Hundred Fifty Only

HSN/SAC	Taxable	Central Tax		State Tax		Total
	Value	Rate	Amount	Rate	Amount	Tax Amount
997224	2,500.00	9%	225.00	9%	225.00	450.00
Total	2,500.00		225.00		225.00	450.00

Tax Amount (in words): Indian Rupee Four Hundred Fifty Only

Company's Bank Details

Bank Name : State Bank of India

A/c No. : 32632562114

Branch & IFS Code: MIDC Andheri (E) & SBIN0007074

Remarks:

Mrs. Meenakshi Dabaria & Mr. Birbal Dabaria. -Residential Flat No. 1001, 10th Floor, "Jimmy Tower III", Crystal Co-Op. Hsg. Soc. Ltd., Plot No. 21, Sector – 17, Village – Koparkhairane, Navi Mumbai, Taluka & District – Thane, PIN Code - 400 709, State –

Maharashtra, Country - India

Company's PAN : AADCV4303R

Declaration

NOTE – AS PER MSME RULES INVOICE NEED TO BE CLEARED WITHIN 45 DAYS OR INTEREST CHARGES APPLICABLE AS PER THE RULE. MSME Registration No. - 27222201137 ■ Head of the second of the s

vasiukala@icici

for Vastukala Consultants (I) Pvt Ltd

Consultants (II) Pvt Ltd

Consultants (II) Pvt Ltd

Consultants (III) Pvt Ltd

Consultants

**Authorised Signatory** 

This is a Computer Generated Invoice





CIN: U74120MH2010PTC207869 MSME Reg. No.: UDYAM-MH-18-0083617 An ISO 9001:2015 Certified Company





Structural Stability Report Prepared For: SBI/ RACPC Sion / Mrs. Meenakshi Dabaria (004182/2302852)

Page 1 of 3

Vastu/Mumbai/2023/10/004182/2302852

05/07-49-NI

Date: 05.10.2023

## Structural Stability Report

Structural Observation Report of Residential Flat No. 1001, 10th Floor, "Jimmy Tower III", Crystal Co-Op. Hsg. Soc. Ltd., Plot No. 21, Sector – 17, Village – Koparkhairane, Navi Mumbai, Taluka & District – Thane, PIN Code - 400 709, State – Maharashtra, Country – India.

Name of Owner: Mrs. Meenakshi Dabaria & Mr. Birbal Dabaria.

This is to certify that on visual inspection, it appears that the structure of the building " Jimmy Tower III" is in normal condition and the future life can be reasonably takes under normal working condition and with proper periodic repairs & maintenance is about 34 years.

## **General Information:**

A.	1	Introduction
1	Name of Building	"Jimmy Tower III", Crystal Co-Op. Hsg. Soc. Ltd.
2	Property Address	Residential Flat No. 1001, 10th Floor, "Jimmy Tower III",
	7)	Crystal Co-Op. Hsg. Soc. Ltd., Plot No. 21, Sector - 17,
		Village – Koparkhairane, Navi Mumbai, Taluka & District –
	Δ.	Thane, PIN Code - 400 709, State – Maharashtra, Country – India
3	Type of Building	Residential use
4	No. of Floors	Ground + 13 Upper Floors
5	Whether stilt / podium / open parking	Covered Parking Space
	provided	N
6	Type of Construction	R.C.C. Framed Structure
7	Type of Foundation	R.C.C. Footing
8	Thickness of the External Walls	9" thick brick walls both side plastered
9	Type of Compound	Brick Masonry Walls
10	Year of Construction	1997 (As per Occupancy Certificate)
11	Present age of building	26 Years
12	Residual age of the building	34 years Subject to proper, preventive periodic
		maintenance & structural repairs.
13	No. of flats (Per Floor)	2 Flats
_14	Methodology adopted	As per visual site inspection







B.	External Observation of the Building	
1	Plaster	Normal Condition
2	Chajjas	Normal Condition
3	Plumbing	Normal Condition
4	Cracks on the external walls	Not:Found
5	Filling cracks on the external walls	Not Found
6	Cracks on columns & beams	Not Found
7	Vegetation	Not Found
8	Leakages of water in the drainage pipes or water pipes	Not Found
9	Dampness external in the wall due to leakages	Not Found
10	Any other observation about the condition of external side of the building	The external condition is Normal
С	Internal Observation of the common areas of the building and captioned premises	
1	Beams (Cracks & Leakages)	Good Condition
2	Columns (Cracks & Leakages)	Good Condition
3	Ceiling (Cracks & Leakages)	Good Condition
4	Leakages inside the property	Not Found
5	Painting inside the property	Good
6	Maintenance of staircase & cracks	Normal

D	Common Observation	
1	Structural Audit of the Building Under Bye	As per Bye Laws No. 77 of Co-Op. Societies Bye Laws
	- Laws No. 77 of the Model Bye Laws	under the Act the society shall conduct a Structural Audit
	(Co-Operative Societies Act / Rules)	of the building of the society as follows
2	Remark	No Structural Audit Report is furnished for the perusal

#### E Conclusion

The captioned building is having Ground + 13 Upper Floors which is constructed in year 1997 (as per Occupancy Certificate). Estimated future life under present circumstances is about 34 years subject to proper, preventive periodic maintenance & structural repairs.

The inspection dated 28.08.2023 reveals no structural damage or deterioration to the building. The building as well as the property is maintained Normal & will stand future life subject to proper, preventive periodic maintenance & structural repairs.

Our Observations about the structure are given above.

The above assessment is based on visual inspection only.

## For VASTUKALA CONSULTANTS (I) PVT. LTD.

Sharadkumar Digitally signed by Siraradkumar B. B. Chalikwar

DN: cn=Sharadkumar B. Chalikwar, o=Vastukała Consultants (I) Pvt. Ltd., ou=CMD, email=cmd@vastukala.org, c Date: 2023.10.05 15:11:22 +05'30'

Director

Auth. Sign.

### Sharadkumar B. Chalikwar

Govt. Reg. Valuer Chartered Engineer (India) Reg. No. (N) CCIT/1-14/52/2008-09

SBI Empanelment No.: SME / TCC / 2016-17 / 156 / Sr. No. - 193





# **Actual Site Photographs**















eate

