

```
{
  "typeOfReport": {
    "value": "APF",
    "label": "APF"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002",
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002"
  },
  "masterTypeOfPurpose": {
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002",
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64a7c4a794dfc26ccf86dc5a"
    },
    "type": "CREDITOFFICER",
    "_id": "64a7c4a794dfc26ccf86dc5d",
    "firstName": "Umesh Devchand ",
    "lastName": "Pagar",
    "mobileNo": "",
    "workMobileNo": "7020235315",
    "email": "umesh.pagar1@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": ""
  }
}
```

```
"expectedFees": null,
"quotedAmount": "5900"
},
"organization": {
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Mashusha Elite, Vrundavan Naka Link Road, Adgaon, ",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "64a7c4a794dfc26ccf86dc5a",
  "name": "Administrative Office Nashik\t",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "Nashik@sbi.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "1st Floor, BSNL CTTC, Building no 45-47, D Road MIDC, Satpur
Nashik-422007"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential_cum_commercial",
  "label": "Residential cum Commercial"
},
"zone": {
  "_id": "63fdaf22ce84bf289baae42d",
  "zoneName": "Nashik Zone"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "63f9ed37ce84bf289ba991ac",
  "role": "FRONTDESK",
  "firstName": "Rushikesh",
  "email": "rushingle2201@gmail.com",
  "lastName": "Pingle",
  "mobileNo": "8788210361",
  "shortName": "RUP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "63f9f4adce84bf289ba9956e",
  "role": "FRONTDESK + ENGINEER",
  "firstName": "Swapnil",
  "email": "waghswapnil309@gmail.com",
  "lastName": "Wagh",
  "mobileNo": "8237116625",
  "designation": "",
  "shortName": "SW",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/63f9f4adce84bf289ba9956e/
profilePhoto_1688707461551_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "62724142afd7d55eddede405",
  "role": "FRONTDESK",
  "firstName": "Sanjay",
  "email": "sanjayrphadol@gmail.com",
  "lastName": "Phadol",
  "mobileNo": "9890380564",
  "designation": "",
  "shortName": "SP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62724142afd7d55eddede405/
profilePhoto_1689235732454_image.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f9147bf3dd69653a591e8c",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Vinita",
```

```
    "email": "vinita.surve@vastukala.org",
    "lastName": "Surve",
    "mobileNo": "9820652818",
    "designation": "",
    "shortName": "V",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
  },
  "checker": "",
  "valuers": []
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.98396062656088",
  "longitude": "73.78231736292057"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
```

```
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Nashik",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Basement",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Nashik",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
```

```
"name": "Tahasil",
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "27+28/A B/1",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shreeji The Crown",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
}
```

```
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "804/B A/5 4/4 803/27 28",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
```

```
"key": "CTSNo",
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
```



```
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422009",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  }
}
```

```
    },
    "locationMapImg": [],
  },
  "outward": {
    "status": false,
    "remark": "SYSTEM_GENERATED"
  },
  "rateVerify": {
    "status": false
  },
  "underConstruction": {
    "rccFootingFoundation": {
      "label": "RCC Footing/Foundation",
      "floorsCompleted": "",
      "percentage": "0.00",
      "isHideFloor": false,
      "status": true
    },
    "rccPlinth": {
      "label": "RCC Plinth",
      "floorsCompleted": "",
      "percentage": "0.00",
      "isHideFloor": false,
      "status": false
    },
    "fullBuildingRcc": {
      "label": "Full Building Rcc",
      "floorsCompleted": "",
      "percentage": "0.00",
      "isHideFloor": false,
      "status": false
    },
    "internalBrickWork": {
      "label": "Internal Brick Work",
      "floorsCompleted": "",
      "percentage": "0.00",
      "isHideFloor": false,
      "status": false
    },
    "externalBrickWork": {
      "label": "External Brick Work",
      "floorsCompleted": "",
      "percentage": "0.00",
      "isHideFloor": false,
      "status": false
    }
  },
}
```

```
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
```

```
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentId": [],
"_id": "6521355a119cca234ddd5f2c",
"ownerName": "Shreeji The Crown",
"ownerPhoneNo": "0253247173",
"fullAddress": " APF No. Basement Floor, Shreeji The Crown, Plot No. 27+28/A B/1,
New/Current Survey No. 804/B A/5 4/4 803/27 28, Village - Nashik, Taluka - Nashik,
```

```
District - Nashik, Nashik, 422009",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1696674092114_1_Architects_Certificate_of_Percentage_of
_Completion_of_Work_Form_1.pdf",
    "path": "cases/6521355a119cca234ddd5f2c/document_1696674092114_1_Architect
s_Certificate_of_Percentage_of_Completion_of_Work_Form_1.pdf",
    "id": "263241",
    "uploadedBy": "63f9ed37ce84bf289ba991ac",
    "createdAt": "Sat Oct 07 2023 16:08:39 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae1247aa6d152c1801b2e8",
      "label": "Layout Plan"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1696674101512_1_Building_Plan_Approval__NA_Order_f
or_plotted_development.pdf",
    "path": "cases/6521355a119cca234ddd5f2c/document_1696674101512_1_Building
_Plan_Approval__NA_Order_for_plotted_development.pdf",
    "id": "701551",
    "uploadedBy": "63f9ed37ce84bf289ba991ac",
    "createdAt": "Sat Oct 07 2023 16:08:39 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae1247aa6d152c1801b2ea",
      "label": "Commencement Certificate"
    },
    "inputs": {
      "documentDate": "31/03/2022",
      "nameOfApprovingAuthority": {
        "value": "Nashik_Municipal_Corporation",
        "label": "Nashik Municipal Corporation"
      },
    },
    "number": {
      "value": "Document_No",

```



```
    "label": "Document No"
  },
  "Document_No": "LND/BP/B2/634/2022"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1696674264754_1_Commencement_Certificates___NA_Order_for_plotted_development.pdf",
"path": "cases/6521355a119cca234ddd5f2c/document_1696674264754_1_Commencement_Certificates___NA_Order_for_plotted_development.pdf",
"id": "498786",
"uploadedBy": "63f9ed37ce84bf289ba991ac",
"createdAt": "Sat Oct 07 2023 16:08:39 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "inputs": {
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": ""
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1696674273642_1_Declaration_about_Commencement_Certificate.pdf",
  "path": "cases/6521355a119cca234ddd5f2c/document_1696674273642_1_Declaration_about_Commencement_Certificate.pdf",
  "id": "532466",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Sat Oct 07 2023 16:08:39 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1696674574362_1_Declaration_in_FORM_B.pdf",
  "path": "cases/6521355a119cca234ddd5f2c/document_1696674574362_1_Declaration_in_FORM_B.pdf",
```

```
"id": "605041",
"uploadedBy": "63f9ed37ce84bf289ba991ac",
"createdAt": "Sat Oct 07 2023 16:08:39 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1696674614341_1.pdf",
  "path": "cases/6521355a119cca234ddd5f2c/document_1696674614341_1.pdf",
  "id": "596389",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Sat Oct 07 2023 16:08:39 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1696674624261_2_Architects_Certificate_of_Percentage_of
_Completion_of_Work_Form_1.pdf",
  "path": "cases/6521355a119cca234ddd5f2c/document_1696674624261_2_Architect
s_Certificate_of_Percentage_of_Completion_of_Work_Form_1.pdf",
  "id": "643622",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Sat Oct 07 2023 16:08:39 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1696674635517_2_Building_Plan_Approval___NA_Order_f
or_plotted_development.pdf",
  "path": "cases/6521355a119cca234ddd5f2c/document_1696674635517_2_Building
_Plan_Approval___NA_Order_for_plotted_development.pdf",
  "id": "731396",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Sat Oct 07 2023 16:08:39 GMT+0530 (India Standard Time)"
}
```

```
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1696674643655_2_Commencement_Certificates___NA_Order_for_plotted_development.pdf",
  "path": "cases/6521355a119cca234ddd5f2c/document_1696674643655_2_Commencement_Certificates___NA_Order_for_plotted_development.pdf",
  "id": "838444",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Sat Oct 07 2023 16:08:39 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1696674652213_2_Declaration_about_Commencement_Certificate.pdf",
  "path": "cases/6521355a119cca234ddd5f2c/document_1696674652213_2_Declaration_about_Commencement_Certificate.pdf",
  "id": "426858",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Sat Oct 07 2023 16:08:39 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1696674661755_3_Building_Plan_Approval___NA_Order_for_plotted_development.pdf",
  "path": "cases/6521355a119cca234ddd5f2c/document_1696674661755_3_Building_Plan_Approval___NA_Order_for_plotted_development.pdf",
  "id": "107490",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Sat Oct 07 2023 16:08:39 GMT+0530 (India Standard Time)"
},
}
```

```
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName":
"document_1696674669441_4_Copy_of_Layout_Approval_in_case_of_layout.pdf",
  "path": "cases/6521355a119cca234ddd5f2c/
document_1696674669441_4_Copy_of_Layout_Approval_in_case_of_layout.pdf",
  "id": "386448",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Sat Oct 07 2023 16:08:39 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1696674683404_29_Building_Plan_Approval__NA_Order_
for_plotted_development.pdf",
  "path": "cases/6521355a119cca234ddd5f2c/document_1696674683404_29_Buildin
g_Plan_Approval__NA_Order_for_plotted_development.pdf",
  "id": "614814",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Sat Oct 07 2023 16:08:39 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1696674692109_DEclaration.pdf",
  "path": "cases/6521355a119cca234ddd5f2c/
document_1696674692109_DEclaration.pdf",
  "id": "629482",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Sat Oct 07 2023 16:08:39 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
```

```
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1696674713841_plan_2.pdf",
  "path": "cases/6521355a119cca234ddd5f2c/
document_1696674713841_plan_2.pdf",
  "id": "986294",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Sat Oct 07 2023 16:08:39 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  },
  "Document_No": "P51600034517"
},
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1696674735388_RERA.pdf",
  "path": "cases/6521355a119cca234ddd5f2c/
document_1696674735388_RERA.pdf",
  "id": "408696",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Sat Oct 07 2023 16:08:39 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "inputs": {
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  }
}
```

```
    },
    "Document_No": "",
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1696674744414_Shreeji_The_Crown.pdf",
  "path": "cases/6521355a119cca234ddd5f2c/
document_1696674744414_Shreeji_The_Crown.pdf",
  "id": "659979",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Sat Oct 07 2023 16:08:39 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae12a8aa6d152c1801b4a7",
    "label": "Title Search Report"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1696674755672_TSR.pdf",
  "path": "cases/6521355a119cca234ddd5f2c/document_1696674755672_TSR.pdf",
  "id": "952006",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Sat Oct 07 2023 16:08:39 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "004274",
"createdBy": "63f9ed37ce84bf289ba991ac",
"caseHistory": [
  {
    "id": "325755",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Oct 07 2023 16:09:22 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Shreeji The Crown",
    "phone": "0253247173",
    "ownershipShare": "",
    "email": "",
    "id": "490679"
  }
],
"proposePurchasers": [],
```

```
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6521408d119cca234ddd7c6a",
    "name":
"externallmg_1696678016165_WhatsApp_Image_20231007_at_45045_PM_1.jpeg",
    "path": "cases/6521355a119cca234ddd5f2c/
externallmg_1696678016165_WhatsApp_Image_20231007_at_45045_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6521408d119cca234ddd7c6b",
    "name":
"externallmg_1696678016220_WhatsApp_Image_20231007_at_45045_PM.jpeg",
    "path": "cases/6521355a119cca234ddd5f2c/
externallmg_1696678016220_WhatsApp_Image_20231007_at_45045_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6521408d119cca234ddd7c6c",
    "name":
"externallmg_1696678018371_WhatsApp_Image_20231007_at_45046_PM_1.jpeg",
    "path": "cases/6521355a119cca234ddd5f2c/
externallmg_1696678018371_WhatsApp_Image_20231007_at_45046_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6521408d119cca234ddd7c6d",
    "name":
"externallmg_1696678020017_WhatsApp_Image_20231007_at_45046_PM.jpeg",
    "path": "cases/6521355a119cca234ddd5f2c/
externallmg_1696678020017_WhatsApp_Image_20231007_at_45046_PM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6521408d119cca234ddd7c6e",
    "name":
"externallmg_1696678020098_WhatsApp_Image_20231007_at_45047_PM_1.jpeg",
    "path": "cases/6521355a119cca234ddd5f2c/
externallmg_1696678020098_WhatsApp_Image_20231007_at_45047_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6521408d119cca234ddd7c6f",
    "name":
"externallmg_1696678023491_WhatsApp_Image_20231007_at_45047_PM.jpeg",
    "path": "cases/6521355a119cca234ddd5f2c/
externallmg_1696678023491_WhatsApp_Image_20231007_at_45047_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6521408d119cca234ddd7c70",
    "name":
"externallmg_1696678025234_WhatsApp_Image_20231007_at_45048_PM_1.jpeg",
    "path": "cases/6521355a119cca234ddd5f2c/
externallmg_1696678025234_WhatsApp_Image_20231007_at_45048_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6521408d119cca234ddd7c71",
    "name":
"externallmg_1696678025297_WhatsApp_Image_20231007_at_45048_PM.jpeg",
    "path": "cases/6521355a119cca234ddd5f2c/
externallmg_1696678025297_WhatsApp_Image_20231007_at_45048_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6521408d119cca234ddd7c72",
```



```
    "name":  
    "externalImg_1696678028826_WhatsApp_Image_20231007_at_45049_PM_1.jpeg",  
    "path": "cases/6521355a119cca234ddd5f2c/  
externalImg_1696678028826_WhatsApp_Image_20231007_at_45049_PM_1.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "6521408d119cca234ddd7c73",  
    "name":  
    "externalImg_1696678028900_WhatsApp_Image_20231007_at_45049_PM_2.jpeg",  
    "path": "cases/6521355a119cca234ddd5f2c/  
externalImg_1696678028900_WhatsApp_Image_20231007_at_45049_PM_2.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "6521408d119cca234ddd7c74",  
    "name":  
    "externalImg_1696678028989_WhatsApp_Image_20231007_at_45049_PM.jpeg",  
    "path": "cases/6521355a119cca234ddd5f2c/  
externalImg_1696678028989_WhatsApp_Image_20231007_at_45049_PM.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "6521408d119cca234ddd7c75",  
    "name":  
    "externalImg_1696678029028_WhatsApp_Image_20231007_at_45050_PM.jpeg",  
    "path": "cases/6521355a119cca234ddd5f2c/  
externalImg_1696678029028_WhatsApp_Image_20231007_at_45050_PM.jpeg",  
    "orientation": "portrait"  
  }  
],  
"externalDocuments": [],  
"processingDocuments": [],  
"remarks": [],  
"createdAt": "2023-10-07T10:39:22.141Z",  
"updatedAt": "2023-10-07T11:27:09.249Z",  
"__v": 0,  
"invoiceId": "6521355a119cca234ddd5f47",  
"updatedBy": "63f9ed37ce84bf289ba991ac",  
"addressForMap": "",
```

"caseReferredBy": "62724142afd7d55eddede405",  
"contactPersonName": "Shreeji The Crown",  
"email": "",  
"isExternal": "false",  
"isUrgent": "false",  
"ownershipShare": "",  
"purchaseValueAsPerDocument": "",  
"relationWithOwner": "self",  
"siteVisitContactNo": "0253247173"

}

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
Composition :			
Other Composition :			