

```
{
  "typeOfReport": {
    "label": "Industrial Report",
    "value": "Industrial_Report"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64744e7cb05e530fb6c7bac8"
    },
    "type": "CREDITOFFICER",
    "_id": "64facbce63830d2aa3b52ec2",
    "firstName": "Bhagat Ram ",
    "lastName": "Kumawat",
    "mobileNo": "",
    "workMobileNo": "7000830634",
    "email": "ubin05542211@unionbankofindia.bank"
  },
  "fees": {
    "type": "agreed",
    "propertyValue": "4400000",
    "discussWithPerson": "Bhagat Ram ",
    "expectedFees": 2200,
    "quotedAmount": "5000"
  },
  "organization": {
```

```
"_id": "6450f43cba18c8062aad0215",
"name": "Indore",
"shortName": "Indore",
"email": "indore@vastukala.org",
"address": "106, 1st Floor, Gold Star Tower, ,576, M G Road, Opp T1 Mall,
Indore-452001, Madhya Pradesh India",
"city": "Indore"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "64744e7cb05e530fb6c7bac8",
  "name": "Sindhi Colony Branch\t",
  "branchCode": "",
  "mobileNo": "02225921813",
  "alternateMobileNo": "",
  "email": "cbssindhicolony@unionbankofindia.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "30, Patel Nagar\nSapna Sangeeta Road,\nIndore -452001"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Industrial",
  "label": "Industrial"
},
"zone": {
  "_id": "6437ee3a8989760c1fb68468",
  "zoneName": "Indore Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "6421248a695fbc66ee1a7ce3",
    "role": "ADMIN",
```

```
"firstName": "Niti",
"email": "niti@vastukala.org",
"lastName": "Kuril",
"mobileNo": "9926411111",
"shortName": "NSK",
"workWithDocumentMaker": "",
"profilePhoto": "users/6421248a695fbc66ee1a7ce3/
profilePhoto_1679893769249_WhatsApp_Image_20230324_at_20338_PM_1.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "644d108bd4903a28b8e52967",
"role": "SITEENGINEER+MAKAR+ RATE VERIFIER + CHECKER",
"firstName": "Somesh",
"email": "somesnahaar111@gmail.com",
"lastName": " Nahar",
"mobileNo": "7354486085",
"designation": "",
"shortName": "Somesh",
"workWithDocumentMaker": "60016f965256c07aec8e6dd6",
"profilePhoto": "users/644d108bd4903a28b8e52967/
profilePhoto_1688544438161_WhatsApp_Image_20230705_at_13245_PM.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "644d108bd4903a28b8e52967",
"role": "SITEENGINEER+MAKAR+ RATE VERIFIER + CHECKER",
"firstName": "Somesh",
"email": "somesnahaar111@gmail.com",
"lastName": " Nahar",
"mobileNo": "7354486085",
"designation": "",
"shortName": "Somesh",
"workWithDocumentMaker": "60016f965256c07aec8e6dd6",
"profilePhoto": "users/644d108bd4903a28b8e52967/
profilePhoto_1688544438161_WhatsApp_Image_20230705_at_13245_PM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "644d067cd4903a28b8e51b30",
"role": "SITEENGINEER+MAKAR",
"firstName": "Akshay Kumar ",
"email": "atrivedi321@gmail.com",
"lastName": "Trivedi",
"mobileNo": "8871809210",
"designation": ""
```

```
    "shortName": "Akshay",
    "workWithDocumentMaker": "60016f965256c07aec8e6dd6",
    "profilePhoto": "users/644d067cd4903a28b8e51b30/
profilePhoto_1688545747727_image.jpeg"
  },
  "checker": {
    "_id": "60016f965256c07aec8e6dd6",
    "profilePhoto": "users\\60016f965256c07aec8e6dd6\
\profilePhoto_1622371927126_Akhilesh Photo (2).jpg",
    "firstName": "Akhilesh",
    "lastName": "Yadav",
    "shortName": "AY",
    "email": "akhilesh.yadav@vastukala.org",
    "designation": "Processing Officer",
    "mobileNo": "9545753921",
    "role": "MAKER + RATE VERFIER + CHEAKER",
    "type": "EMPLOYEE",
    "workWithDocumentMaker": "6009222ca16fab0f2af9b0bf"
  },
  "valuers": []
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "22.632220079647354",
  "longitude": "75.58140925977563"
},
"geo": {
  "type": "Point",
  "coordinates": [
    75.58140925977563,
    22.632220079647354
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-12",
      "remark": ""
    },
    {
      "status": "COMPLETED",
```

```
    "dateTime": "2023-10-12",
    "remark": ""
  },
  {
    "status": "COMPLETED",
    "dateTime": "2023-10-06",
    "remark": "MANUAL_IN_TASK"
  }
],
"schedule": [],
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Pithampur",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Ground",
```

```
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Dhar",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Indore",
  "label": false
},
"tahasilNo": {
  "status": true,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "Dhar ",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "01",
  "label": true
},
"buildingName": {
  "status": false,
```

```
"name": "Building Name",
"key": "buildingName",
"value": "",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Pithampur Industrial Area Sector No. 3 ",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
}
```

```
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
```



```
"key": "municipalityWardNo",
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "454 774",
  "label": false
},
}
```

```
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "areaType": "Built Up",
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Mon Oct 16 2023 16:01:43 GMT+0530 (India Standard Time)",
  "number": "2303017",
  "dayCount": "16",
  "monthCount": "214",
  "generatedBy": "60016f965256c07aec8e6dd6"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": true
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
```

```
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
```

```
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
    "title": "Interior Decorations",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
```

```
"SITE_INSPECTION": true,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": true,
"status": true,
"caseStatus": "REPORTGENERATED",
"paymentId": [],
"_id": "6521495e119cca234ddda795",
"ownerName": "M/S Kamla Auto Industries ",
"ownerPhoneNo": "9827009754",
"appAddress": "Industrial Land at Plot No.1, Pithampur Industrial Area Sector No. 3,
Pithampur, Tehsil & District - Dhar, PIN – 454 774,",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Lease Agreement",
      "value": "60ae1297aa6d152c1801b459"
    }
  },
  "isHardCopy": false,
  "path": "cases/6521495e119cca234ddda795/
document_1696680103955_2276456.pdf",
  "fileName": "document_1696680103955_2276456.pdf",
  "displayStatus": false,
  "id": "903161",
  "uploadedBy": "6421248a695fbc66ee1a7ce3",
  "createdAt": "Sat Oct 07 2023 17:34:04 GMT+0530 (India Standard Time)"
```



```
}
],
"gstNo": "",
"caseNumber": "004284",
"createdBy": "6421248a695fbc66ee1a7ce3",
"caseHistory": [
  {
    "id": "114996",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Oct 07 2023 17:34:46 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "M/S Kamla Auto Industries ",
    "phone": "9827009754",
    "ownershipShare": "",
    "email": "",
    "id": "955672"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652d12f1316e1359cebd230f",
    "name":
      "externallmg_1697452785561_WhatsApp_Image_20231006_at_43241_PM_1.jpeg",
    "path": "cases/6521495e119cca234ddda795/
      externallmg_1697452785561_WhatsApp_Image_20231006_at_43241_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652d12f1316e1359cebd2310",
    "name":
      "externallmg_1697452785565_WhatsApp_Image_20231006_at_43241_PM_2.jpeg",
```

```
    "path": "cases/6521495e119cca234ddda795/
externallmg_1697452785565_WhatsApp_Image_20231006_at_43241_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652d12f1316e1359cebd2311",
    "name":
"externallmg_1697452785569_WhatsApp_Image_20231006_at_43241_PM.jpeg",
    "path": "cases/6521495e119cca234ddda795/
externallmg_1697452785569_WhatsApp_Image_20231006_at_43241_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652d12f1316e1359cebd2312",
    "name":
"externallmg_1697452785575_WhatsApp_Image_20231006_at_43242_PM_1.jpeg",
    "path": "cases/6521495e119cca234ddda795/
externallmg_1697452785575_WhatsApp_Image_20231006_at_43242_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652d12f1316e1359cebd2313",
    "name":
"externallmg_1697452785579_WhatsApp_Image_20231006_at_43242_PM_2.jpeg",
    "path": "cases/6521495e119cca234ddda795/
externallmg_1697452785579_WhatsApp_Image_20231006_at_43242_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652d12f1316e1359cebd2314",
    "name":
"externallmg_1697452785581_WhatsApp_Image_20231006_at_43242_PM.jpeg",
    "path": "cases/6521495e119cca234ddda795/
externallmg_1697452785581_WhatsApp_Image_20231006_at_43242_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "652d12f1316e1359cebd2315",
  "name":
"externallmg_1697452785584_WhatsApp_Image_20231006_at_43243_PM_1.jpeg",
  "path": "cases/6521495e119cca234ddda795/
externallmg_1697452785584_WhatsApp_Image_20231006_at_43243_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652d12f1316e1359cebd2316",
  "name":
"externallmg_1697452785587_WhatsApp_Image_20231006_at_43243_PM.jpeg",
  "path": "cases/6521495e119cca234ddda795/
externallmg_1697452785587_WhatsApp_Image_20231006_at_43243_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652d12f1316e1359cebd2317",
  "name":
"externallmg_1697452785590_WhatsApp_Image_20231006_at_43244_PM_1.jpeg",
  "path": "cases/6521495e119cca234ddda795/
externallmg_1697452785590_WhatsApp_Image_20231006_at_43244_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652d12f1316e1359cebd2318",
  "name":
"externallmg_1697452785592_WhatsApp_Image_20231006_at_43244_PM_2.jpeg",
  "path": "cases/6521495e119cca234ddda795/
externallmg_1697452785592_WhatsApp_Image_20231006_at_43244_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652d12f1316e1359cebd2319",
  "name":
"externallmg_1697452785594_WhatsApp_Image_20231006_at_43244_PM.jpeg",
  "path": "cases/6521495e119cca234ddda795/
externallmg_1697452785594_WhatsApp_Image_20231006_at_43244_PM.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652d12f1316e1359cebd231a",
    "name":
"externallmg_1697452785596_WhatsApp_Image_20231006_at_43245_PM_1.jpeg",
    "path": "cases/6521495e119cca234ddda795/
externallmg_1697452785596_WhatsApp_Image_20231006_at_43245_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652d12f1316e1359cebd231b",
    "name":
"externallmg_1697452785598_WhatsApp_Image_20231006_at_43245_PM.jpeg",
    "path": "cases/6521495e119cca234ddda795/
externallmg_1697452785598_WhatsApp_Image_20231006_at_43245_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652d12f1316e1359cebd231c",
    "name":
"externallmg_1697452785601_WhatsApp_Image_20231006_at_43246_PM_1.jpeg",
    "path": "cases/6521495e119cca234ddda795/
externallmg_1697452785601_WhatsApp_Image_20231006_at_43246_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652d12f1316e1359cebd231d",
    "name":
"externallmg_1697452785602_WhatsApp_Image_20231006_at_43246_PM_2.jpeg",
    "path": "cases/6521495e119cca234ddda795/
externallmg_1697452785602_WhatsApp_Image_20231006_at_43246_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652d12f1316e1359cebd231e",
```

```
    "name":
"externallmg_1697452785604_WhatsApp_Image_20231006_at_43246_PM.jpeg",
    "path": "cases/6521495e119cca234ddda795/
externallmg_1697452785604_WhatsApp_Image_20231006_at_43246_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652d12f1316e1359cebd231f",
    "name":
"externallmg_1697452785605_WhatsApp_Image_20231006_at_43247_PM_1.jpeg",
    "path": "cases/6521495e119cca234ddda795/
externallmg_1697452785605_WhatsApp_Image_20231006_at_43247_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652d12f1316e1359cebd2320",
    "name":
"externallmg_1697452785607_WhatsApp_Image_20231006_at_43247_PM_2.jpeg",
    "path": "cases/6521495e119cca234ddda795/
externallmg_1697452785607_WhatsApp_Image_20231006_at_43247_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652d1312316e1359cebd23cb",
    "name":
"externallmg_1697452818208_WhatsApp_Image_20231006_at_43249_PM_1.jpeg",
    "path": "cases/6521495e119cca234ddda795/
externallmg_1697452818208_WhatsApp_Image_20231006_at_43249_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652d1312316e1359cebd23cc",
    "name":
"externallmg_1697452818211_WhatsApp_Image_20231006_at_43249_PM_2.jpeg",
    "path": "cases/6521495e119cca234ddda795/
externallmg_1697452818211_WhatsApp_Image_20231006_at_43249_PM_2.jpeg",
    "orientation": "landscape"
  },
  }
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652d1312316e1359cebd23cd",
  "name":
"externallmg_1697452818214_WhatsApp_Image_20231006_at_43249_PM.jpeg",
  "path": "cases/6521495e119cca234ddda795/
externallmg_1697452818214_WhatsApp_Image_20231006_at_43249_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652d1312316e1359cebd23ce",
  "name":
"externallmg_1697452818216_WhatsApp_Image_20231006_at_43250_PM_1.jpeg",
  "path": "cases/6521495e119cca234ddda795/
externallmg_1697452818216_WhatsApp_Image_20231006_at_43250_PM_1.jpeg",
  "orientation": "landscape"
}
],
"externalDocuments": [
  {
    "originalname": "Kamala Pvt.Ltd..doc",
    "filename": "1697199538585_Kamala_PvtLtd.doc",
    "path": "cases/6521495e119cca234ddda795/
externalDocuments/1697199538585_Kamala_PvtLtd.doc",
    "size": "2980864",
    "documentType": {
      "value": "649998c6cab24d3d1a2cc577",
      "label": "Draft Word Report"
    },
    "createdAt": "Fri Oct 13 2023 17:49:00 GMT+0530 (India Standard Time)",
    "uploadedBy": "644d067cd4903a28b8e51b30"
  },
  {
    "originalname": "Kamla Auto Industries - Pithampur.doc",
    "filename": "1697452483848_Kamla_Auto_Industries__Pithampur.doc",
    "path": "cases/6521495e119cca234ddda795/
externalDocuments/1697452483848_Kamla_Auto_Industries__Pithampur.doc",
    "size": "3646464",
    "documentType": {
      "value": "64058cdff10de22571d01b37",
      "label": "Final Word Report"
    },
    "createdAt": "Mon Oct 16 2023 16:04:44 GMT+0530 (India Standard Time)",
```

```
    "uploadedBy": "60016f965256c07aec8e6dd6"
  }
],
"processingDocuments": [
  {
    "originalname": "Kamala Pvt.Ltd..doc",
    "filename": "1697437451524_Kamala_PvtLtd.doc",
    "path": "cases/6521495e119cca234ddda795/
processingDocuments/1697437451524_Kamala_PvtLtd.doc",
    "size": "2980864",
    "createdAt": "Mon Oct 16 2023 11:54:13 GMT+0530 (India Standard Time)",
    "uploadedBy": "644d067cd4903a28b8e51b30"
  },
  {
    "originalname": "Amendment Lease Deed.pdf",
    "filename": "1697452516508_Amendment_Lease_Deed.pdf",
    "path": "cases/6521495e119cca234ddda795/
processingDocuments/1697452516508_Amendment_Lease_Deed.pdf",
    "size": "1101425",
    "createdAt": "Mon Oct 16 2023 16:05:16 GMT+0530 (India Standard Time)",
    "uploadedBy": "60016f965256c07aec8e6dd6"
  },
  {
    "originalname": "Kamla Auto Industries - Pithampur.xlsx",
    "filename": "1697452516526_Kamla_Auto_Industries__Pithampur.xlsx",
    "path": "cases/6521495e119cca234ddda795/
processingDocuments/1697452516526_Kamla_Auto_Industries__Pithampur.xlsx",
    "size": "13177",
    "createdAt": "Mon Oct 16 2023 16:05:16 GMT+0530 (India Standard Time)",
    "uploadedBy": "60016f965256c07aec8e6dd6"
  },
  {
    "originalname": "Lease Deed (1).pdf",
    "filename": "1697452516528_Lease_Deed_1.pdf",
    "path": "cases/6521495e119cca234ddda795/
processingDocuments/1697452516528_Lease_Deed_1.pdf",
    "size": "5597499",
    "createdAt": "Mon Oct 16 2023 16:05:16 GMT+0530 (India Standard Time)",
    "uploadedBy": "60016f965256c07aec8e6dd6"
  },
  {
    "originalname": "Old Valuation.pdf",
    "filename": "1697452516632_Old_Valuation.pdf",
    "path": "cases/6521495e119cca234ddda795/
processingDocuments/1697452516632_Old_Valuation.pdf",
    "size": "3298503",
```

```

    "createdAt": "Mon Oct 16 2023 16:05:16 GMT+0530 (India Standard Time)",
    "uploadedBy": "60016f965256c07aec8e6dd6"
  },
  {
    "originalname": "Visit Format .pdf",
    "filename": "1697452516678_Visit_Format_.pdf",
    "path": "cases/6521495e119cca234ddda795/
processingDocuments/1697452516678_Visit_Format_.pdf",
    "size": "435917",
    "createdAt": "Mon Oct 16 2023 16:05:16 GMT+0530 (India Standard Time)",
    "uploadedBy": "60016f965256c07aec8e6dd6"
  }
],
"remarks": [],
"createdAt": "2023-10-07T12:04:46.688Z",
"updatedAt": "2023-10-16T10:40:18.287Z",
"__v": 0,
"invoiceId": "6521495f119cca234ddda7db",
"fullAddress": " Industrial Report No. Ground Floor, Plot No. 01, Pithampur Industrial
Area Sector No. 3 , Village - Pithampur, Tahasil Dhar , District - Dhar, Indore, 454 774,
State - Madhya Pradesh",
"updatedAtBy": "60016f965256c07aec8e6dd6",
"addressForMap": "",
"caseReferredBy": "6421248a695fbc66ee1a7ce3",
"contactPersonName": "M/S Kamla Auto Industries ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9827009754",
"reportGeneratedDate": "Mon Oct 16 2023 16:01:35 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2023-10-06"
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			