PROFORMA INVOICE

Invoice No. Dated Vastukala Consultants (I) Pvt Ltd B1-001, U/B FLOOR, PG-2929/23-24 16-Oct-23 BOOMERANG, CHANDIVALI FARM ROAD, **Delivery Note** Mode/Terms of Payment ANDHERI-EAST 400072 AGAINST REPORT GSTIN/UIN: 27AADCV4303R1ZX Reference No. & Date. Other References State Name: Maharashtra, Code: 27 E-Mail: accounts@vastukala.org Buyer's Order No. Dated Buyer (Bill to) STATE BANK OF INDIA- RASMECCC Panvel Dispatch Doc No. **Delivery Note Date** RASMECCC Panvel 004424/2303025 Sharda Terrace, Shop No 5, Ground Floor, Dispatched through Destination Plot No 65, Sector-11, CBD Belapur GSTIN/UIN : 27AAAC\$8577K2ZO State Name : Maharashtra, Code : 27 Terms of Delivery Si **Particulars** HSN/SAC GST Amount Rate No. 1 STRUCTURAL REPORT FEE 997224 18 % 2,500.00 (Technical Inspection and Certification Services) CGST 225,00 SGST 225.00 Total 2,950.00 Amount Chargeable (in words) E. & O.E Indian Rupee Two Thousand Nine Hundred Fifty Only HSN/SAC Taxable Central Tax State Tax Total Value Rate Amount Rate Amount Tax Amount 2,500.00 997224 225,00 225.00 450.00 9% 9% Total 2,500.00 225.00 225.00 450.00 Tax Amount (in words): Indian Rupee Four Hundred Fifty Only Company's Bank Details Bank Name : State Bank of India A/c No. 32632562114 Branch & IFS Code: MIDC Andheri (E) & SBIN0007074 Mrs. Kanchan Subhash Ghuge - Report of Residential Flat No. 1:2, 1st Floor, Building No. A-2, "Shree Ganesh Co-op. Hsg. Soc. Ltd.," Plot No. 1, Sector -28, Village - Nerul, Taluka - Thane, District - Thane, Navi Mumbai, PIN - 400706, State - Maharashtra,

> UPI Virtual ID : vastukala@icici for Vastukala Consultants (I) Pvt Ltd

Asmita Rathod 🖺

Authorised Signatory

This is a Computer Generated Invoice

Country - India Company's PAN

Declaration

: AADCV4303R

NOTE - AS PER MSME RULES INVOICE NEED TO

BE CLEARED WITHIN 45 DAYS OR INTEREST

CHARGES APPLICABLE AS PER THE RULE. MSME Registration No. - 27222201137





CIN: U74120MH2010PTC207869 MSME Reg. No.: UDYAM-MH-18-0083617 An ISO 9001:2015 Certified Company





Valuation Report Prepared For: SBI / RASMECCC Panvel Branch / Mrs. Kanchan Subhash Ghuge (004424/2303025) Page 1 of 3

Vastu/Mumbai/10/2023/004424/2303025 16/24-222-SKVS Date 16.10.2023

Structural Stability Report

Structural Observation Report of Residential Flat No. 1:2, 1st Floor, Building No. A-2, "Shree Ganesh Co-op. Hsg. Soc. Ltd.," Plot No. 1, Sector – 28, Village – Nerul, Taluka – Thane, District – Thane, Navi Mumbai, PIN – 400706, State – Maharashtra, Country – India.

Name of Owners: Mrs. Kanchan Subhash Ghuge

This is to certify that on visual inspection, it appears that the structure at "Shree Ganesh Co-op. Hsg. Soc. Ltd." is in good condition and the future life can be reasonably takes under good condition and with proper periodic repairs & maintenance is about 33 years.

General Information:

A.		Introduction
1	Name of Building	"Shree Ganesh Co-op. Hsg. Soc. Ltd.,"
2	Property Address	Residential Flat No. 1:2, 1st Floor, Building No. A-2,
	\	"Shree Ganesh Co-op. Hsg. Soc. Ltd.," Plot No. 1,
	\ \	Sector – 28, Village – Nerul, Taluka – Thane, District –
	\ \	Thane, Navi Mumbai, PIN – 400706, State – Maharashtra,
		Country – India.
3	Type of Building	Residential
4	No. of Floors	Stilt + 7 Upper Floors
5	Whether stilt / podium / open parking	Open / Stilt Car Parking
	provided	1
6	Type of Construction	R.C.C. Framed Structure
7	Type of Foundation	R.C.C. Footing
8	Thickness of the External Walls	9" thick brick walls both sides plastered
9	Type of Compound	Brick Masonry Walls
10	Year of Construction	1996 (As per Occupancy Certificate)
11	Present age of building Think In	27 years — Create
12	Residual age of the building	33 years Subject to proper, preventive periodic
		maintenance & structural repairs.
13	No. of flats (Per Floor)	1st Floor is having 4 Flats
14	Methodology adopted	As per visual site inspection
B.	External O	bservation of the Building
1	Plaster	Good Condition
2	Chajjas	Good Condition
3	Plumbing	Good Condition
4	Cracks on the external walls	Not found
5	Filling cracks on the external walls	Not found
6	Cracks on columns & beams	Not found
7	Vegetation	Not found





Regd. Office: B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Andheri (East), Mumbai - 400 072, (M.S.), INDIA

TeleFax: +91 22 28371325/24 mumbai@vastukala.org

8	Leakages of water in the drainage pipes	Not found
_	or water pipes	
9	Dampness external in the wall due to	Not found
	leakages	
10	Any other observation about the	The external condition of the building is good.
	condition of external side of the building	
С	Internal Observation of the common areas of the building and captioned premises	
1	Beams (Cracks & Leakages)	Not found
2	Columns (Cracks & Leakages)	Not found
3	Ceiling (Cracks & Leakages)	Not found
4	Leakages inside the property	Not found
5	Painting inside the property	Not found
6	Maintenance of staircase & cracks	Not found

D	Common Observation	
1	Structural Audit of the Building Under Bye	As per bye Laws No. 77 of Co-Op. Societies bye Laws
	- Laws No. 77 of the Model Bye Laws	under the Act the society shall conduct a Structural Audit
	(Co-Operative Societies Act / Rules)	of the building of the society as follows
2	Remark	No Structural Audit Report is furnished for the perusal

E Conclusion

The captioned building is having Stilt + 7 Upper Floors which are constructed in year 1996 (as per occupancy certificate). Estimated future life under present circumstances is about 33 years subject to proper, preventive periodic maintenance & structural repairs.

The inspection dated 06.09.2023 reveals no structural damage or deterioration to the building. The building as well as the property is maintained in good condition & will stand future life subject to proper, preventive periodic maintenance & Good structural repairs.

Our Observations about the structure are given above.

The above assessment is based on visual inspection only.

For VASTUKALA CONSULTANTS (I) PVT. LTD. ate. Create

Sharadkumar Digitally s Chalkwar B. Chalikwar Ou=CMD.

Digitally signed by Sharadkumar B.
Chalikwar
DN: cn=Sharadkumar B. Chalikwar,
o=Vastukala Consultants (I) Pvt. Ltd.,
ou=CMD, email=cmd@vastukala.org, c=IN
Date: 2023.10.16 17:47:12 +05:30'

Director

Auth. Sign.

Sharadkumar B. Chalikwar

Govt. Reg. Valuer Chartered Engineer (India)

Reg. No. (N) CCIT/1-14/52/2008-09

SBI Empanelment No.: SME/TCC/2021-22/85/13





Actual site photographs

















