



PLOT AREA CALCULATION
SCALE: 1:200

1	20.38 X 4.55 X 0.50	=	46.32
2	26.50 X 1.25 X 0.50	=	16.56
3	26.50 X 1.36 X 0.50	=	18.29
4	25.11 X 0.51 X 0.50	=	6.29
5	25.11 X 0.52 X 0.50	=	6.53
6	27.48 X 0.53 X 0.50	=	7.29
7	28.49 X 0.54 X 0.50	=	7.70
8	28.49 X 0.55 X 0.50	=	7.84
9	28.49 X 0.56 X 0.50	=	7.98
10	28.49 X 0.57 X 0.50	=	8.12
11	28.49 X 0.58 X 0.50	=	8.26
12	28.49 X 0.59 X 0.50	=	8.40
13	28.49 X 0.60 X 0.50	=	8.54
14	28.49 X 0.61 X 0.50	=	8.68
15	28.49 X 0.62 X 0.50	=	8.82
16	28.49 X 0.63 X 0.50	=	8.96
17	28.49 X 0.64 X 0.50	=	9.10
18	28.49 X 0.65 X 0.50	=	9.24
19	28.49 X 0.66 X 0.50	=	9.38
20	28.49 X 0.67 X 0.50	=	9.52
21	28.49 X 0.68 X 0.50	=	9.66
22	28.49 X 0.69 X 0.50	=	9.80
23	28.49 X 0.70 X 0.50	=	9.94
24	28.49 X 0.71 X 0.50	=	10.08
25	28.49 X 0.72 X 0.50	=	10.22
26	28.49 X 0.73 X 0.50	=	10.36
27	28.49 X 0.74 X 0.50	=	10.50
28	28.49 X 0.75 X 0.50	=	10.64
29	28.49 X 0.76 X 0.50	=	10.78
30	28.49 X 0.77 X 0.50	=	10.92
31	28.49 X 0.78 X 0.50	=	11.06
32	28.49 X 0.79 X 0.50	=	11.20
33	28.49 X 0.80 X 0.50	=	11.34
34	28.49 X 0.81 X 0.50	=	11.48
35	28.49 X 0.82 X 0.50	=	11.62
36	28.49 X 0.83 X 0.50	=	11.76
37	28.49 X 0.84 X 0.50	=	11.90
38	28.49 X 0.85 X 0.50	=	12.04
39	28.49 X 0.86 X 0.50	=	12.18
40	28.49 X 0.87 X 0.50	=	12.32
41	28.49 X 0.88 X 0.50	=	12.46
42	28.49 X 0.89 X 0.50	=	12.60
43	28.49 X 0.90 X 0.50	=	12.74
44	28.49 X 0.91 X 0.50	=	12.88
45	28.49 X 0.92 X 0.50	=	13.02
46	28.49 X 0.93 X 0.50	=	13.16
47	28.49 X 0.94 X 0.50	=	13.30
48	28.49 X 0.95 X 0.50	=	13.44
49	28.49 X 0.96 X 0.50	=	13.58
50	28.49 X 0.97 X 0.50	=	13.72
51	28.49 X 0.98 X 0.50	=	13.86
52	28.49 X 0.99 X 0.50	=	14.00
53	28.49 X 1.00 X 0.50	=	14.14
54	28.49 X 1.01 X 0.50	=	14.28
55	28.49 X 1.02 X 0.50	=	14.42
56	28.49 X 1.03 X 0.50	=	14.56
57	28.49 X 1.04 X 0.50	=	14.70
58	28.49 X 1.05 X 0.50	=	14.84
59	28.49 X 1.06 X 0.50	=	14.98
60	28.49 X 1.07 X 0.50	=	15.12
61	28.49 X 1.08 X 0.50	=	15.26
62	28.49 X 1.09 X 0.50	=	15.40
63	28.49 X 1.10 X 0.50	=	15.54
64	28.49 X 1.11 X 0.50	=	15.68
65	28.49 X 1.12 X 0.50	=	15.82
66	28.49 X 1.13 X 0.50	=	15.96
67	28.49 X 1.14 X 0.50	=	16.10
68	28.49 X 1.15 X 0.50	=	16.24
69	28.49 X 1.16 X 0.50	=	16.38
70	28.49 X 1.17 X 0.50	=	16.52
71	28.49 X 1.18 X 0.50	=	16.66
72	28.49 X 1.19 X 0.50	=	16.80
73	28.49 X 1.20 X 0.50	=	16.94
74	28.49 X 1.21 X 0.50	=	17.08
75	28.49 X 1.22 X 0.50	=	17.22
76	28.49 X 1.23 X 0.50	=	17.36
77	28.49 X 1.24 X 0.50	=	17.50
78	28.49 X 1.25 X 0.50	=	17.64
79	28.49 X 1.26 X 0.50	=	17.78
80	28.49 X 1.27 X 0.50	=	17.92
81	28.49 X 1.28 X 0.50	=	18.06
82	28.49 X 1.29 X 0.50	=	18.20
83	28.49 X 1.30 X 0.50	=	18.34
84	28.49 X 1.31 X 0.50	=	18.48
85	28.49 X 1.32 X 0.50	=	18.62
86	28.49 X 1.33 X 0.50	=	18.76
87	28.49 X 1.34 X 0.50	=	18.90
88	28.49 X 1.35 X 0.50	=	19.04
89	28.49 X 1.36 X 0.50	=	19.18
90	28.49 X 1.37 X 0.50	=	19.32
91	28.49 X 1.38 X 0.50	=	19.46
92	28.49 X 1.39 X 0.50	=	19.60
93	28.49 X 1.40 X 0.50	=	19.74
94	28.49 X 1.41 X 0.50	=	19.88
95	28.49 X 1.42 X 0.50	=	20.02
96	28.49 X 1.43 X 0.50	=	20.16
97	28.49 X 1.44 X 0.50	=	20.30
98	28.49 X 1.45 X 0.50	=	20.44
99	28.49 X 1.46 X 0.50	=	20.58
100	28.49 X 1.47 X 0.50	=	20.72
101	28.49 X 1.48 X 0.50	=	20.86
102	28.49 X 1.49 X 0.50	=	21.00
103	28.49 X 1.50 X 0.50	=	21.14
104	28.49 X 1.51 X 0.50	=	21.28
105	28.49 X 1.52 X 0.50	=	21.42
106	28.49 X 1.53 X 0.50	=	21.56
107	28.49 X 1.54 X 0.50	=	21.70
108	28.49 X 1.55 X 0.50	=	21.84
109	28.49 X 1.56 X 0.50	=	21.98
110	28.49 X 1.57 X 0.50	=	22.12
111	28.49 X 1.58 X 0.50	=	22.26
112	28.49 X 1.59 X 0.50	=	22.40
113	28.49 X 1.60 X 0.50	=	22.54
114	28.49 X 1.61 X 0.50	=	22.68
115	28.49 X 1.62 X 0.50	=	22.82
116	28.49 X 1.63 X 0.50	=	22.96
117	28.49 X 1.64 X 0.50	=	23.10
118	28.49 X 1.65 X 0.50	=	23.24
119	28.49 X 1.66 X 0.50	=	23.38
120	28.49 X 1.67 X 0.50	=	23.52
121	28.49 X 1.68 X 0.50	=	23.66
122	28.49 X 1.69 X 0.50	=	23.80
123	28.49 X 1.70 X 0.50	=	23.94
124	28.49 X 1.71 X 0.50	=	24.08
125	28.49 X 1.72 X 0.50	=	24.22
126	28.49 X 1.73 X 0.50	=	24.36
127	28.49 X 1.74 X 0.50	=	24.50
128	28.49 X 1.75 X 0.50	=	24.64
129	28.49 X 1.76 X 0.50	=	24.78
130	28.49 X 1.77 X 0.50	=	24.92
131	28.49 X 1.78 X 0.50	=	25.06
132	28.49 X 1.79 X 0.50	=	25.20
133	28.49 X 1.80 X 0.50	=	25.34
134	28.49 X 1.81 X 0.50	=	25.48
135	28.49 X 1.82 X 0.50	=	25.62
136	28.49 X 1.83 X 0.50	=	25.76
137	28.49 X 1.84 X 0.50	=	25.90
138	28.49 X 1.85 X 0.50	=	26.04
139	28.49 X 1.86 X 0.50	=	26.18
140	28.49 X 1.87 X 0.50	=	26.32
141	28.49 X 1.88 X 0.50	=	26.46
142	28.49 X 1.89 X 0.50	=	26.60
143	28.49 X 1.90 X 0.50	=	26.74
144	28.49 X 1.91 X 0.50	=	26.88
145	28.49 X 1.92 X 0.50	=	27.02
146	28.49 X 1.93 X 0.50	=	27.16
147	28.49 X 1.94 X 0.50	=	27.30
148	28.49 X 1.95 X 0.50	=	27.44
149	28.49 X 1.96 X 0.50	=	27.58
150	28.49 X 1.97 X 0.50	=	27.72
151	28.49 X 1.98 X 0.50	=	27.86
152	28.49 X 1.99 X 0.50	=	28.00
153	28.49 X 2.00 X 0.50	=	28.14
154	28.49 X 2.01 X 0.50	=	28.28
155	28.49 X 2.02 X 0.50	=	28.42
156	28.49 X 2.03 X 0.50	=	28.56
157	28.49 X 2.04 X 0.50	=	28.70
158	28.49 X 2.05 X 0.50	=	28.84
159	28.49 X 2.06 X 0.50	=	28.98
160	28.49 X 2.07 X 0.50	=	29.12
161	28.49 X 2.08 X 0.50	=	29.26
162	28.49 X 2.09 X 0.50	=	29.40
163	28.49 X 2.10 X 0.50	=	29.54
164	28.49 X 2.11 X 0.50	=	29.68
165	28.49 X 2.12 X 0.50	=	29.82
166	28.49 X 2.13 X 0.50	=	29.96
167	28.49 X 2.14 X 0.50	=	30.10
168	28.49 X 2.15 X 0.50	=	30.24
169	28.49 X 2.16 X 0.50	=	30.38
170	28.49 X 2.17 X 0.50	=	30.52
171	28.49 X 2.18 X 0.50	=	30.66
172	28.49 X 2.19 X 0.50	=	30.80
173	28.49 X 2.20 X 0.50	=	30.94
174	28.49 X 2.21 X 0.50	=	31.08
175	28.49 X 2.22 X 0.50	=	31.22
176	28.49 X 2.23 X 0.50	=	31.36
177	28.49 X 2.24 X 0.50	=	31.50
178	28.49 X 2.25 X 0.50	=	31.64
179	28.49 X 2.26 X 0.50	=	31.78
180	28.49 X 2.27 X 0.50	=	31.92
181	28.49 X 2.28 X 0.50	=	32.06
182	28.49 X 2.29 X 0.50	=	32.20
183	28.49 X 2.30 X 0.50	=	32.34
184	28.49 X 2.31 X 0.50	=	32.48
185	28.49 X 2.32 X 0.50	=	32.62
186	28.49 X 2.33 X 0.50	=	32.76
187	28.49 X 2.34 X 0.50	=	32.90
188	28.49 X 2.35 X 0.50	=	33.04
189	28.49 X 2.36 X 0.50	=	33.18
190	28.49 X 2.37 X 0.50	=	33.32
191	28.49 X 2.38 X 0.50	=	33.46
192	28.49 X 2.39 X 0.50	=	33.60
193	28.49 X 2.40 X 0.50	=	33.74
194	28.49 X 2.41 X 0.50	=	33.88
195	28.49 X 2.42 X 0.50	=	34.02
196	28.49 X 2.43 X 0.50	=	34.16
197	28.49 X 2.44 X 0.50	=	34.30
198	28.49 X 2.45 X 0.50	=	34.44
199	28.49 X 2.46 X 0.50	=	34.58
200	28.49 X 2.47 X 0.50	=	34.72
201	28.49 X 2.48 X 0.50	=	34.86
202	28.49 X 2.49 X 0.50	=	35.00
203	28.49 X 2.50 X 0.50	=	35.14
204	28.49 X 2.51 X 0.50	=	35.28
205	28.49 X 2.52 X 0.50	=	35.42
206	28.49 X 2.53 X 0.50	=	35.56
207	28.49 X 2.54 X 0.50	=	35.70
208	28.49 X 2.55 X 0.50	=	35.84
209	28.49 X 2.56 X 0.50	=	35.98
210	28.49 X 2.57 X 0.50	=	36.12
211	28.49 X 2.58 X 0.50	=	36.26
212	28.49 X 2.59 X 0.50	=	36.40
213	28.49 X 2.60 X 0.50	=	36.54
214	28.49 X 2.61 X 0.50	=	36.68
215	28.49 X 2.62 X 0.50	=	36.82
216	28.49 X 2.63 X 0.50	=	36.96
217	28.49 X 2.64 X 0.50	=	37.10
218	28.49 X 2.65 X 0.50	=	37.24
219	28.49 X 2.66 X 0.50	=	37.38
220	28.49 X 2.67 X 0.50	=	37.52
221	28.49 X 2.68 X 0.50	=	37.66
222	28.49 X 2.69 X 0.50	=	37.80
223	28.49 X 2.70 X 0.50	=	37.94
224	28.49 X 2.71 X 0.50	=	38.08
225	28.49 X 2.72 X 0.50	=	38.22
226	28.49 X 2.73 X 0.50	=	38.36
227	28.49 X 2.74 X 0.50	=	38.50
228	28.49 X 2.75 X 0.50	=	38.64
229	28.49 X 2.76 X 0.50	=	38.78
230	28.49 X 2.77 X 0.50	=	38.92
231	28.49 X 2.78 X 0.50	=	39.06
232	28.49 X 2.79 X 0.50	=	39.20
233	28.49 X 2.80 X 0.50	=	39.34
234	28.49 X 2.81 X 0.50	=	39.48
235	28.49 X 2.82 X 0.50	=	39.62
236	28.49 X 2.83 X 0.50	=	39.76
237	28.49 X 2.84 X 0.50	=	39.90
238	28.49 X 2.85 X 0.50	=	40.04
239	28.49 X 2.86 X 0.50	=	40.18
240	28.49 X 2.87 X 0.50	=	40.32
241	28.49 X 2.88 X 0.50	=	40.46
242	28.49 X 2.89 X 0.50	=	40.60
243	28.49 X 2.90 X 0.50	=	40.74
244	28.49 X 2.91 X 0.50	=	40.88
245	28.49 X 2.92 X 0.50	=	41.02
246	28.49 X 2.93 X 0.50	=	41.16
247	2		