

```
{
  "typeOfReport": {
    "label": "Office",
    "value": "Office"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Banking Purpose",
    "value": "Banking_Purpose"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63ad7b55191f7b344b003bce"
    },
    "type": "CREDITOFFICER",
    "_id": "655b464b5586e008158de0d0",
    "firstName": "Kundan",
    "lastName": "Kumar",
    "mobileNo": "",
    "workMobileNo": "9031620745",
    "email": "kundan.kumar3@unionbankofindia.bank"
  },
  "fees": {
    "type": "quoted",
    "propertyValue": "22000000",
    "discussWithPerson": "Kundan",
    "expectedFees": 11000,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63ad7b55191f7b344b003bce",
  "name": "UBI-Mid Corporate Branch",
  "branchCode": "",
  "mobileNo": "7219107800",
  "alternateMobileNo": "",
  "email": "cb0024@corpbank.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Veena Chambers 21,Dalal Street,Fort-Mumbai"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Commercial",
  "label": "Commercial"
},
"zone": {
  "_id": "60f93be845132d6a6bdda676",
  "zoneName": "MUMBAI SOUTH"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "62727444afd7d55eddee092c",
    "role": "PICKUPPERSON",
```

```
"firstName": "Shantilal",
"email": "shantilal@vastukala.org",
"lastName": "Patel",
"mobileNo": "9969039853",
"shortName": "SHP",
"workWithDocumentMaker": "",
"profilePhoto": "users/62727444afd7d55eddee092c/
profilePhoto_1668057663775_WhatsApp_Image_20221110_at_104853_AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "648fcad91b499c2d52dc86f3",
"role": "SITEENGINEER",
"firstName": "Barkat",
"email": "barkathodekar68@gmail.com",
"lastName": "Hodekar",
"mobileNo": "8879011615",
"designation": "Site Engg",
"shortName": "Barkat",
"workWithDocumentMaker": "",
"profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "64dc7184ccaf1e7b7f637f47",
"role": "FRONTDESK",
"firstName": "Binumon",
"email": "binu@vastukala.org",
"lastName": "Moozhickal",
"mobileNo": "9930252906",
"designation": "Back Office Team Leader",
"shortName": "BS",
"workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
"profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"maker": "",
"checker": "",
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
]
}
]
```

```
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
```

```
    "PANNo": "AERPC9086P",
    "fatherName": "Baburao"
  }
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.076992452714997",
  "longitude": "72.85830593500002"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.85830593500002,
    19.076992452714997
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-11-22",
      "remark": ""
    }
  ],
  "schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  }
}
```

```
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Kolekalyan",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Basement",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
```

```
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "C 66 G Block",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "One BKC",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
}
```

```
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "C",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
```



```
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1616",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
```

```
"status": false,
"name": "Police Station(P.S)",
"key": "policeStation",
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Santacruz West",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
```

```
"finalLatLng": {
  "coordinates": []
},
"locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
```

```
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
```

```
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"paymentId": [],
"_id": "655b79be5586e008158e1132",
"audioRemarks": [],
"ownerName": "Talib And Shamsi Construction Pvt Ltd ",
```



```
"ownerPhoneNo": "9892040259",
"appAddress": "1616 16 floor c wing\nc 66 CTS No 4207\nBandra Kurla complex
\nMumbai -400051",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Any Other Document",
      "value": "60ae124aaa6d152c1801b2f7"
    },
    "isHardCopy": false,
    "path": "cases/655b79be5586e008158e1132/
document_1700493691755_111805.pdf",
    "fileName": "document_1700493691755_111805.pdf",
    "displayStatus": false,
    "id": "195284",
    "uploadedBy": "62727444afd7d55eddee092c",
    "createdAt": "Mon Nov 20 2023 20:52:38 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1700543787828_1616_Bkc.pdf",
    "path": "cases/655b79be5586e008158e1132/
document_1700543787828_1616_Bkc.pdf",
    "id": "482591",
    "uploadedBy": "6006d4ce5080a310ac1fdcf2",
    "createdAt": "Tue Nov 21 2023 10:46:34 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae1248aa6d152c1801b2ee",
      "label": "Previous Valuation Report"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1700722433720_Ms_Tabil__shamsi_ubi_Bkc_ubi_fort.pdf",
    "path": "cases/655b79be5586e008158e1132/
document_1700722433720_Ms_Tabil__shamsi_ubi_Bkc_ubi_fort.pdf",
    "id": "300355",
    "uploadedBy": "64dc7184ccaf1e7b7f637f47",
    "createdAt": "Thu Nov 23 2023 12:23:53 GMT+0530 (India Standard Time)"
  }
]
```

```
}
],
"caseNumber": "005138",
"createdBy": "62727444afd7d55eddee092c",
"caseHistory": [
  {
    "id": "532292",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Nov 20 2023 20:52:38 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Talib And Shamsi Construction Pvt Ltd ",
    "phone": "9892040259",
    "ownershipShare": "",
    "email": "",
    "id": "225748"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655de2705586e008159124e0",
    "name": "externalImg_1700651342125_1700651402671_image_0.jpeg",
    "path": "cases/655b79be5586e008158e1132/externalImg_1700651342125_1700651402671_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655de2705586e008159124e1",
    "name": "externalImg_1700651345693_1700651402671_image_1.jpeg",
    "path": "cases/655b79be5586e008158e1132/externalImg_1700651345693_1700651402671_image_1.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655de2705586e008159124e2",
  "name": "externallmg_1700651349832_1700651402671_image_2.jpeg",
  "path": "cases/655b79be5586e008158e1132/
externallmg_1700651349832_1700651402671_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655de2705586e008159124e3",
  "name": "externallmg_1700651352528_1700651402671_image_3.jpeg",
  "path": "cases/655b79be5586e008158e1132/
externallmg_1700651352528_1700651402671_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655de2705586e008159124e4",
  "name": "externallmg_1700651353814_1700651402671_image_4.jpeg",
  "path": "cases/655b79be5586e008158e1132/
externallmg_1700651353814_1700651402671_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655de2705586e008159124e5",
  "name": "externallmg_1700651355088_1700651402671_image_5.jpeg",
  "path": "cases/655b79be5586e008158e1132/
externallmg_1700651355088_1700651402671_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655de2705586e008159124e6",
  "name": "externallmg_1700651358833_1700651402671_image_6.jpeg",
  "path": "cases/655b79be5586e008158e1132/
externallmg_1700651358833_1700651402671_image_6.jpeg",
  "orientation": "portrait"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655de2705586e008159124e7",
  "name": "externallmg_1700651361313_1700651402671_image_7.jpeg",
  "path": "cases/655b79be5586e008158e1132/
externallmg_1700651361313_1700651402671_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655de2705586e008159124e8",
  "name": "externallmg_1700651365693_1700651402671_image_8.jpeg",
  "path": "cases/655b79be5586e008158e1132/
externallmg_1700651365693_1700651402671_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655de2705586e008159124e9",
  "name": "externallmg_1700651368853_1700651402671_image_9.jpeg",
  "path": "cases/655b79be5586e008158e1132/
externallmg_1700651368853_1700651402671_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655de2705586e008159124ea",
  "name": "externallmg_1700651421848_1700651476309_image_0.jpeg",
  "path": "cases/655b79be5586e008158e1132/
externallmg_1700651421848_1700651476309_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655de2705586e008159124eb",
  "name": "externallmg_1700651433504_1700651476310_image_1.jpeg",
  "path": "cases/655b79be5586e008158e1132/
externallmg_1700651433504_1700651476310_image_1.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655de2705586e008159124ec",
  "name": "externallmg_1700651450727_1700651476310_image_2.jpeg",
  "path": "cases/655b79be5586e008158e1132/
externallmg_1700651450727_1700651476310_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655de2705586e008159124ed",
  "name": "externallmg_1700651457097_1700651476310_image_3.jpeg",
  "path": "cases/655b79be5586e008158e1132/
externallmg_1700651457097_1700651476310_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655de2705586e008159124ee",
  "name": "externallmg_1700651460038_1700651476310_image_4.jpeg",
  "path": "cases/655b79be5586e008158e1132/
externallmg_1700651460038_1700651476310_image_4.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655de2705586e008159124ef",
  "name": "externallmg_1700651462586_1700651476310_image_5.jpeg",
  "path": "cases/655b79be5586e008158e1132/
externallmg_1700651462586_1700651476310_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655de2705586e008159124f0",
  "name": "externallmg_1700651464551_1700651476310_image_6.jpeg",
  "path": "cases/655b79be5586e008158e1132/
externallmg_1700651464551_1700651476310_image_6.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655de2705586e008159124f1",
    "name": "externallmg_1700651467267_1700651476310_image_7.jpeg",
    "path": "cases/655b79be5586e008158e1132/
externallmg_1700651467267_1700651476310_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655de2705586e008159124f2",
    "name": "externallmg_1700651468982_1700651476310_image_8.jpeg",
    "path": "cases/655b79be5586e008158e1132/
externallmg_1700651468982_1700651476310_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655de2705586e008159124f3",
    "name": "externallmg_1700651474169_1700651476310_image_9.jpeg",
    "path": "cases/655b79be5586e008158e1132/
externallmg_1700651474169_1700651476310_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655de2705586e008159124f4",
    "name": "externallmg_1700651550951_1700651608452_image_0.jpeg",
    "path": "cases/655b79be5586e008158e1132/
externallmg_1700651550951_1700651608452_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655de2705586e008159124f5",
    "name": "externallmg_1700651553060_1700651608452_image_1.jpeg",
    "path": "cases/655b79be5586e008158e1132/
externallmg_1700651553060_1700651608452_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "655de2705586e008159124f6",
  "name": "externallmg_1700651557068_1700651608452_image_2.jpeg",
  "path": "cases/655b79be5586e008158e1132/
externallmg_1700651557068_1700651608452_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655de2705586e008159124f7",
  "name": "externallmg_1700651559561_1700651608452_image_3.jpeg",
  "path": "cases/655b79be5586e008158e1132/
externallmg_1700651559561_1700651608452_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655de2705586e008159124f8",
  "name": "externallmg_1700651561920_1700651608452_image_4.jpeg",
  "path": "cases/655b79be5586e008158e1132/
externallmg_1700651561920_1700651608452_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655de2705586e008159124f9",
  "name": "externallmg_1700651564715_1700651608452_image_5.jpeg",
  "path": "cases/655b79be5586e008158e1132/
externallmg_1700651564715_1700651608452_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655de2705586e008159124fa",
  "name": "externallmg_1700651569041_1700651608452_image_6.jpeg",
  "path": "cases/655b79be5586e008158e1132/
externallmg_1700651569041_1700651608452_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "655de2705586e008159124fb",
    "name": "externallmg_1700651573005_1700651608452_image_7.jpeg",
    "path": "cases/655b79be5586e008158e1132/
externallmg_1700651573005_1700651608452_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655de2705586e008159124fc",
    "name": "externallmg_1700651575495_1700651608452_image_8.jpeg",
    "path": "cases/655b79be5586e008158e1132/
externallmg_1700651575495_1700651608452_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655de2705586e008159124fd",
    "name": "externallmg_1700651576600_1700651608452_image_9.jpeg",
    "path": "cases/655b79be5586e008158e1132/
externallmg_1700651576600_1700651608452_image_9.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655de2705586e008159124fe",
    "name": "externallmg_1700651579645_1700651608452_image_10.jpeg",
    "path": "cases/655b79be5586e008158e1132/
externallmg_1700651579645_1700651608452_image_10.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655de2705586e008159124ff",
    "name": "externallmg_1700651583285_1700651608452_image_11.jpeg",
    "path": "cases/655b79be5586e008158e1132/
externallmg_1700651583285_1700651608452_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655de2705586e00815912500",
```



```
    "name": "externallmg_1700651588355_1700651608452_image_12.jpeg",
    "path": "cases/655b79be5586e008158e1132/
externallmg_1700651588355_1700651608452_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655de2705586e00815912501",
    "name": "externallmg_1700651593055_1700651608452_image_13.jpeg",
    "path": "cases/655b79be5586e008158e1132/
externallmg_1700651593055_1700651608452_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655de2705586e00815912502",
    "name": "externallmg_1700651599545_1700651608452_image_14.jpeg",
    "path": "cases/655b79be5586e008158e1132/
externallmg_1700651599545_1700651608452_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655de2705586e00815912503",
    "name": "externallmg_1700651603775_1700651608452_image_15.jpeg",
    "path": "cases/655b79be5586e008158e1132/
externallmg_1700651603775_1700651608452_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655de2705586e00815912504",
    "name": "externallmg_1700651608566_1700651608452_image_16.jpeg",
    "path": "cases/655b79be5586e008158e1132/
externallmg_1700651608566_1700651608452_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655de2705586e00815912505",
    "name": "externallmg_1700651615355_1700651608453_image_17.jpeg",
```

```
    "path": "cases/655b79be5586e008158e1132/
externallmg_1700651615355_1700651608453_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655de2705586e00815912506",
    "name": "externallmg_1700651619014_1700651608453_image_18.jpeg",
    "path": "cases/655b79be5586e008158e1132/
externallmg_1700651619014_1700651608453_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "655de2705586e00815912507",
    "name": "externallmg_1700651304527_1700651363537_image_0.jpeg",
    "path": "cases/655b79be5586e008158e1132/
externallmg_1700651304527_1700651363537_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "655de2705586e00815912508",
    "name": "externallmg_1700651305890_1700651363537_image_1.jpeg",
    "path": "cases/655b79be5586e008158e1132/
externallmg_1700651305890_1700651363537_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "655de2705586e00815912509",
    "name": "externallmg_1700651307774_1700651363537_image_2.jpeg",
    "path": "cases/655b79be5586e008158e1132/
externallmg_1700651307774_1700651363537_image_2.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "TALIB AND SHAMSI CONSTRUCTION PVT LTD - Office No.
1616 -UBI-Mid Corporate Branch.xlsx",
```

```
    "filename": "1700631963742_TALIB_AND_SHAMSI_CONSTRUCTION_PVT_LTD_
_Office_No_1616__UBIMid_Corporate_Branch.xlsx",
    "path": "cases/655b79be5586e008158e1132/processingDocuments/170063196374
2_TALIB_AND_SHAMSI_CONSTRUCTION_PVT_LTD__Office_No_1616__UBIMid_Co
rporate_Branch.xlsx",
    "size": "1878718",
    "createdAt": "Wed Nov 22 2023 11:16:03 GMT+0530 (India Standard Time)",
    "uploadedBy": "64dc7184ccaf1e7b7f637f47"
  }
],
"leadRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "64dc7184ccaf1e7b7f637f47",
      "role": "FRONTDESK",
      "firstName": "Binumon",
      "lastName": "Moozhickal",
      "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "655d95855586e0081590264b",
    "note": "Value given for confirmation",
    "taskId": "655c3cac5586e008158e5495",
    "createdAt": "2023-11-22T05:45:41.657Z"
  },
  {
    "createdBy": {
      "_id": "64dc7184ccaf1e7b7f637f47",
      "role": "FRONTDESK",
      "firstName": "Binumon",
      "lastName": "Moozhickal",
      "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "655d95a05586e00815902669",
    "note": "Value given for confirmation",
    "taskId": "655c3cac5586e008158e5495",
    "createdAt": "2023-11-22T05:46:08.375Z"
  }
]
```

```

],
"createdAt": "2023-11-20T15:22:38.482Z",
"updatedAt": "2023-11-23T06:53:53.942Z",
"__v": 0,
"invoiceId": "655b79be5586e008158e113b",
"updatedBy": "64dc7184ccaf1e7b7f637f47",
"fullAddress": "Commercial Office No. 1616, Basement Floor, Wing - C, One BKC, Plot
No. C 66 G Block, Village - Kolkalyan, Santacruz West, Mumbai, State - Maharashtra,
India",
"addressForMap": "",
"caseReferredBy": "62727444afd7d55eddee092c",
"contactPersonName": "Talib And Shamsi Construction Pvt Ltd ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9892040259"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			