

```
{
  "typeOfReport": {
    "label": "Land and Building",
    "value": "Land_and_Building"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002",
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002"
  },
  "masterTypeOfPurpose": {
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002",
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "657853889e3cbd4940aa2867"
    },
    "type": "CREDITOFFICER",
    "_id": "657853889e3cbd4940aa2869",
    "firstName": "Jagmohan ",
    "lastName": "Das",
    "mobileNo": "",
    "workMobileNo": "9617635035",
    "email": "jagmohan.das@sbi.co.in"
  },
  "fees": {
    "type": "quoted",
    "propertyValue": "9500000",
    "discussWithPerson": "Jagmohan ",
  }
}
```

```
"expectedFees": 4750,
"quotedAmount": "3500"
},
"organization": {
  "_id": "6450f43cba18c8062aad0215",
  "name": "Indore",
  "shortName": "Indore",
  "email": "indore@vastukala.org",
  "address": "106, 1st Floor, Gold Star Tower, ,576, M G Road, Opp T1 Mall,
Indore-452001, Madhya Pradesh India",
  "city": "Indore"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "657853889e3cbd4940aa2867",
  "name": "Stressed Assets Recovery Branch(SARB)",
  "branchCode": "",
  "mobileNo": "07312473464",
  "alternateMobileNo": "",
  "email": "sbi.10007@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "1st Floor,5, Yeshwant Niwas Road, \nIndore - 452003"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Industrial",
  "label": "Industrial"
},
"zone": {
  "_id": "641831ac96b58848585f5124",
  "zoneName": "Indore Zone"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "6421248a695fbc66ee1a7ce3",
  "role": "ADMIN",
  "firstName": "Niti",
  "email": "niti@vastukala.org",
  "lastName": "Kuril",
  "mobileNo": "9926411111",
  "shortName": "NSK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/6421248a695fbc66ee1a7ce3/
profilePhoto_1679893769249_WhatsApp_Image_20230324_at_20338_PM_1.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "644d108bd4903a28b8e52967",
  "role": "SITEENGINEER+MAKAR+ RATE VERIFIER + CHECKER",
  "firstName": "Somesh",
  "email": "someshnaha111@gmail.com",
  "lastName": "Nahar",
  "mobileNo": "7354486085",
  "designation": "",
  "shortName": "Somesh",
  "workWithDocumentMaker": "60016f965256c07aec8e6dd6",
  "profilePhoto": "users/644d108bd4903a28b8e52967/
profilePhoto_1688544438161_WhatsApp_Image_20230705_at_13245_PM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "62737f2dafd7d55eddee4665",
  "role": "FRONTDESK",
  "firstName": "Dinesh",
  "email": "dinesh.kanere@vastukala.org",
  "lastName": "Kanere",
  "mobileNo": "9826531111",
  "designation": "",
  "shortName": "DKK",
  "workWithDocumentMaker": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "63fc6744ce84bf289ba9f7e0",
  "role": "MAKER",
  "firstName": "Bhupendra ",
  "email": "bhupendresanoriya@gmail.com",
  "lastName": "Sanoriya ",
```

```
"mobileNo": "9981052269",
"designation": "",
"shortName": "BS",
"workWithDocumentMaker": "",
"profilePhoto": "users/63fc6744ce84bf289ba9f7e0/
profilePhoto_1695463251139_image.jpeg"
},
"checker": {
  "_id": "60016f965256c07aec8e6dd6",
  "profilePhoto": "users\\60016f965256c07aec8e6dd6\
\profilePhoto_1622371927126_Akhilesh Photo (2).jpg",
  "firstName": "Akhilesh",
  "lastName": "Yadav",
  "shortName": "AY",
  "email": "akhilesh.yadav@vastukala.org",
  "designation": "Processing Officer",
  "mobileNo": "9545753921",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "type": "EMPLOYEE",
  "workWithDocumentMaker": "6009222ca16fab0f2af9b0bf"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "[N]C.C.I.T/I -14/52/2008-09",
        "label": "Wealth Tax"
      }
    ]
  },
  "type": "EMPLOYEE",
  "_id": "6084131a13f01f158c6ea1f3",
  "PANNo": "AEAPC7114Q",
  "role": "VALUER",
  "firstName": "Sharadkumar",
  "fatherName": "Baburao",
  "email": "cmd@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9422171100",
  "designation": "CMD",
  "registrationNo": [
    {
      "title": {
        "value": "Wealth_Tax",
        "label": "Wealth Tax"
      }
    }
  ],
  "_id": "6084131a13f01f158c6ea1f4",
```

```
        "number": "[N]C.C.I.T/I -14/52/2008-09"
      }
    ],
    "shortName": "SBC",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
  }
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "21.65522177514788",
  "longitude": "74.67930980169315"
},
"geo": {
  "type": "Point",
  "coordinates": [
    74.67930980169315,
    21.65522177514788
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "12/12/2023 12:00 am"
    },
    {
      "dateTime": "12/12/2023 12:00 am"
    }
  ]
},
"visitedDate": [],
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
```

```
"state": {
  "status": true,
  "name": "State",
  "key": "state",
  "value": "Maharashtra",
  "label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Baljhiri",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Ground",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Badwani",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
```

```
"value": "",
"label": false
},
"tahasilNo": {
  "status": true,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "Pansemal",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
```

```
"status": true,
"name": "Street 2",
"key": "street2",
"value": " Pansemal Road ",
"label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "92/1 & 93/2",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
```



```
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
```

```
"name": "SRO",
"key": "SRO",
"value": "",
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "455 111",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
```

```
"isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Fri Jan 05 2024 11:06:22 GMT+0530 (India Standard Time)",
  "number": "2304347",
  "dayCount": "2",
  "monthCount": "49",
  "generatedBy": "60016f965256c07aec8e6dd6"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
```

```
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
```

```
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": true,
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
},
```

```
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```

```
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
}
```



```
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REPORTGENERATED",
"invoices": [],
"paymentId": [],
"_id": "6578569f9e3cbd4940aa34d5",
"ownerName": "Ravindra Motiram Choudhary ",
"ownerPhoneNo": "9617635035",
"appAddress": "\nIndustrial Land & Building bearing Survey No. 92/1 & 93/2,
Pansemal Road \n Gram Baljhiri, Tehsil Pansemal, District Badwani, PIN – 455 111,\n State – Madhya Pradesh, Country – India\n\n\n",
"remark": "contact no is of a banker since it is a NPA case ",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "path": "cases/6578569f9e3cbd4940aa34d5/
document_1702385086472_2133939.pdf",
    "fileName": "document_1702385086472_2133939.pdf",
    "displayStatus": false,
    "id": "200929",
    "uploadedBy": "6421248a695fbc66ee1a7ce3",
    "createdAt": "Tue Dec 12 2023 18:18:31 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "005575",
"createdBy": "6421248a695fbc66ee1a7ce3",
"caseHistory": [
  {
    "id": "257238",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Dec 12 2023 18:18:31 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Ravindra Motiram Choudhary ",
    "phone": "9617635035",
```

```
    "ownershipShare": "",
    "email": "",
    "id": "118591"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6597973e2fcdd54ce8dc73fb",
    "name": "externalImg_1704433470747_Inside_1.jpeg",
    "path": "cases/6578569f9e3cbd4940aa34d5/
externalImg_1704433470747_Inside_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6597973e2fcdd54ce8dc73fc",
    "name": "externalImg_1704433470754_Inside_2.jpeg",
    "path": "cases/6578569f9e3cbd4940aa34d5/
externalImg_1704433470754_Inside_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6597973e2fcdd54ce8dc73fd",
    "name": "externalImg_1704433470765_Inside_3.jpeg",
    "path": "cases/6578569f9e3cbd4940aa34d5/
externalImg_1704433470765_Inside_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6597973e2fcdd54ce8dc73fe",
    "name": "externalImg_1704433470776_Inside_4.jpeg",
```

```
    "path": "cases/6578569f9e3cbd4940aa34d5/
externallmg_1704433470776_Inside_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6597973e2fcdd54ce8dc73ff",
    "name": "externallmg_1704433470785_Inside_5.jpeg",
    "path": "cases/6578569f9e3cbd4940aa34d5/
externallmg_1704433470785_Inside_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6597973e2fcdd54ce8dc7400",
    "name": "externallmg_1704433470795_Inside_6.jpeg",
    "path": "cases/6578569f9e3cbd4940aa34d5/
externallmg_1704433470795_Inside_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6597973e2fcdd54ce8dc7401",
    "name": "externallmg_1704433470806_Inside_7.jpeg",
    "path": "cases/6578569f9e3cbd4940aa34d5/
externallmg_1704433470806_Inside_7.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6597973e2fcdd54ce8dc7402",
    "name": "externallmg_1704433470814_Inside_8.jpeg",
    "path": "cases/6578569f9e3cbd4940aa34d5/
externallmg_1704433470814_Inside_8.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6597973e2fcdd54ce8dc7403",
    "name": "externallmg_1704433470827_Inside_9.jpeg",
    "path": "cases/6578569f9e3cbd4940aa34d5/
externallmg_1704433470827_Inside_9.jpeg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6597973e2fcdd54ce8dc7404",
  "name": "externallmg_1704433470832_Inside_10.jpeg",
  "path": "cases/6578569f9e3cbd4940aa34d5/
externallmg_1704433470832_Inside_10.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6597973e2fcdd54ce8dc7405",
  "name": "externallmg_1704433470838_Outside_1.jpeg",
  "path": "cases/6578569f9e3cbd4940aa34d5/
externallmg_1704433470838_Outside_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6597973e2fcdd54ce8dc7406",
  "name": "externallmg_1704433470851_Outside_2.jpeg",
  "path": "cases/6578569f9e3cbd4940aa34d5/
externallmg_1704433470851_Outside_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6597973e2fcdd54ce8dc7407",
  "name": "externallmg_1704433470860_Outside_3.jpeg",
  "path": "cases/6578569f9e3cbd4940aa34d5/
externallmg_1704433470860_Outside_3.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6597973e2fcdd54ce8dc7408",
  "name": "externallmg_1704433470876_Outside_4.jpeg",
  "path": "cases/6578569f9e3cbd4940aa34d5/
externallmg_1704433470876_Outside_4.jpeg",
  "orientation": "landscape"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6597974b2fcdd54ce8dc743a",
  "name": "externallmg_1704433483251_Outside_5.jpeg",
  "path": "cases/6578569f9e3cbd4940aa34d5/
externallmg_1704433483251_Outside_5.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6597974b2fcdd54ce8dc743b",
  "name": "externallmg_1704433483263_Outside_6.jpeg",
  "path": "cases/6578569f9e3cbd4940aa34d5/
externallmg_1704433483263_Outside_6.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6597974b2fcdd54ce8dc743c",
  "name": "externallmg_1704433483268_Outside_7.jpeg",
  "path": "cases/6578569f9e3cbd4940aa34d5/
externallmg_1704433483268_Outside_7.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6597974b2fcdd54ce8dc743d",
  "name": "externallmg_1704433483277_Outside_8.jpeg",
  "path": "cases/6578569f9e3cbd4940aa34d5/
externallmg_1704433483277_Outside_8.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6597974b2fcdd54ce8dc743e",
  "name": "externallmg_1704433483289_Outside_9.jpeg",
  "path": "cases/6578569f9e3cbd4940aa34d5/
externallmg_1704433483289_Outside_9.jpeg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6597974b2fcdd54ce8dc743f",
  "name": "externallmg_1704433483302_Outside_10.jpeg",
  "path": "cases/6578569f9e3cbd4940aa34d5/
externallmg_1704433483302_Outside_10.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6597974b2fcdd54ce8dc7440",
  "name": "externallmg_1704433483316_Outside_11.jpeg",
  "path": "cases/6578569f9e3cbd4940aa34d5/
externallmg_1704433483316_Outside_11.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6597974b2fcdd54ce8dc7441",
  "name": "externallmg_1704433483328_Outside_12.jpeg",
  "path": "cases/6578569f9e3cbd4940aa34d5/
externallmg_1704433483328_Outside_12.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6597974b2fcdd54ce8dc7442",
  "name": "externallmg_1704433483338_Outside_13.jpeg",
  "path": "cases/6578569f9e3cbd4940aa34d5/
externallmg_1704433483338_Outside_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6597974b2fcdd54ce8dc7443",
  "name": "externallmg_1704433483348_Outside_14.jpeg",
  "path": "cases/6578569f9e3cbd4940aa34d5/
externallmg_1704433483348_Outside_14.jpeg",
  "orientation": "landscape"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6597974b2fcdd54ce8dc7444",
    "name": "externallmg_1704433483350_Outside_15.jpeg",
    "path": "cases/6578569f9e3cbd4940aa34d5/
externallmg_1704433483350_Outside_15.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6597974b2fcdd54ce8dc7445",
    "name": "externallmg_1704433483365_Outside.jpeg",
    "path": "cases/6578569f9e3cbd4940aa34d5/
externallmg_1704433483365_Outside.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659797582fcdd54ce8dc747d",
    "name": "externallmg_1704433496523_Godown_1.jpeg",
    "path": "cases/6578569f9e3cbd4940aa34d5/
externallmg_1704433496523_Godown_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659797582fcdd54ce8dc747e",
    "name": "externallmg_1704433496528_Godown_2.jpeg",
    "path": "cases/6578569f9e3cbd4940aa34d5/
externallmg_1704433496528_Godown_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659797582fcdd54ce8dc747f",
    "name": "externallmg_1704433496532_Labour_Room.jpeg",
    "path": "cases/6578569f9e3cbd4940aa34d5/
externallmg_1704433496532_Labour_Room.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "659797582fcdd54ce8dc7480",
  "name": "externalImg_1704433496542_Office_Cum_Security_Cabin.jpeg",
  "path": "cases/6578569f9e3cbd4940aa34d5/
externalImg_1704433496542_Office_Cum_Security_Cabin.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659797582fcdd54ce8dc7481",
  "name":
"externalImg_1704433496551_WhatsApp_Image_20231216_at_114419_AM.jpeg",
  "path": "cases/6578569f9e3cbd4940aa34d5/
externalImg_1704433496551_WhatsApp_Image_20231216_at_114419_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659797582fcdd54ce8dc7482",
  "name": "externalImg_1704433496562_Working_Area_Shed_1.jpeg",
  "path": "cases/6578569f9e3cbd4940aa34d5/
externalImg_1704433496562_Working_Area_Shed_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659797582fcdd54ce8dc7483",
  "name": "externalImg_1704433496574_Working_Area_Shed_2.jpeg",
  "path": "cases/6578569f9e3cbd4940aa34d5/
externalImg_1704433496574_Working_Area_Shed_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659797582fcdd54ce8dc7484",
  "name": "externalImg_1704433496585_Working_Area_Shed_3.jpeg",
  "path": "cases/6578569f9e3cbd4940aa34d5/
externalImg_1704433496585_Working_Area_Shed_3.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
```



```
"status": false,
  "_id": "659797582fcdd54ce8dc7485",
  "name": "externalImg_1704433496593_Working_Area_Shed_4.jpeg",
  "path": "cases/6578569f9e3cbd4940aa34d5/
externalImg_1704433496593_Working_Area_Shed_4.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659797642fcdd54ce8dc74cc",
  "name": "externalImg_1704433508049_Working_Shed_1.jpeg",
  "path": "cases/6578569f9e3cbd4940aa34d5/
externalImg_1704433508049_Working_Shed_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659797642fcdd54ce8dc74cd",
  "name": "externalImg_1704433508051_Working_Shed_2.jpeg",
  "path": "cases/6578569f9e3cbd4940aa34d5/
externalImg_1704433508051_Working_Shed_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659797642fcdd54ce8dc74ce",
  "name": "externalImg_1704433508053_Working_Shed_3.jpeg",
  "path": "cases/6578569f9e3cbd4940aa34d5/
externalImg_1704433508053_Working_Shed_3.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659797642fcdd54ce8dc74cf",
  "name": "externalImg_1704433508055_Working_Shed_4.jpeg",
  "path": "cases/6578569f9e3cbd4940aa34d5/
externalImg_1704433508055_Working_Shed_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "659797642fcdd54ce8dc74d0",
    "name": "externallmg_1704433508057_Working_Shed_5.jpeg",
    "path": "cases/6578569f9e3cbd4940aa34d5/
externallmg_1704433508057_Working_Shed_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659797642fcdd54ce8dc74d1",
    "name": "externallmg_1704433508058_Working_Shed_6.jpeg",
    "path": "cases/6578569f9e3cbd4940aa34d5/
externallmg_1704433508058_Working_Shed_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659797642fcdd54ce8dc74d2",
    "name": "externallmg_1704433508060_Working_Shed_7.jpeg",
    "path": "cases/6578569f9e3cbd4940aa34d5/
externallmg_1704433508060_Working_Shed_7.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659797642fcdd54ce8dc74d3",
    "name": "externallmg_1704433508062_Working_Shed_8.jpeg",
    "path": "cases/6578569f9e3cbd4940aa34d5/
externallmg_1704433508062_Working_Shed_8.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659797642fcdd54ce8dc74d4",
    "name": "externallmg_1704433508065_Working_Shed_9.jpeg",
    "path": "cases/6578569f9e3cbd4940aa34d5/
externallmg_1704433508065_Working_Shed_9.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659797642fcdd54ce8dc74d5",
```

```
    "name": "externalImg_1704433508067_Working_Shed_10.jpeg",
    "path": "cases/6578569f9e3cbd4940aa34d5/
externalImg_1704433508067_Working_Shed_10.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659797642fcdd54ce8dc74d6",
    "name": "externalImg_1704433508071_Working_Shed_11.jpeg",
    "path": "cases/6578569f9e3cbd4940aa34d5/
externalImg_1704433508071_Working_Shed_11.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659797642fcdd54ce8dc74d7",
    "name": "externalImg_1704433508073_Working_Shed_12.jpeg",
    "path": "cases/6578569f9e3cbd4940aa34d5/
externalImg_1704433508073_Working_Shed_12.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [
  {
    "originalname": "Ravindra So Shri. Motiram Choudhary- Industrial land And
Building.doc",
    "filename": "1702551105482_Ravindra_So_Shri_Motiram_Choudhary_Industrial_la
nd_And_Building.doc",
    "path": "cases/6578569f9e3cbd4940aa34d5/externalDocuments/1702551105482_R
avindra_So_Shri_Motiram_Choudhary_Industrial_land_And_Building.doc",
    "size": "3721216",
    "documentType": {
      "value": "649998c6cab24d3d1a2cc577",
      "label": "Draft Word Report"
    },
    "createdAt": "Thu Dec 14 2023 16:21:46 GMT+0530 (India Standard Time)",
    "uploadedBy": "63fc6744ce84bf289ba9f7e0"
  },
  {
    "originalname": "Ravindra So Shri. Motiram Choudhary- Industrial land And
Building.doc",
    "filename": "1704433378132_Ravindra_So_Shri_Motiram_Choudhary_Industrial_la
nd_And_Building.doc",
    "path": "cases/6578569f9e3cbd4940aa34d5/externalDocuments/1704433378132_R
```

```
avindra_So_Shri_Motiram_Choudhary_Industrial_land_And_Building.doc",
  "size": "3741184",
  "documentType": {
    "value": "64058cdff10de22571d01b37",
    "label": "Final Word Report"
  },
  "createdAt": "Fri Jan 05 2024 11:12:58 GMT+0530 (India Standard Time)",
  "uploadedBy": "60016f965256c07aec8e6dd6"
},
],
"processingDocuments": [
  {
    "originalname": "D. K Jain Report Valuation Report.pdf",
    "filename": "1702551141547_D_K_Jain_Report_Valuation_Report.pdf",
    "path": "cases/6578569f9e3cbd4940aa34d5/
processingDocuments/1702551141547_D_K_Jain_Report_Valuation_Report.pdf",
    "size": "3045462",
    "createdAt": "Thu Dec 14 2023 16:22:24 GMT+0530 (India Standard Time)",
    "uploadedBy": "63fc6744ce84bf289ba9f7e0"
  },
  {
    "originalname": "Ravindra So Shri. Motiram Choudhary - Industrial land And
Building Calculation.xlsx",
    "filename": "1702551142108_Ravindra_So_Shri_Motiram_Choudhary__Industrial_l
and_And_Building_Calculation.xlsx",
    "path": "cases/6578569f9e3cbd4940aa34d5/processingDocuments/1702551142108
_Ravindra_So_Shri_Motiram_Choudhary__Industrial_land_And_Building_Calculation.xl
sx",
    "size": "318398",
    "createdAt": "Thu Dec 14 2023 16:22:24 GMT+0530 (India Standard Time)",
    "uploadedBy": "63fc6744ce84bf289ba9f7e0"
  },
  {
    "originalname": "Sale deed Survey No 92.1 n 93.2 (1).pdf",
    "filename": "1702551142119_Sale_deed_Survey_No__921_n_932_1.pdf",
    "path": "cases/6578569f9e3cbd4940aa34d5/
processingDocuments/1702551142119_Sale_deed_Survey_No__921_n_932_1.pdf",
    "size": "4517879",
    "createdAt": "Thu Dec 14 2023 16:22:24 GMT+0530 (India Standard Time)",
    "uploadedBy": "63fc6744ce84bf289ba9f7e0"
  },
  {
    "originalname": "Valuation .pdf",
    "filename": "1702551142806_Valuation_.pdf",
    "path": "cases/6578569f9e3cbd4940aa34d5/
processingDocuments/1702551142806_Valuation_.pdf",
```

```
"size": "5193523",
"createdAt": "Thu Dec 14 2023 16:22:24 GMT+0530 (India Standard Time)",
"uploadedBy": "63fc6744ce84bf289ba9f7e0"
},
{
"originalname": "Visit Format.pdf",
"filename": "1702551144213_Visit_Format.pdf",
"path": "cases/6578569f9e3cbd4940aa34d5/
processingDocuments/1702551144213_Visit_Format.pdf",
"size": "301126",
"createdAt": "Thu Dec 14 2023 16:22:24 GMT+0530 (India Standard Time)",
"uploadedBy": "63fc6744ce84bf289ba9f7e0"
},
{
"originalname": "Diversion Order 93-2.pdf",
"filename": "1704433440673_Diversion_Order_932.pdf",
"path": "cases/6578569f9e3cbd4940aa34d5/
processingDocuments/1704433440673_Diversion_Order_932.pdf",
"size": "1181449",
"createdAt": "Fri Jan 05 2024 11:14:00 GMT+0530 (India Standard Time)",
"uploadedBy": "60016f965256c07aec8e6dd6"
},
{
"originalname": "Previous Valuation Report (1).pdf",
"filename": "1704433440699_Previous_Valuation_Report_1.pdf",
"path": "cases/6578569f9e3cbd4940aa34d5/
processingDocuments/1704433440699_Previous_Valuation_Report_1.pdf",
"size": "3045462",
"createdAt": "Fri Jan 05 2024 11:14:00 GMT+0530 (India Standard Time)",
"uploadedBy": "60016f965256c07aec8e6dd6"
},
{
"originalname": "Previous Valuation Report (2).pdf",
"filename": "1704433440802_Previous_Valuation_Report_2.pdf",
"path": "cases/6578569f9e3cbd4940aa34d5/
processingDocuments/1704433440802_Previous_Valuation_Report_2.pdf",
"size": "5193523",
"createdAt": "Fri Jan 05 2024 11:14:00 GMT+0530 (India Standard Time)",
"uploadedBy": "60016f965256c07aec8e6dd6"
},
{
"originalname": "Ravindra So Shri. Motiram Choudhary - Industrial land And
Building Calculation.xlsx",
"filename": "1704433440894_Ravindra_So_Shri_Motiram_Choudhary__Industrial_l
and_And_Building_Calculation.xlsx",
"path": "cases/6578569f9e3cbd4940aa34d5/processingDocuments/1704433440894
```

_Ravindra_So_Shri_Motiram_Choudhary__Industrial_land_And_Building_Calculation.xlsx",

"size": "320626",
"createdAt": "Fri Jan 05 2024 11:14:00 GMT+0530 (India Standard Time)",
"uploadedBy": "60016f965256c07aec8e6dd6"

},
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2023-12-12T12:48:31.376Z",
"updatedAt": "2024-01-05T05:45:08.151Z",
"__v": 0,
"invoiceId": "6578569f9e3cbd4940aa34db",
"assignmentType": {
"value": "Commercial",
"label": "Commercial"

},
"fullAddress": "Industrial Land and Building No. Ground Floor, New/Current Survey No. 92/1 & 93/2, Pansemal Road , Village - Baljhiri, Tahasil Pansemal, District - Badwani, 455 111, State - Maharashtra, India",

"updatedBy": "60016f965256c07aec8e6dd6",
"addressForMap": "",
"caseReferredBy": "6421248a695fbc66ee1a7ce3",
"contactPersonName": "Ravindra Motiram Choudhary ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9617635035"

}

Name	Length	Width	Total
------	--------	-------	-------

Composition :

Other

Composition :
