

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9e6"
    },
    "type": "CREDITOFFICER",
    "_id": "64c8b0a2a5c3051014f5f888",
    "firstName": "Priti",
    "lastName": "Madam",
    "mobileNo": "",
    "workMobileNo": "9773028294",
    "email": "preeti.shinde@comsosbank.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "6418456a96b58848585f8cb2",
"name": "Thane",
"email": "thane@vastukala.com",
"phone": "1234567890",
"address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
"city": "Thane",
"shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9e6",
  "branchCode": "000014",
  "type": "BRANCH",
  "name": "Dombivali (East) Branch",
  "email": "dombivali@cosmosbank.in",
  "mobileNo": "02512435618",
  "alternateMobileNo": "",
  "address": "Sindhurg C.H.S., Ground Floor, Tilak Chowk, Tilak Nagar, Dombivali
(East), Taluka Kalyan, District Thane - 400605, State - Maharashtra, Country - India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "656aa949cebbe1714411d21b",
  "role": "FRONTDESK",
  "firstName": "Priyanka",
  "email": "thane@vastukala.org",
  "lastName": "Pawar",
  "mobileNo": "8928414480",
  "shortName": "PCP",
  "workWithDocumentMaker": "627222afafd7d55eddeddd82"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "64e5a649daae6a1c98101989",
  "role": "SITEENGINEER",
  "firstName": "Sameer",
  "email": "sameeryp2010@gmail.com",
  "lastName": "Parab",
  "mobileNo": "8291009567",
  "designation": "Site Engineer",
  "shortName": "Sameer",
  "workWithDocumentMaker": "62ea09ea4e679b264caf07d7"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
  "designation": "",
  "shortName": "PS",
```

```
"workWithDocumentMaker": "60f915d3f3dd69653a592199",
"profilePhoto": "users/627222afafd7d55eddedd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
        "number": "CAT-I-F-1763"
      },
      {
        "title": {
          "value": "Chartered_Engineer",
          "label": "Chartered Engineer"
        },
        "_id": "60af80072ffdf65bcd658653",
        "number": "AM161706-3"
      }
    ]
  }
]
```

```
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.203341",
  "longitude": "73.120605"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.120605,
    19.203341
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-12-14",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-12-14",
      "remark": ""
    }
  ]
}
```

```
    "status": "COMPLETED",
    "dateTime": "2023-12-14",
    "remark": ""
  },
  {
    "status": "COMPLETED",
    "dateTime": "2023-12-14",
    "remark": ""
  }
],
"schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false,
  "area": "860.00",
  "rate": "10002.00",
  "yearOfConstruction": "2021",
  "compositionOfBuilding": "Stilt + Podium + 1st to 23rd Upper Floors"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Davadi",
    "label": true
  }
},
```

```
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "2",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "08",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Dombivli (East)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kalyan",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
```

```
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Catalina",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
```



```
"status": true,
"name": "Project Name",
"key": "projectName",
"value": "Regancy Anantam ",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "101/3A, 3B, 3K, 3D, 47/1, 44/2 & 48",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "207",
```

```
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
```

```
"name": "Postal Code",
"key": "postalCode",
"value": "",
"label": false
},
"suburb": {
"status": false,
"name": "Suburb",
"key": "suburb",
"value": "",
"label": false
}
},
"general": {
"unitBoundaries": {
"isDisplay": false
}
},
"igrFinalRate": {
"floorRatePercentage": "0.00"
},
"outgoingDetail": {
"monthlyRent": ""
},
"siteMeasurement": {
"isSiteVisitAllowed": true
},
"finalPlinthArea": {
"area": "0.00"
},
"routeMap": {
"finalLatLng": {
"coordinates": []
},
"locationMapImg": []
},
"outward": {
"status": false,
"remark": "SYSTEM_GENERATED"
},
"rateVerify": {
"status": false
},
"underConstruction": {
"rccFootingFoundation": {
"label": "RCC Footing/Foundation",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"rccPlinth": {
"label": "RCC Plinth",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
"label": "Full Building Rcc",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
}
```

```
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
```

```
"max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
    "title": "Interior Decorations",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
```



```
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"_id": "65799e4c3fcadc6777685e6c",
"ownerName": "Sheth Arti Chinar",
"ownerPhoneNo": "9833894243",
"fullAddress": "Residential Flat No. 207, 2nd Floor, Building No 08, Catalina, Regancy
Anantam , Village - Davadi, Taluka - Kalyan, District - Thane, Dombivli (East), State -
Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
  },
  "inputs": {
    "documentDate": "29/10/2021",
    "from": {
      "value": "Promoter",
      "label": "Promoter"
    }
  }
]
```

```
    },
    "Promoter": "M/s. Regency Nirman Limited.",
    "to": {
      "value": "purchaser",
      "label": "purchaser"
    },
    "purchaser": "Sheth Arti Chinar",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "12134/2021"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1702469189853_Aarati_Chinar_Sheth_Cos_D.pdf",
  "path": "cases/65799e4c3fcadc6777685e6c/
document_1702469189853_Aarati_Chinar_Sheth_Cos_D.pdf",
  "id": "627371",
  "uploadedBy": "656aa949cebbe1714411d21b",
  "createdAt": "Wed Dec 13 2023 17:36:36 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1279aa6d152c1801b3d4",
    "label": "Amended Commencement Certificate"
  },
  "inputs": {
    "documentDate": "09/04/2021",
    "nameOfApprovingAuthority": {
      "value": "Kalyan_Dombivli_Municipal_Corporation",
      "label": "Kalyan Dombivli Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "KDMC / TPD / BP / 27 Village / 2018 – 2019 / 14 / 14 "
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1702627220512_CC.pdf",
  "path": "cases/65799e4c3fcadc6777685e6c/document_1702627220512_CC.pdf",
  "id": "917120",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Fri Dec 15 2023 13:39:20 GMT+0530 (India Standard Time)"
}
```

```
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "15/07/2021",
    "nameOfApprovingAuthority": {
      "value": "Kalyan_Dombivli_Municipal_Corporation",
      "label": "Kalyan Dombivli Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "KDMC / TPD / CC / 27 Village / 164"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1702627268383_OC.pdf",
"path": "cases/65799e4c3fcadc6777685e6c/document_1702627268383_OC.pdf",
"id": "644366",
"uploadedBy": "627222afafd7d55eddedd82",
"createdAt": "Fri Dec 15 2023 13:39:20 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2e8",
    "label": "Layout Plan"
  },
  "inputs": {
    "documentDate": "09/04/2021",
    "nameOfApprovingAuthority": {
      "value": "Kalyan_Dombivli_Municipal_Corporation",
      "label": "Kalyan Dombivli Municipal Corporation"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  },
  "Document_No": "KDMC / TPD / BP / 27 Village / 2018 – 2019 / 14 / 14 "
},
"isHardCopy": false,
"displayStatus": false,
"fileName":
"document_1702627322301_5_Copy_of_Layout_Approval_in_case_of_layout_23.pdf",
```

```
"path": "cases/65799e4c3fcadc6777685e6c/
document_1702627322301_5_Copy_of_Layout_Approval_in_case_of_layout_23.pdf",
"id": "849959",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Fri Dec 15 2023 13:39:20 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "09/09/2021",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "P51700020186"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1702627760603_P51700020186.pdf",
"path": "cases/65799e4c3fcadc6777685e6c/
document_1702627760603_P51700020186.pdf",
"id": "819875",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Fri Dec 15 2023 13:39:20 GMT+0530 (India Standard Time)"
}
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "005600",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
  {
    "id": "668828",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Dec 13 2023 17:36:36 GMT+0530 (India Standard Time)"
  }
]
```

```
],
"owners": [
  {
    "name": "Sheth Arti Chinar",
    "phone": "9833894243",
    "ownershipShare": "",
    "email": "",
    "id": "215332"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657b1e8e3fcadc67776a55b3",
    "name": "externallmg_1702567427429_1702567512648_image_0.jpeg",
    "path": "cases/65799e4c3fcadc6777685e6c/externallmg_1702567427429_1702567512648_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657b1e8e3fcadc67776a55b4",
    "name": "externallmg_1702567434649_1702567512648_image_1.jpeg",
    "path": "cases/65799e4c3fcadc6777685e6c/externallmg_1702567434649_1702567512648_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657b1e8e3fcadc67776a55b5",
    "name": "externallmg_1702567447309_1702567512648_image_2.jpeg",
    "path": "cases/65799e4c3fcadc6777685e6c/externallmg_1702567447309_1702567512648_image_2.jpeg",
    "orientation": "landscape"
  },
],
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657b1e8e3fcadc67776a55b6",
  "name": "externallmg_1702567455789_1702567512648_image_3.jpeg",
  "path": "cases/65799e4c3fcadc6777685e6c/
externallmg_1702567455789_1702567512648_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657b1e8e3fcadc67776a55b7",
  "name": "externallmg_1702567466294_1702567512648_image_4.jpeg",
  "path": "cases/65799e4c3fcadc6777685e6c/
externallmg_1702567466294_1702567512648_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657b1e8e3fcadc67776a55b8",
  "name": "externallmg_1702567477954_1702567512648_image_5.jpeg",
  "path": "cases/65799e4c3fcadc6777685e6c/
externallmg_1702567477954_1702567512648_image_5.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657b1e8e3fcadc67776a55b9",
  "name": "externallmg_1702567491759_1702567512648_image_6.jpeg",
  "path": "cases/65799e4c3fcadc6777685e6c/
externallmg_1702567491759_1702567512648_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657b1e8e3fcadc67776a55ba",
  "name": "externallmg_1702567507609_1702567512648_image_7.jpeg",
  "path": "cases/65799e4c3fcadc6777685e6c/
externallmg_1702567507609_1702567512648_image_7.jpeg",
  "orientation": "landscape"
},
{

```

```
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "657b1e8e3fcadc67776a55bb",
"name": "externallmg_1702567524413_1702567512648_image_9.jpeg",
"path": "cases/65799e4c3fcadc6777685e6c/
externallmg_1702567524413_1702567512648_image_9.jpeg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "657b1e8e3fcadc67776a55bc",
"name": "externallmg_1702567527045_1702567512648_image_10.jpeg",
"path": "cases/65799e4c3fcadc6777685e6c/
externallmg_1702567527045_1702567512648_image_10.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "657b1e8e3fcadc67776a55bd",
"name": "externallmg_1702567527955_1702567512648_image_12.jpeg",
"path": "cases/65799e4c3fcadc6777685e6c/
externallmg_1702567527955_1702567512648_image_12.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "657b1e8e3fcadc67776a55be",
"name": "externallmg_1702567528524_1702567512649_image_13.jpeg",
"path": "cases/65799e4c3fcadc6777685e6c/
externallmg_1702567528524_1702567512649_image_13.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "657b1e8e3fcadc67776a55bf",
"name": "externallmg_1702567529089_1702567512649_image_14.jpeg",
"path": "cases/65799e4c3fcadc6777685e6c/
externallmg_1702567529089_1702567512649_image_14.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "657b1e8e3fcadc67776a55c0",
  "name": "externallmg_1702567530074_1702567512649_image_15.jpeg",
  "path": "cases/65799e4c3fcadc6777685e6c/
externallmg_1702567530074_1702567512649_image_15.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657b1e8e3fcadc67776a55c1",
  "name": "externallmg_1702567530714_1702567512649_image_16.jpeg",
  "path": "cases/65799e4c3fcadc6777685e6c/
externallmg_1702567530714_1702567512649_image_16.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657b1e8e3fcadc67776a55c2",
  "name": "externallmg_1702567531254_1702567512649_image_17.jpeg",
  "path": "cases/65799e4c3fcadc6777685e6c/
externallmg_1702567531254_1702567512649_image_17.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "657b1e8e3fcadc67776a55c3",
  "name": "externallmg_1702567333244_1702567419595_image_0.jpeg",
  "path": "cases/65799e4c3fcadc6777685e6c/
externallmg_1702567333244_1702567419595_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "657b1e8e3fcadc67776a55c4",
  "name": "externallmg_1702567354223_1702567419595_image_1.jpeg",
  "path": "cases/65799e4c3fcadc6777685e6c/
externallmg_1702567354223_1702567419595_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
```



```
    "_id": "657b1e8e3fcadc67776a55c5",
    "name": "externalimg_1702567375531_1702567419595_image_2.jpeg",
    "path": "cases/65799e4c3fcadc6777685e6c/
externalimg_1702567375531_1702567419595_image_2.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "cosmos - calculation - manish.xlsx",
    "filename": "1702618345885_cosmos__calculation__manish.xlsx",
    "path": "cases/65799e4c3fcadc6777685e6c/
processingDocuments/1702618345885_cosmos__calculation__manish.xlsx",
    "size": "16820",
    "createdAt": "Fri Dec 15 2023 11:02:27 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "reference report.pdf",
    "filename": "1702618345887_reference_report.pdf",
    "path": "cases/65799e4c3fcadc6777685e6c/
processingDocuments/1702618345887_reference_report.pdf",
    "size": "18455031",
    "createdAt": "Fri Dec 15 2023 11:02:27 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "summary - sheth.xlsx",
    "filename": "1702618347473_summary__sheth.xlsx",
    "path": "cases/65799e4c3fcadc6777685e6c/
processingDocuments/1702618347473_summary__sheth.xlsx",
    "size": "2017696",
    "createdAt": "Fri Dec 15 2023 11:02:27 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2023-12-13T12:06:36.715Z",
"updatedAt": "2023-12-15T08:09:20.721Z",
"__v": 0,
"invoiceId": "65799e4c3fcadc6777685e72",
"updatedBy": "627222afafd7d55eddedd82",
"addressForMap": "",
```

"caseReferredBy": "6410199a140f140ffc59b58c",
"contactPersonName": "Sheth Arti Chinar",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9833894243"

}

Name	Length	Width	Total
Composition :			
Other Composition :			