

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9e6"
    },
    "type": "CREDITOFFICER",
    "_id": "64c8b0a2a5c3051014f5f888",
    "firstName": "Priti",
    "lastName": "Madam",
    "mobileNo": "",
    "workMobileNo": "9773028294",
    "email": "preeti.shinde@comsosbank.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "6418456a96b58848585f8cb2",
"name": "Thane",
"email": "thane@vastukala.com",
"phone": "1234567890",
"address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
"city": "Thane",
"shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9e6",
  "branchCode": "000014",
  "type": "BRANCH",
  "name": "Dombivali (East) Branch",
  "email": "dombivali@cosmosbank.in",
  "mobileNo": "02512435618",
  "alternateMobileNo": "",
  "address": "Sindhurg C.H.S., Ground Floor, Tilak Chowk, Tilak Nagar, Dombivali
(East), Taluka Kalyan, District Thane - 400605, State - Maharashtra, Country - India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "656aa949cebbe1714411d21b",
  "role": "FRONTDESK",
  "firstName": "Priyanka",
  "email": "thane@vastukala.org",
  "lastName": "Pawar",
  "mobileNo": "8928414480",
  "shortName": "PCP",
  "workWithDocumentMaker": "627222afafd7d55eddeddd82"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "6572cc17d4a67a1d0041f807",
  "role": "SITEENGINEER",
  "firstName": "Laxmi ",
  "email": "wadkarlaxmi1009@gmail.com",
  "lastName": "Salvi (Wadkar)          ",
  "mobileNo": "7057004925",
  "designation": "Site Engg",
  "shortName": "LS",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordinatiion",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
  "designation": "",
  "shortName": "PS",
```

```
"workWithDocumentMaker": "60f915d3f3dd69653a592199",
"profilePhoto": "users/627222afafd7d55eddedd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
        "number": "CAT-I-F-1763"
      },
      {
        "title": {
          "value": "Chartered_Engineer",
          "label": "Chartered Engineer"
        },
        "_id": "60af80072ffdf65bcd658653",
        "number": "AM161706-3"
      }
    ]
  }
]
```

```
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.223654579528905",
  "longitude": "73.10952735120786"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "16/12/2023 12:00 am"
    }
  ]
},
"visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
```

```
"finalMeasurementType": "Sq. Ft.",
"underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Kanchangaon",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "5",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
    "value": "Thane",
    "label": true
  },
}
```

```
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Dombivli (East)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kalyan",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shree Shankheshwar Villa Co. - Op. Hsg. Soc. Ltd",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
```

```
"value": "Bhoirwadi",
"label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "R. B. T. school, Khambalpada",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": true,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "101/ (Part)",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "29/4, 29/1, 29/3, 29/2 & 29/5",
  "label": true
},
"hissaNo": {
```



```
"status": false,
"name": "Hissa No.",
"key": "hissaNo",
"value": "",
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "504",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
```

```
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
```

```
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
```

```
    "percentage": "0.00",
    "isHideFloor": true,
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
```

```
"title": "Showcases",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
```



```
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentId": [],
"_id": "657d30743fcadc67776c813d",
"ownerName": "Mr. Resham Viren Shah & Mrs. Gopika Resham Shah",
"ownerPhoneNo": "9819209234",
"fullAddress": " Flat No. 504, 5th Floor, Wing - A, Shree Shankheshwar Villa Co. - Op.
Hsg. Soc. Ltd, R. B. T. school, Khambalpada, Bhoirwadi, Village - Kanchangaon, Taluka
- Kalyan, District - Thane, Dombivli (East)",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "12/12/2023",
      "from": {
        "value": "Transferor",
        "label": "Transferor"
      },
      "Transferor": "Mr. Bhagesh Eknath Gavli",
      "to": {
        "value": "transferee",
        "label": "transferee"
      },
      "transferee": "Mr. Resham Viren Shah & Mrs. Gopika Resham Shah",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "18014/2023"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1702703192609_115305.pdf",
    "path": "cases/657d30743fcadc67776c813d/
document_1702703192609_115305.pdf",
    "id": "483727",
    "uploadedBy": "656aa949cebbe1714411d21b",
    "createdAt": "Sat Dec 16 2023 10:37:00 GMT+0530 (India Standard Time)"
  }
]
```

```
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "30/07/2015",
    "nameOfApprovingAuthority": {
      "value": "Kalyan_Dombivli_Municipal_Corporation",
      "label": "Kalyan Dombivli Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "KDMC / NRV / CC / DV / 102 "
},
"isHardCopy": false,
"displayStatus": true,
"path": "cases/657d30743fcadc67776c813d/
document_1702901127571_125890.pdf",
"fileName": "document_1702901127571_125890.pdf",
"id": "934617",
"uploadedBy": "627222afafd7d55eddedd82",
"createdAt": "Mon Dec 18 2023 17:36:49 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "20/03/2014",
    "nameOfApprovingAuthority": {
      "value": "Kalyan_Dombivli_Municipal_Corporation",
      "label": "Kalyan Dombivli Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "KDMC / NRV / BP / DV / 2012 - 2013 / 32 / 39 "
},
"isHardCopy": false,
"displayStatus": true,
```

```
    "fileName": "document_1702901209662_137894.pdf",
    "path": "cases/657d30743fcadc67776c813d/
document_1702901209662_137894.pdf",
    "id": "804963",
    "uploadedBy": "627222afafd7d55eddeddd82",
    "createdAt": "Mon Dec 18 2023 17:36:49 GMT+0530 (India Standard Time)"
  }
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "005673",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
  {
    "id": "738089",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Dec 16 2023 10:37:00 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Resham Viren Shah & Mrs. Gopika Resham Shah",
    "phone": "9819209234",
    "ownershipShare": "",
    "email": "",
    "id": "621507"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657fe8e965d49d78457ae5ce",
    "name":
"externallmg_1702881513308_WhatsApp_Image_20231218_at_113009_AM.jpeg",
```

```
    "path": "cases/657d30743fcadc67776c813d/
externallmg_1702881513308_WhatsApp_Image_20231218_at_113009_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657fe8e965d49d78457ae5cf",
    "name":
"externallmg_1702881513311_WhatsApp_Image_20231218_at_113010_AM_1.jpeg",
    "path": "cases/657d30743fcadc67776c813d/
externallmg_1702881513311_WhatsApp_Image_20231218_at_113010_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657fe8e965d49d78457ae5d0",
    "name":
"externallmg_1702881513315_WhatsApp_Image_20231218_at_113010_AM.jpeg",
    "path": "cases/657d30743fcadc67776c813d/
externallmg_1702881513315_WhatsApp_Image_20231218_at_113010_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657fe8e965d49d78457ae5d1",
    "name":
"externallmg_1702881513317_WhatsApp_Image_20231218_at_113011_AM_1.jpeg",
    "path": "cases/657d30743fcadc67776c813d/
externallmg_1702881513317_WhatsApp_Image_20231218_at_113011_AM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657fe8e965d49d78457ae5d2",
    "name":
"externallmg_1702881513322_WhatsApp_Image_20231218_at_113011_AM_2.jpeg",
    "path": "cases/657d30743fcadc67776c813d/
externallmg_1702881513322_WhatsApp_Image_20231218_at_113011_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "657fe8e965d49d78457ae5d3",
    "name":
"externallmg_1702881513324_WhatsApp_Image_20231218_at_113011_AM.jpeg",
    "path": "cases/657d30743fcadc67776c813d/
externallmg_1702881513324_WhatsApp_Image_20231218_at_113011_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657fe8e965d49d78457ae5d4",
    "name":
"externallmg_1702881513327_WhatsApp_Image_20231218_at_113012_AM_1.jpeg",
    "path": "cases/657d30743fcadc67776c813d/
externallmg_1702881513327_WhatsApp_Image_20231218_at_113012_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657fe8e965d49d78457ae5d5",
    "name":
"externallmg_1702881513329_WhatsApp_Image_20231218_at_113012_AM.jpeg",
    "path": "cases/657d30743fcadc67776c813d/
externallmg_1702881513329_WhatsApp_Image_20231218_at_113012_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657fe8e965d49d78457ae5d6",
    "name":
"externallmg_1702881513331_WhatsApp_Image_20231218_at_113013_AM_1.jpeg",
    "path": "cases/657d30743fcadc67776c813d/
externallmg_1702881513331_WhatsApp_Image_20231218_at_113013_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657fe8e965d49d78457ae5d7",
    "name":
"externallmg_1702881513337_WhatsApp_Image_20231218_at_113013_AM_2.jpeg",
    "path": "cases/657d30743fcadc67776c813d/
externallmg_1702881513337_WhatsApp_Image_20231218_at_113013_AM_2.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657fe8e965d49d78457ae5d8",
    "name":
"externallmg_1702881513340_WhatsApp_Image_20231218_at_113013_AM.jpeg",
    "path": "cases/657d30743fcadc67776c813d/
externallmg_1702881513340_WhatsApp_Image_20231218_at_113013_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657fe90365d49d78457ae631",
    "name":
"externallmg_1702881539064_WhatsApp_Image_20231218_at_113014_AM.jpeg",
    "path": "cases/657d30743fcadc67776c813d/
externallmg_1702881539064_WhatsApp_Image_20231218_at_113014_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657fe90365d49d78457ae632",
    "name":
"externallmg_1702881539067_WhatsApp_Image_20231218_at_113015_AM_1.jpeg",
    "path": "cases/657d30743fcadc67776c813d/
externallmg_1702881539067_WhatsApp_Image_20231218_at_113015_AM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657fe90365d49d78457ae633",
    "name":
"externallmg_1702881539069_WhatsApp_Image_20231218_at_113015_AM_2.jpeg",
    "path": "cases/657d30743fcadc67776c813d/
externallmg_1702881539069_WhatsApp_Image_20231218_at_113015_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657fe90365d49d78457ae634",
```

```
"name":
"externallmg_1702881539070_WhatsApp_Image_20231218_at_113015_AM.jpeg",
  "path": "cases/657d30743fcadc67776c813d/
externallmg_1702881539070_WhatsApp_Image_20231218_at_113015_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657fe90365d49d78457ae635",
  "name":
"externallmg_1702881539075_WhatsApp_Image_20231218_at_113016_AM_1.jpeg",
  "path": "cases/657d30743fcadc67776c813d/
externallmg_1702881539075_WhatsApp_Image_20231218_at_113016_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657fe90365d49d78457ae636",
  "name":
"externallmg_1702881539076_WhatsApp_Image_20231218_at_113016_AM.jpeg",
  "path": "cases/657d30743fcadc67776c813d/
externallmg_1702881539076_WhatsApp_Image_20231218_at_113016_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657fe90365d49d78457ae637",
  "name":
"externallmg_1702881539079_WhatsApp_Image_20231218_at_113017_AM_2.jpeg",
  "path": "cases/657d30743fcadc67776c813d/
externallmg_1702881539079_WhatsApp_Image_20231218_at_113017_AM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657fe90365d49d78457ae638",
  "name":
"externallmg_1702881539080_WhatsApp_Image_20231218_at_113017_AM.jpeg",
  "path": "cases/657d30743fcadc67776c813d/
externallmg_1702881539080_WhatsApp_Image_20231218_at_113017_AM.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657fe90365d49d78457ae639",
  "name":
"externallmg_1702881539083_WhatsApp_Image_20231218_at_113018_AM_1.jpeg",
  "path": "cases/657d30743fcadc67776c813d/
externallmg_1702881539083_WhatsApp_Image_20231218_at_113018_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657fe90365d49d78457ae63a",
  "name":
"externallmg_1702881539085_WhatsApp_Image_20231218_at_113018_AM.jpeg",
  "path": "cases/657d30743fcadc67776c813d/
externallmg_1702881539085_WhatsApp_Image_20231218_at_113018_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657fe90f65d49d78457ae687",
  "name":
"externallmg_1702881551119_WhatsApp_Image_20231218_at_113017_AM_1.jpeg",
  "path": "cases/657d30743fcadc67776c813d/
externallmg_1702881551119_WhatsApp_Image_20231218_at_113017_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657fe90f65d49d78457ae688",
  "name":
"externallmg_1702881551123_WhatsApp_Image_20231218_at_113019_AM_2.jpeg",
  "path": "cases/657d30743fcadc67776c813d/
externallmg_1702881551123_WhatsApp_Image_20231218_at_113019_AM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657fe90f65d49d78457ae689",
  "name":
"externallmg_1702881551125_WhatsApp_Image_20231218_at_113019_AM.jpeg",
```



```
    "path": "cases/657d30743fcadc67776c813d/
externallmg_1702881551125_WhatsApp_Image_20231218_at_113019_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657fe90f65d49d78457ae68a",
    "name":
"externallmg_1702881551126_WhatsApp_Image_20231218_at_113020_AM.jpeg",
    "path": "cases/657d30743fcadc67776c813d/
externallmg_1702881551126_WhatsApp_Image_20231218_at_113020_AM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation Sheet NEW COSMOS.xlsx",
    "filename": "1702884436047_Calculation_Sheet_NEW_COSMOS.xlsx",
    "path": "cases/657d30743fcadc67776c813d/
processingDocuments/1702884436047_Calculation_Sheet_NEW_COSMOS.xlsx",
    "size": "3221789",
    "createdAt": "Mon Dec 18 2023 12:57:16 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2023-12-16T05:07:01.021Z",
"updatedAt": "2023-12-18T12:06:49.761Z",
"__v": 0,
"invoiceId": "657d30753fcadc67776c8146",
"updatedBy": "627222afafd7d55eddeddd82",
"addressForMap": "",
"caseReferredBy": "6410199a140f140ffc59b58c",
"contactPersonName": "Mr. Resham Viren Shah & Mrs. Gopika Resham Shah",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9819209234"
}
```

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			