

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63b26652191f7b344b008cac"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f66be948726cc141b93",
    "email": "sbi.04380@sbi.co.in",
    "firstName": "BHAUSAHEB ",
    "mobileNo": "",
    "workMobileNo": "9167778443",
    "lastName": "PATIL"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "50000000",
    "discussWithPerson": "BHAUSAHEB ",
    "expectedFees": 25000,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63b26652191f7b344b008cac",
  "name": "HLST BKC",
  "branchCode": "",
  "mobileNo": "022-26445021",
  "alternateMobileNo": "",
  "email": "sbi.04380@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "HLST Synergy Building, 1st floor, C – 6, G Block\nBandra Kurla
Complex, Bandra (East),\nMumbai – 400 051."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "62723addafd7d55eddeddfe4",
```

```
"role": "PICKUPPERSON",
"firstName": "Ramkrishna ",
"email": "rampatakar1991@gmail.com",
"lastName": "Patkar",
"mobileNo": "7045746060",
"shortName": "RP",
"workWithDocumentMaker": "",
"profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "60f949ce45132d6a6bddbcc3",
"role": "SITEENGINEER",
"firstName": "Tushar ",
"email": "tusharbhuwad90@gmail.com",
"lastName": "Bhuwad",
"mobileNo": "9082053889",
"designation": "",
"shortName": "TSB",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f949ce45132d6a6bddbcc3/
profilePhoto_1668058314746_WhatsApp_Image_20221110_at_105931_AM.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"maker": null,
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
]
}
]
```

```
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
```

```
\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
],
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.199075644700937",
  "longitude": "72.83038527329958"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.83038527329958,
    19.199075644700937
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "30/12/2023 11:00 am"
    },
    {
      "dateTime": "30/12/2023 12:00 am"
    }
  ]
},
"visitedDate": [],
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
```

```
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Chincholi",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "3",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "A-46",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
```

```
"status": false,
"name": "Tahasil",
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Prashant CHSL",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Gokuldhama",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Gen A K Vaidhya Marg",
```

```
"label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
```



```
"name": "CTS No.",
"key": "CTSNo",
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "301",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
}
```

```
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Borivali West",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
```

```
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
```

```
"selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
```

```
"title": "Kitchen arrangements",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD",
  "Name": "Lead",
  "Value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
```



```
"paymentId": [],
"_id": "658fab20545844510d0b5a65",
"ownerName": "Heena wadhwanii ",
"ownerPhoneNo": "9779586571",
"appAddress": "flat no 301, bldg no -A 46, Prashant co operative housing society Ltd,
Gokuldham, gen.A.k Vaidya Marg, goregaon East ",
"remark": "proposed byear case \n\nStaff case ",
"documents": [
  {
    "documentType": {
      "label": "Any Other Document",
      "value": "60ae124aaa6d152c1801b2f7"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/658fab20545844510d0b5a65/
document_1703914234278_.1703914329138_01",
    "fileName": "document_1703914234278_.1703914329138_01",
    "id": "361370",
    "uploadedBy": "62723addafd7d55eddeddfe4",
    "createdAt": "Sat Dec 30 2023 11:01:12 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1703917435342_2_Society_Registration_Certificate_Prasha
nt_Society_1.pdf",
    "path": "cases/658fab20545844510d0b5a65/document_1703917435342_2_Society
_Regisration_Certificate_Prashant_Society_1.pdf",
    "id": "197480",
    "uploadedBy": "62691c48afd7d55eddecfda3",
    "createdAt": "Sat Dec 30 2023 11:55:59 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1703917445586_4_Society_Assessment_Bill_Prashant_So
ciety_March_2022.pdf",
```

```
"path": "cases/658fab20545844510d0b5a65/document_1703917445586_4_Society
_Assessment_Bill_Prashant_Society_March_2022.pdf",
"id": "761090",
"uploadedBy": "62691c48afd7d55eddecfda3",
"createdAt": "Sat Dec 30 2023 11:55:59 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName":
"document_1703917454961_7_Architect_Certificate_Prashant_Society.pdf",
  "path": "cases/658fab20545844510d0b5a65/
document_1703917454961_7_Architect_Certificate_Prashant_Society.pdf",
  "id": "810120",
  "uploadedBy": "62691c48afd7d55eddecfda3",
  "createdAt": "Sat Dec 30 2023 11:55:59 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName":
"document_1703917465649_3_Property_Card_Extract_Prashant_Society.pdf",
  "path": "cases/658fab20545844510d0b5a65/
document_1703917465649_3_Property_Card_Extract_Prashant_Society.pdf",
  "id": "103933",
  "uploadedBy": "62691c48afd7d55eddecfda3",
  "createdAt": "Sat Dec 30 2023 11:55:59 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName":
"document_1703917479683_3_Property_Card_Extract_Prashant_Society.pdf",
  "path": "cases/658fab20545844510d0b5a65/
document_1703917479683_3_Property_Card_Extract_Prashant_Society.pdf",
```

```
"id": "932030",
"uploadedBy": "62691c48afd7d55eddecfda3",
"createdAt": "Sat Dec 30 2023 11:55:59 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1703917491226_5_Society_Assessment_Bill_Receipt_Prashant_Society.pdf",
  "path": "cases/658fab20545844510d0b5a65/document_1703917491226_5_Society_Assessment_Bill_Receipt_Prashant_Society.pdf",
  "id": "153477",
  "uploadedBy": "62691c48afd7d55eddecfda3",
  "createdAt": "Sat Dec 30 2023 11:55:59 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1703917508237_6_1st__last_page_of_Prashant_Society_Conveyance_Deed_dated_25sept1989.pdf",
  "path": "cases/658fab20545844510d0b5a65/document_1703917508237_6_1st__last_page_of_Prashant_Society_Conveyance_Deed_dated_25sept1989.pdf",
  "id": "311620",
  "uploadedBy": "62691c48afd7d55eddecfda3",
  "createdAt": "Sat Dec 30 2023 11:55:59 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1703917521925_A46_Prashant_CHS_Occupancy_Certificate_number_CE_3647_BSII_AP_dated_15_Dec_1984.pdf",
  "path": "cases/658fab20545844510d0b5a65/document_1703917521925_A46_Prashant_CHS_Occupancy_Certificate_number_CE_3647_BSII_AP_dated_15_Dec_1984.pdf",
  "id": "311620",
  "uploadedBy": "62691c48afd7d55eddecfda3",
  "createdAt": "Sat Dec 30 2023 11:55:59 GMT+0530 (India Standard Time)"
}
```

```
"id": "434775",
"uploadedBy": "62691c48afd7d55eddecfda3",
"createdAt": "Sat Dec 30 2023 11:55:59 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1703917538467_Architect_Letter_Occupancy_certificate_OC_A46_Prashant_Society.pdf",
  "path": "cases/658fab20545844510d0b5a65/document_1703917538467_Architect_Letter_Occupancy_certificate_OC_A46_Prashant_Society.pdf",
  "id": "786899",
  "uploadedBy": "62691c48afd7d55eddecfda3",
  "createdAt": "Sat Dec 30 2023 11:55:59 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1703917555441_Architect_Letter_Occupancy_certificate_OC_A46_Prashant_Society.pdf",
  "path": "cases/658fab20545844510d0b5a65/document_1703917555441_Architect_Letter_Occupancy_certificate_OC_A46_Prashant_Society.pdf",
  "id": "998134",
  "uploadedBy": "62691c48afd7d55eddecfda3",
  "createdAt": "Sat Dec 30 2023 11:55:59 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "006018",
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
  {
    "id": "139213",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Dec 30 2023 11:01:12 GMT+0530 (India Standard Time)"
  }
],
"owners": [
```

```
{
  "name": "Heena wadhwanii ",
  "phone": "9779586571",
  "ownershipShare": "",
  "email": "",
  "id": "323563"
},
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658fb838545844510d0ba9f7",
    "name": "externalImg_1703917624031_12_29_2023_05_42_26_PM.jpg",
    "path": "cases/658fab20545844510d0b5a65/
externalImg_1703917624031_12_29_2023_05_42_26_PM.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658fb838545844510d0ba9f8",
    "name": "externalImg_1703917624044_12_29_2023_05_42_33_PM.jpg",
    "path": "cases/658fab20545844510d0b5a65/
externalImg_1703917624044_12_29_2023_05_42_33_PM.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658fb838545844510d0ba9f9",
    "name": "externalImg_1703917624048_12_29_2023_05_42_50_PM.jpg",
    "path": "cases/658fab20545844510d0b5a65/
externalImg_1703917624048_12_29_2023_05_42_50_PM.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "658fb838545844510d0ba9fa",
  "name": "externallmg_1703917624051_12_29_2023_05_43_17_PM.jpg",
  "path": "cases/658fab20545844510d0b5a65/
externallmg_1703917624051_12_29_2023_05_43_17_PM.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "658fb838545844510d0ba9fb",
  "name": "externallmg_1703917624054_12_29_2023_05_44_36_PM.jpg",
  "path": "cases/658fab20545844510d0b5a65/
externallmg_1703917624054_12_29_2023_05_44_36_PM.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "658fb838545844510d0ba9fc",
  "name": "externallmg_1703917624056_12_29_2023_05_44_46_PM.jpg",
  "path": "cases/658fab20545844510d0b5a65/
externallmg_1703917624056_12_29_2023_05_44_46_PM.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "658fb838545844510d0ba9fd",
  "name": "externallmg_1703917624058_12_29_2023_06_01_00_PM.jpg",
  "path": "cases/658fab20545844510d0b5a65/
externallmg_1703917624058_12_29_2023_06_01_00_PM.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "658fb838545844510d0ba9fe",
  "name": "externallmg_1703917624060_12_29_2023_06_01_08_PM.jpg",
  "path": "cases/658fab20545844510d0b5a65/
externallmg_1703917624060_12_29_2023_06_01_08_PM.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "658fb838545844510d0ba9ff",
    "name": "externallmg_1703917624062_12_29_2023_06_02_07_PM.jpg",
    "path": "cases/658fab20545844510d0b5a65/
externallmg_1703917624062_12_29_2023_06_02_07_PM.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658fb838545844510d0baa00",
    "name": "externallmg_r_1703917624065_IMG20231229175434.jpg",
    "path": "cases/658fab20545844510d0b5a65/
externallmg_r_1703917624065_IMG20231229175434.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658fb838545844510d0baa01",
    "name": "externallmg_r_1703917624067_IMG20231229175438.jpg",
    "path": "cases/658fab20545844510d0b5a65/
externallmg_r_1703917624067_IMG20231229175438.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658fb838545844510d0baa02",
    "name": "externallmg_r_1703917624069_IMG20231229175441.jpg",
    "path": "cases/658fab20545844510d0b5a65/
externallmg_r_1703917624069_IMG20231229175441.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658fb838545844510d0baa03",
    "name": "externallmg_r_1703917624071_IMG20231229180005.jpg",
    "path": "cases/658fab20545844510d0b5a65/
externallmg_r_1703917624071_IMG20231229180005.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658fb847545844510d0baa7a",
```

```
    "name": "externallmg_1703917638873_Screenshot_2023122917480517_3d9111e2d3171bf4882369f490c087b4.jpg",
    "path": "cases/658fab20545844510d0b5a65/externallmg_1703917638873_Screenshot_2023122917480517_3d9111e2d3171bf4882369f490c087b4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658fb847545844510d0baa7b",
    "name": "externallmg_1703917638892_12_29_2023_05_43_13_PM.jpg",
    "path": "cases/658fab20545844510d0b5a65/externallmg_1703917638892_12_29_2023_05_43_13_PM.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658fb847545844510d0baa7c",
    "name": "externallmg_1703917638896_12_29_2023_05_44_51_PM.jpg",
    "path": "cases/658fab20545844510d0b5a65/externallmg_1703917638896_12_29_2023_05_44_51_PM.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658fb847545844510d0baa7d",
    "name": "externallmg_1703917638901_12_29_2023_06_00_39_PM.jpg",
    "path": "cases/658fab20545844510d0b5a65/externallmg_1703917638901_12_29_2023_06_00_39_PM.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658fb847545844510d0baa7e",
    "name": "externallmg_1703917638904_12_29_2023_06_00_47_PM.jpg",
    "path": "cases/658fab20545844510d0b5a65/externallmg_1703917638904_12_29_2023_06_00_47_PM.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658fb847545844510d0baa7f",
```



```
    "name": "externallmg_1703917638906_12_29_2023_06_00_54_PM.jpg",
    "path": "cases/658fab20545844510d0b5a65/
externallmg_1703917638906_12_29_2023_06_00_54_PM.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658fb847545844510d0baa80",
    "name": "externallmg_1703917638909_12_29_2023_06_01_15_PM.jpg",
    "path": "cases/658fab20545844510d0b5a65/
externallmg_1703917638909_12_29_2023_06_01_15_PM.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658fb847545844510d0baa81",
    "name": "externallmg_1703917638911_12_29_2023_06_01_22_PM.jpg",
    "path": "cases/658fab20545844510d0b5a65/
externallmg_1703917638911_12_29_2023_06_01_22_PM.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658fb847545844510d0baa82",
    "name": "externallmg_1703917638914_12_29_2023_06_01_49_PM.jpg",
    "path": "cases/658fab20545844510d0b5a65/
externallmg_1703917638914_12_29_2023_06_01_49_PM.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658fb847545844510d0baa83",
    "name": "externallmg_1703917638916_12_29_2023_06_01_59_PM.jpg",
    "path": "cases/658fab20545844510d0b5a65/
externallmg_1703917638916_12_29_2023_06_01_59_PM.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658fb847545844510d0baa84",
    "name": "externallmg_1703917638918_12_29_2023_06_02_15_PM.jpg",
```

```
    "path": "cases/658fab20545844510d0b5a65/
externallmg_1703917638918_12_29_2023_06_02_15_PM.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658fb847545844510d0baa85",
    "name": "externallmg_1703917638920_12_29_2023_06_02_27_PM.jpg",
    "path": "cases/658fab20545844510d0b5a65/
externallmg_1703917638920_12_29_2023_06_02_27_PM.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658fb847545844510d0baa86",
    "name": "externallmg_1703917638923_12_29_2023_06_05_01_PM.jpg",
    "path": "cases/658fab20545844510d0b5a65/
externallmg_1703917638923_12_29_2023_06_05_01_PM.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658fb847545844510d0baa87",
    "name": "externallmg_1703917638925_12_29_2023_06_05_07_PM.jpg",
    "path": "cases/658fab20545844510d0b5a65/
externallmg_1703917638925_12_29_2023_06_05_07_PM.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658fb847545844510d0baa88",
    "name": "externallmg_1703917638929_12_29_2023_06_05_16_PM.jpg",
    "path": "cases/658fab20545844510d0b5a65/
externallmg_1703917638929_12_29_2023_06_05_16_PM.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658fb847545844510d0baa89",
    "name": "externallmg_r_1703917638871_IMG20231229181131.jpg",
    "path": "cases/658fab20545844510d0b5a65/
externallmg_r_1703917638871_IMG20231229181131.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "658fb847545844510d0baa8a",
  "name": "externallmg_r_1703917638932_IMG20231229181155.jpg",
  "path": "cases/658fab20545844510d0b5a65/
externallmg_r_1703917638932_IMG20231229181155.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "658fb847545844510d0baa8b",
  "name": "externallmg_r_1703917638868_IMG20231229181123.jpg",
  "path": "cases/658fab20545844510d0b5a65/
externallmg_r_1703917638868_IMG20231229181123.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "658fb847545844510d0baa8c",
  "name": "externallmg_r_1703917638934_IMG20231229181206.jpg",
  "path": "cases/658fab20545844510d0b5a65/
externallmg_r_1703917638934_IMG20231229181206.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "658fb87e545844510d0bab59",
  "name": "externallmg_r_1703917694297_IMG20231230105835.jpg",
  "path": "cases/658fab20545844510d0b5a65/
externallmg_r_1703917694297_IMG20231230105835.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "658fb87e545844510d0bab5a",
  "name": "externallmg_r_1703917694240_IMG20231230105823.jpg",
  "path": "cases/658fab20545844510d0b5a65/
externallmg_r_1703917694240_IMG20231230105823.jpg",
  "orientation": "portrait"
}
```

```

    }
  ],
  "externalDocuments": [],
  "processingDocuments": [],
  "leadRemarks": [],
  "audioRemarks": [],
  "remarks": [],
  "createdAt": "2023-12-30T05:31:12.341Z",
  "updatedAt": "2023-12-30T06:28:14.947Z",
  "__v": 0,
  "invoiceId": "658fab20545844510d0b5a6e",
  "assignmentType": {
    "value": "Retail",
    "label": "Retail"
  },
  "fullAddress": "Residential Flat No. 301, 3rd Floor, Building No A-46, Prashant CHSL, Gokuldham , Gen A K Vaidhya Marg, Village - Chincholi, Borivali West, Mumbai, State - Maharashtra, India",
  "updatedBy": "62691c48afd7d55eddecfda3",
  "uniqueNo": "",
  "addressForMap": "",
  "caseReferredBy": "62723addafd7d55eddeddfe4",
  "contactPersonName": "Heena wadhwanii ",
  "email": "",
  "isExternal": "false",
  "isUrgent": "false",
  "ownershipShare": "",
  "purchaseValueAsPerDocument": "",
  "relationWithOwner": "self",
  "siteVisitContactNo": "9779586571"
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			