

```
{
  "typeOfReport": {
    "label": "Gala",
    "value": "Gala"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856ba90"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f65be948726cc141935",
    "email": "swaraj.sharma@sbi.co.in",
    "firstName": "SWARAJ ",
    "mobileNo": "",
    "workMobileNo": "9029457924",
    "lastName": "SHARMA"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "1000000",
    "discussWithPerson": "SWARAJ ",
    "expectedFees": 500,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856ba90",
  "branchCode": "000279",
  "type": "BRANCH",
  "name": "Industrial Finance Branch Sakinaka",
  "email": "sbi.06613@sbi.co.in",
  "mobileNo": "02228527554",
  "alternateMobileNo": "",
  "address": "1st Floor, Lekhraj Bhawan, Sakivihar Road, Andheri (East), Mumbai -
400072, State - Maharashtra, Country - India",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Commercial",
  "label": "Commercial"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
  "_id": "62723addafd7d55eddeddfe4",
  "role": "PICKUPPERSON",
  "firstName": "Ramkrishna ",
  "email": "rampatakar1991@gmail.com",
  "lastName": "Patkar",
  "mobileNo": "7045746060",
  "shortName": "RP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
},
  "deliveryPerson": {
    "type": "EMPLOYEE",
    "_id": "62723addafd7d55eddeddfe4",
    "role": "PICKUPPERSON",
    "firstName": "Ramkrishna ",
    "email": "rampatakar1991@gmail.com",
    "lastName": "Patkar",
    "mobileNo": "7045746060",
    "shortName": "RP",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "648fcad91b499c2d52dc86f3",
    "role": "SITEENGINEER",
    "firstName": "Barkat",
    "email": "barkathodekar68@gmail.com",
    "lastName": "Hodekar",
    "mobileNo": "8879011615",
    "designation": "Site Engg",
    "shortName": "Barkat",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "60eeaeddf3dd69653a581316",
    "role": "MAKER + RATE VERIFIER + CHEAKER",
    "firstName": "Shyam",
    "email": "shyam@vastukala.org",
    "lastName": "Kajvilkar",
    "mobileNo": "9765074720",
```

```
    "designation": "",
    "shortName": "SK",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shyma_Photo.jpg"
  },
  "maker": {
    "type": "EMPLOYEE",
    "_id": "60eebe33f3dd69653a5837ae",
    "role": "MAKER",
    "firstName": "Shamal",
    "email": "shamal@vastukala.org",
    "lastName": "Bodke",
    "mobileNo": "9821740317",
    "designation": "",
    "shortName": "SB",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60eebe33f3dd69653a5837ae\
\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
  },
  "checker": {
    "type": "EMPLOYEE",
    "_id": "60eeaeddf3dd69653a581316",
    "role": "MAKER + RATE VERIFIER + CHECKER",
    "firstName": "Shyam",
    "email": "shyam@vastukala.org",
    "lastName": "Kajvilkar",
    "mobileNo": "9765074720",
    "designation": "",
    "shortName": "SK",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shyma_Photo.jpg"
  },
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "IBBI/RV/07/2018/10366",
          "label": "Registered Valuer"
        }
      ]
    },
    {
      "type": "EMPLOYEE",
      "_id": "5ffe92d27737ca4d986b6453",
      "role": "VALUER",
      "firstName": "Manoj",
```

```
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
```

```
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.100449371738602",
  "longitude": "72.87984441965818"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.87984441965818,
    19.100449371738602
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-01-04",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-01-04",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  }
}
```

```
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Mohili",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "1",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "13AB",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
```

```
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kurla",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "New Samhita Commercial Co-op. Society Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Off. A. K. Road",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Sakinaka",
  "label": false
},
```



```
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Samhita Complex",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
```

```
"value": "758",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "43",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
```

```
"status": false,
"name": "Police Station(P.S)",
"key": "policeStation",
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 072",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Andheri (East)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "MS_Rolling_Shutter",
    "label": "MS Rolling Shutter"
  },
  "windows": {
    "value": "Aluminium_Sliding_Window_",
    "label": "Aluminium Sliding Window "
  },
  "fittings": {
```

```
"value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
  "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
},
"finishing": {
  "value": "Cement_Plastering",
  "label": "Cement Plastering"
}
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MCGM",
    "label": "Municipal Corporation of Greater Mumbai (MCGM)"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "MTNL Road",
    "west": "Mithi River",
    "south": "Building No. 17",
    "east": "Samhita Road"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
    "south": "Details not available",
    "east": "Details not available"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Details not available",
      "east": "Details not available",
```

```
    "south": "Details not available",
    "west": "Details not available"
  },
  "asPerDocument": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Approved Building plans were not provided and
not verified.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A."
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "62.99999999999999",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "17299",
  "depreciatedBuildingRate": "999.00000000000002"
},
"igrRate": {
  "propertyName": "Commercial Office",
  "rate": "151830",
  "landRate": "53370",
  "igrImage": "cases/659643302fcdd54ce8dae084/igr_1704437676205_Image.png",
  "squareMeterGuideLineRate": "151830.00",
  "squareFeetGuideLineRate": "14105.00"
},
"igrFinalRate": {
  "floorRatePercentage": "80",
  "depreciationPercentage": "58",
  "rate": "10264.00",
  "squareFeetGuideLineRate": "10264.00",
  "squareMeterGuideLineRate": "110477.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  }
},
```

```
"propertyTypeOfUseList": {
  "value": "Industrial",
  "label": "Industrial"
},
"propertyOccupiedByList": {
  "value": "Owner_Occupied",
  "label": "Owner Occupied"
},
"monthlyRent": "42,000",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per MCGM norms",
"tenantName": "",
"maintenanceOfFlat": "Normal"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Open Car Parking",
  "constructionWorkStatus": {
```

```
"value": "Completed",
"label": "Completed"
},
"asthetikLook": {
"value": "Plain_Looking",
"label": "Plain Looking"
},
"dateOfConstruction": {
"date": "1",
"month": "1",
"year": "1982",
"fullDate": "1/1/1982"
},
"planningArea": {
"value": "Commercial",
"label": "Commercial"
},
"typeOfStructure": {
"value": "R.C.C._Framed_Structure",
"label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
"value": "rcc",
"label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
"value": "Normal",
"label": "Normal"
},
"materialUsedList": {
"value": "Information_Not_Available",
"label": "Information Not Available"
},
"buildingSpecification": {
"value": "Standard",
"label": "Standard"
},
"structuralSafety": {
"value": "Normal",
"label": "Normal"
},
"protAgainstNatDis": {
"value": "Information_not_available",
"label": "Information not available"
},
"sewerageSystem": {
```

```
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
"walls": {
"value": "1",
"label": "Yes"
},
"appearanceOfTheBuilding": {
"value": "Normal",
"label": "Normal"
},
"maintenanceOfTheBuilding": {
"value": "Normal",
"label": "Normal"
},
"maintenanceIssues": {
"value": "Information_not_available",
"label": "Information not available"
},
"visibleDamageInBuilding": {
"value": "0",
"label": "No"
},
"systemOfAirConditioning": {
"value": "Information_not_available",
"label": "Information not available"
},
"provisionOfFirefighting": {
"value": "Information_not_available",
"label": "Information not available"
},
"groundStilt": {
"value": "ground",
"label": "Ground"
},
"yearOfConstructionAsPer": {
"value": "as_per_agreement",
"label": "As per agreement"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "18",
"ageOfBuilding": "42",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
```



```
"noOfFloors": "2",
"flatFloorNo": "1",
"noOfLifts": "",
"noOfDwellingUnitsInBuilding": "22"
},
"finalPlinthArea": {
  "area": "840.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Agreement"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Metro_Station",
      "label": "Metro Station"
    },
    "routeMapImg": "cases/659643302fcdd54ce8dae084/
routeMap_1704449410847_Image.png",
    "routeLat": "19.100472",
    "routeLng": "72.879889",
    "stationName": "Sakinaka",
    "routeDistance": "1.1 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "w2vpjii",
      "name": "w2vpjii",
      "image": "cases/659643302fcdd54ce8dae084/
routeMap_1704449302729_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
```

```
"totalwardrobesRate": "0",
"wardrobesQty": "0",
"showcasesQty": "0",
"showcasesRate": "0",
"totalshowcasesRate": "0",
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "14531160.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "14531160.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Fri Jan 05 2024 15:50:52 GMT+0530 (India Standard Time)",
  "number": "2304357",
  "dayCount": "12",
  "monthCount": "59",
  "generatedBy": "60eeaeddf3dd69653a581316"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
```

```
"label": "RCC Footing/Foundation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"rccPlinth": {
"label": "RCC Plinth",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
"label": "Full Building Rcc",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "8621760.00",
  "selectedBuildUpValue": "840.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "6596d3cf2fcdd54ce8dc2d7e",
      "name": "externalImg_1704383418980_1704383521671_image_2.jpeg",
      "path": "cases/659643302fcdd54ce8dae084/
externalImg_1704383418980_1704383521671_image_2.jpeg",
      "orientation": "landscape"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
```

```
    "_id": "6596d3cf2fcdd54ce8dc2d8d",
    "name": "externalimg_1704383426070_1704383521671_image_17.jpeg",
    "path": "cases/659643302fcdd54ce8dae084/
externalimg_1704383426070_1704383521671_image_17.jpeg",
    "orientation": "portrait"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "6596d3cf2fcdd54ce8dc2d88",
    "name": "externalimg_1704383423859_1704383521671_image_12.jpeg",
    "path": "cases/659643302fcdd54ce8dae084/
externalimg_1704383423859_1704383521671_image_12.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6596d3cf2fcdd54ce8dc2d86",
    "name": "externalimg_1704383422590_1704383521671_image_10.jpeg",
    "path": "cases/659643302fcdd54ce8dae084/
externalimg_1704383422590_1704383521671_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6596d3cf2fcdd54ce8dc2d83",
    "name": "externalimg_1704383421177_1704383521671_image_7.jpeg",
    "path": "cases/659643302fcdd54ce8dae084/
externalimg_1704383421177_1704383521671_image_7.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6596d3cf2fcdd54ce8dc2d82",
    "name": "externalimg_1704383420929_1704383521671_image_6.jpeg",
    "path": "cases/659643302fcdd54ce8dae084/
externalimg_1704383420929_1704383521671_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6596d3cf2fcdd54ce8dc2d7e",
    "name": "externalimg_1704383418980_1704383521671_image_2.jpeg",
    "path": "cases/659643302fcdd54ce8dae084/
externalimg_1704383418980_1704383521671_image_2.jpeg",
```

```
    "orientation": "landscape"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "6596d3cf2fcdd54ce8dc2d73",
    "name": "Gala",
    "path": "cases/659643302fcdd54ce8dae084/
externallmg_1704383380318_1704383484547_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6596d3cf2fcdd54ce8dc2d74",
    "name": "Gala",
    "path": "cases/659643302fcdd54ce8dae084/
externallmg_1704383380376_1704383484547_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6596d3cf2fcdd54ce8dc2d78",
    "name": "Gala",
    "path": "cases/659643302fcdd54ce8dae084/
externallmg_1704383381810_1704383484547_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6596d3cf2fcdd54ce8dc2d79",
    "name": "Gala",
    "path": "cases/659643302fcdd54ce8dae084/
externallmg_1704383381900_1704383484547_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6596d3cf2fcdd54ce8dc2d7b",
    "name": "Gala",
    "path": "cases/659643302fcdd54ce8dae084/
externallmg_1704383382660_1704383484547_image_8.jpeg",
    "orientation": "portrait"
  },
}
```

```
{
  "status": false,
  "_id": "6596d3cf2fcdd54ce8dc2d87",
  "name": "Gala",
  "path": "cases/659643302fcdd54ce8dae084/
externallmg_1704383423341_1704383521671_image_11.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "6596d3cf2fcdd54ce8dc2d8b",
  "name": "Gala",
  "path": "cases/659643302fcdd54ce8dae084/
externallmg_1704383425520_1704383521671_image_15.jpeg",
  "orientation": "portrait"
}
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "17600",
    "max": "26123"
  },
  "builtUpRateRange": {
    "min": "16000",
    "max": "21770"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
```



```
"title": "Showcases",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
```

```
"isSiteMeasurementAllowed": true,
"finalValuationArea": "840.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORDELIVERY",
"invoices": [],
"paymentId": [],
"_id": "659643302fcdd54ce8dae084",
"ownerName": "Shri. Ravindra Manikchand Shingi",
"ownerPhoneNo": "9821214603",
"appAddress": "Gala no 43, new samhita commercial co-operative housing society
Ltd, 13 AB ,samhita complex, off .A.k Road, sakinaka ",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    },
    "inputs": {
      "documentDate": "06/10/2004",
      "from": {
        "value": "Seller",
        "label": "Seller"
      },
      "Seller": "M/s. Aditya International",
      "to": {
        "value": "Purchasers",
        "label": "Purchasers"
      },
      "Purchasers": "Shri. Ravindra Manikchand Shingi",
      "number": {
        "value": "Registration_No",
        "label": "Registration No"
      },
      "Registration_No": "9774/2004"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "614688",
    "path": "cases/659643302fcdd54ce8dae084/
document_1704346312678_1704346417482_gala_43__shingi.pdf",
    "fileName": "document_1704346312678_1704346417482_gala_43__shingi.pdf"
```

```
},
{
  "documentType": {
    "value": "60ae1248aa6d152c1801b2ef",
    "label": "Society Share Certificate"
  },
  "inputs": {
    "documentDate": "28/09/2016",
    "to": {
      "value": "Purchasers",
      "label": "Purchasers"
    },
    "Purchasers": "Shri. Ravindra Manikchand Shingi",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "043"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1704448270002_Share.pdf",
  "path": "cases/659643302fcdd54ce8dae084/document_1704448270002_Share.pdf",
  "id": "785034",
  "uploadedBy": "60eebe33f3dd69653a5837ae",
  "createdAt": "Fri Jan 05 2024 15:21:10 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "6077c791395bc80714864a30",
    "label": "Electricity Bill"
  },
  "inputs": {
    "documentDate": "20/12/2023",
    "number": {
      "value": "CA_No",
      "label": "CA No"
    },
    "CA_No": "151586107"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1704448315721_Electricity.pdf",
  "path": "cases/659643302fcdd54ce8dae084/
document_1704448315721_Electricity.pdf",
  "id": "632547",
```

```
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Fri Jan 05 2024 15:21:55 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "07/04/1981",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_of_Greater_Mumbai",
      "label": "Municipal Corporation of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "CE / 2414 / BPES / A"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1704693615870_203182.pdf",
"path": "cases/659643302fcdd54ce8dae084/
document_1704693615870_203182.pdf",
"id": "377820",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Mon Jan 08 2024 11:30:15 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "006093",
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
  {
    "id": "826005",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Jan 04 2024 11:03:36 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Shri. Ravindra Manikchand Shingi",
    "phone": "9821214603",
    "ownershipShare": "",
    "email": ""
  }
]
```

```
"id": "216212"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "794157",
  "name": "Gala",
  "length": "38.33",
  "length1": "38",
  "length2": "4",
  "width": "20.33",
  "width1": "20",
  "width2": "4",
  "totalArea": "779.44",
  "images": [],
  "extraAreas": [],
  "finalArea": "779.44"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "659552",
  "selectAreaTypeDocument": "Built_Up",
  "totalAreaDocument": "840",
  "squareMeterArea": "78.04",
  "docFinalBuiltUp": "0.00",
  "docFinalBuiltUpSquareMeter": "0.00",
  "docBultupPercentage": "",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0.00",
```

```
    "docFinalSaleableSquareMeter": "0.00"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "6597a7bb2fcdd54ce8dcc25a",
    "property": "Commercial Office",
    "area": "1000",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Built_Up",
    "floor": "",
    "source": "Nobroker.com",
    "expectedPrice": "17500000",
    "expectedRate": "17500.00",
    "builtUpExpectedRate": "0.00",
    "image": "cases/659643302fcdd54ce8dae084/
indicator_1704437553556_Image.png",
    "squareMeter": "92.90",
    "id": "259029"
  },
  {
    "printlnReport": true,
    "_id": "6597a7bb2fcdd54ce8dcc25b",
    "property": "Commercial Office",
    "area": "1000",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Built_Up",
    "source": "Nobroker.com",
    "expectedPrice": "16000000",
    "expectedRate": "16000.00",
    "builtUpExpectedRate": "0.00",
    "image": "cases/659643302fcdd54ce8dae084/
indicator_1704437571048_Image.png",
    "squareMeter": "92.90",
    "id": "896033"
  },
  {
    "printlnReport": true,
    "_id": "6597a7bb2fcdd54ce8dcc25c",
    "property": "Commercial Office",
```

```
"area": "1091",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"source": "https://www.99acres.com/",
"expectedPrice": "28500000",
"expectedRate": "26122.82",
"builtUpExpectedRate": "21769.02",
"image": "cases/659643302fcdd54ce8dae084/
indicator_1704437608676_Image.png",
"squareMeter": "101.36",
"id": "455372"
}
],
"externalImages": [
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "6596d3cf2fcdd54ce8dc2d73",
"name": "externalimg_1704383380318_1704383484547_image_0.jpeg",
"path": "cases/659643302fcdd54ce8dae084/
externalimg_1704383380318_1704383484547_image_0.jpeg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "6596d3cf2fcdd54ce8dc2d74",
"name": "externalimg_1704383380376_1704383484547_image_1.jpeg",
"path": "cases/659643302fcdd54ce8dae084/
externalimg_1704383380376_1704383484547_image_1.jpeg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "6596d3cf2fcdd54ce8dc2d75",
"name": "externalimg_1704383380558_1704383484547_image_2.jpeg",
"path": "cases/659643302fcdd54ce8dae084/
externalimg_1704383380558_1704383484547_image_2.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
```



```
    "_id": "6596d3cf2fcdd54ce8dc2d76",
    "name": "externalimg_1704383380977_1704383484547_image_3.jpeg",
    "path": "cases/659643302fcdd54ce8dae084/
externalimg_1704383380977_1704383484547_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6596d3cf2fcdd54ce8dc2d77",
    "name": "externalimg_1704383381277_1704383484547_image_4.jpeg",
    "path": "cases/659643302fcdd54ce8dae084/
externalimg_1704383381277_1704383484547_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6596d3cf2fcdd54ce8dc2d78",
    "name": "externalimg_1704383381810_1704383484547_image_5.jpeg",
    "path": "cases/659643302fcdd54ce8dae084/
externalimg_1704383381810_1704383484547_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6596d3cf2fcdd54ce8dc2d79",
    "name": "externalimg_1704383381900_1704383484547_image_6.jpeg",
    "path": "cases/659643302fcdd54ce8dae084/
externalimg_1704383381900_1704383484547_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6596d3cf2fcdd54ce8dc2d7a",
    "name": "externalimg_1704383382379_1704383484547_image_7.jpeg",
    "path": "cases/659643302fcdd54ce8dae084/
externalimg_1704383382379_1704383484547_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6596d3cf2fcdd54ce8dc2d7b",
```

```
    "name": "externalImg_1704383382660_1704383484547_image_8.jpeg",
    "path": "cases/659643302fcdd54ce8dae084/
externalImg_1704383382660_1704383484547_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6596d3cf2fcdd54ce8dc2d7c",
    "name": "externalImg_1704383418064_1704383521671_image_0.jpeg",
    "path": "cases/659643302fcdd54ce8dae084/
externalImg_1704383418064_1704383521671_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6596d3cf2fcdd54ce8dc2d7d",
    "name": "externalImg_1704383418618_1704383521671_image_1.jpeg",
    "path": "cases/659643302fcdd54ce8dae084/
externalImg_1704383418618_1704383521671_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6596d3cf2fcdd54ce8dc2d7e",
    "name": "externalImg_1704383418980_1704383521671_image_2.jpeg",
    "path": "cases/659643302fcdd54ce8dae084/
externalImg_1704383418980_1704383521671_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6596d3cf2fcdd54ce8dc2d7f",
    "name": "externalImg_1704383419616_1704383521671_image_3.jpeg",
    "path": "cases/659643302fcdd54ce8dae084/
externalImg_1704383419616_1704383521671_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6596d3cf2fcdd54ce8dc2d80",
    "name": "externalImg_1704383419843_1704383521671_image_4.jpeg",
```

```
    "path": "cases/659643302fcdd54ce8dae084/
externallmg_1704383419843_1704383521671_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6596d3cf2fcdd54ce8dc2d81",
    "name": "externallmg_1704383420572_1704383521671_image_5.jpeg",
    "path": "cases/659643302fcdd54ce8dae084/
externallmg_1704383420572_1704383521671_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6596d3cf2fcdd54ce8dc2d82",
    "name": "externallmg_1704383420929_1704383521671_image_6.jpeg",
    "path": "cases/659643302fcdd54ce8dae084/
externallmg_1704383420929_1704383521671_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6596d3cf2fcdd54ce8dc2d83",
    "name": "externallmg_1704383421177_1704383521671_image_7.jpeg",
    "path": "cases/659643302fcdd54ce8dae084/
externallmg_1704383421177_1704383521671_image_7.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6596d3cf2fcdd54ce8dc2d84",
    "name": "externallmg_1704383422018_1704383521671_image_8.jpeg",
    "path": "cases/659643302fcdd54ce8dae084/
externallmg_1704383422018_1704383521671_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6596d3cf2fcdd54ce8dc2d85",
    "name": "externallmg_1704383422219_1704383521671_image_9.jpeg",
    "path": "cases/659643302fcdd54ce8dae084/
externallmg_1704383422219_1704383521671_image_9.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6596d3cf2fcdd54ce8dc2d86",
  "name": "externallmg_1704383422590_1704383521671_image_10.jpeg",
  "path": "cases/659643302fcdd54ce8dae084/
externallmg_1704383422590_1704383521671_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6596d3cf2fcdd54ce8dc2d87",
  "name": "externallmg_1704383423341_1704383521671_image_11.jpeg",
  "path": "cases/659643302fcdd54ce8dae084/
externallmg_1704383423341_1704383521671_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6596d3cf2fcdd54ce8dc2d88",
  "name": "externallmg_1704383423859_1704383521671_image_12.jpeg",
  "path": "cases/659643302fcdd54ce8dae084/
externallmg_1704383423859_1704383521671_image_12.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6596d3cf2fcdd54ce8dc2d89",
  "name": "externallmg_1704383424639_1704383521671_image_13.jpeg",
  "path": "cases/659643302fcdd54ce8dae084/
externallmg_1704383424639_1704383521671_image_13.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6596d3cf2fcdd54ce8dc2d8a",
  "name": "externallmg_1704383424996_1704383521671_image_14.jpeg",
  "path": "cases/659643302fcdd54ce8dae084/
externallmg_1704383424996_1704383521671_image_14.jpeg",
  "orientation": "portrait"
}
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6596d3cf2fcdd54ce8dc2d8b",
    "name": "externallmg_1704383425520_1704383521671_image_15.jpeg",
    "path": "cases/659643302fcdd54ce8dae084/
externallmg_1704383425520_1704383521671_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6596d3cf2fcdd54ce8dc2d8c",
    "name": "externallmg_1704383425792_1704383521671_image_16.jpeg",
    "path": "cases/659643302fcdd54ce8dae084/
externallmg_1704383425792_1704383521671_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6596d3cf2fcdd54ce8dc2d8d",
    "name": "externallmg_1704383426070_1704383521671_image_17.jpeg",
    "path": "cases/659643302fcdd54ce8dae084/
externallmg_1704383426070_1704383521671_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6596d3cf2fcdd54ce8dc2d8e",
    "name": "externallmg_1704383299294_1704383398681_image_0.jpeg",
    "path": "cases/659643302fcdd54ce8dae084/
externallmg_1704383299294_1704383398681_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6596d3cf2fcdd54ce8dc2d8f",
    "name": "externallmg_1704383299485_1704383398681_image_1.jpeg",
    "path": "cases/659643302fcdd54ce8dae084/
externallmg_1704383299485_1704383398681_image_1.jpeg",
    "orientation": "portrait"
  }
}
```

```
],
"externalDocuments": [
  {
    "originalname": "Valuation_REport_Ravindra Manikchand Shingi.pdf",
    "filename": "1704518283604_Valuation_REport_Ravindra_Manikchand_Shingi.pdf",
    "path": "cases/659643302fcdd54ce8dae084/externalDocuments/1704518283604_Valuation_REport_Ravindra_Manikchand_Shingi.pdf",
    "size": "1206906",
    "documentType": {
      "value": "640ece6024088f0f94ee4ea8",
      "label": "Final PDF Report"
    },
    "createdAt": "Sat Jan 06 2024 10:48:03 GMT+0530 (India Standard Time)",
    "uploadedBy": "63f31d626f9c2254a9b39144"
  }
],
"processingDocuments": [
  {
    "originalname": "AGR.pdf",
    "filename": "1704437708786_AGR.pdf",
    "path": "cases/659643302fcdd54ce8dae084/processingDocuments/1704437708786_AGR.pdf",
    "size": "21740646",
    "createdAt": "Fri Jan 05 2024 12:25:09 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "externallmg_1704383299294_1704383398681_image_0.jpeg",
    "filename": "1704437709166_externallmg_1704383299294_1704383398681_image_0.jpeg",
    "path": "cases/659643302fcdd54ce8dae084/processingDocuments/1704437709166_externallmg_1704383299294_1704383398681_image_0.jpeg",
    "size": "763177",
    "createdAt": "Fri Jan 05 2024 12:25:09 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "externallmg_1704383299485_1704383398681_image_1.jpeg",
    "filename": "1704437709229_externallmg_1704383299485_1704383398681_image_1.jpeg",
    "path": "cases/659643302fcdd54ce8dae084/processingDocuments/1704437709229_externallmg_1704383299485_1704383398681_image_1.jpeg",
    "size": "1186949",
    "createdAt": "Fri Jan 05 2024 12:25:09 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  }
],
```

```
{
  "originalname": "Summary New=RAVINDRA.xlsx",
  "filename": "1704437709250_Summary_NewRAVINDRA.xlsx",
  "path": "cases/659643302fcdd54ce8dae084/
processingDocuments/1704437709250_Summary_NewRAVINDRA.xlsx",
  "size": "2760392",
  "createdAt": "Fri Jan 05 2024 12:25:09 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "64cde526dc9f3034f3fefa49",
      "role": "FRONTDESK",
      "firstName": "Rashmi",
      "lastName": "Jadhav",
      "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
    },
    "workType": "MAKER",
    "display": true,
    "status": true,
    "_id": "659b8d0b8f39506e8346c5bd",
    "note": "Revised (Task Reopen)",
    "taskId": "6597a7df2fcdd54ce8dcc2aa",
    "createdAt": "2024-01-08T05:50:03.592Z"
  },
  {
    "createdBy": {
      "_id": "64cde526dc9f3034f3fefa49",
      "role": "FRONTDESK",
      "firstName": "Rashmi",
      "lastName": "Jadhav",
      "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
    },
    "workType": "PRINT",
    "display": true,
    "status": true,
    "_id": "659b8d1e8f39506e8346c673",
    "note": "Revised (Task Reopen)",
    "taskId": "6597dd088f39506e83445dd7",
    "createdAt": "2024-01-08T05:50:22.040Z"
  }
]
```

```
    },
    {
      "createdBy": {
        "_id": "64cde526dc9f3034f3fefa49",
        "role": "FRONTDESK",
        "firstName": "Rashmi",
        "lastName": "Jadhav",
        "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
      },
      "workType": "SIGNED_REPORT_UPLOAD",
      "display": true,
      "status": true,
      "_id": "659b8d2a8f39506e8346c74c",
      "note": "Revised (Task Reopen)",
      "taskId": "6597de818f39506e8344625e",
      "createdAt": "2024-01-08T05:50:34.343Z"
    }
  ],
  "createdAt": "2024-01-04T05:33:36.419Z",
  "updatedAt": "2024-01-08T06:00:15.972Z",
  "__v": 0,
  "invoiceId": "659643302fcdd54ce8dae08d",
  "assignmentType": {
    "value": "Retail",
    "label": "Retail"
  },
  },
  "fullAddress": "Commercial Gala No. 43, 1st Floor, Building No 13AB, New Samhita
Commercial Co-op. Society Ltd., Samhita Complex, CTS No. 758, Off. A. K. Road,
Sakinaka, Village - Mohili, Andheri (East), Taluka - Kurla, District - Mumbai Suburban,
Mumbai, PIN - 400 072, State - Maharashtra, India",
  "updatedBy": "60eebe33f3dd69653a5837ae",
  "addressForMap": "",
  "caseReferredBy": "62723addafd7d55eddeddfe4",
  "contactPersonName": "Mr. Sachin Pajave",
  "email": "",
  "isExternal": "false",
  "isUrgent": "false",
  "ownershipShare": "",
  "purchaseValueAsPerDocument": "",
  "relationWithOwner": "Office Boy",
  "siteVisitContactNo": "8419967178",
  "buildingServicesRate": "2700",
  "finalAreaType": "Built Up Area",
  "finalAsPerArea": "Agreement",
  "finalBuiltUpPercentage": "0",
```



```
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 840.00",
"flatRate": "19000",
"landOtherRate": "16300",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"briefDescOfProperty": "Gala",
"carpetTotal": "779.44",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "857.38",
"finalCarpetArea": "779.44",
"finalSalableArea": "943.12",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Fri Jan 05 2024 14:36:00 GMT+0530 (India Standard Time)",
"siteVisitDate": "2024-01-04"
}
```

Name	Length	Width	Total
Composition :			
Gala	38'4"	20'4"	779.44
Other Composition :			