

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "65cc9275d93fe4510d4f7448"
    },
    "type": "CREDITOFFICER",
    "_id": "65cc9275d93fe4510d4f744a",
    "firstName": "Gaurang",
    "lastName": "Mandawale",
    "mobileNo": "",
    "workMobileNo": "9890395744",
    "email": "Panchpakhadi.Navimumbai@bankofindia.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "00",
    "discussWithPerson": "Gaurang",
    "expectedFees": null,
    "quotedAmount": "5000"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180a",
  "type": "BANK",
  "name": "Bank of India",
  "displayName": "Bank of India",
  "initial": "BOI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "65cc9275d93fe4510d4f7448",
  "name": "Panchpakhadi",
  "branchCode": "00068",
  "mobileNo": "02225335533",
  "alternateMobileNo": "02225335840",
  "email": "Panchpakhadi.Navimumbai@bankofindia.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Vandana House Near Vandana Cinema, L B S Marg, Thane West
-400602"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e2f4b16576061dae469446",
  "zoneName": "Navi Mumbai Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "60af3d172ffdf65bcd6585cd",
"role": "PICKUPPERSON",
"firstName": "Sachin",
"email": "sachin.joshi@vastukala.org",
"lastName": "Joshi",
"mobileNo": "9167204063",
"shortName": "SJ",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60af3d172ffdf65bcd6585cd\
\profilePhoto_1622372567671_Sachin Joshi Photo 3 (2).jpg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "60f949ce45132d6a6bddbcc3",
"role": "SITEENGINEER",
"firstName": "Tushar ",
"email": "tusharbhuwad90@gmail.com",
"lastName": "Bhuwad",
"mobileNo": "9082053889",
"designation": "",
"shortName": "TSB",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f949ce45132d6a6bddbcc3/
profilePhoto_1668058314746_WhatsApp_Image_20221110_at_105931_AM.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "64dc7184ccaf1e7b7f637f47",
"role": "FRONTDESK",
"firstName": "Binumon",
"email": "binu@vastukala.org",
"lastName": "Moozhickal",
"mobileNo": "9930252906",
"designation": "Back Office Team Leader",
"shortName": "BS",
"workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
"profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "62fe044a48a26047e6552796",
"role": "MAKER",
"firstName": "Pradnya ",
"email": "pradnya@vastukala.org",
"lastName": "Rasam",
```

```
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": null,
"valuers": [
{
  "valuersRegistrationNumber": [
    {
      "value": "IBBI/RV/07/2018/10366",
      "label": "Registered Valuer"
    }
  ],
  "type": "EMPLOYEE",
  "_id": "5ffe92d27737ca4d986b6453",
  "role": "VALUER",
  "firstName": "Manoj",
  "email": "manoj@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9819597579",
  "designation": "Registered Valuer",
  "registrationNo": [
    {
      "title": {
        "label": "IBBI"
      },
      "_id": "60af80072ffdf65bcd658651",
      "number": "IBBI/RV/07/2018/10366"
    },
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      },
      "_id": "60af80072ffdf65bcd658652",
      "number": "CAT-I-F-1763"
    },
    {
      "title": {
        "value": "Chartered_Engineer",
        "label": "Chartered Engineer"
      },
      "_id": "60af80072ffdf65bcd658653",
```

```
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.105892561368357",
  "longitude": "72.8515608613811"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.8515608613811,
    19.105892561368357
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "14/02/2024 04:24 pm"
    }
  ]
},
"visitedDate": [],
"marketAnalysisAndRemark": {
  "audioNotes": []
}
```

```
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Vile Parle",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "5",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": false,
    "name": "District",
    "key": "district",
```

```
"value": "",
"label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Dattaramanand",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
```

```
"status": true,
"name": "Street 1",
"key": "street1",
"value": "Hanuman Cross ROad No 2",
"label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "H",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
```



```
"label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "504",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
```

```
"name": "Mouza",
"key": "mouza",
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Vle Pare East",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
}
```

```
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```

```
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
```



```
"value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"invoices": [],
"paymentId": [],
"_id": "65cc974dd93fe4510d4f8b01",
"ownerName": "Sidus Buildcon India Pvt Ltd",
"ownerPhoneNo": "9769683377",
"appAddress": "Flat no 504,5floor,H-wing,Dattaramanand CHS,Hangman Cross Road
no 2,Vile Parle East ",
"remark": "+91 97696 83377 Vaibhav Pendnekar ",
"documents": [
{
  "documentType": {
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/65cc974dd93fe4510d4f8b01/
document_1707906817520_1707906964096_Kaagaz_20240214_132807476608.pdf",
  "fileName":
"document_1707906817520_1707906964096_Kaagaz_20240214_132807476608.pdf",
  "id": "246987",
  "uploadedBy": "60af3d172ffdf65bcd6585cd",
  "createdAt": "Wed Feb 14 2024 16:04:53 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "006970",
"createdBy": "60af3d172ffdf65bcd6585cd",
"caseHistory": [
{
  "id": "899991",
  "title": "Create Lead",
  "description": "Create Lead",
  "datetime": "Wed Feb 14 2024 16:04:53 GMT+0530 (India Standard Time)"
}
],
"owners": [
{
```

```
"name": "Sidus Buildcon India Pvt Ltd",
"phone": "9769683377",
"ownershipShare": "",
"email": "",
"id": "431091"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "65ced23019837c7e5fdc1b9f",
"name": "externalimg_r_1708053040554_IMG20240215184513.jpg",
"path": "cases/65cc974dd93fe4510d4f8b01/
externalimg_r_1708053040554_IMG20240215184513.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "65ced23019837c7e5fdc1ba0",
"name": "externalimg_r_1708053040547_IMG20240215182705.jpg",
"path": "cases/65cc974dd93fe4510d4f8b01/
externalimg_r_1708053040547_IMG20240215182705.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "65ced23019837c7e5fdc1ba1",
"name": "externalimg_r_1708053040540_IMG20240215182704.jpg",
"path": "cases/65cc974dd93fe4510d4f8b01/
externalimg_r_1708053040540_IMG20240215182704.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
```

```
    "_id": "65ced23019837c7e5fdc1ba2",
    "name": "externallmg_r_1708053040560_TimePhoto_20240215_180846.jpg",
    "path": "cases/65cc974dd93fe4510d4f8b01/
externallmg_r_1708053040560_TimePhoto_20240215_180846.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ced23019837c7e5fdc1ba3",
    "name": "externallmg_r_1708053040568_TimePhoto_20240215_180848.jpg",
    "path": "cases/65cc974dd93fe4510d4f8b01/
externallmg_r_1708053040568_TimePhoto_20240215_180848.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ced23019837c7e5fdc1ba4",
    "name": "externallmg_r_1708053040572_TimePhoto_20240215_180856.jpg",
    "path": "cases/65cc974dd93fe4510d4f8b01/
externallmg_r_1708053040572_TimePhoto_20240215_180856.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ced23019837c7e5fdc1ba5",
    "name": "externallmg_r_1708053040577_TimePhoto_20240215_180857.jpg",
    "path": "cases/65cc974dd93fe4510d4f8b01/
externallmg_r_1708053040577_TimePhoto_20240215_180857.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ced23019837c7e5fdc1ba6",
    "name": "externallmg_r_1708053040580_TimePhoto_20240215_180919.jpg",
    "path": "cases/65cc974dd93fe4510d4f8b01/
externallmg_r_1708053040580_TimePhoto_20240215_180919.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ced23019837c7e5fdc1ba7",
```

```
    "name": "externallmg_r_1708053040613_TimePhoto_20240215_180922.jpg",
    "path": "cases/65cc974dd93fe4510d4f8b01/
externallmg_r_1708053040613_TimePhoto_20240215_180922.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ced23019837c7e5fdc1ba8",
    "name": "externallmg_r_1708053040621_TimePhoto_20240215_180928.jpg",
    "path": "cases/65cc974dd93fe4510d4f8b01/
externallmg_r_1708053040621_TimePhoto_20240215_180928.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ced23019837c7e5fdc1ba9",
    "name": "externallmg_r_1708053040625_TimePhoto_20240215_180947.jpg",
    "path": "cases/65cc974dd93fe4510d4f8b01/
externallmg_r_1708053040625_TimePhoto_20240215_180947.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ced23019837c7e5fdc1baa",
    "name": "externallmg_r_1708053040631_TimePhoto_20240215_181113.jpg",
    "path": "cases/65cc974dd93fe4510d4f8b01/
externallmg_r_1708053040631_TimePhoto_20240215_181113.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ced23019837c7e5fdc1bab",
    "name": "externallmg_r_1708053040634_TimePhoto_20240215_181707.jpg",
    "path": "cases/65cc974dd93fe4510d4f8b01/
externallmg_r_1708053040634_TimePhoto_20240215_181707.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ced23019837c7e5fdc1bac",
    "name": "externallmg_r_1708053040638_TimePhoto_20240215_181722.jpg",
```

```
    "path": "cases/65cc974dd93fe4510d4f8b01/
externallmg_r_1708053040638_TimePhoto_20240215_181722.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ced23019837c7e5fdc1bad",
    "name": "externallmg_r_1708053040641_TimePhoto_20240215_181724.jpg",
    "path": "cases/65cc974dd93fe4510d4f8b01/
externallmg_r_1708053040641_TimePhoto_20240215_181724.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ced23019837c7e5fdc1bae",
    "name": "externallmg_r_1708053040644_TimePhoto_20240215_181849.jpg",
    "path": "cases/65cc974dd93fe4510d4f8b01/
externallmg_r_1708053040644_TimePhoto_20240215_181849.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ced23019837c7e5fdc1baf",
    "name": "externallmg_r_1708053040647_TimePhoto_20240215_182114.jpg",
    "path": "cases/65cc974dd93fe4510d4f8b01/
externallmg_r_1708053040647_TimePhoto_20240215_182114.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ced23019837c7e5fdc1bb0",
    "name": "externallmg_r_1708053040651_TimePhoto_20240215_182134.jpg",
    "path": "cases/65cc974dd93fe4510d4f8b01/
externallmg_r_1708053040651_TimePhoto_20240215_182134.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ced23019837c7e5fdc1bb1",
    "name": "externallmg_r_1708053040653_TimePhoto_20240215_182217.jpg",
    "path": "cases/65cc974dd93fe4510d4f8b01/
externallmg_r_1708053040653_TimePhoto_20240215_182217.jpg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ced23019837c7e5fdc1bb2",
    "name": "externallmg_r_1708053040656_TimePhoto_20240215_182824.jpg",
    "path": "cases/65cc974dd93fe4510d4f8b01/
externallmg_r_1708053040656_TimePhoto_20240215_182824.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ced26b19837c7e5fdc1bfb",
    "name": "externallmg_r_1708053099469_IMG20240215182650.jpg",
    "path": "cases/65cc974dd93fe4510d4f8b01/
externallmg_r_1708053099469_IMG20240215182650.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ced26b19837c7e5fdc1bfc",
    "name": "externallmg_r_1708053099473_TimePhoto_20240215_180829.jpg",
    "path": "cases/65cc974dd93fe4510d4f8b01/
externallmg_r_1708053099473_TimePhoto_20240215_180829.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ced26b19837c7e5fdc1bfd",
    "name": "externallmg_r_1708053099457_TimePhoto_20240215_182824.jpg",
    "path": "cases/65cc974dd93fe4510d4f8b01/
externallmg_r_1708053099457_TimePhoto_20240215_182824.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ced26b19837c7e5fdc1bfe",
    "name": "externallmg_r_1708053099463_TimePhoto_20240215_184456.jpg",
    "path": "cases/65cc974dd93fe4510d4f8b01/
externallmg_r_1708053099463_TimePhoto_20240215_184456.jpg",
    "orientation": "portrait"
  }
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ced26b19837c7e5fdc1bff",
    "name": "externallmg_r_1708053099483_TimePhoto_20240215_181711.jpg",
    "path": "cases/65cc974dd93fe4510d4f8b01/
externallmg_r_1708053099483_TimePhoto_20240215_181711.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ced26b19837c7e5fdc1c00",
    "name": "externallmg_r_1708053099477_TimePhoto_20240215_180831.jpg",
    "path": "cases/65cc974dd93fe4510d4f8b01/
externallmg_r_1708053099477_TimePhoto_20240215_180831.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ced26b19837c7e5fdc1c01",
    "name": "externallmg_r_1708053099487_TimePhoto_20240215_181827.jpg",
    "path": "cases/65cc974dd93fe4510d4f8b01/
externallmg_r_1708053099487_TimePhoto_20240215_181827.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ced26b19837c7e5fdc1c02",
    "name": "externallmg_r_1708053099480_TimePhoto_20240215_180904.jpg",
    "path": "cases/65cc974dd93fe4510d4f8b01/
externallmg_r_1708053099480_TimePhoto_20240215_180904.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ced26b19837c7e5fdc1c03",
    "name": "externallmg_r_1708053099489_TimePhoto_20240215_182013.jpg",
    "path": "cases/65cc974dd93fe4510d4f8b01/
externallmg_r_1708053099489_TimePhoto_20240215_182013.jpg",
    "orientation": "portrait"
  },
  },
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65ced26b19837c7e5fdc1c04",
  "name": "externallmg_r_1708053099496_TimePhoto_20240215_182104.jpg",
  "path": "cases/65cc974dd93fe4510d4f8b01/
externallmg_r_1708053099496_TimePhoto_20240215_182104.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65ced26b19837c7e5fdc1c05",
  "name": "externallmg_r_1708053099498_TimePhoto_20240215_182112.jpg",
  "path": "cases/65cc974dd93fe4510d4f8b01/
externallmg_r_1708053099498_TimePhoto_20240215_182112.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65ced26b19837c7e5fdc1c06",
  "name": "externallmg_r_1708053099492_TimePhoto_20240215_182059.jpg",
  "path": "cases/65cc974dd93fe4510d4f8b01/
externallmg_r_1708053099492_TimePhoto_20240215_182059.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65ced26b19837c7e5fdc1c07",
  "name": "externallmg_r_1708053099503_TimePhoto_20240215_182127.jpg",
  "path": "cases/65cc974dd93fe4510d4f8b01/
externallmg_r_1708053099503_TimePhoto_20240215_182127.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65ced26b19837c7e5fdc1c08",
  "name": "externallmg_r_1708053099500_TimePhoto_20240215_182122.jpg",
  "path": "cases/65cc974dd93fe4510d4f8b01/
externallmg_r_1708053099500_TimePhoto_20240215_182122.jpg",
  "orientation": "portrait"
},
{
```



```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ced26b19837c7e5fdc1c09",
    "name": "externalimg_r_1708053099506_TimePhoto_20240215_182220.jpg",
    "path": "cases/65cc974dd93fe4510d4f8b01/
externalimg_r_1708053099506_TimePhoto_20240215_182220.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ced26b19837c7e5fdc1c0a",
    "name": "externalimg_r_1708053099508_TimePhoto_20240215_182239.jpg",
    "path": "cases/65cc974dd93fe4510d4f8b01/
externalimg_r_1708053099508_TimePhoto_20240215_182239.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ced26b19837c7e5fdc1c0b",
    "name": "externalimg_r_1708053099510_TimePhoto_20240215_182410.jpg",
    "path": "cases/65cc974dd93fe4510d4f8b01/
externalimg_r_1708053099510_TimePhoto_20240215_182410.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ced26b19837c7e5fdc1c0c",
    "name": "externalimg_r_1708053099513_TimePhoto_20240215_182420.jpg",
    "path": "cases/65cc974dd93fe4510d4f8b01/
externalimg_r_1708053099513_TimePhoto_20240215_182420.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ced26b19837c7e5fdc1c0d",
    "name": "externalimg_r_1708053099517_TimePhoto_20240215_184449.jpg",
    "path": "cases/65cc974dd93fe4510d4f8b01/
externalimg_r_1708053099517_TimePhoto_20240215_184449.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "65ced26b19837c7e5fdc1c0e",
  "name": "externalImg_r_1708053099515_TimePhoto_20240215_182438.jpg",
  "path": "cases/65cc974dd93fe4510d4f8b01/
externalImg_r_1708053099515_TimePhoto_20240215_182438.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65ced2a319837c7e5fdc1c44",
  "name": "externalImg_1708053154588_Screenshot_2024021521500035_3d9111e2
d3171bf4882369f490c087b4.jpg",
  "path": "cases/65cc974dd93fe4510d4f8b01/externalImg_1708053154588_Screensh
ot_2024021521500035_3d9111e2d3171bf4882369f490c087b4.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65ced2a319837c7e5fdc1c45",
  "name": "externalImg_r_1708053154525_IMG20240216000753.jpg",
  "path": "cases/65cc974dd93fe4510d4f8b01/
externalImg_r_1708053154525_IMG20240216000753.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65ced2a319837c7e5fdc1c46",
  "name": "externalImg_r_1708053154471_IMG20240216000736.jpg",
  "path": "cases/65cc974dd93fe4510d4f8b01/
externalImg_r_1708053154471_IMG20240216000736.jpg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "SIDUS BUILDCON INDIA PVT LTD -Flat No. 504 - Bank Of India
( Panchpakhadi ).xlsx",
    "filename": "1708069971197_SIDUS_BUILDCON_INDIA_PVT_LTD_Flat_No_504_
_Bank_Of_India__Panchpakhadi_.xlsx",
    "path": "cases/65cc974dd93fe4510d4f8b01/processingDocuments/1708069971197_
SIDUS_BUILDCON_INDIA_PVT_LTD_Flat_No_504__Bank_Of_India__Panchpakhadi_
.xlsx",
```

```
"size": "3555768",
"createdAt": "Fri Feb 16 2024 13:22:51 GMT+0530 (India Standard Time)",
"uploadedBy": "64dc7184ccaf1e7b7f637f47"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
{
"createdBy": {
"_id": "64dc7184ccaf1e7b7f637f47",
"role": "FRONTDESK",
"firstName": "Binumon",
"lastName": "Moozhickal",
"profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"workType": "RATE_VERIFY",
"display": true,
"status": true,
"_id": "65cf144219837c7e5fdd21c1",
"note": "Value given for confirmation",
"taskId": "65cc9b50d93fe4510d4f9e16",
"createdAt": "2024-02-16T07:52:34.270Z"
},
{
"createdBy": {
"_id": "64dc7184ccaf1e7b7f637f47",
"role": "FRONTDESK",
"firstName": "Binumon",
"lastName": "Moozhickal",
"profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"workType": "RATE_VERIFY",
"display": true,
"status": true,
"_id": "65cf145719837c7e5fdd21cf",
"note": "Value given for confirmation",
"taskId": "65cc9b50d93fe4510d4f9e16",
"createdAt": "2024-02-16T07:52:55.109Z"
},
{
"createdBy": {
"_id": "64dc7184ccaf1e7b7f637f47",
"role": "FRONTDESK",
```

```

    "firstName": "Binumon",
    "lastName": "Moozhickal",
    "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "65cf145a19837c7e5fdd21d5",
  "note": "Value given for confirmation",
  "taskId": "65cc9b50d93fe4510d4f9e16",
  "createdAt": "2024-02-16T07:52:58.009Z"
}
],
"createdAt": "2024-02-14T10:34:54.003Z",
"updatedAt": "2024-02-16T09:09:53.993Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 504, 5th Floor, Wing - H, Dattaramanand,
Hanuman Cross ROad No 2, Village - Vile Parle, Vile Pare East, Mumbai",
"updatedBy": "62fe044a48a26047e6552796",
"addressForMap": "",
"caseReferredBy": "60af3d172ffdf65bcd6585cd",
"contactPersonName": "Sidus Buildcon India Pvt Ltd",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9769683377"
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			