

```
{
  "typeOfReport": {
    "value": "Lenders_Engineers_Report_(LIE)",
    "label": "Lenders_Engineers Report (LIE)"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Lenders_Engineers_Report_(LIE)",
    "label": "Lenders_Engineers Report (LIE)"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7cc"
    },
    "type": "CREDITOFFICER",
    "_id": "64338d21d267175d008119f1",
    "firstName": "Manish",
    "lastName": "Jha",
    "mobileNo": "",
    "workMobileNo": "9049983319",
    "email": ""
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "20000"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7cc",
  "branchCode": "13340",
  "type": "BRANCH",
  "name": "SME Chembur Branch",
  "email": "sbi.13340@sbi.co.in",
  "mobileNo": "02225273906",
  "alternateMobileNo": "02225273907",
  "address": "Unit No. 11, (BLDG NO. 11), Ground Floor, Corporate Park, Sion-
Trombay Road, Chembur, Mumbai – 400 071, State – Maharashtra, Country – India.",
  "ledgerName": "",
  "fax": "02225274524",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"deliveryPerson": {
  "type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "designation": "",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
```

```
"mobileNo": "9767983840",
"designation": "",
"shortName": "PPP",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "designation": "",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"checker": {
  "_id": "60f91822f3dd69653a5922e3",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg",
  "firstName": "Prayush ",
  "lastName": "Parekh ",
  "shortName": "PPP",
  "email": "prayush@vastukala.org",
  "designation": "",
  "mobileNo": "9767983840",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "type": "EMPLOYEE",
  "workWithDocumentMaker": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "[N]C.C.I.T/I -14/52/2008-09",
        "label": "Wealth Tax"
      }
    ]
  },
  "type": "EMPLOYEE",
  "_id": "6084131a13f01f158c6ea1f3",
  "PANNo": "AEAPC7114Q",
```

```
"role": "VALUER",
"firstName": "Sharadkumar",
"fatherName": "Baburao",
"email": "cmd@vastukala.org",
"lastName": " Chalikwar",
"mobileNo": "9422171100",
"designation": "CMD",
"registrationNo": [
  {
    "title": {
      "value": "Wealth_Tax",
      "label": "Wealth Tax"
    },
    "_id": "6084131a13f01f158c6ea1f4",
    "number": "[N]C.C.I.T/I -14/52/2008-09"
  }
],
"shortName": "SBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\6084131a13f01f158c6ea1f3\
\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.06912185170992",
  "longitude": "72.87583525582238"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "26/12/2023 05:00 pm"
    }
  ]
},
],
```

```
"visitedDate": [
  {
    "status": "COMPLETED",
    "dateTime": "2023-10-09",
    "remark": "MANUAL_IN_TASK"
  }
],
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Kurla - IV",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "16",
    "label": false
  },
  "buildingNo": {
```

```
"status": false,
"name": "Building No",
"key": "buildingNo",
"value": "",
"label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Kurla (West)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kurla",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Yojan One",
```

```
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Match Factory Lane, H.P.K Marg",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A & B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
```



```
"name": "Old Survey No.",
"key": "oldSurveyNumber",
"value": "",
"label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "131 (pt),131/1 to 131/50, 131/52 to 131/84",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
}
```

```
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400070",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
```

```
    "key": "suburb",
    "value": "",
    "label": false
  }
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
```



```
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"invoices": [],
"paymentIds": [],
"_id": "65e174a56cca1c6793bc2806",
"paymentId": [],
"ownerName": "M/s. Meru Realty LLP",
"ownerPhoneNo": "9930084006",
"fullAddress": " Lenders_Engineers Report (LIE) No. 16th Floor, Wing - A & B, Yojan
One, CTS No. 131 (pt),131/1 to 131/50, 131/52 to 131/84, Match Factory Lane, H.P.K
Marg, Village - Kurla - IV, Taluka - Kurla, District - Mumbai Suburban, Kurla (West),
400070",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "641d4da529e5586db05ed8e8",
      "label": "CA Certificate"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1703582226711_Means_of_Finance_21102023.pdf",
    "path": "cases/65e174a56cca1c6793bc2806/
document_1703582226711_Means_of_Finance_21102023.pdf",
    "id": "229121",
    "uploadedBy": "60f91822f3dd69653a5922e3",
    "createdAt": "Tue Dec 26 2023 15:00:41 GMT+0530 (India Standard Time)"
  }
],
```

```
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"caseNumber": "007360",
"createdBy": "60f91822f3dd69653a5922e3",
"caseHistory": [
  {
    "id": "943350",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Dec 26 2023 15:00:41 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "M/s. Meru Realty LLP",
    "phone": "9930084006",
    "ownershipShare": "",
    "email": "",
    "id": "903190"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e56da1f9222577acb83356",
    "name": "externalImg_1709534625523_IMG_20240104_144428.jpg",
    "path": "cases/65e174a56cca1c6793bc2806/externalImg_1709534625523_IMG_20240104_144428.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e56da1f9222577acb83357",
    "name": "externalImg_r_1709534625460_IMG_20240104_144305.jpg",
```

```
    "path": "cases/65e174a56cca1c6793bc2806/
externallmg_r_1709534625460_IMG_20240104_144305.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e56da1f9222577acb83358",
    "name": "externallmg_r_1709534625464_IMG_20240104_144310.jpg",
    "path": "cases/65e174a56cca1c6793bc2806/
externallmg_r_1709534625464_IMG_20240104_144310.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e56da1f9222577acb83359",
    "name": "externallmg_r_1709534625468_IMG_20240104_144312.jpg",
    "path": "cases/65e174a56cca1c6793bc2806/
externallmg_r_1709534625468_IMG_20240104_144312.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e56da1f9222577acb8335a",
    "name": "externallmg_r_1709534625477_IMG_20240104_144313.jpg",
    "path": "cases/65e174a56cca1c6793bc2806/
externallmg_r_1709534625477_IMG_20240104_144313.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e56da1f9222577acb8335b",
    "name": "externallmg_r_1709534625486_IMG_20240104_144315.jpg",
    "path": "cases/65e174a56cca1c6793bc2806/
externallmg_r_1709534625486_IMG_20240104_144315.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65e56da1f9222577acb8335c",
    "name": "externallmg_r_1709534625494_IMG_20240104_144411.jpg",
    "path": "cases/65e174a56cca1c6793bc2806/
externallmg_r_1709534625494_IMG_20240104_144411.jpg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e56da1f9222577acb8335d",
  "name": "externallmg_r_1709534625506_IMG_20240104_144420.jpg",
  "path": "cases/65e174a56cca1c6793bc2806/
externallmg_r_1709534625506_IMG_20240104_144420.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e56da1f9222577acb8335e",
  "name": "externallmg_r_1709534625518_IMG_20240104_144421.jpg",
  "path": "cases/65e174a56cca1c6793bc2806/
externallmg_r_1709534625518_IMG_20240104_144421.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e56da1f9222577acb8335f",
  "name": "externallmg_r_1709534625539_IMG_20240104_144435.jpg",
  "path": "cases/65e174a56cca1c6793bc2806/
externallmg_r_1709534625539_IMG_20240104_144435.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e56da1f9222577acb83360",
  "name": "externallmg_r_1709534625547_IMG_20240104_144439.jpg",
  "path": "cases/65e174a56cca1c6793bc2806/
externallmg_r_1709534625547_IMG_20240104_144439.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65e56da1f9222577acb83361",
  "name": "externallmg_r_1709534625556_IMG_20240104_144447.jpg",
  "path": "cases/65e174a56cca1c6793bc2806/
externallmg_r_1709534625556_IMG_20240104_144447.jpg",
  "orientation": "landscape"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65e56da1f9222577acb83362",
      "name": "externalImg_r_1709534625567_IMG_20240104_144458.jpg",
      "path": "cases/65e174a56cca1c6793bc2806/
externalImg_r_1709534625567_IMG_20240104_144458.jpg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65e56da1f9222577acb83363",
      "name": "externalImg_r_1709534625579_IMG_20240104_144502.jpg",
      "path": "cases/65e174a56cca1c6793bc2806/
externalImg_r_1709534625579_IMG_20240104_144502.jpg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65e56da1f9222577acb83364",
      "name": "externalImg_r_1709534625586_IMG_20240104_144505.jpg",
      "path": "cases/65e174a56cca1c6793bc2806/
externalImg_r_1709534625586_IMG_20240104_144505.jpg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65e56da1f9222577acb83365",
      "name": "externalImg_r_1709534625595_IMG_20240104_144508.jpg",
      "path": "cases/65e174a56cca1c6793bc2806/
externalImg_r_1709534625595_IMG_20240104_144508.jpg",
      "orientation": "landscape"
    }
  ],
  "externalDocuments": [
    {
      "originalname": "3rd LIE Report Yojan One.docx",
      "filename": "1703589673373_3rd_LIE_Report_Yojan_One.docx",
      "path": "cases/65e174a56cca1c6793bc2806/
externalDocuments/1703589673373_3rd_LIE_Report_Yojan_One.docx",
      "size": "6092224",
      "documentType": {
```

```
    "value": "649998c6cab24d3d1a2cc577",
    "label": "Draft Word Report"
  },
  "createdAt": "Tue Dec 26 2023 16:51:13 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91822f3dd69653a5922e3"
},
{
  "originalname": "3rd LIE Report Yojan One.docx",
  "filename": "1703589743914_3rd_LIE_Report_Yojan_One.docx",
  "path": "cases/65e174a56cca1c6793bc2806/
externalDocuments/1703589743914_3rd_LIE_Report_Yojan_One.docx",
  "size": "6091982",
  "documentType": {
    "value": "64058cdff10de22571d01b37",
    "label": "Final Word Report"
  },
  "createdAt": "Tue Dec 26 2023 16:52:24 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91822f3dd69653a5922e3"
},
{
  "originalname": "Valuation_Report_Yojan_One_3rd_LIE_Report.pdf",
  "filename": "1703750944128_Valuation_Report_Yojan_One_3rd_LIE_Report.pdf",
  "path": "cases/65e174a56cca1c6793bc2806/externalDocuments/1703750944128_Valuation_Report_Yojan_One_3rd_LIE_Report.pdf",
  "size": "2302561",
  "documentType": {
    "value": "640ece6024088f0f94ee4ea8",
    "label": "Final PDF Report"
  },
  "createdAt": "Thu Dec 28 2023 13:39:04 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f9589345132d6a6bddcc3a"
},
{
  "originalname": "1703917875972_5899 Yojan One.pdf",
  "filename": "1703917778038_1703917875972_5899_Yojan_One.pdf",
  "path": "cases/65e174a56cca1c6793bc2806/
externalDocuments/1703917778038_1703917875972_5899_Yojan_One.pdf",
  "size": "512417",
  "documentType": {
    "value": "60ae124daa6d152c1801b307",
    "label": "Office Copy"
  },
  "createdAt": "Sat Dec 30 2023 11:59:39 GMT+0530 (India Standard Time)",
  "uploadedBy": "60b7177d2ffdf65bcd65882a"
}
],
```

```

"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-03-01T06:24:37.819Z",
"updatedAt": "2024-03-04T06:43:45.767Z",
"__v": 0,
"invoiceId": null,
"updatedBy": "60f91822f3dd69653a5922e3",
"addressForMap": "",
"caseReferredBy": "60f91822f3dd69653a5922e3",
"contactPersonName": "M/s. Meru Realty LLP",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9930084006",
"reportGeneratedDate": "Tue Dec 26 2023 16:53:05 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2023-10-09"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			