

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "65e6cd5cf9222577acba7566"
    },
    "type": "CREDITOFFICER",
    "_id": "65e6cd5cf9222577acba7568",
    "firstName": "Priyanka",
    "lastName": "Tomar",
    "mobileNo": "",
    "workMobileNo": "8076605795",
    "email": "priyanka.tomar@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "00",
    "discussWithPerson": "Priyanka",
    "expectedFees": null,
    "quotedAmount": "10000"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "65e6cd5cf9222577acba7566",
  "name": "SME NEPZ NOIDA",
  "branchCode": "",
  "mobileNo": "01202462329",
  "alternateMobileNo": "",
  "email": "sbi.09837@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "NEPZ NOIDA BRANCH, PHASE 2, DIST GHAZIABAD UTTAR
PRADESH - 201305M\nGAUTAM BUDDHA NAGAR\n201305\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
  "_id": "60af3d172ffdf65bcd6585cd",
  "role": "PICKUPPERSON",
  "firstName": "Sachin",
  "email": "sachin.joshi@vastukala.org",
  "lastName": "Joshi",
  "mobileNo": "9167204063",
  "shortName": "SJ",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60af3d172ffdf65bcd6585cd\\
\\profilePhoto_1622372567671_Sachin Joshi Photo 3 (2).jpg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f949ce45132d6a6bddbcc3",
  "role": "SITEENGINEER",
  "firstName": "Tushar ",
  "email": "tusharbhuwad90@gmail.com",
  "lastName": "Bhuwad",
  "mobileNo": "9082053889",
  "designation": "",
  "shortName": "TSB",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f949ce45132d6a6bddbcc3/
profilePhoto_1668058314746_WhatsApp_Image_20221110_at_105931_AM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shyma_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
```

```

"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shymam_Photo.jpg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
}
],
}
]

```

```
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.141771061935028",
  "longitude": "72.83473974579633"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.83473974579633,
    19.141771061935028
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "14/03/2024 10:54 am"
    },
    {
      "dateTime": "14/03/2024 12:00 am"
    },
    {
      "dateTime": "14/03/2024 12:00 am"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-03-14",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-03-14",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-03-14",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "3BHK",
  "label": "3 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
```

```
"state": {
  "status": true,
  "name": "State",
  "key": "state",
  "value": "Maharashtra",
  "label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Oshiwara",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "21",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "1",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
```

```
"value": "Mumbai",
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Andheri",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Dheeraj Gaurav Heights 1 Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Off. New Link Road",
  "label": false
},
"street2": {
```



```
"status": true,
"name": "Street 2",
"key": "street2",
"value": "Opp. Infinity Mall",
"label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "41(Part)",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
```

```
"label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "588, 589, 590 & 591",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "2101",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
```

```
"name": "SRO",
"key": "SRO",
"value": "",
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400053",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Andheri (West)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "ItalianMarbleFlooring",
    "label": "Italian Marble Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  }
}
```

```
},
"windows": {
  "value": "PowderCoatedAluminiumSliding",
  "label": "Powder Coated Aluminium Sliding"
},
"fittings": {
  "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
  "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
},
"finishing": {
  "value": "Cement_Plastering",
  "label": "Cement Plastering"
}
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MCGM",
    "label": "Municipal Corporation of Greater Mumbai (MCGM)"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "90 Feet Road",
    "west": "Maurya Classic",
    "south": "Building No. 2 & 3",
    "east": "Link Plaza"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
    "south": "Details not available",
```

```
"east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "asPerDocument": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Occupancy Certificate is available, we assumed that
the construction is as per approved plan",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": ""
},
"compositeRate": {
  "remark": "As per site inspection, building external repairing work was in progress.",
  "depreciationPercentage": "33",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "31010",
  "depreciatedBuildingRate": "2010"
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "216220",
  "landRate": "116090",
  "igrImage": "cases/65f151f8857bdc098a9c99bc/igr_1711622459854_Image.png",
  "squareMeterGuideLineRate": "248653.00",
  "squareFeetGuideLineRate": "23101.00"
},
"igrFinalRate": {
  "floorRatePercentage": "15",
  "depreciationPercentage": "78",
  "rate": "20391.00",
  "squareMeterGuideLineRate": "219489.00",
```

```
"squareFeetGuideLineRate": "20391.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Tenant_Occupied",
    "label": "Tenant Occupied"
  },
  "monthlyRent": "70,000/- Present rental income per month",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "N.A.",
  "floorSpaceIndex": "As per MCGM norms",
  "tenantName": "Mr. Sandeep Chatterjee",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Average",
    "label": "Average"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "N.A."
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\\_Thk._Brick_Masonry",
    "label": "6\\_Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  }
}
```

```
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "Car Parking Space No. 244",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2002",
  "fullDate": "1/1/2002"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
```

```
"label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
}
```



```
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "38",
"ageOfBuilding": "22",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "24",
"flatFloorNo": "21",
"noOfLifts": "3",
"noOfDwellingUnitsInBuilding": "3"
},
"finalPlinthArea": {
  "area": "1408.80",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Metro_Station",
      "label": "Metro Station"
    },
    "routeMapImg": "cases/65f151f8857bdc098a9c99bc/
routeMap_1711622592835_Image.png",
    "routeLat": "19.141362",
    "routeLng": "72.834381",
    "stationName": "Lower Oshiwara",
    "routeDistance": "400 M."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "lxt1t7",
      "name": "lxt1t7",

```

```
    "image": "cases/65f151f8857bdc098a9c99bc/
routeMap_1711622535163_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "36405740.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValue": "0",
  "finalValue": "36405740.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Fri Mar 29 2024 17:41:58 GMT+0530 (India Standard Time)",
  "number": "2305816",
  "dayCount": "26",
  "monthCount": "564",
```

```
"generatedBy": "5fc78e26625ecd20ec1f88e9"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "28726841.00",
  "selectedBuildUpValue": "1408.80",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "66054a155ca1625e506577ef",
      "name": "externalImg_r_1711622676766_TimePhoto_20240314_142308.jpg",
      "path": "cases/65f151f8857bdc098a9c99bc/
externalImg_r_1711622676766_TimePhoto_20240314_142308.jpg",
```

```
    "orientation": "portrait"
  }
],
"selfieWithSiteVisitImages": [],
"externalPhotos": [
  {
    "status": false,
    "_id": "66054a155ca1625e506577ed",
    "name": "externallmg_r_1711622676757_TimePhoto_20240314_142233.jpg",
    "path": "cases/65f151f8857bdc098a9c99bc/
externallmg_r_1711622676757_TimePhoto_20240314_142233.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66054a095ca1625e50657796",
    "name": "externallmg_r_1711622665208_TimePhoto_20240314_135418.jpg",
    "path": "cases/65f151f8857bdc098a9c99bc/
externallmg_r_1711622665208_TimePhoto_20240314_135418.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66054a095ca1625e50657791",
    "name": "externallmg_r_1711622665195_IMG20240314142049.jpg",
    "path": "cases/65f151f8857bdc098a9c99bc/
externallmg_r_1711622665195_IMG20240314142049.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66054a155ca1625e506577eb",
    "name": "externallmg_r_1711622676744_TimePhoto_20240314_142224.jpg",
    "path": "cases/65f151f8857bdc098a9c99bc/
externallmg_r_1711622676744_TimePhoto_20240314_142224.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66054a155ca1625e506577ef",
    "name": "externallmg_r_1711622676766_TimePhoto_20240314_142308.jpg",
    "path": "cases/65f151f8857bdc098a9c99bc/
externallmg_r_1711622676766_TimePhoto_20240314_142308.jpg",
    "orientation": "portrait"
  }
],
```

```
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "66054a155ca1625e506577e6",
    "name": "Living Room",
    "path": "cases/65f151f8857bdc098a9c99bc/
externallmg_r_1711622676697_TimePhoto_20240314_140308.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66054a155ca1625e506577e7",
    "name": "Living Room",
    "path": "cases/65f151f8857bdc098a9c99bc/
externallmg_r_1711622676704_TimePhoto_20240314_140318.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66054a095ca1625e5065779f",
    "name": "Living Room",
    "path": "cases/65f151f8857bdc098a9c99bc/
externallmg_r_1711622665243_TimePhoto_20240314_140240.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66054a095ca1625e506577a2",
    "name": "Living Room",
    "path": "cases/65f151f8857bdc098a9c99bc/
externallmg_r_1711622665250_TimePhoto_20240314_140301.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66054a155ca1625e506577e8",
    "name": "Living Room",
    "path": "cases/65f151f8857bdc098a9c99bc/
externallmg_r_1711622676701_TimePhoto_20240314_140314.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66054a095ca1625e506577a1",
```

```
    "name": "Living Room",
    "path": "cases/65f151f8857bdc098a9c99bc/
externallmg_r_1711622665248_TimePhoto_20240314_140251.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66054a095ca1625e5065779e",
    "name": "Living Room",
    "path": "cases/65f151f8857bdc098a9c99bc/
externallmg_r_1711622665240_TimePhoto_20240314_140222.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66054a095ca1625e5065779d",
    "name": "Living Room",
    "path": "cases/65f151f8857bdc098a9c99bc/
externallmg_r_1711622665236_TimePhoto_20240314_140216.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66054a095ca1625e50657797",
    "name": "Living Room",
    "path": "cases/65f151f8857bdc098a9c99bc/
externallmg_r_1711622665213_TimePhoto_20240314_135953.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66054a155ca1625e506577ea",
    "name": "Living Room",
    "path": "cases/65f151f8857bdc098a9c99bc/
externallmg_r_1711622676712_TimePhoto_20240314_141840.jpg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
```



```
"max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
    "title": "Interior Decorations",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
```

```
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "1174.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentIds": [],
"_id": "65f151f8857bdc098a9c99bc",
"ownerName": "Mr. Prabhat Kumar",
"ownerPhoneNo": "0000000000",
"appAddress": "Flat No. 2101, 21floor Dheeraj Gaurav Heights-1 off. New Link Road
Andheri west Mumbai-400053",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "27/03/2002",
      "from": {
```

```
    "value": "Developers",
    "label": "Developers"
  },
  "Developers": "M/s. Ravi Foundation",
  "to": {
    "value": "Purchaser",
    "label": "Purchaser"
  },
  "Purchaser": "Mr. Prabhat Kumar",
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "2020/2002"
},
"isHardCopy": false,
"displayStatus": true,
"id": "895992",
"path": "cases/65f151f8857bdc098a9c99bc/document_1710320448611_171032062
2127_Dheeraj_Gaurav_Heights_Agreement_Paper1.pdf",
"fileName": "document_1710320448611_1710320622127_Dheeraj_Gaurav_Heights
_Agreement_Paper1.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "12/07/2001",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_of_Greater_Mumbai",
      "label": "Municipal Corporation of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "CE / 5985 / WS / AK"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1711621292918_AGR.pdf",
  "path": "cases/65f151f8857bdc098a9c99bc/document_1711621292918_AGR.pdf",
  "id": "244893",
  "uploadedBy": "60eeaeddf3dd69653a581316",
```

```
"createdAt": "Thu Mar 28 2024 15:51:33 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "08/11/2002",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_of_Greater_Mumbai",
      "label": "Municipal Corporation of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "CE / 5985 / WS / AK"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1711621422563_OC.pdf",
"path": "cases/65f151f8857bdc098a9c99bc/document_1711621422563_OC.pdf",
"id": "839581",
"uploadedBy": "60eeaeddf3dd69653a581316",
"createdAt": "Thu Mar 28 2024 15:53:42 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1248aa6d152c1801b2ef",
    "label": "Society Share Certificate"
  },
  "inputs": {
    "documentDate": "06/11/2006",
    "nameOfApprovingAuthority": {
      "value": "SOCIETY",
      "label": "SOCIETY"
    }
  },
  "to": {
    "value": "purchaser",
    "label": "purchaser"
  },
  "purchaser": "Prabhat Kumar",
  "number": {
    "value": "No",
    "label": "No"
  }
}
```

```
    },
    "No": "58"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1711621472513_SHARE.pdf",
  "path": "cases/65f151f8857bdc098a9c99bc/
document_1711621472513_SHARE.pdf",
  "id": "233925",
  "uploadedBy": "60eeaeddf3dd69653a581316",
  "createdAt": "Thu Mar 28 2024 15:54:32 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1285aa6d152c1801b40d",
    "label": "Car Parking Allotment Letter"
  },
  "inputs": {
    "documentDate": "22/10/2013",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "DGHS / 01 / 2013"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1711621508128_CAR_PARKING.pdf",
  "path": "cases/65f151f8857bdc098a9c99bc/
document_1711621508128_CAR_PARKING.pdf",
  "id": "841543",
  "uploadedBy": "60eeaeddf3dd69653a581316",
  "createdAt": "Thu Mar 28 2024 15:55:08 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "007639",
"createdBy": "60af3d172ffdf65bcd6585cd",
"caseHistory": [
  {
    "id": "336077",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Mar 13 2024 12:42:56 GMT+0530 (India Standard Time)"
  }
],
"owners": [
```

```
{
  "name": "Mr. Prabhat Kumar",
  "phone": "0000000000",
  "ownershipShare": "",
  "email": "",
  "id": "147897"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "294655",
    "name": "Living Room",
    "length": "11.83",
    "length1": "11",
    "length2": "10",
    "width": "21.17",
    "width1": "21",
    "width2": "2",
    "totalArea": "250.47",
    "images": [],
    "extraAreas": [],
    "finalArea": "250.47"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "name": "Dining",
    "length": "8.67",
    "length1": "8",
    "length2": "8",
    "width": "8.83",
    "width1": "8",
    "width2": "10",
    "totalArea": "76.56",
    "images": [],
    "extraAreas": [],
    "finalArea": "76.56"
  }
]
```

```
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Passage",
  "length": "1.67",
  "length1": "1",
  "length2": "8",
  "width": "2.17",
  "width1": "2",
  "width2": "2",
  "totalArea": "3.61",
  "images": [],
  "extraAreas": [],
  "finalArea": "3.61"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Passage",
  "length": "3.42",
  "length1": "3",
  "length2": "5",
  "width": "13.00",
  "width1": "13",
  "width2": "00",
  "totalArea": "44.42",
  "images": [],
  "extraAreas": [],
  "finalArea": "44.42"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Kitchen",
  "length": "12.92",
  "length1": "12",
```



```
"length2": "11",
"width": "8.33",
"width1": "8",
"width2": "4",
"totalArea": "107.64",
"images": [],
"extraAreas": [],
"finalArea": "107.64"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "13.33",
  "length1": "13",
  "length2": "4",
  "width": "10.08",
  "width1": "10",
  "width2": "1",
  "totalArea": "134.44",
  "images": [],
  "extraAreas": [],
  "finalArea": "134.44"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Bedroom",
  "length": "10.08",
  "length1": "10",
  "length2": "1",
  "width": "13.83",
  "width1": "13",
  "width2": "10",
  "totalArea": "139.49",
  "images": [],
  "extraAreas": [],
  "finalArea": "139.49"
},
{

```

```
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "7",
"name": "Toilet",
"length": "7.67",
"length1": "7",
"length2": "8",
"width": "5.50",
"width1": "5",
"width2": "6",
"totalArea": "42.17",
"images": [],
"extraAreas": [],
"finalArea": "42.17"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Bedroom",
  "length": "13.92",
  "length1": "13",
  "length2": "11",
  "width": "11.25",
  "width1": "11",
  "width2": "3",
  "totalArea": "156.56",
  "images": [],
  "extraAreas": [],
  "finalArea": "156.56"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Toilet",
  "length": "8.83",
  "length1": "8",
  "length2": "10",
  "width": "5.17",
```

```
"width1": "5",
"width2": "2",
"totalArea": "45.64",
"images": [],
"extraAreas": [],
"finalArea": "45.64"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "10",
  "name": "Toilet",
  "length": "8.33",
  "length1": "8",
  "length2": "4",
  "width": "3.83",
  "width1": "3",
  "width2": "10",
  "totalArea": "31.94",
  "images": [],
  "extraAreas": [],
  "finalArea": "31.94"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "11",
  "name": "Balcony",
  "length": "6.08",
  "length1": "6",
  "length2": "1",
  "width": "5.17",
  "width1": "5",
  "width2": "2",
  "totalArea": "31.43",
  "images": [],
  "extraAreas": [],
  "finalArea": "31.43"
},
{
  "measurementType": {
    "value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "id": "13",
  "name": "Balcony",
  "length": "",
  "length1": "4",
  "length2": "3",
  "width": "",
  "width1": "8",
  "width2": "9",
  "totalArea": "37.19",
  "images": [],
  "finalArea": "37.19",
  "extraAreas": []
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "561329",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "1174",
    "squareMeterArea": "109.07",
    "docFinalBuiltUp": "1408.8",
    "docFinalBuiltUpSquareMeter": "130.884",
    "docBuiltupPercentage": "20",
    "docSaleablePercentage": "20",
    "docFinalSaleable": "1690.56",
    "docFinalSaleableSquareMeter": "157.06079999999997"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": false,
    "_id": "660548e65ca1625e506573bd",
    "property": "Residential Flat",
```

```
"area": "801",
"builtUpPercentage": "0",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Built_Up",
"source": "Index_no.2",
"expectedPrice": "20500000",
"expectedRate": "25593.01",
"builtUpExpectedRate": "20500000",
"image": "cases/65f151f8857bdc098a9c99bc/
indicator_1711622288459_Image.jpeg",
"squareMeter": "74.42",
"id": "815121"
},
{
  "printlnReport": false,
  "_id": "660548e65ca1625e506573be",
  "property": "Residential Flat",
  "area": "1400",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "magic_bricks",
  "expectedPrice": "42500000",
  "expectedRate": "30357.14",
  "builtUpExpectedRate": "25297.62",
  "image": "cases/65f151f8857bdc098a9c99bc/
indicator_1711622319670_Image.png",
  "squareMeter": "130.06",
  "id": "707775"
},
{
  "printlnReport": false,
  "_id": "660548e65ca1625e506573bf",
  "property": "Residential Flat",
  "area": "1300",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "source": "Housing.Com",
  "expectedPrice": "32500000",
  "expectedRate": "25000.00",
  "builtUpExpectedRate": "32500000",
  "image": "cases/65f151f8857bdc098a9c99bc/
indicator_1711622345313_Image.png",
```

```
"squareMeter": "120.77",
"id": "254033"
},
{
  "printlnReport": false,
  "_id": "660548e65ca1625e506573c0",
  "property": "Residential Flat",
  "area": "1500",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "source": "https://www.99acres.com/",
  "expectedPrice": "40000000",
  "expectedRate": "26666.67",
  "builtUpExpectedRate": "40000000",
  "image": "cases/65f151f8857bdc098a9c99bc/
indicator_1711622374176_Image.png",
  "squareMeter": "139.35",
  "id": "733915"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66054a095ca1625e5065778f",
    "name": "externalImg_r_1711622665182_IMG20240314141912.jpg",
    "path": "cases/65f151f8857bdc098a9c99bc/
externalImg_r_1711622665182_IMG20240314141912.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66054a095ca1625e50657790",
    "name": "externalImg_r_1711622665192_IMG20240314142043.jpg",
    "path": "cases/65f151f8857bdc098a9c99bc/
externalImg_r_1711622665192_IMG20240314142043.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66054a095ca1625e50657791",
    "name": "externalImg_r_1711622665195_IMG20240314142049.jpg",
```

```
    "path": "cases/65f151f8857bdc098a9c99bc/
externallmg_r_1711622665195_IMG20240314142049.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66054a095ca1625e50657792",
    "name": "externallmg_r_1711622665187_IMG20240314141913.jpg",
    "path": "cases/65f151f8857bdc098a9c99bc/
externallmg_r_1711622665187_IMG20240314141913.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66054a095ca1625e50657793",
    "name": "externallmg_r_1711622665199_IMG20240314142100.jpg",
    "path": "cases/65f151f8857bdc098a9c99bc/
externallmg_r_1711622665199_IMG20240314142100.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66054a095ca1625e50657794",
    "name": "externallmg_r_1711622665204_IMG20240314142101.jpg",
    "path": "cases/65f151f8857bdc098a9c99bc/
externallmg_r_1711622665204_IMG20240314142101.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66054a095ca1625e50657795",
    "name": "externallmg_r_1711622665211_TimePhoto_20240314_135934.jpg",
    "path": "cases/65f151f8857bdc098a9c99bc/
externallmg_r_1711622665211_TimePhoto_20240314_135934.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66054a095ca1625e50657796",
    "name": "externallmg_r_1711622665208_TimePhoto_20240314_135418.jpg",
    "path": "cases/65f151f8857bdc098a9c99bc/
externallmg_r_1711622665208_TimePhoto_20240314_135418.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66054a095ca1625e50657797",
  "name": "externallmg_r_1711622665213_TimePhoto_20240314_135953.jpg",
  "path": "cases/65f151f8857bdc098a9c99bc/
externallmg_r_1711622665213_TimePhoto_20240314_135953.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66054a095ca1625e50657798",
  "name": "externallmg_r_1711622665215_TimePhoto_20240314_135957.jpg",
  "path": "cases/65f151f8857bdc098a9c99bc/
externallmg_r_1711622665215_TimePhoto_20240314_135957.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66054a095ca1625e50657799",
  "name": "externallmg_r_1711622665227_TimePhoto_20240314_140055.jpg",
  "path": "cases/65f151f8857bdc098a9c99bc/
externallmg_r_1711622665227_TimePhoto_20240314_140055.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66054a095ca1625e5065779a",
  "name": "externallmg_r_1711622665221_TimePhoto_20240314_140001.jpg",
  "path": "cases/65f151f8857bdc098a9c99bc/
externallmg_r_1711622665221_TimePhoto_20240314_140001.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66054a095ca1625e5065779b",
  "name": "externallmg_r_1711622665230_TimePhoto_20240314_140132.jpg",
  "path": "cases/65f151f8857bdc098a9c99bc/
externallmg_r_1711622665230_TimePhoto_20240314_140132.jpg",
  "orientation": "portrait"
}
```



```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66054a095ca1625e5065779c",
      "name": "externallmg_r_1711622665234_TimePhoto_20240314_140134.jpg",
      "path": "cases/65f151f8857bdc098a9c99bc/
externallmg_r_1711622665234_TimePhoto_20240314_140134.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66054a095ca1625e5065779d",
      "name": "externallmg_r_1711622665236_TimePhoto_20240314_140216.jpg",
      "path": "cases/65f151f8857bdc098a9c99bc/
externallmg_r_1711622665236_TimePhoto_20240314_140216.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66054a095ca1625e5065779e",
      "name": "externallmg_r_1711622665240_TimePhoto_20240314_140222.jpg",
      "path": "cases/65f151f8857bdc098a9c99bc/
externallmg_r_1711622665240_TimePhoto_20240314_140222.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66054a095ca1625e5065779f",
      "name": "externallmg_r_1711622665243_TimePhoto_20240314_140240.jpg",
      "path": "cases/65f151f8857bdc098a9c99bc/
externallmg_r_1711622665243_TimePhoto_20240314_140240.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66054a095ca1625e506577a0",
      "name": "externallmg_r_1711622665245_TimePhoto_20240314_140248.jpg",
      "path": "cases/65f151f8857bdc098a9c99bc/
externallmg_r_1711622665245_TimePhoto_20240314_140248.jpg",
      "orientation": "portrait"
    },
  },
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66054a095ca1625e506577a1",
  "name": "externallmg_r_1711622665248_TimePhoto_20240314_140251.jpg",
  "path": "cases/65f151f8857bdc098a9c99bc/
externallmg_r_1711622665248_TimePhoto_20240314_140251.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66054a095ca1625e506577a2",
  "name": "externallmg_r_1711622665250_TimePhoto_20240314_140301.jpg",
  "path": "cases/65f151f8857bdc098a9c99bc/
externallmg_r_1711622665250_TimePhoto_20240314_140301.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66054a155ca1625e506577e6",
  "name": "externallmg_r_1711622676697_TimePhoto_20240314_140308.jpg",
  "path": "cases/65f151f8857bdc098a9c99bc/
externallmg_r_1711622676697_TimePhoto_20240314_140308.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66054a155ca1625e506577e7",
  "name": "externallmg_r_1711622676704_TimePhoto_20240314_140318.jpg",
  "path": "cases/65f151f8857bdc098a9c99bc/
externallmg_r_1711622676704_TimePhoto_20240314_140318.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66054a155ca1625e506577e8",
  "name": "externallmg_r_1711622676701_TimePhoto_20240314_140314.jpg",
  "path": "cases/65f151f8857bdc098a9c99bc/
externallmg_r_1711622676701_TimePhoto_20240314_140314.jpg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66054a155ca1625e506577e9",
    "name": "externallmg_r_1711622676706_TimePhoto_20240314_141834.jpg",
    "path": "cases/65f151f8857bdc098a9c99bc/
externallmg_r_1711622676706_TimePhoto_20240314_141834.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66054a155ca1625e506577ea",
    "name": "externallmg_r_1711622676712_TimePhoto_20240314_141840.jpg",
    "path": "cases/65f151f8857bdc098a9c99bc/
externallmg_r_1711622676712_TimePhoto_20240314_141840.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66054a155ca1625e506577eb",
    "name": "externallmg_r_1711622676744_TimePhoto_20240314_142224.jpg",
    "path": "cases/65f151f8857bdc098a9c99bc/
externallmg_r_1711622676744_TimePhoto_20240314_142224.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66054a155ca1625e506577ec",
    "name": "externallmg_r_1711622676717_TimePhoto_20240314_142221.jpg",
    "path": "cases/65f151f8857bdc098a9c99bc/
externallmg_r_1711622676717_TimePhoto_20240314_142221.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66054a155ca1625e506577ed",
    "name": "externallmg_r_1711622676757_TimePhoto_20240314_142233.jpg",
    "path": "cases/65f151f8857bdc098a9c99bc/
externallmg_r_1711622676757_TimePhoto_20240314_142233.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "66054a155ca1625e506577ee",
  "name": "externallmg_r_1711622676772_TimePhoto_20240314_142324.jpg",
  "path": "cases/65f151f8857bdc098a9c99bc/
externallmg_r_1711622676772_TimePhoto_20240314_142324.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66054a155ca1625e506577ef",
  "name": "externallmg_r_1711622676766_TimePhoto_20240314_142308.jpg",
  "path": "cases/65f151f8857bdc098a9c99bc/
externallmg_r_1711622676766_TimePhoto_20240314_142308.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66054a155ca1625e506577f0",
  "name": "externallmg_r_1711622676761_TimePhoto_20240314_142306.jpg",
  "path": "cases/65f151f8857bdc098a9c99bc/
externallmg_r_1711622676761_TimePhoto_20240314_142306.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66054a155ca1625e506577f1",
  "name": "externallmg_r_1711622676777_TimePhoto_20240314_142416.jpg",
  "path": "cases/65f151f8857bdc098a9c99bc/
externallmg_r_1711622676777_TimePhoto_20240314_142416.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66054a155ca1625e506577f2",
  "name": "externallmg_r_1711622676781_TimePhoto_20240314_142418.jpg",
  "path": "cases/65f151f8857bdc098a9c99bc/
externallmg_r_1711622676781_TimePhoto_20240314_142418.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "66054a155ca1625e506577f3",
    "name": "externalimg_r_1711622676785_TimePhoto_20240314_142711.jpg",
    "path": "cases/65f151f8857bdc098a9c99bc/
externalimg_r_1711622676785_TimePhoto_20240314_142711.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66054a155ca1625e506577f4",
    "name": "externalimg_r_1711622676787_TimePhoto_20240314_142714.jpg",
    "path": "cases/65f151f8857bdc098a9c99bc/
externalimg_r_1711622676787_TimePhoto_20240314_142714.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "AGR.pdf",
    "filename": "1711622795330_AGR.pdf",
    "path": "cases/65f151f8857bdc098a9c99bc/
processingDocuments/1711622795330_AGR.pdf",
    "size": "59583989",
    "createdAt": "Thu Mar 28 2024 16:16:36 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "CAR PARKING.pdf",
    "filename": "1711622796562_CAR_PARKING.pdf",
    "path": "cases/65f151f8857bdc098a9c99bc/
processingDocuments/1711622796562_CAR_PARKING.pdf",
    "size": "1243991",
    "createdAt": "Thu Mar 28 2024 16:16:36 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "IGR-01.pdf",
    "filename": "1711622796583_IGR01.pdf",
    "path": "cases/65f151f8857bdc098a9c99bc/
processingDocuments/1711622796583_IGR01.pdf",
    "size": "150507",
    "createdAt": "Thu Mar 28 2024 16:16:36 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
```

```
    "originalname": "IGR-02.pdf",
    "filename": "1711622796588_IGR02.pdf",
    "path": "cases/65f151f8857bdc098a9c99bc/
processingDocuments/1711622796588_IGR02.pdf",
    "size": "152383",
    "createdAt": "Thu Mar 28 2024 16:16:36 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "IGR-03.pdf",
    "filename": "1711622796592_IGR03.pdf",
    "path": "cases/65f151f8857bdc098a9c99bc/
processingDocuments/1711622796592_IGR03.pdf",
    "size": "159417",
    "createdAt": "Thu Mar 28 2024 16:16:36 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "IGR-04.pdf",
    "filename": "1711622796597_IGR04.pdf",
    "path": "cases/65f151f8857bdc098a9c99bc/
processingDocuments/1711622796597_IGR04.pdf",
    "size": "147764",
    "createdAt": "Thu Mar 28 2024 16:16:36 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "IGR-05.pdf",
    "filename": "1711622796602_IGR05.pdf",
    "path": "cases/65f151f8857bdc098a9c99bc/
processingDocuments/1711622796602_IGR05.pdf",
    "size": "157911",
    "createdAt": "Thu Mar 28 2024 16:16:36 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "IGR-06.pdf",
    "filename": "1711622796606_IGR06.pdf",
    "path": "cases/65f151f8857bdc098a9c99bc/
processingDocuments/1711622796606_IGR06.pdf",
    "size": "156837",
    "createdAt": "Thu Mar 28 2024 16:16:36 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "IGR-07.pdf",
```

```
    "filename": "1711622796611_IGR07.pdf",
    "path": "cases/65f151f8857bdc098a9c99bc/
processingDocuments/1711622796611_IGR07.pdf",
    "size": "158733",
    "createdAt": "Thu Mar 28 2024 16:16:36 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "IGR-08.pdf",
    "filename": "1711622830048_IGR08.pdf",
    "path": "cases/65f151f8857bdc098a9c99bc/
processingDocuments/1711622830048_IGR08.pdf",
    "size": "155876",
    "createdAt": "Thu Mar 28 2024 16:17:10 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "IGR-09.pdf",
    "filename": "1711622830052_IGR09.pdf",
    "path": "cases/65f151f8857bdc098a9c99bc/
processingDocuments/1711622830052_IGR09.pdf",
    "size": "150720",
    "createdAt": "Thu Mar 28 2024 16:17:10 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "IGR-10.pdf",
    "filename": "1711622830059_IGR10.pdf",
    "path": "cases/65f151f8857bdc098a9c99bc/
processingDocuments/1711622830059_IGR10.pdf",
    "size": "164250",
    "createdAt": "Thu Mar 28 2024 16:17:10 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "IMG20240315021953.jpg",
    "filename": "1711622830071_IMG20240315021953.jpg",
    "path": "cases/65f151f8857bdc098a9c99bc/
processingDocuments/1711622830071_IMG20240315021953.jpg",
    "size": "3493185",
    "createdAt": "Thu Mar 28 2024 16:17:10 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "IMG20240315022643.jpg",
    "filename": "1711622830153_IMG20240315022643.jpg",
```

```
    "path": "cases/65f151f8857bdc098a9c99bc/
processingDocuments/1711622830153_IMG20240315022643.jpg",
    "size": "3471466",
    "createdAt": "Thu Mar 28 2024 16:17:10 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "OC.pdf",
    "filename": "1711622830249_OC.pdf",
    "path": "cases/65f151f8857bdc098a9c99bc/
processingDocuments/1711622830249_OC.pdf",
    "size": "2292443",
    "createdAt": "Thu Mar 28 2024 16:17:10 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "SHARE.pdf",
    "filename": "1711622830347_SHARE.pdf",
    "path": "cases/65f151f8857bdc098a9c99bc/
processingDocuments/1711622830347_SHARE.pdf",
    "size": "622690",
    "createdAt": "Thu Mar 28 2024 16:17:10 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "Summary New=PRABHAT.xlsx",
    "filename": "1711622830387_Summary_NewPRABHAT.xlsx",
    "path": "cases/65f151f8857bdc098a9c99bc/
processingDocuments/1711622830387_Summary_NewPRABHAT.xlsx",
    "size": "4990881",
    "createdAt": "Thu Mar 28 2024 16:17:10 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "60eeaeddf3dd69653a581316",
      "role": "MAKER + RATE VERFIER + CHEAKER",
      "firstName": "Shyam",
      "lastName": "Kajvilkar",
      "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shyma_Photo.jpg"
    }
  }
],
```



```
"workType": "MAKER",
"display": true,
"status": true,
"_id": "65f599f1857bdc098aa46a12",
"note": "Pending for value confirmation",
"taskId": "65f3d1f5857bdc098aa022d2",
"createdAt": "2024-03-16T13:09:05.476Z"
},
{
  "createdBy": {
    "_id": "60eeaeddf3dd69653a581316",
    "role": "MAKER + RATE VERFIER + CHEAKER",
    "firstName": "Shyam",
    "lastName": "Kajvilkar",
    "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shyam_Photo.jpg"
  },
  "workType": "MAKER",
  "display": true,
  "status": true,
  "_id": "66054e8a5ca1625e506589d0",
  "note": "Draft Report Sent to Bank",
  "taskId": "65f3d1f5857bdc098aa022d2",
  "createdAt": "2024-03-28T11:03:38.472Z"
}
],
"createdAt": "2024-03-13T07:12:56.653Z",
"updatedAt": "2024-03-29T12:20:43.000Z",
"__v": 0,
"uniqueNo": "",
"updatedBy": "5fc78e26625ecd20ec1f88e9",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 2101, 21st Floor, Building No 1, Dheeraj Gaurav
Heights 1 Co-op. Hsg. Soc. Ltd., Off. New Link Road, Opp. Infinity Mall, Village -
Oshiwara, Andheri (West), Taluka - Andheri, District - Mumbai Suburban, Mumbai,
400053, State - Maharashtra, India",
"addressForMap": "",
"caseReferredBy": "60af3d172ffdf65bcd6585cd",
"contactPersonName": "Mr. Sandeep Chatterjee",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": ""
```

```
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Tenant",
"siteVisitContactNo": "0000000000",
"briefDescOfProperty": "3 Bedroom + Living Room + Kitchen + Dining + 2 Passage +
3 Toilet + 2 Balcony",
"carpetTotal": "1101.56",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0.00",
"builtupPercentage": "20",
"finalBuiltupArea": "1321.87",
"finalCarpetArea": "1101.56",
"finalSalableArea": "1586.25",
"salablePercentage": "20",
"toBeAdded": "",
"extendOfSiteRemark": "\nAll the above areas are within 6% of the Agreement for Sale
Area. The above calculations and detail measurements taken by us prove that the
Agreement for Sale area is not exorbitantly inflated. Hence, valuation is based on the
Agreement for Sale area.\n\n",
"siteMeasurementRemark": "",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalSaleablePercentage": "20",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 1174.00",
"buildingServicesRate": "3000",
"flatRate": "32000",
"landOtherRate": "29000",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
  "leaseTo": "",
  "remainingLeasePeriod": 0,
  "leaseDate": ""
}
},
```

"reportGeneratedDate": "Fri Mar 29 2024 15:50:32 GMT+0530 (India Standard Time)",
"siteVisitDate": "2024-03-14"

}

Name	Length	Width	Total
Composition :			
Living Room	11'10"	21'2"	250.47
Dining	8'8"	8'10"	76.56
Passage	1'8"	2'2"	3.61
Passage	3'5"	13'00"	44.42
Kitchen	12'11"	8'4"	107.64
Bedroom	13'4"	10'1"	134.44
Bedroom	10'1"	13'10"	139.49
Toilet	7'8"	5'6"	42.17
Bedroom	13'11"	11'3"	156.56
Toilet	8'10"	5'2"	45.64
Toilet	8'4"	3'10"	31.94
Balcony	6'1"	5'2"	31.43
Balcony	4'3"	8'9"	37.19
Other Composition :			