

```
{
  "typeOfReport": {
    "label": "Gala",
    "value": "Gala"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63ad7dca191f7b344b003ede"
    },
    "type": "CREDITOFFICER",
    "_id": "65c33048b0ec7f2151fdb8bc",
    "firstName": "Shashank ",
    "lastName": "Kumar",
    "mobileNo": "",
    "workMobileNo": "7905284698",
    "email": "shashank.kumar@unionbankofindia.bank"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "3453720....5929779",
    "discussWithPerson": "Shashank ",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63ad7dca191f7b344b003ede",
  "name": "UBI-GOREGAON (EAST)",
  "branchCode": "",
  "mobileNo": "\022-26863400 022-26862835",
  "alternateMobileNo": "",
  "email": "goregaon@unionbankofindia.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "172/73, Shree Sadan, Shantaben Estate, Goregoan (East), Mumbai -
400 063."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f93be845132d6a6bdda676",
  "zoneName": "MUMBAI SOUTH"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
    "_id": "60af6ae22ffdf65bcd65861d",
    "role": "PICKUPPERSON",
    "firstName": "Sunil",
    "email": "misalsunil87@gmail.com",
    "lastName": "Misal",
    "mobileNo": "8422982721",
    "shortName": "SM",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60af6ae22ffdf65bcd65861d\\
\\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "648fcad91b499c2d52dc86f3",
    "role": "SITEENGINEER",
    "firstName": "Barkat",
    "email": "barkathodekar68@gmail.com",
    "lastName": "Hodekar",
    "mobileNo": "8879011615",
    "designation": "Site Engg",
    "shortName": "Barkat",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "60f915d3f3dd69653a592199",
    "role": "MAKER + RATE VERFIER + CHEAKER",
    "firstName": "Shobha",
    "email": "shobha@vastukala.org",
    "lastName": "Kuperkar",
    "mobileNo": "9004134140",
    "designation": "",
    "shortName": "SH",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
  },
  "maker": null,
  "checker": null,
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "IBBI/RV/07/2018/10366",
```

```
    "label": "Registered Valuer"
  }
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": ""
```

```
    "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
    "PANNo": "AERPC9086P",
    "fatherName": "Baburao"
  }
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.11629774727361",
  "longitude": "72.88518603891134"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.88518603891134,
    19.11629774727361
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "20/03/2024 06:09 pm"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  }
}
```

```
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Marol",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Ground",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
```

```
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Raj Industrial Complex Premises CHSL",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Military Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
}
```

```
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "C",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
```



```
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "Gala No 24",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
```

```
"status": false,
"name": "Police Station(P.S)",
"key": "policeStation",
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Andheri East",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
```

```
"finalLatLng": {
  "coordinates": []
},
"locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
```

```
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
```

```
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentIds": [],
"_id": "65fad3f65ca1625e50589cc4",
"ownerName": "Jatin Todi "
```



```
"ownerPhoneNo": "9820293331",
"appAddress": "Gala no 24 & 24 A C- Wing Raj Industrial Complex Premices Co-
operative HSG Soc Ltd Military Road Marol Andheri East 400059",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/65fad3f65ca1625e50589cc4/
document_1710936713061_1710936894838_Gala_No_24.pdf",
    "fileName": "document_1710936713061_1710936894838_Gala_No_24.pdf",
    "id": "694669",
    "uploadedBy": "60af6ae22ffdf65bcd65861d",
    "createdAt": "Wed Mar 20 2024 17:47:57 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": "Deed Of Gift",
      "value": "60ae1253aa6d152c1801b323"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/65fad3f65ca1625e50589cc4/
document_1710936776324_1710936957609_Gala_No_24A.pdf",
    "fileName": "document_1710936776324_1710936957609_Gala_No_24A.pdf",
    "id": "198213",
    "uploadedBy": "60af6ae22ffdf65bcd65861d",
    "createdAt": "Wed Mar 20 2024 17:47:57 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "007858",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "652898",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Mar 20 2024 17:47:58 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
```

```
"name": "Jatin Todi ",
"phone": "9820293331",
"ownershipShare": "",
"email": "",
"id": "630514"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65fe8b525ca1625e505e137f",
  "name": "externalimg_1711180622799_1711180805146_image_0.jpeg",
  "path": "cases/65fad3f65ca1625e50589cc4/
externalimg_1711180622799_1711180805146_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65fe8c3f5ca1625e505e1610",
  "name": "externalimg_1711180861806_1711181046189_image_0.jpeg",
  "path": "cases/65fad3f65ca1625e50589cc4/
externalimg_1711180861806_1711181046189_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65fe8c115ca1625e505e1560",
  "name": "externalimg_1711180810002_1711180839528_image_0.jpeg",
  "path": "cases/65fad3f65ca1625e50589cc4/
externalimg_1711180810002_1711180839528_image_0.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "65fe8c115ca1625e505e1561",
    "name": "externallmg_1711180811427_1711180839528_image_1.jpeg",
    "path": "cases/65fad3f65ca1625e50589cc4/
externallmg_1711180811427_1711180839528_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fe8c115ca1625e505e1562",
    "name": "externallmg_1711180811923_1711180839528_image_2.jpeg",
    "path": "cases/65fad3f65ca1625e50589cc4/
externallmg_1711180811923_1711180839528_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fe8c115ca1625e505e1563",
    "name": "externallmg_1711180812113_1711180839528_image_3.jpeg",
    "path": "cases/65fad3f65ca1625e50589cc4/
externallmg_1711180812113_1711180839528_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fe8c115ca1625e505e1564",
    "name": "externallmg_1711180812300_1711180839528_image_4.jpeg",
    "path": "cases/65fad3f65ca1625e50589cc4/
externallmg_1711180812300_1711180839528_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fe8c115ca1625e505e1565",
    "name": "externallmg_1711180812517_1711180839528_image_5.jpeg",
    "path": "cases/65fad3f65ca1625e50589cc4/
externallmg_1711180812517_1711180839528_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fe8c115ca1625e505e1566",
```

```
    "name": "externallmg_1711180813064_1711180839528_image_6.jpeg",
    "path": "cases/65fad3f65ca1625e50589cc4/
externallmg_1711180813064_1711180839528_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fe8c115ca1625e505e1567",
    "name": "externallmg_1711180813780_1711180839528_image_7.jpeg",
    "path": "cases/65fad3f65ca1625e50589cc4/
externallmg_1711180813780_1711180839528_image_7.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fe8c115ca1625e505e1568",
    "name": "externallmg_1711180814317_1711180839528_image_8.jpeg",
    "path": "cases/65fad3f65ca1625e50589cc4/
externallmg_1711180814317_1711180839528_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fe8c115ca1625e505e1569",
    "name": "externallmg_1711180814415_1711180839528_image_9.jpeg",
    "path": "cases/65fad3f65ca1625e50589cc4/
externallmg_1711180814415_1711180839528_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fe8c115ca1625e505e156a",
    "name": "externallmg_1711180815093_1711180839528_image_10.jpeg",
    "path": "cases/65fad3f65ca1625e50589cc4/
externallmg_1711180815093_1711180839528_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fe8c115ca1625e505e156b",
    "name": "externallmg_1711180815757_1711180839528_image_11.jpeg",
```

```
    "path": "cases/65fad3f65ca1625e50589cc4/
externallmg_1711180815757_1711180839528_image_11.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fe8c115ca1625e505e156c",
    "name": "externallmg_1711180816192_1711180839528_image_12.jpeg",
    "path": "cases/65fad3f65ca1625e50589cc4/
externallmg_1711180816192_1711180839528_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fe8c115ca1625e505e156d",
    "name": "externallmg_1711180816614_1711180839528_image_13.jpeg",
    "path": "cases/65fad3f65ca1625e50589cc4/
externallmg_1711180816614_1711180839528_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fe8c115ca1625e505e156e",
    "name": "externallmg_1711180816986_1711180839528_image_14.jpeg",
    "path": "cases/65fad3f65ca1625e50589cc4/
externallmg_1711180816986_1711180839528_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fe8c115ca1625e505e156f",
    "name": "externallmg_1711180817155_1711180839528_image_15.jpeg",
    "path": "cases/65fad3f65ca1625e50589cc4/
externallmg_1711180817155_1711180839528_image_15.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fe8c675ca1625e505e1657",
    "name": "externallmg_1711180885111_1711181067851_image_0.jpeg",
    "path": "cases/65fad3f65ca1625e50589cc4/
externallmg_1711180885111_1711181067851_image_0.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65fe8c675ca1625e505e1658",
  "name": "externallmg_1711180886835_1711181067851_image_1.jpeg",
  "path": "cases/65fad3f65ca1625e50589cc4/
externallmg_1711180886835_1711181067851_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65fe8c675ca1625e505e1659",
  "name": "externallmg_1711180887166_1711181067851_image_2.jpeg",
  "path": "cases/65fad3f65ca1625e50589cc4/
externallmg_1711180887166_1711181067851_image_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65fe8c675ca1625e505e165a",
  "name": "externallmg_1711180887956_1711181067851_image_3.jpeg",
  "path": "cases/65fad3f65ca1625e50589cc4/
externallmg_1711180887956_1711181067851_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65fe8c675ca1625e505e165b",
  "name": "externallmg_1711180888861_1711181067851_image_4.jpeg",
  "path": "cases/65fad3f65ca1625e50589cc4/
externallmg_1711180888861_1711181067851_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65fe8c675ca1625e505e165c",
  "name": "externallmg_1711180890086_1711181067851_image_5.jpeg",
  "path": "cases/65fad3f65ca1625e50589cc4/
externallmg_1711180890086_1711181067851_image_5.jpeg",
  "orientation": "portrait"
}
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fe8c675ca1625e505e165d",
    "name": "externallmg_1711180891006_1711181067851_image_6.jpeg",
    "path": "cases/65fad3f65ca1625e50589cc4/
externallmg_1711180891006_1711181067851_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fe8c675ca1625e505e165e",
    "name": "externallmg_1711180892051_1711181067851_image_7.jpeg",
    "path": "cases/65fad3f65ca1625e50589cc4/
externallmg_1711180892051_1711181067851_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fe8c675ca1625e505e165f",
    "name": "externallmg_1711180892986_1711181067852_image_8.jpeg",
    "path": "cases/65fad3f65ca1625e50589cc4/
externallmg_1711180892986_1711181067852_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fe8c675ca1625e505e1660",
    "name": "externallmg_1711180893956_1711181067852_image_9.jpeg",
    "path": "cases/65fad3f65ca1625e50589cc4/
externallmg_1711180893956_1711181067852_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fe8c675ca1625e505e1661",
    "name": "externallmg_1711180894586_1711181067852_image_10.jpeg",
    "path": "cases/65fad3f65ca1625e50589cc4/
externallmg_1711180894586_1711181067852_image_10.jpeg",
    "orientation": "portrait"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65fe8c675ca1625e505e1662",
  "name": "externallmg_1711180895766_1711181067852_image_11.jpeg",
  "path": "cases/65fad3f65ca1625e50589cc4/
externallmg_1711180895766_1711181067852_image_11.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65fe8c675ca1625e505e1663",
  "name": "externallmg_1711180896736_1711181067852_image_12.jpeg",
  "path": "cases/65fad3f65ca1625e50589cc4/
externallmg_1711180896736_1711181067852_image_12.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65fe8c675ca1625e505e1664",
  "name": "externallmg_1711180897421_1711181067852_image_13.jpeg",
  "path": "cases/65fad3f65ca1625e50589cc4/
externallmg_1711180897421_1711181067852_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65fe8c675ca1625e505e1665",
  "name": "externallmg_1711180899101_1711181067852_image_14.jpeg",
  "path": "cases/65fad3f65ca1625e50589cc4/
externallmg_1711180899101_1711181067852_image_14.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65fe8c675ca1625e505e1666",
  "name": "externallmg_1711180901106_1711181067852_image_15.jpeg",
  "path": "cases/65fad3f65ca1625e50589cc4/
externallmg_1711180901106_1711181067852_image_15.jpeg",
  "orientation": "portrait"
}
],
```



```
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "60f915d3f3dd69653a592199",
      "role": "MAKER + RATE VERIFIER + CHEAKER",
      "firstName": "Shobha",
      "lastName": "Kuperkar",
      "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "65fbd4805ca1625e5059b800",
    "note": "Rate verification done",
    "taskId": "65fad8355ca1625e5058b78b",
    "createdAt": "2024-03-21T06:32:32.667Z"
  }
],
"createdAt": "2024-03-20T12:17:58.233Z",
"updatedAt": "2024-03-23T08:01:43.144Z",
"__v": 0,
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"fullAddress": "Residential Gala No. Gala No 24, Ground Floor, Wing - C, Raj Industrial
Complex Premises CHSL, Military Road, Village - Marol, Andheri East, Mumbai",
"updatedBy": "648fcad91b499c2d52dc86f3",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Jatin Todi ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9820293331"
}
```

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			