

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "640f306e63e4271bcefdbb9e"
    },
    "type": "CREDITOFFICER",
    "_id": "64b7cf4dd0368073e3faafb0",
    "firstName": "Chintamani",
    "lastName": "Joshi",
    "mobileNo": "",
    "workMobileNo": "9833242472",
    "email": "chintamani.joshi@cosmosbank.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "640f306e63e4271bcefd9e",
  "name": "Kalyan Khadakpada Branch",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "kalyan@cosmosbank.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Ground floor, Shiv Villa Apt. Opp. gagangiri Soc. Sai Chowk, Khadakpada
Kalyan West 421301\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "656aa949cebbe1714411d21b",
  "role": "FRONTDESK",
  "firstName": "Priyanka",
  "email": "thane@vastukala.org",
  "lastName": "Pawar",
  "mobileNo": "8928414480",
  "shortName": "PCP",
  "workWithDocumentMaker": "627222afafd7d55eddeddd82"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "64e5a649daae6a1c98101989",
  "role": "SITEENGINEER",
  "firstName": "Sameer",
  "email": "sameeryp2010@gmail.com",
  "lastName": "Parab",
  "mobileNo": "8291009567",
  "designation": "Site Engineer",
  "shortName": "Sameer",
  "workWithDocumentMaker": "62ea09ea4e679b264caf07d7"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
  "designation": "",
  "shortName": "PS",
```

```
"workWithDocumentMaker": "60f915d3f3dd69653a592199",
"profilePhoto": "users/627222afafd7d55eddedd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
        "number": "CAT-I-F-1763"
      },
      {
        "title": {
          "value": "Chartered_Engineer",
          "label": "Chartered Engineer"
        },
        "_id": "60af80072ffdf65bcd658653",
        "number": "AM161706-3"
      }
    ]
  }
]
```

```
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.24780807958297",
  "longitude": "73.17048414608244"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-03-23",
      "remark": "lumsum 130cr"
    }
  ]
},
"schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
}
```

```
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Ulhasnagar - 1 (Mharal)",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "8",
    "label": false
  },
  "buildingNo": {
    "status": true,
    "name": "Building No",
    "key": "buildingNo",
    "value": "11",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
    "value": "Thane",
```

```
"label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Ulhasnagar",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Regency Antila ",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
```

```
"name": "Street 1",
"key": "street1",
"value": "",
"label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Phase - III",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "40, 41, 42, 43, 44, 46, 47, 48, 49, 51, 52, 54, 55, 56, 57 & 58",
  "label": true
}
```



```
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "802",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
```

```
"key": "mouza",
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 421 001",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
}
},
"igrFinalRate": {
```

```
"floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
}
```

```
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
```

```
    "label": "Work Completed (%)",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": true,
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
}
```

```
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
```



```
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"invoices": [],
"paymentIds": [],
"_id": "65fd73cc5ca1625e505cc881",
"ownerName": "Mr. Suresh Hariram Tikani, Mrs. Asha Suresh Tikani & Mr. Pritesh
Suresh Tikani",
"ownerPhoneNo": "9822244122",
"fullAddress": "Residential Flat No. 802, 8th Floor, Building No 11, Wing - B, Regency
Antila , Phase - III, Village - Ulhasnagar - 1 (Mharal), District - Thane, Ulhasnagar, PIN
Code - 421 001",
"remark": "lumsun 130cr",
"documents": [
{
"documentType": {
"value": "60af48bf2ffdf65bcd6585fa",
"label": "Agreement for sale"
},
"inputs": {
"documentDate": "19/03/2024",
"from": {
"value": "Seller",
"label": "Seller"
},
"to": {
"value": "purchaser",
"label": "purchaser"
},
"purchaser": "Mr. Suresh Hariram Tikani, Mrs. Asha Suresh Tikani & Mr. Pritesh
Suresh Tikani",
"number": {
"value": "No",
"label": "No"
},
"No": "1246/2024"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1711108994403_regency_flat.pdf",
```

```
"path": "cases/65fd73cc5ca1625e505cc881/
document_1711108994403_regency_flat.pdf",
"id": "292929",
"uploadedBy": "656aa949cebbe1714411d21b",
"createdAt": "Fri Mar 22 2024 17:34:28 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "inputs": {
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1711109027362_Society_Regn_Certificate_of_IRIS_A__B_
CoOp_Soc_Ltd.pdf",
  "path": "cases/65fd73cc5ca1625e505cc881/document_1711109027362_Society_Re
gn_Certificate_of_IRIS_A__B_CoOp_Soc_Ltd.pdf",
  "id": "371825",
  "uploadedBy": "656aa949cebbe1714411d21b",
  "createdAt": "Fri Mar 22 2024 17:34:28 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "24/03/2021",
    "nameOfApprovingAuthority": {
      "value": "Ulhasnagar_Municipal_Corporation",
      "label": "Ulhasnagar Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "UMP / NRV / BP / 125 / 13 / 266 "
},
"isHardCopy": false,
"displayStatus": true,
```

```
"id": "869549",
"path": "cases/65fd73cc5ca1625e505cc881/
document_1711109060495_Completion_Certificate_C2_24032021.pdf",
"fileName": "document_1711109060495_Completion_Certificate_C2_24032021.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "15/03/2021",
    "nameOfApprovingAuthority": {
      "value": "Ulhasnagar_Municipal_Corporation",
      "label": "Ulhasnagar Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "UMP / NRV / BP / 125 / 13 / 250 "
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1711180273945_163977.pdf",
"path": "cases/65fd73cc5ca1625e505cc881/
document_1711180273945_163977.pdf",
"id": "906330",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Sat Mar 23 2024 13:30:18 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae126faa6d152c1801b3a3",
    "label": "Parking Allotment Letter"
  },
  "inputs": {
    "documentDate": "11/04/2022"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1711180818266_138580.pdf",
  "path": "cases/65fd73cc5ca1625e505cc881/
document_1711180818266_138580.pdf",
  "id": "690770",
  "uploadedBy": "627222afafd7d55eddeddd82",
```

```
    "createdAt": "Sat Mar 23 2024 13:30:18 GMT+0530 (India Standard Time)"
  }
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "007925",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
  {
    "id": "157424",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Mar 22 2024 17:34:28 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Suresh Hariram Tikani, Mrs. Asha Suresh Tikani & Mr. Pritesh Suresh Tikani",
    "phone": "9822244122",
    "ownershipShare": "",
    "email": "",
    "id": "311648"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fe69285ca1625e505d721c",
    "name": "externalImg_1711171866738_1711172050074_image_0.jpeg",
    "path": "cases/65fd73cc5ca1625e505cc881/externalImg_1711171866738_1711172050074_image_0.jpeg",
    "orientation": "portrait"
  },
  {
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fe69285ca1625e505d721d",
    "name": "externallmg_1711171868412_1711172050074_image_1.jpeg",
    "path": "cases/65fd73cc5ca1625e505cc881/
externallmg_1711171868412_1711172050074_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fe69285ca1625e505d721e",
    "name": "externallmg_1711171872064_1711172050074_image_2.jpeg",
    "path": "cases/65fd73cc5ca1625e505cc881/
externallmg_1711171872064_1711172050074_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fe69285ca1625e505d721f",
    "name": "externallmg_1711171872086_1711172050074_image_3.jpeg",
    "path": "cases/65fd73cc5ca1625e505cc881/
externallmg_1711171872086_1711172050074_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fe69285ca1625e505d7220",
    "name": "externallmg_1711171872404_1711172050074_image_4.jpeg",
    "path": "cases/65fd73cc5ca1625e505cc881/
externallmg_1711171872404_1711172050074_image_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fe69285ca1625e505d7221",
    "name": "externallmg_1711171873530_1711172050074_image_5.jpeg",
    "path": "cases/65fd73cc5ca1625e505cc881/
externallmg_1711171873530_1711172050074_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "65fe69285ca1625e505d7222",
  "name": "externallmg_1711171873953_1711172050074_image_6.jpeg",
  "path": "cases/65fd73cc5ca1625e505cc881/
externallmg_1711171873953_1711172050074_image_6.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65fe69285ca1625e505d7223",
  "name": "externallmg_1711171876259_1711172050074_image_7.jpeg",
  "path": "cases/65fd73cc5ca1625e505cc881/
externallmg_1711171876259_1711172050074_image_7.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65fe69285ca1625e505d7224",
  "name": "externallmg_1711171876266_1711172050074_image_8.jpeg",
  "path": "cases/65fd73cc5ca1625e505cc881/
externallmg_1711171876266_1711172050074_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65fe69285ca1625e505d7225",
  "name": "externallmg_1711171876276_1711172050074_image_9.jpeg",
  "path": "cases/65fd73cc5ca1625e505cc881/
externallmg_1711171876276_1711172050074_image_9.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65fe69285ca1625e505d7226",
  "name": "externallmg_1711171876503_1711172050074_image_10.jpeg",
  "path": "cases/65fd73cc5ca1625e505cc881/
externallmg_1711171876503_1711172050074_image_10.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "65fe69285ca1625e505d7227",
    "name": "externallmg_1711171879881_1711172050074_image_11.jpeg",
    "path": "cases/65fd73cc5ca1625e505cc881/
externallmg_1711171879881_1711172050074_image_11.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fe69285ca1625e505d7228",
    "name": "externallmg_1711171879895_1711172050074_image_12.jpeg",
    "path": "cases/65fd73cc5ca1625e505cc881/
externallmg_1711171879895_1711172050074_image_12.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65fe69285ca1625e505d7229",
    "name": "externallmg_1711171879901_1711172050074_image_13.jpeg",
    "path": "cases/65fd73cc5ca1625e505cc881/
externallmg_1711171879901_1711172050074_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65fe68985ca1625e505d6e94",
    "name": "externallmg_1711171729232_1711171914993_image_0.jpeg",
    "path": "cases/65fd73cc5ca1625e505cc881/
externallmg_1711171729232_1711171914993_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65fe68985ca1625e505d6e95",
    "name": "externallmg_1711171730414_1711171914993_image_1.jpeg",
    "path": "cases/65fd73cc5ca1625e505cc881/
externallmg_1711171730414_1711171914993_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65fe68985ca1625e505d6e97",
```

```
    "name": "externalImg_1711171734083_1711171914993_image_3.jpeg",
    "path": "cases/65fd73cc5ca1625e505cc881/
externalImg_1711171734083_1711171914993_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65fe68985ca1625e505d6e99",
    "name": "externalImg_1711171735619_1711171914993_image_5.jpeg",
    "path": "cases/65fd73cc5ca1625e505cc881/
externalImg_1711171735619_1711171914993_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65fe68e35ca1625e505d6f3f",
    "name": "externalImg_1711171810209_1711171985143_image_0.jpeg",
    "path": "cases/65fd73cc5ca1625e505cc881/
externalImg_1711171810209_1711171985143_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65fe68e35ca1625e505d6f40",
    "name": "externalImg_1711171810800_1711171985143_image_1.jpeg",
    "path": "cases/65fd73cc5ca1625e505cc881/
externalImg_1711171810800_1711171985143_image_1.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "cosmos - calculation - suresh.xlsx",
    "filename": "1711175951605_cosmos__calculation__suresh.xlsx",
    "path": "cases/65fd73cc5ca1625e505cc881/
processingDocuments/1711175951605_cosmos__calculation__suresh.xlsx",
    "size": "16842",
    "createdAt": "Sat Mar 23 2024 12:09:11 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "Summary - suresh.xlsx",
```



```

    "filename": "1711175951609_Summary__suresh.xlsx",
    "path": "cases/65fd73cc5ca1625e505cc881/
processingDocuments/1711175951609_Summary__suresh.xlsx",
    "size": "3107187",
    "createdAt": "Sat Mar 23 2024 12:09:11 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-03-22T12:04:28.675Z",
"updatedAt": "2024-03-23T08:00:18.354Z",
"__v": 0,
"updatedBy": "627222afafd7d55eddeddd82",
"addressForMap": "",
"caseReferredBy": "6006d4ce5080a310ac1fdcf2",
"contactPersonName": "Mr. Suresh Hariram Tikani, Mrs. Asha Suresh Tikani & Mr.
Pritesh Suresh Tikani",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9822244122"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			