

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "MSME_Loan",
    "label": "MSME Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856ba5b"
    },
    "type": "CREDITOFFICER",
    "_id": "6618d39953f88c65a60be9f3",
    "firstName": "Shubhanshu",
    "lastName": "Singh",
    "mobileNo": "",
    "workMobileNo": "8294344455",
    "email": "cbsmohamedalird@unionbankofindia.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856ba5b",
  "branchCode": "000019",
  "type": "BRANCH",
  "name": "Mohammed Ali Road Branch",
  "email": "cbsmohamedalird@unionbankofindia.com",
  "mobileNo": "02223443556",
  "alternateMobileNo": "",
  "address": "56,Karim Building,Mohammed Ali Road,Mumbai-400003",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f93be845132d6a6bdda676",
  "zoneName": "MUMBAI SOUTH"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "62727444afd7d55eddee092c",
"role": "PICKUPPERSON",
"firstName": "Shantilal",
"email": "shantilal@vastukala.org",
"lastName": "Patel",
"mobileNo": "9969039853",
"shortName": "SHP",
"workWithDocumentMaker": "",
"profilePhoto": "users/62727444afd7d55eddee092c/
profilePhoto_1668057663775_WhatsApp_Image_20221110_at_104853_AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "60f949ce45132d6a6bddbcc3",
"role": "SITEENGINEER",
"firstName": "Tushar ",
"email": "tusharbhuwad90@gmail.com",
"lastName": "Bhuwad",
"mobileNo": "9082053889",
"designation": "",
"shortName": "TSB",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f949ce45132d6a6bddbcc3/
profilePhoto_1668058314746_WhatsApp_Image_20221110_at_105931_AM.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60eeaeddf3dd69653a581316",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Shyam",
"email": "shyam@vastukala.org",
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shym_Photo.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "60f91b6f344e052188ffd1fc",
"role": "MAKER",
"firstName": "Jayaraja",
"email": "jayaraja@vastukala.org",
"lastName": "Acharya",
```

```
"mobileNo": "9867664219",
"designation": "",
"shortName": "JA",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
},
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
        "number": "CAT-I-F-1763"
      },
      {
        "title": {
          "value": "Chartered_Engineer",
          "label": "Chartered Engineer"
        },
        "_id": "60af80072ffdf65bcd658653",
```

```
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.089096062834486",
  "longitude": "72.8421801491406"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "12/04/2024 11:38 am"
    },
    {
      "dateTime": "12/04/2024 12:00 am"
    },
    {
      "dateTime": "12/04/2024 12:00 am"
    }
  ]
}
```

```
    }
  ],
  "visitedDate": [],
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
    "value": "",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "5",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
```

```
"label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Andheri",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "6",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Rajesh Sunita Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
```

```
"name": "Sector",
"key": "selectArea",
"value": "",
"label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Gujjar Lane",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
}
```



```
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "502",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
```

```
"key": "khataNo",
"value": "",
"label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 054",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Santacruz (West), Mumbai",
  "label": false
}
}
```

```
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/6618d1ae53f88c65a60bde45/
routeMap_1712904340416_Image.png",
    "routeLat": "19.078869",
    "routeLng": "72.837151",
    "stationName": "Santacruz",
    "routeDistance": "800m"
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "jmhpy",
      "name": "jmhpy",
    }
  ]
}
```

```
    "image": "cases/6618d1ae53f88c65a60bde45/
routeMap_1712903926186_Image.png"
  }
]
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
```

```
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "6618d2e853f88c65a60be407",
      "name": "externallmg_r_1712902887946_TimePhoto_20240408_131827.jpg",
      "path": "cases/6618d1ae53f88c65a60bde45/
externallmg_r_1712902887946_TimePhoto_20240408_131827.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "6618d2e853f88c65a60be3fe",
      "name": "externallmg_r_1712902887918_TimePhoto_20240408_131402.jpg",
      "path": "cases/6618d1ae53f88c65a60bde45/
externallmg_r_1712902887918_TimePhoto_20240408_131402.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "6618d2e853f88c65a60be406",
      "name": "externallmg_r_1712902887945_TimePhoto_20240408_131817.jpg",
      "path": "cases/6618d1ae53f88c65a60bde45/
externallmg_r_1712902887945_TimePhoto_20240408_131817.jpg",
      "orientation": "portrait"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "6618d2e853f88c65a60be401",
      "name": "externallmg_r_1712902887931_TimePhoto_20240408_131702.jpg",
      "path": "cases/6618d1ae53f88c65a60bde45/
externallmg_r_1712902887931_TimePhoto_20240408_131702.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "6618d2e853f88c65a60be405",
      "name": "externallmg_r_1712902887942_TimePhoto_20240408_131800.jpg",
      "path": "cases/6618d1ae53f88c65a60bde45/
externallmg_r_1712902887942_TimePhoto_20240408_131800.jpg",
      "orientation": "portrait"
    }
  ],
}
```

```
{
  "status": false,
  "_id": "6618d2e853f88c65a60be40a",
  "name": "externallmg_r_1712902887955_TimePhoto_20240408_131846.jpg",
  "path": "cases/6618d1ae53f88c65a60bde45/externallmg_r_1712902887955_TimePhoto_20240408_131846.jpg",
  "orientation": "portrait"
},
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```



```
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
{others": {
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
totalValues": {
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
taskStatus": {
"SITE_INSPECTION": false,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
createCase": "true",
type": "CASE",
leadType": {
"label": "Lead",
"value": "LEAD"
},
siteVisitType": "FULL",
isSiteMeasurementAllowed": true,
finalValuationArea": "0",
empanelmentNo": [],
isAdvanceInvoice": false,
status": true,
```

```
"caseStatus": "SITEVISITCOMPLETED",
"invoices": [],
"paymentIds": [],
"_id": "6618d1ae53f88c65a60bde45",
"ownerName": "Aarti Prakash Desai",
"ownerPhoneNo": "9920261212",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "9322825208",
"contactPersonName": "Hemangi",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "Aarti Prakash Desai",
    "phone": "9920261212",
    "ownershipShare": "",
    "email": "",
    "id": "284807"
  }
],
"caseReferredBy": "62727444afd7d55eddee092c",
"relationWithOwner": "Contact Person",
"fullAddress": "Residential Flat No. 502, 5th Floor, Rajesh Sunita Co-op. Hsg. Soc.
Ltd., Plot No. 6, Gujjar Lane, Santacruz (West), Mumbai, Taluka - Andheri, District -
Mumbai Suburban, Mumbai, PIN - 400 054, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1712902539907_ACE_Scanner_2024_04_125.pdf",
    "path": "cases/6618d1ae53f88c65a60bde45/
document_1712902539907_ACE_Scanner_2024_04_125.pdf",
    "id": "905854",
    "uploadedBy": "6006d4ce5080a310ac1fdfc2",
    "createdAt": "Fri Apr 12 2024 11:46:14 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    }
  }
]
```

```
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1712902568304_72804.pdf",
    "path": "cases/6618d1ae53f88c65a60bde45/
document_1712902568304_72804.pdf",
    "id": "931110",
    "uploadedBy": "6006d4ce5080a310ac1fdcf2",
    "createdAt": "Fri Apr 12 2024 11:46:14 GMT+0530 (India Standard Time)"
  }
],
"isUrgent": "false",
"isExternal": "false",
"proposePurchaserName": "",
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "008198",
"createdBy": "6006d4ce5080a310ac1fdcf2",
"caseHistory": [
  {
    "id": "883096",
    "title": "Create Case",
    "description": "Create Case",
    "datetime": "Fri Apr 12 2024 11:46:14 GMT+0530 (India Standard Time)"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6618d2d853f88c65a60be3c9",
    "name": "externallmg_1712902872168_Screenshot_2024040813193915_3d9111e2
d3171bf4882369f490c087b4.jpg",
    "path": "cases/6618d1ae53f88c65a60bde45/externallmg_1712902872168_Screens
hot_2024040813193915_3d9111e2d3171bf4882369f490c087b4.jpg",
    "orientation": "portrait"
  }
]
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6618d2d853f88c65a60be3ca",
  "name": "externallmg_r_1712902872172_TimePhoto_20240408_124939.jpg",
  "path": "cases/6618d1ae53f88c65a60bde45/
externallmg_r_1712902872172_TimePhoto_20240408_124939.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6618d2d853f88c65a60be3cb",
  "name": "externallmg_r_1712902872180_TimePhoto_20240408_130251.jpg",
  "path": "cases/6618d1ae53f88c65a60bde45/
externallmg_r_1712902872180_TimePhoto_20240408_130251.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6618d2d853f88c65a60be3cc",
  "name": "externallmg_r_1712902872176_TimePhoto_20240408_130247.jpg",
  "path": "cases/6618d1ae53f88c65a60bde45/
externallmg_r_1712902872176_TimePhoto_20240408_130247.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6618d2d853f88c65a60be3cd",
  "name": "externallmg_r_1712902872183_TimePhoto_20240408_130257.jpg",
  "path": "cases/6618d1ae53f88c65a60bde45/
externallmg_r_1712902872183_TimePhoto_20240408_130257.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6618d2d853f88c65a60be3ce",
  "name": "externallmg_r_1712902872186_TimePhoto_20240408_130306.jpg",
  "path": "cases/6618d1ae53f88c65a60bde45/
externallmg_r_1712902872186_TimePhoto_20240408_130306.jpg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6618d2d853f88c65a60be3cf",
  "name": "externallmg_r_1712902872191_TimePhoto_20240408_130326.jpg",
  "path": "cases/6618d1ae53f88c65a60bde45/
externallmg_r_1712902872191_TimePhoto_20240408_130326.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6618d2d853f88c65a60be3d0",
  "name": "externallmg_r_1712902872188_TimePhoto_20240408_130317.jpg",
  "path": "cases/6618d1ae53f88c65a60bde45/
externallmg_r_1712902872188_TimePhoto_20240408_130317.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6618d2d853f88c65a60be3d1",
  "name": "externallmg_r_1712902872193_TimePhoto_20240408_130343.jpg",
  "path": "cases/6618d1ae53f88c65a60bde45/
externallmg_r_1712902872193_TimePhoto_20240408_130343.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6618d2d853f88c65a60be3d2",
  "name": "externallmg_r_1712902872195_TimePhoto_20240408_130353.jpg",
  "path": "cases/6618d1ae53f88c65a60bde45/
externallmg_r_1712902872195_TimePhoto_20240408_130353.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6618d2e853f88c65a60be3fa",
  "name": "externallmg_r_1712902887906_TimePhoto_20240408_130400.jpg",
  "path": "cases/6618d1ae53f88c65a60bde45/
externallmg_r_1712902887906_TimePhoto_20240408_130400.jpg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6618d2e853f88c65a60be3fb",
    "name": "externallmg_r_1712902887912_TimePhoto_20240408_131349.jpg",
    "path": "cases/6618d1ae53f88c65a60bde45/
externallmg_r_1712902887912_TimePhoto_20240408_131349.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6618d2e853f88c65a60be3fc",
    "name": "externallmg_r_1712902887915_TimePhoto_20240408_131359.jpg",
    "path": "cases/6618d1ae53f88c65a60bde45/
externallmg_r_1712902887915_TimePhoto_20240408_131359.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6618d2e853f88c65a60be3fd",
    "name": "externallmg_r_1712902887908_TimePhoto_20240408_130414.jpg",
    "path": "cases/6618d1ae53f88c65a60bde45/
externallmg_r_1712902887908_TimePhoto_20240408_130414.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6618d2e853f88c65a60be3fe",
    "name": "externallmg_r_1712902887918_TimePhoto_20240408_131402.jpg",
    "path": "cases/6618d1ae53f88c65a60bde45/
externallmg_r_1712902887918_TimePhoto_20240408_131402.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6618d2e853f88c65a60be3ff",
    "name": "externallmg_r_1712902887928_TimePhoto_20240408_131627.jpg",
    "path": "cases/6618d1ae53f88c65a60bde45/
externallmg_r_1712902887928_TimePhoto_20240408_131627.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "6618d2e853f88c65a60be400",
  "name": "externalimg_r_1712902887923_TimePhoto_20240408_131623.jpg",
  "path": "cases/6618d1ae53f88c65a60bde45/
externalimg_r_1712902887923_TimePhoto_20240408_131623.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6618d2e853f88c65a60be401",
  "name": "externalimg_r_1712902887931_TimePhoto_20240408_131702.jpg",
  "path": "cases/6618d1ae53f88c65a60bde45/
externalimg_r_1712902887931_TimePhoto_20240408_131702.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6618d2e853f88c65a60be402",
  "name": "externalimg_r_1712902887934_TimePhoto_20240408_131703.jpg",
  "path": "cases/6618d1ae53f88c65a60bde45/
externalimg_r_1712902887934_TimePhoto_20240408_131703.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6618d2e853f88c65a60be403",
  "name": "externalimg_r_1712902887937_TimePhoto_20240408_131756.jpg",
  "path": "cases/6618d1ae53f88c65a60bde45/
externalimg_r_1712902887937_TimePhoto_20240408_131756.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6618d2e853f88c65a60be404",
  "name": "externalimg_r_1712902887939_TimePhoto_20240408_131758.jpg",
  "path": "cases/6618d1ae53f88c65a60bde45/
externalimg_r_1712902887939_TimePhoto_20240408_131758.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```



```
    "_id": "6618d2e853f88c65a60be405",
    "name": "externallmg_r_1712902887942_TimePhoto_20240408_131800.jpg",
    "path": "cases/6618d1ae53f88c65a60bde45/
externallmg_r_1712902887942_TimePhoto_20240408_131800.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6618d2e853f88c65a60be406",
    "name": "externallmg_r_1712902887945_TimePhoto_20240408_131817.jpg",
    "path": "cases/6618d1ae53f88c65a60bde45/
externallmg_r_1712902887945_TimePhoto_20240408_131817.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6618d2e853f88c65a60be407",
    "name": "externallmg_r_1712902887946_TimePhoto_20240408_131827.jpg",
    "path": "cases/6618d1ae53f88c65a60bde45/
externallmg_r_1712902887946_TimePhoto_20240408_131827.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6618d2e853f88c65a60be408",
    "name": "externallmg_r_1712902887949_TimePhoto_20240408_131828.jpg",
    "path": "cases/6618d1ae53f88c65a60bde45/
externallmg_r_1712902887949_TimePhoto_20240408_131828.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6618d2e853f88c65a60be409",
    "name": "externallmg_r_1712902887952_TimePhoto_20240408_131844.jpg",
    "path": "cases/6618d1ae53f88c65a60bde45/
externallmg_r_1712902887952_TimePhoto_20240408_131844.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6618d2e853f88c65a60be40a",
```

```
    "name": "externalImg_r_1712902887955_TimePhoto_20240408_131846.jpg",
    "path": "cases/6618d1ae53f88c65a60bde45/
externalImg_r_1712902887955_TimePhoto_20240408_131846.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6618d2e853f88c65a60be40b",
    "name": "externalImg_r_1712902887958_TimePhoto_20240408_131902.jpg",
    "path": "cases/6618d1ae53f88c65a60bde45/
externalImg_r_1712902887958_TimePhoto_20240408_131902.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6618d2e853f88c65a60be40c",
    "name": "externalImg_r_1712902887960_TimePhoto_20240408_131905.jpg",
    "path": "cases/6618d1ae53f88c65a60bde45/
externalImg_r_1712902887960_TimePhoto_20240408_131905.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6618d30753f88c65a60be4e6",
    "name": "externalImg_r_1712902918636_IMG20240408154913.jpg",
    "path": "cases/6618d1ae53f88c65a60bde45/
externalImg_r_1712902918636_IMG20240408154913.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6618d30753f88c65a60be4e7",
    "name": "externalImg_r_1712902918569_IMG20240408154857.jpg",
    "path": "cases/6618d1ae53f88c65a60bde45/
externalImg_r_1712902918569_IMG20240408154857.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
```

```
"remarks": [
  {
    "createdBy": {
      "_id": "60eeaeddf3dd69653a581316",
      "role": "MAKER + RATE VERIFIER + CHEAKER",
      "firstName": "Shyam",
      "lastName": "Kajvilkar",
      "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shyam_Photo.jpg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "6618dc2b53f88c65a60c0b84",
    "note": "Pending for Approved Plan (Blue Print), Occupancy Certificate,
Commencement Certificate regarding addition FSI area. ",
    "taskId": "6618d1af53f88c65a60bde63",
    "createdAt": "2024-04-12T07:00:59.003Z"
  },
  {
    "createdBy": {
      "_id": "60eeaeddf3dd69653a581316",
      "role": "MAKER + RATE VERIFIER + CHEAKER",
      "firstName": "Shyam",
      "lastName": "Kajvilkar",
      "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shyam_Photo.jpg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "6618e56953f88c65a60c22f7",
    "note": "Pending for Approved Plan (Blue Print), Occupancy Certificate,
Commencement Certificate regarding addition FSI area. ",
    "taskId": "6618d1af53f88c65a60bde63",
    "createdAt": "2024-04-12T07:40:25.394Z"
  }
],
"createdAt": "2024-04-12T06:16:14.653Z",
"updatedAt": "2024-04-13T04:43:23.545Z",
"__v": 0,
"addressForMap": "",
"updatedBy": "60f91b6f344e052188ffd1fc"
}
```

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			