

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": true,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6436535ee4256a03ecde45c8"
    },
    "type": "CREDITOFFICER",
    "_id": "6436535ee4256a03ecde45ca",
    "firstName": "Deepika ",
    "lastName": "Kumari",
    "mobileNo": "",
    "workMobileNo": "1981955591",
    "email": ""
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "8500000",
    "discussWithPerson": "Deepika ",
    "expectedFees": 4250,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6436535ee4256a03ecde45c8",
  "name": "Nepean Sea Road Branch (01862) ",
  "branchCode": "",
  "mobileNo": "02223676710",
  "alternateMobileNo": "",
  "email": "sbi.01862@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "8-A, Garden View Appt. \n\nKheshwala Premises Co-Op Society \n\nLJ
Marg, Mumbai-400006 "
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "62727444afd7d55eddee092c",
"role": "PICKUPPERSON",
"firstName": "Shantilal",
"email": "shantilal@vastukala.org",
"lastName": "Patel",
"mobileNo": "9969039853",
"shortName": "SHP",
"workWithDocumentMaker": "",
"profilePhoto": "users/62727444afd7d55eddee092c/
profilePhoto_1668057663775_WhatsApp_Image_20221110_at_104853_AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "62720a36afd7d55eddedc4a7",
"role": "SITEENGINEER",
"firstName": "Anwar",
"email": "anwar21786@gmail.com",
"lastName": "Shaikh",
"mobileNo": "8552884500",
"designation": "",
"shortName": "AS",
"workWithDocumentMaker": "",
"profilePhoto": "users/62720a36afd7d55eddedc4a7/
profilePhoto_1668059819446_anwar_2.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60eeaeddf3dd69653a581316",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Shyam",
"email": "shyam@vastukala.org",
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shyma_Photo.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "62691c48afd7d55eddecfda3",
"role": "SITEENGINEER+MAKAR",
"firstName": "Bhavika",
"email": "bhavikachavan0102@gmail.com",
"lastName": "chavan",
```

```
"mobileNo": "8390804382",
"designation": "Site Engineer",
"shortName": "BH",
"workWithDocumentMaker": "",
"profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
},
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
"value": "FIIV",
"label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
"title": {
"value": "Chartered_Engineer",
"label": "Chartered Engineer"
},
"_id": "60af80072ffdf65bcd658653",
```

```
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.215421325220944",
  "longitude": "72.853280140073"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.853280140073,
    19.215421325220944
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "3/05/2024 10:55 am"
    },
    {
      "dateTime": "3/05/2024 12:00 am"
    }
  ]
},
"visitedDate": []
```

```
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Poisar",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "4",
    "label": false
  },
  "buildingNo": {
    "status": true,
    "name": "Building No",
    "key": "buildingNo",
```

```
"value": "1",
"label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Borivali (West)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Borivali",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Sunderdham Co - Op Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
```

```
"status": false,
"name": "Sector",
"key": "selectArea",
"value": "",
"label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Ram Baug Lane",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Off S V Road",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "C",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
```



```
"label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "3",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "436, 436/1, 436/2, 436/3 & 436/4",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "412",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
```

```
"name": "Khata No",
"key": "khataNo",
"value": "",
"label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 067",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
```

```
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows_with_M._S._Grills",
    "label": "Powder coated Aluminum sliding windows with M. S. Grills"
  },
  "fittings": {
    "value": "Concealed_plumbing_with_C.P._fittings._Concealed_Electrical_wiring",
    "label": "Concealed plumbing with C.P. fittings. Concealed Electrical wiring"
  },
  "finishing": {
    "value": "Cement_Plastering_+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Semi_Urban",
    "label": "Semi Urban"
  },
  "townplanApprovedByList": {
    "value": "MCGM",
    "label": "Municipal Corporation of Greater Mumbai (MCGM)"
  },
  "whetherCoveredUnderAnyState": {
```

```
"value": "No",
"label": "No"
},
"asPerActualAgreement": {
  "north": "Vraj Dham CHSL ",
  "west": "Sunder Dham Building No. 2",
  "south": "Slum Area",
  "east": "Railway Track "
},
"asPerDocumentAgreement": {
  "north": "Details not available",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Occupancy Certificate is available it may be assumed that the construction is as per Sanctioned Plan.",
"approvePlanVerified": "N.A",
"empanelledOfApprovePlan": "N.A",
"unauthorizedConstruction": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
```

```
"areaStatusList": {
  "value": "Middle_Class",
  "label": "Middle Class"
},
"propertyTypeOfUseList": {
  "value": "Residential_Purpose",
  "label": "Residential Purpose"
},
"propertyOccupiedByList": {
  "value": "Seller_Occupied",
  "label": "Seller Occupied"
},
"monthlyRent": "N.A",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per MCGM norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located at developing area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
```

```
"label": "Yes"
},
"carParking": "Open Parking",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "1990",
  "fullDate": "1/1/1990"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
```

```
"value": "Designed_as_per_I.S._codes",
"label": "Designed as per I.S. codes"
},
"sewerageSystem": {
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
"walls": {
"value": "1",
"label": "Yes"
},
"appearanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenancelssues": {
"value": "1",
"label": "Yes"
},
"visibleDamageInBuilding": {
"value": "1",
"label": "Yes"
},
"systemOfAirConditioning": {
"value": "1",
"label": "Yes"
},
"provisionOfFirefighting": {
"value": "1",
"label": "Yes"
},
"groundStilt": {
"value": "ground",
"label": "Ground"
},
"yearOfConstructionAsPer": {
"value": "as_per_occupancy_certificate",
"label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "26",
```

```
"ageOfBuilding": "34",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "6",
"flatFloorNo": "4",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "520.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Any Other Document"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/6634695ef76f30369f4e6c33/
routeMap_1715247831009_Image.png",
    "routeLat": "19.214726",
    "routeLng": "72.853391",
    "stationName": "Kandivali",
    "routeDistance": "2.3 Km"
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "nnsk6",
      "name": "nnsk6",
      "image": "cases/6634695ef76f30369f4e6c33/
routeMap_1715247471562_Image.png"
    }
  ]
}
```



```
]
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
```

```
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0.00",
  "selectedBuildUpValue": "520.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
```

```
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
}
```

```
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "520.00",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"invoices": [],
"paymentIds": [],
"_id": "6634695ef76f30369f4e6c33",
```

```
"ownerName": "Hansaben J Sheth",
"ownerPhoneNo": "7021096745",
"appAddress": "shashikant Shirke \nc 412 sunder dham \nBoriwali w\nMumbai
400092",
"remark": "Proposed Buyer Shashikant Shirke ",
"documents": [
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "id": "175604",
    "path": "cases/6634695ef76f30369f4e6c33/document_1714711283753_171471078
9997_SHASHIKANT_SHIRKE_LOAN_0001_1.pdf",
    "fileName": "document_1714711283753_1714710789997_SHASHIKANT_SHIRKE_
LOAN_0001_1.pdf"
  },
  {
    "documentType": {
      "value": "60ae1247aa6d152c1801b2ea",
      "label": "Commencement Certificate"
    },
    "inputs": {
      "documentDate": "03/07/1981",
      "nameOfApprovingAuthority": {
        "value": "Municipal_Corporation_of_Greater_Mumbai",
        "label": "Municipal Corporation of Greater Mumbai"
      },
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "CE / 4697 /BSII / A / R"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1715147008530_216342.pdf",
    "path": "cases/6634695ef76f30369f4e6c33/
document_1715147008530_216342.pdf",
    "id": "819616",
    "uploadedBy": "62691c48afd7d55eddecfda3",
    "createdAt": "Wed May 08 2024 11:13:28 GMT+0530 (India Standard Time)"
  },
  {

```

```
"documentType": {
  "value": "60ae124baa6d152c1801b2fd",
  "label": "Occupancy Certificate"
},
"inputs": {
  "documentDate": "24/02/1990",
  "nameOfApprovingAuthority": {
    "value": "Municipal_Corporation_of_Greater_Mumbai",
    "label": "Municipal Corporation of Greater Mumbai"
  },
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "CE / 4697 /BSII / AR"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1715147103630_237052.pdf",
"path": "cases/6634695ef76f30369f4e6c33/
document_1715147103630_237052.pdf",
"id": "888235",
"uploadedBy": "62691c48afd7d55eddecfda3",
"createdAt": "Wed May 08 2024 11:15:03 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "008506",
"createdBy": "62727444afd7d55eddee092c",
"caseHistory": [
  {
    "id": "891344",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri May 03 2024 10:04:38 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Hansaben J Sheth",
    "phone": "7021096745",
    "ownershipShare": "",
    "email": "",
    "id": "370069"
  }
],
"proposePurchasers": [
```



```
{
  "name": "Shashikant Shirke "
}
],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "5",
    "name": "Bedroom",
    "length": "9.67",
    "length1": "9",
    "length2": "8",
    "width": "16.75",
    "width1": "16",
    "width2": "9",
    "totalArea": "161.92",
    "images": [],
    "finalArea": "161.92",
    "extraAreas": []
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "name": "Bedroom",
    "length": "9.67",
    "length1": "9",
    "length2": "8",
    "width": "10.58",
    "width1": "10",
    "width2": "7",
    "totalArea": "102.31",
    "images": [],
    "extraAreas": [],
    "finalArea": "102.31"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    }
  }
]
```

```
},
  "id": "2",
  "name": "Kitchen",
  "length": "8.50",
  "length1": "8",
  "length2": "6",
  "width": "9.75",
  "width1": "9",
  "width2": "9",
  "totalArea": "82.87",
  "images": [],
  "extraAreas": [],
  "finalArea": "82.87"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "WC",
  "length": "3.42",
  "length1": "3",
  "length2": "5",
  "width": "3.67",
  "width1": "3",
  "width2": "8",
  "totalArea": "12.53",
  "images": [],
  "extraAreas": [],
  "finalArea": "12.53"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bathroom",
  "length": "6.42",
  "length1": "6",
  "length2": "5",
  "width": "3.50",
  "width1": "3",
  "width2": "6",
  "totalArea": "22.46",
```

```
"images": [],
"extraAreas": [],
"finalArea": "22.46"
}
],
"otherComposition": [
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Passage",
    "value": "Passage"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "0",
  "length": "1.42",
  "length1": "1",
  "length2": "5",
  "width": "9.58",
  "width1": "9",
  "width2": "7",
  "totalArea": "13.58",
  "images": [],
  "extraAreas": [],
  "finalArea": "13.58",
  "percentageBeforeTotal": "13.58",
  "percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Passage",
    "value": "Passage"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
}
```

```
"id": "1",
"length": "3.33",
"length1": "3",
"length2": "4",
"width": "7.42",
"width1": "7",
"width2": "5",
"totalArea": "24.72",
"images": [],
"extraAreas": [],
"finalArea": "24.72",
"percentageBeforeTotal": "24.72",
"percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Passage",
    "value": "Passage"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "length": "1.58",
  "length1": "1",
  "length2": "7",
  "width": "9.67",
  "width1": "9",
  "width2": "8",
  "totalArea": "15.31",
  "images": [],
  "extraAreas": [],
  "finalArea": "15.31",
  "percentageBeforeTotal": "15.31",
  "percentage": "100"
}
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
```

```
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "250748",
  "selectAreaTypeDocument": "Built_Up",
  "totalAreaDocument": "520",
  "squareMeterArea": "48.31",
  "docFinalBuiltUp": "0.00",
  "docFinalBuiltUpSquareMeter": "0.00",
  "docBultupPercentage": "",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663476bd4511fa6f226f97a2",
    "name":
"externallmg_1714714300669_WhatsApp_Image_20240502_at_193236_1.jpeg",
    "path": "cases/6634695ef76f30369f4e6c33/
externallmg_1714714300669_WhatsApp_Image_20240502_at_193236_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663476bd4511fa6f226f97a3",
    "name":
"externallmg_1714714300675_WhatsApp_Image_20240502_at_193216.jpeg",
    "path": "cases/6634695ef76f30369f4e6c33/
externallmg_1714714300675_WhatsApp_Image_20240502_at_193216.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663476bd4511fa6f226f97a4",
```

```
    "name":  
    "externallmg_1714714300683_WhatsApp_Image_20240502_at_193227.jpeg",  
    "path": "cases/6634695ef76f30369f4e6c33/  
externallmg_1714714300683_WhatsApp_Image_20240502_at_193227.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "663476bd4511fa6f226f97a5",  
    "name":  
    "externallmg_1714714300689_WhatsApp_Image_20240502_at_193228.jpeg",  
    "path": "cases/6634695ef76f30369f4e6c33/  
externallmg_1714714300689_WhatsApp_Image_20240502_at_193228.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "663476bd4511fa6f226f97a6",  
    "name":  
    "externallmg_1714714300696_WhatsApp_Image_20240502_at_193229_1.jpeg",  
    "path": "cases/6634695ef76f30369f4e6c33/  
externallmg_1714714300696_WhatsApp_Image_20240502_at_193229_1.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "663476bd4511fa6f226f97a7",  
    "name":  
    "externallmg_1714714300703_WhatsApp_Image_20240502_at_193229.jpeg",  
    "path": "cases/6634695ef76f30369f4e6c33/  
externallmg_1714714300703_WhatsApp_Image_20240502_at_193229.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "663476bd4511fa6f226f97a8",  
    "name":  
    "externallmg_1714714300708_WhatsApp_Image_20240502_at_193231_1.jpeg",  
    "path": "cases/6634695ef76f30369f4e6c33/  
externallmg_1714714300708_WhatsApp_Image_20240502_at_193231_1.jpeg",  
    "orientation": "portrait"  
  },  
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663476bd4511fa6f226f97a9",
  "name":
"externallmg_1714714300715_WhatsApp_Image_20240502_at_193231.jpeg",
  "path": "cases/6634695ef76f30369f4e6c33/
externallmg_1714714300715_WhatsApp_Image_20240502_at_193231.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663476bd4511fa6f226f97aa",
  "name":
"externallmg_1714714300723_WhatsApp_Image_20240502_at_193232_1.jpeg",
  "path": "cases/6634695ef76f30369f4e6c33/
externallmg_1714714300723_WhatsApp_Image_20240502_at_193232_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663476bd4511fa6f226f97ab",
  "name":
"externallmg_1714714300728_WhatsApp_Image_20240502_at_193232_2.jpeg",
  "path": "cases/6634695ef76f30369f4e6c33/
externallmg_1714714300728_WhatsApp_Image_20240502_at_193232_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663476bd4511fa6f226f97ac",
  "name":
"externallmg_1714714300732_WhatsApp_Image_20240502_at_193232.jpeg",
  "path": "cases/6634695ef76f30369f4e6c33/
externallmg_1714714300732_WhatsApp_Image_20240502_at_193232.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663476bd4511fa6f226f97ad",
  "name":
"externallmg_1714714300735_WhatsApp_Image_20240502_at_193233_1.jpeg",
```

```
    "path": "cases/6634695ef76f30369f4e6c33/
externallmg_1714714300735_WhatsApp_Image_20240502_at_193233_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663476bd4511fa6f226f97ae",
    "name":
"externallmg_1714714300738_WhatsApp_Image_20240502_at_193233.jpeg",
    "path": "cases/6634695ef76f30369f4e6c33/
externallmg_1714714300738_WhatsApp_Image_20240502_at_193233.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663476bd4511fa6f226f97af",
    "name":
"externallmg_1714714300741_WhatsApp_Image_20240502_at_193234_1.jpeg",
    "path": "cases/6634695ef76f30369f4e6c33/
externallmg_1714714300741_WhatsApp_Image_20240502_at_193234_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663476bd4511fa6f226f97b0",
    "name":
"externallmg_1714714300745_WhatsApp_Image_20240502_at_193234.jpeg",
    "path": "cases/6634695ef76f30369f4e6c33/
externallmg_1714714300745_WhatsApp_Image_20240502_at_193234.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663476bd4511fa6f226f97b1",
    "name":
"externallmg_1714714300748_WhatsApp_Image_20240502_at_193235_1.jpeg",
    "path": "cases/6634695ef76f30369f4e6c33/
externallmg_1714714300748_WhatsApp_Image_20240502_at_193235_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```



```
"status": false,
  "_id": "663476bd4511fa6f226f97b2",
  "name":
"externalImg_1714714300751_WhatsApp_Image_20240502_at_193235.jpeg",
  "path": "cases/6634695ef76f30369f4e6c33/
externalImg_1714714300751_WhatsApp_Image_20240502_at_193235.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663476bd4511fa6f226f97b3",
  "name":
"externalImg_1714714300755_WhatsApp_Image_20240502_at_193236.jpeg",
  "path": "cases/6634695ef76f30369f4e6c33/
externalImg_1714714300755_WhatsApp_Image_20240502_at_193236.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-05-03T04:34:38.747Z",
"updatedAt": "2024-05-09T09:43:51.391Z",
"__v": 0,
"uniqueNo": "",
"updatedBy": "62691c48afd7d55eddecfda3",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 412, 4th Floor, Building No 1, Wing - C,
Sunderdham Co - Op Hsg. Soc. Ltd., Ram Baug Lane, Off S V Road, Village - Poisar,
Taluka - Borivali, District - Mumbai Suburban, Borivali (West), PIN - 400 067, State -
Maharashtra, India",
"addressForMap": "",
"caseReferredBy": "62727444afd7d55eddee092c",
"contactPersonName": "Hansaben J Sheth",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "Shashikant Shirke ",
"purchaseValueAsPerDocument": "",
```

"relationWithOwner": "self",
 "siteVisitContactNo": "7021096745",
 "briefDescOfProperty": "2 Bedroom + Kitchen + WC + Bathroom",
 "carpetTotal": "382.09",
 "finalMeasurementType": "Sq. Ft.",
 "otherCarpetTotal": "53.61",
 "otherCompositionBuiltUpTotal": "0.00",
 "otherCompositionCarpetTotal": "53.61",
 "otherCompositionSaleableTotal": "0.00",
 "builtupPercentage": "10",
 "finalBuiltupArea": "479.27",
 "finalCarpetArea": "435.70",
 "finalSalableArea": "527.20",
 "salablePercentage": "10",
 "toBeAdded": "",
 "extendOfSiteRemark": "",
 "siteMeasurementRemark": "",
 "finalAreaType": "Built Up Area",
 "finalAsPerArea": "Any Other Document",
 "finalBuiltUpPercentage": "0",
 "finalCarpetConvertToBuiltUpPer": "0",
 "finalSaleablePercentage": "0",
 "finalValuationAreaString": "Built Up Area in Sq. Ft. = 520.00"

Name	Length	Width	Total
Composition :			
Bedroom	9'8"	16'9"	161.92
Bedroom	9'8"	10'7"	102.31
Kitchen	8'6"	9'9"	82.87
WC	3'5"	3'8"	12.53
Bathroom	6'5"	3'6"	22.46
Other Composition :			
Passage	1'5"	9'7"	13.58
Passage	3'4"	7'5"	24.72
Passage	1'7"	9'8"	15.31