

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9b2"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94230efb",
    "firstName": "Pratibha Bhatia",
    "email": "0_default_pratibha.bhatia@cosmosbank.in",
    "mobileNo": "-",
    "workMobileNo": "9820701094",
    "lastName": "Bhatia"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "6451645",
    "discussWithPerson": "Pratibha Bhatia",
    "expectedFees": 3225.8225,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9b2",
  "branchCode": "000012",
  "type": "BRANCH",
  "name": "Bandra (West) Branch",
  "email": "pratibha.bhatia@cosmosbank.in",
  "mobileNo": "02226402884",
  "alternateMobileNo": "",
  "address": "16, Lubina Turner Road, Opp. Tava Restaurant Bandra (West), Mumbai -
400 050, State - Maharashtra, Country - India.",
  "ledgerName": "COSMOS BANK- BANDRA WEST BRANCH",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "62723addafd7d55eddeddfe4",
  "role": "PICKUPPERSON",
  "firstName": "Ramkrishna ",
  "email": "rampatakar1991@gmail.com",
  "lastName": "Patkar",
  "mobileNo": "7045746060",
  "shortName": "RP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f949ce45132d6a6bddbcc3",
  "role": "SITEENGINEER",
  "firstName": "Tushar ",
  "email": "tusharbhuwad90@gmail.com",
  "lastName": "Bhuwad",
  "mobileNo": "9082053889",
  "designation": "",
  "shortName": "TSB",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f949ce45132d6a6bddbcc3/
profilePhoto_1668058314746_WhatsApp_Image_20221110_at_105931_AM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64dc7184ccaf1e7b7f637f47",
  "role": "FRONTDESK",
  "firstName": "Binumon",
  "email": "binu@vastukala.org",
  "lastName": "Moozhickal",
  "mobileNo": "9930252906",
  "designation": "Back Office Team Leader",
  "shortName": "BS",
  "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
  "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
```

```
    "value": "IBBI/RV/07/2018/10366",
    "label": "Registered Valuer"
  }
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
```

```
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
    "PANNo": "AERPC9086P",
    "fatherName": "Baburao"
  }
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.222713316105896",
  "longitude": "72.84514174236911"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.84514174236911,
    19.222713316105896
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "8/05/2024 11:37 am"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
```

```
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": false,
  "name": "Village",
  "key": "village",
  "value": "",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "1",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
```

```
"name": "Tehsil",
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Hill Lake View CHSL",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Dattaji Salvi Marg",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Off V D Road",
  "label": false
}
```

```
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
```



```
"key": "CTSNo",
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "13",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
```

```
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Andheri West",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
}
```

```
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
}
```

```
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
```

```
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```

```
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
```



```
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentIds": [],
"_id": "663b0d2bd34acf0916e26726",
"ownerName": "Prakash G Lotankar ",
"ownerPhoneNo": "9920611976",
"appAddress": "flat no 13, 1st floor, Hill lake view chsl, Dattaji salvi marg, Andheri
West ",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Any Other Document",
      "value": "60ae124aaa6d152c1801b2f7"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/663b0d2bd34acf0916e26726/
document_1715146399679_1715146185974_prakash_Lotankar.pdf",
    "fileName": "document_1715146399679_1715146185974_prakash_Lotankar.pdf",
    "id": "187767",
    "uploadedBy": "62723addafd7d55eddeddfe4",
    "createdAt": "Wed May 08 2024 11:18:23 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "008586",
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
  {
    "id": "108499",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed May 08 2024 10:57:07 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Prakash G Lotankar ",
    "phone": "9920611976",
    "ownershipShare": "",
    "email": "",
    "id": "518190"
```

```
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663e0b3e235f497497947437",
    "name": "externalImg_r_1715342141605_IMG20240510090603.jpg",
    "path": "cases/663b0d2bd34acf0916e26726/
externalImg_r_1715342141605_IMG20240510090603.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663e0b3e235f497497947438",
    "name": "externalImg_r_1715342141602_IMG20240510090511.jpg",
    "path": "cases/663b0d2bd34acf0916e26726/
externalImg_r_1715342141602_IMG20240510090511.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663e0b3e235f497497947439",
    "name": "externalImg_r_1715342141620_IMG20240510092123.jpg",
    "path": "cases/663b0d2bd34acf0916e26726/
externalImg_r_1715342141620_IMG20240510092123.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663e0b3e235f49749794743a",
    "name": "externalImg_r_1715342141609_IMG20240510091731.jpg",
    "path": "cases/663b0d2bd34acf0916e26726/
externalImg_r_1715342141609_IMG20240510091731.jpg",
    "orientation": "portrait"
  }
]
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663e0b3e235f49749794743b",
  "name": "externallmg_r_1715342141632_IMG20240510092222.jpg",
  "path": "cases/663b0d2bd34acf0916e26726/
externallmg_r_1715342141632_IMG20240510092222.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663e0b3e235f49749794743c",
  "name": "externallmg_r_1715342141634_TimePhoto_20240510_091445.jpg",
  "path": "cases/663b0d2bd34acf0916e26726/
externallmg_r_1715342141634_TimePhoto_20240510_091445.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663e0b3e235f49749794743d",
  "name": "externallmg_r_1715342141628_IMG20240510092125.jpg",
  "path": "cases/663b0d2bd34acf0916e26726/
externallmg_r_1715342141628_IMG20240510092125.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663e0b3e235f49749794743e",
  "name": "externallmg_r_1715342141638_TimePhoto_20240510_091456.jpg",
  "path": "cases/663b0d2bd34acf0916e26726/
externallmg_r_1715342141638_TimePhoto_20240510_091456.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663e0b3e235f49749794743f",
  "name": "externallmg_r_1715342141646_TimePhoto_20240510_091523.jpg",
  "path": "cases/663b0d2bd34acf0916e26726/
externallmg_r_1715342141646_TimePhoto_20240510_091523.jpg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663e0b3e235f497497947440",
  "name": "externallmg_r_1715342141643_TimePhoto_20240510_091515.jpg",
  "path": "cases/663b0d2bd34acf0916e26726/
externallmg_r_1715342141643_TimePhoto_20240510_091515.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663e0b3e235f497497947441",
  "name": "externallmg_r_1715342141640_TimePhoto_20240510_091504.jpg",
  "path": "cases/663b0d2bd34acf0916e26726/
externallmg_r_1715342141640_TimePhoto_20240510_091504.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663e0b3e235f497497947442",
  "name": "externallmg_r_1715342141649_TimePhoto_20240510_091541.jpg",
  "path": "cases/663b0d2bd34acf0916e26726/
externallmg_r_1715342141649_TimePhoto_20240510_091541.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663e0b3e235f497497947443",
  "name": "externallmg_r_1715342141651_TimePhoto_20240510_091543.jpg",
  "path": "cases/663b0d2bd34acf0916e26726/
externallmg_r_1715342141651_TimePhoto_20240510_091543.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663e0b3e235f497497947444",
  "name": "externallmg_r_1715342141654_TimePhoto_20240510_091549.jpg",
  "path": "cases/663b0d2bd34acf0916e26726/
externallmg_r_1715342141654_TimePhoto_20240510_091549.jpg",
  "orientation": "landscape"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663e0b3e235f497497947445",
    "name": "externallmg_r_1715342141657_TimePhoto_20240510_091558.jpg",
    "path": "cases/663b0d2bd34acf0916e26726/
externallmg_r_1715342141657_TimePhoto_20240510_091558.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663e0b4f235f497497947473",
    "name": "externallmg_1715342159273_Screenshot_2024051009081618_3d9111e2
d3171bf4882369f490c087b4.jpg",
    "path": "cases/663b0d2bd34acf0916e26726/externallmg_1715342159273_Screens
hot_2024051009081618_3d9111e2d3171bf4882369f490c087b4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663e0b4f235f497497947474",
    "name": "externallmg_r_1715342159223_TimePhoto_20240510_091558.jpg",
    "path": "cases/663b0d2bd34acf0916e26726/
externallmg_r_1715342159223_TimePhoto_20240510_091558.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663e0b4f235f497497947475",
    "name": "externallmg_r_1715342159228_TimePhoto_20240510_092033.jpg",
    "path": "cases/663b0d2bd34acf0916e26726/
externallmg_r_1715342159228_TimePhoto_20240510_092033.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663e0b4f235f497497947476",
    "name": "externallmg_r_1715342159225_TimePhoto_20240510_092022.jpg",
    "path": "cases/663b0d2bd34acf0916e26726/
externallmg_r_1715342159225_TimePhoto_20240510_092022.jpg",
    "orientation": "portrait"
  },
  {
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663e0b4f235f497497947477",
    "name": "externallmg_r_1715342159231_TimePhoto_20240510_092417.jpg",
    "path": "cases/663b0d2bd34acf0916e26726/
externallmg_r_1715342159231_TimePhoto_20240510_092417.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663e0b4f235f497497947478",
    "name": "externallmg_r_1715342159234_TimePhoto_20240510_092449.jpg",
    "path": "cases/663b0d2bd34acf0916e26726/
externallmg_r_1715342159234_TimePhoto_20240510_092449.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663e0b4f235f497497947479",
    "name": "externallmg_r_1715342159238_TimePhoto_20240510_092451.jpg",
    "path": "cases/663b0d2bd34acf0916e26726/
externallmg_r_1715342159238_TimePhoto_20240510_092451.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663e0b4f235f49749794747a",
    "name": "externallmg_r_1715342159240_TimePhoto_20240510_092505.jpg",
    "path": "cases/663b0d2bd34acf0916e26726/
externallmg_r_1715342159240_TimePhoto_20240510_092505.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663e0b4f235f49749794747b",
    "name": "externallmg_r_1715342159243_TimePhoto_20240510_092510.jpg",
    "path": "cases/663b0d2bd34acf0916e26726/
externallmg_r_1715342159243_TimePhoto_20240510_092510.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "663e0b4f235f49749794747c",
  "name": "externallmg_r_1715342159246_TimePhoto_20240510_092513.jpg",
  "path": "cases/663b0d2bd34acf0916e26726/
externallmg_r_1715342159246_TimePhoto_20240510_092513.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663e0b4f235f49749794747d",
  "name": "externallmg_r_1715342159255_TimePhoto_20240510_092524.jpg",
  "path": "cases/663b0d2bd34acf0916e26726/
externallmg_r_1715342159255_TimePhoto_20240510_092524.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663e0b4f235f49749794747e",
  "name": "externallmg_r_1715342159250_TimePhoto_20240510_092516.jpg",
  "path": "cases/663b0d2bd34acf0916e26726/
externallmg_r_1715342159250_TimePhoto_20240510_092516.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663e0b4f235f49749794747f",
  "name": "externallmg_r_1715342159257_IMG20240510090556.jpg",
  "path": "cases/663b0d2bd34acf0916e26726/
externallmg_r_1715342159257_IMG20240510090556.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663e0b4f235f497497947480",
  "name": "externallmg_r_1715342159268_IMG20240510091832.jpg",
  "path": "cases/663b0d2bd34acf0916e26726/
externallmg_r_1715342159268_IMG20240510091832.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "663e0b4f235f497497947481",
    "name": "externallmg_r_1715342159278_TimePhoto_20240510_091529.jpg",
    "path": "cases/663b0d2bd34acf0916e26726/
externallmg_r_1715342159278_TimePhoto_20240510_091529.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663e0b4f235f497497947482",
    "name": "externallmg_r_1715342159261_IMG20240510090558.jpg",
    "path": "cases/663b0d2bd34acf0916e26726/
externallmg_r_1715342159261_IMG20240510090558.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663e0b4f235f497497947483",
    "name": "externallmg_r_1715342159269_IMG20240510092117.jpg",
    "path": "cases/663b0d2bd34acf0916e26726/
externallmg_r_1715342159269_IMG20240510092117.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663e0b4f235f497497947484",
    "name": "externallmg_r_1715342159281_TimePhoto_20240510_091600.jpg",
    "path": "cases/663b0d2bd34acf0916e26726/
externallmg_r_1715342159281_TimePhoto_20240510_091600.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663e0b4f235f497497947485",
    "name": "externallmg_r_1715342159285_TimePhoto_20240510_092407.jpg",
    "path": "cases/663b0d2bd34acf0916e26726/
externallmg_r_1715342159285_TimePhoto_20240510_092407.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "663e0dc0235f4974979476ff",
```



```
"name":
"externallmg_1715342784053_WhatsApp_Image_20240510_at_173149.jpeg",
  "path": "cases/663b0d2bd34acf0916e26726/
externallmg_1715342784053_WhatsApp_Image_20240510_at_173149.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "663e0dc0235f497497947700",
  "name":
"externallmg_1715342784056_WhatsApp_Image_20240510_at_173148.jpeg",
  "path": "cases/663b0d2bd34acf0916e26726/
externallmg_1715342784056_WhatsApp_Image_20240510_at_173148.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
{
  "originalname": "RAKASH G LOTANKAR - Flat No. 13 - Cosmos Bank ( Bandra
(West) Branch ).xlsx",
  "filename": "1715153058099_RAKASH_G_LOTANKAR__Flat_No_13__Cosmos_Ba
nk__Bandra_West_Branch_.xlsx",
  "path": "cases/663b0d2bd34acf0916e26726/processingDocuments/1715153058099
_RAKASH_G_LOTANKAR__Flat_No_13__Cosmos_Bank__Bandra_West_Branch_.xls
x",
  "size": "2088551",
  "createdAt": "Wed May 08 2024 12:54:19 GMT+0530 (India Standard Time)",
  "uploadedBy": "64dc7184ccaf1e7b7f637f47"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-05-08T05:27:07.593Z",
"updatedAt": "2024-05-10T12:06:24.158Z",
"__v": 0,
"uniqueNo": "",
"updatedBy": "6006d4ce5080a310ac1fdfc2",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 13, 1st Floor, Hill Lake View CHSL, Dattaji Salvi
Marg, Off V D Road, Andheri West, Mumbai",
```

```
"addressForMap": "",
"caseReferredBy": "62723addafd7d55eddeddfe4",
"contactPersonName": "Prakash G Lotankar ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9920611976"
```

}

Name	Length	Width	Total
Composition :			
Other			
Composition :			