

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856ba5b"
    },
    "type": "CREDITOFFICER",
    "_id": "658aa7eab7b4df714dac471b",
    "firstName": "Subhi",
    "lastName": "Hussaini",
    "mobileNo": "",
    "workMobileNo": "8980759252",
    "email": "1ubi0531847@unionbankofindia.bank"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "8500000",
    "discussWithPerson": "Subhi",
    "expectedFees": 4250,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856ba5b",
  "branchCode": "000019",
  "type": "BRANCH",
  "name": "Mohammed Ali Road Branch",
  "email": "cbasmohamedalird@unionbankofindia.com",
  "mobileNo": "02223443556",
  "alternateMobileNo": "",
  "address": "56,Karim Building,Mohammed Ali Road,Mumbai-400003",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f93be845132d6a6bdda676",
  "zoneName": "MUMBAI SOUTH"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "62727444afd7d55eddee092c",
"role": "PICKUPPERSON",
"firstName": "Shantilal",
"email": "shantilal@vastukala.org",
"lastName": "Patel",
"mobileNo": "9969039853",
"shortName": "SHP",
"workWithDocumentMaker": "",
"profilePhoto": "users/62727444afd7d55eddee092c/
profilePhoto_1668057663775_WhatsApp_Image_20221110_at_104853_AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "60f949ce45132d6a6bddbcc3",
"role": "SITEENGINEER",
"firstName": "Tushar ",
"email": "tusharbhuwad90@gmail.com",
"lastName": "Bhuwad",
"mobileNo": "9082053889",
"designation": "",
"shortName": "TSB",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f949ce45132d6a6bddbcc3/
profilePhoto_1668058314746_WhatsApp_Image_20221110_at_105931_AM.jpeg"
},
"rateVerifier": null,
"maker": null,
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
]
},
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
```

```
"title": {
  "label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.133070",
```

```
"longitude": "72.828497"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.828497,
    19.13307
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
    "value": "",
    "label": true
  },
  "floorNo": {
    "status": true,
```

```
"name": "Floor No",
"key": "floorNo",
"value": "4",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai ",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Oshivra Andheri West",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
}
```

```
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Indra Darshan 2 Shri Swami Samarth prashan oshivra East Unit No13 chs
Ltd off ",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "New link road. ",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
```

```
"name": "Project Name",
"key": "projectName",
"value": "",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "403",
  "label": false
}
```



```
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
```

```
    "key": "postalCode",
    "value": "400053",
    "label": false
  },
  "suburb": {
    "status": false,
    "name": "Suburb",
    "key": "suburb",
    "value": "",
    "label": false
  }
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  }
},
"locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
}
```

```
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
    "label": "External Plastering",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
```

```
},
"builtUpRateRange": {
  "min": "0.00",
  "max": "0.00"
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
```

```
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentIds": [],
"_id": "66445b9f8c135a5bbc77b0de",
"ownerName": "Smt Renu R.Mantri ",
"ownerPhoneNo": "8850134388",
"appAddress": "Flat No 403\n4th floor \nIndra Darshan 2\nShri Swami Samarth
prashan \noshivra East Unit No13 chs Ltd \noff New link road. Oshivra \nAndheri West
\nMumbai 400053",
"remark": "",
"documents": [
  {
    "documentType": {
```



```
    "label": "Old Valution Report ",
    "value": "60ae1296aa6d152c1801b455"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/66445b9f8c135a5bbc77b0de/
document_1715755870100_1715755654432_Smt_Renu_R_Mantri_old_Report_.pdf",
  "fileName":
"document_1715755870100_1715755654432_Smt_Renu_R_Mantri_old_Report_.pdf",
  "id": "968189",
  "uploadedBy": "62727444afd7d55eddee092c",
  "createdAt": "Wed May 15 2024 12:22:15 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "008698",
"createdBy": "62727444afd7d55eddee092c",
"caseHistory": [
  {
    "id": "549443",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed May 15 2024 12:22:15 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Smt Renu R.Mantri ",
    "phone": "8850134388",
    "ownershipShare": "",
    "email": "",
    "id": "918082"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6644926575934e3f09c47e36",
```

```
    "name": "externalimg_r_1715769957077_IMG20240513150646.jpg",
    "path": "cases/66445b9f8c135a5bbc77b0de/
externalimg_r_1715769957077_IMG20240513150646.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6644926575934e3f09c47e37",
    "name": "externalimg_r_1715769957083_IMG20240513151942.jpg",
    "path": "cases/66445b9f8c135a5bbc77b0de/
externalimg_r_1715769957083_IMG20240513151942.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6644926575934e3f09c47e38",
    "name": "externalimg_r_1715769957072_IMG20240513150637.jpg",
    "path": "cases/66445b9f8c135a5bbc77b0de/
externalimg_r_1715769957072_IMG20240513150637.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6644926575934e3f09c47e39",
    "name": "externalimg_r_1715769957087_IMG20240514103803.jpg",
    "path": "cases/66445b9f8c135a5bbc77b0de/
externalimg_r_1715769957087_IMG20240514103803.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6644926575934e3f09c47e3a",
    "name": "externalimg_r_1715769957098_TimePhoto_20240513_150609.jpg",
    "path": "cases/66445b9f8c135a5bbc77b0de/
externalimg_r_1715769957098_TimePhoto_20240513_150609.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6644926575934e3f09c47e3b",
    "name": "externalimg_r_1715769957091_TimePhoto_20240513_150606.jpg",
```

```
    "path": "cases/66445b9f8c135a5bbc77b0de/
externallmg_r_1715769957091_TimePhoto_20240513_150606.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6644926575934e3f09c47e3c",
    "name": "externallmg_r_1715769957104_TimePhoto_20240513_152511.jpg",
    "path": "cases/66445b9f8c135a5bbc77b0de/
externallmg_r_1715769957104_TimePhoto_20240513_152511.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6644926575934e3f09c47e3d",
    "name": "externallmg_r_1715769957101_TimePhoto_20240513_152434.jpg",
    "path": "cases/66445b9f8c135a5bbc77b0de/
externallmg_r_1715769957101_TimePhoto_20240513_152434.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6644926575934e3f09c47e3e",
    "name": "externallmg_r_1715769957107_TimePhoto_20240514_104341.jpg",
    "path": "cases/66445b9f8c135a5bbc77b0de/
externallmg_r_1715769957107_TimePhoto_20240514_104341.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6644926575934e3f09c47e3f",
    "name": "externallmg_r_1715769957110_TimePhoto_20240514_104353.jpg",
    "path": "cases/66445b9f8c135a5bbc77b0de/
externallmg_r_1715769957110_TimePhoto_20240514_104353.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6644926575934e3f09c47e40",
    "name": "externallmg_r_1715769957112_TimePhoto_20240514_104602.jpg",
    "path": "cases/66445b9f8c135a5bbc77b0de/
externallmg_r_1715769957112_TimePhoto_20240514_104602.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6644926575934e3f09c47e41",
  "name": "externallmg_r_1715769957116_TimePhoto_20240514_104604.jpg",
  "path": "cases/66445b9f8c135a5bbc77b0de/
externallmg_r_1715769957116_TimePhoto_20240514_104604.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6644926575934e3f09c47e42",
  "name": "externallmg_r_1715769957118_TimePhoto_20240514_104610.jpg",
  "path": "cases/66445b9f8c135a5bbc77b0de/
externallmg_r_1715769957118_TimePhoto_20240514_104610.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6644926575934e3f09c47e43",
  "name": "externallmg_r_1715769957120_TimePhoto_20240514_104612.jpg",
  "path": "cases/66445b9f8c135a5bbc77b0de/
externallmg_r_1715769957120_TimePhoto_20240514_104612.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6644926575934e3f09c47e44",
  "name": "externallmg_r_1715769957122_TimePhoto_20240514_104624.jpg",
  "path": "cases/66445b9f8c135a5bbc77b0de/
externallmg_r_1715769957122_TimePhoto_20240514_104624.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6644927775934e3f09c47e61",
  "name": "externallmg_r_1715769975068_TimePhoto_20240514_104710.jpg",
  "path": "cases/66445b9f8c135a5bbc77b0de/
externallmg_r_1715769975068_TimePhoto_20240514_104710.jpg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6644927775934e3f09c47e62",
      "name": "externallmg_r_1715769975078_TimePhoto_20240514_105137.jpg",
      "path": "cases/66445b9f8c135a5bbc77b0de/externallmg_r_1715769975078_TimePhoto_20240514_105137.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6644927775934e3f09c47e63",
      "name": "externallmg_r_1715769975070_TimePhoto_20240514_104715.jpg",
      "path": "cases/66445b9f8c135a5bbc77b0de/externallmg_r_1715769975070_TimePhoto_20240514_104715.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6644927775934e3f09c47e64",
      "name": "externallmg_r_1715769975073_TimePhoto_20240514_104723.jpg",
      "path": "cases/66445b9f8c135a5bbc77b0de/externallmg_r_1715769975073_TimePhoto_20240514_104723.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6644927775934e3f09c47e65",
      "name": "externallmg_r_1715769975080_TimePhoto_20240514_105403.jpg",
      "path": "cases/66445b9f8c135a5bbc77b0de/externallmg_r_1715769975080_TimePhoto_20240514_105403.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6644927775934e3f09c47e66",
      "name": "externallmg_r_1715769975082_TimePhoto_20240514_105405.jpg",
      "path": "cases/66445b9f8c135a5bbc77b0de/externallmg_r_1715769975082_TimePhoto_20240514_105405.jpg",
      "orientation": "portrait"
    },
  ],
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6644927775934e3f09c47e67",
  "name": "externallmg_r_1715769975085_TimePhoto_20240514_105409.jpg",
  "path": "cases/66445b9f8c135a5bbc77b0de/
externallmg_r_1715769975085_TimePhoto_20240514_105409.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6644927775934e3f09c47e68",
  "name": "externallmg_r_1715769975087_TimePhoto_20240514_105412.jpg",
  "path": "cases/66445b9f8c135a5bbc77b0de/
externallmg_r_1715769975087_TimePhoto_20240514_105412.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6644927775934e3f09c47e69",
  "name": "externallmg_r_1715769975091_TimePhoto_20240514_105612.jpg",
  "path": "cases/66445b9f8c135a5bbc77b0de/
externallmg_r_1715769975091_TimePhoto_20240514_105612.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6644927775934e3f09c47e6a",
  "name": "externallmg_r_1715769975089_TimePhoto_20240514_105605.jpg",
  "path": "cases/66445b9f8c135a5bbc77b0de/
externallmg_r_1715769975089_TimePhoto_20240514_105605.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6644927775934e3f09c47e6b",
  "name": "externallmg_r_1715769975094_TimePhoto_20240514_105635.jpg",
  "path": "cases/66445b9f8c135a5bbc77b0de/
externallmg_r_1715769975094_TimePhoto_20240514_105635.jpg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6644927775934e3f09c47e6c",
    "name": "externallmg_r_1715769975097_TimePhoto_20240514_105637.jpg",
    "path": "cases/66445b9f8c135a5bbc77b0de/
externallmg_r_1715769975097_TimePhoto_20240514_105637.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6644927775934e3f09c47e6d",
    "name": "externallmg_r_1715769975100_TimePhoto_20240514_105651.jpg",
    "path": "cases/66445b9f8c135a5bbc77b0de/
externallmg_r_1715769975100_TimePhoto_20240514_105651.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6644927775934e3f09c47e6e",
    "name": "externallmg_r_1715769975103_TimePhoto_20240514_105957.jpg",
    "path": "cases/66445b9f8c135a5bbc77b0de/
externallmg_r_1715769975103_TimePhoto_20240514_105957.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6644927775934e3f09c47e6f",
    "name": "externallmg_r_1715769975106_TimePhoto_20240514_105959.jpg",
    "path": "cases/66445b9f8c135a5bbc77b0de/
externallmg_r_1715769975106_TimePhoto_20240514_105959.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6644927775934e3f09c47e70",
    "name": "externallmg_r_1715769975110_TimePhoto_20240514_110000.jpg",
    "path": "cases/66445b9f8c135a5bbc77b0de/
externallmg_r_1715769975110_TimePhoto_20240514_110000.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "6644927775934e3f09c47e71",
  "name": "externallmg_r_1715769975113_TimePhoto_20240514_110003.jpg",
  "path": "cases/66445b9f8c135a5bbc77b0de/
externallmg_r_1715769975113_TimePhoto_20240514_110003.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6644927775934e3f09c47e72",
  "name": "externallmg_r_1715769975116_TimePhoto_20240514_110038.jpg",
  "path": "cases/66445b9f8c135a5bbc77b0de/
externallmg_r_1715769975116_TimePhoto_20240514_110038.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6644927775934e3f09c47e73",
  "name": "externallmg_r_1715769975119_IMG20240513150635.jpg",
  "path": "cases/66445b9f8c135a5bbc77b0de/
externallmg_r_1715769975119_IMG20240513150635.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6644927775934e3f09c47e74",
  "name": "externallmg_r_1715769975122_TimePhoto_20240513_152418.jpg",
  "path": "cases/66445b9f8c135a5bbc77b0de/
externallmg_r_1715769975122_TimePhoto_20240513_152418.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "664492919ab4ee3f05183c9c",
  "name": "externallmg_r_1715770000508_IMG20240515065237.jpg",
  "path": "cases/66445b9f8c135a5bbc77b0de/
externallmg_r_1715770000508_IMG20240515065237.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```



```

    "_id": "664492919ab4ee3f05183c9d",
    "name": "externalimg_r_1715770000436_IMG20240515065227.jpg",
    "path": "cases/66445b9f8c135a5bbc77b0de/
externalimg_r_1715770000436_IMG20240515065227.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-05-15T06:52:15.650Z",
"updatedAt": "2024-05-15T10:46:41.230Z",
"__v": 0,
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"fullAddress": "Residential Flat No. 403, 4th Floor, Indra Darshan 2 Shri Swami
Samarth prashan oshivra East Unit No13 chs Ltd off , New link road. , District -
Mumbai , Oshivra Andheri West, 400053, State - Maharashtra, India",
"updatedBy": "6006d4ce5080a310ac1fdfc2",
"addressForMap": "",
"caseReferredBy": "",
"contactPersonName": "Smt Renu R.Mantri ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "8850134388"
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			