

```
{
  "typeOfReport": {
    "label": "Office",
    "value": "Office"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64c200299d3a3e4ed9d327b3"
    },
    "type": "CREDITOFFICER",
    "_id": "65dd8c75e333566c7d303504",
    "firstName": "Manish",
    "lastName": "Mohan",
    "mobileNo": "",
    "workMobileNo": "9321793287",
    "email": "rmre1.svroadborivali@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "9857210",
    "discussWithPerson": "Manish",
    "expectedFees": 4928.6050000000005,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "64c200299d3a3e4ed9d327b3",
  "name": "S.V. Road Borivali West Branch ( 15781 S M E Branch)",
  "branchCode": "",
  "mobileNo": "2228954972",
  "alternateMobileNo": "",
  "email": "sbi.15781@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "101. 1st Floor, Landmark Building, Near Petrol Pump, S.V Road, Borivali
(West), Mumbai - 400 092 "
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Commercial",
  "value": "Commercial"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
    "_id": "60af6ae22ffdf65bcd65861d",
    "role": "PICKUPPERSON",
    "firstName": "Sunil",
    "email": "misalsunil87@gmail.com",
    "lastName": "Misal",
    "mobileNo": "8422982721",
    "shortName": "SM",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60af6ae22ffdf65bcd65861d\\
\\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "62720a36afd7d55eddedc4a7",
    "role": "SITEENGINEER",
    "firstName": "Anwar",
    "email": "anwar21786@gmail.com",
    "lastName": "Shaikh",
    "mobileNo": "8552884500",
    "designation": "",
    "shortName": "AS",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/62720a36afd7d55eddedc4a7/
profilePhoto_1668059819446_anwar_2.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "64dc7184ccaf1e7b7f637f47",
    "role": "FRONTDESK",
    "firstName": "Binumon",
    "email": "binu@vastukala.org",
    "lastName": "Moozhickal",
    "mobileNo": "9930252906",
    "designation": "Back Office Team Leader",
    "shortName": "BS",
    "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
    "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
  },
  "maker": {
    "type": "EMPLOYEE",
    "_id": "62fe044a48a26047e6552796",
    "role": "MAKER",
    "firstName": "Pradnya ",
    "email": "pradnya@vastukala.org",
    "lastName": "Rasam",
```

```
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "64dc7184ccaf1e7b7f637f47",
  "role": "FRONTDESK",
  "firstName": "Binumon",
  "email": "binu@vastukala.org",
  "lastName": "Moozhickal",
  "mobileNo": "9930252906",
  "designation": "Back Office Team Leader",
  "shortName": "BS",
  "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
  "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  "type": "EMPLOYEE",
  "_id": "5ffe92d27737ca4d986b6453",
  "role": "VALUER",
  "firstName": "Manoj",
  "email": "manoj@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9819597579",
  "designation": "Registered Valuer",
  "registrationNo": [
    {
      "title": {
        "label": "IBBI"
      },
      "_id": "60af80072ffdf65bcd658651",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  {

```

```
"title": {
  "value": "FIIV",
  "label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.258226458105163",
  "longitude": "72.85368465439726"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.85368465439726,
    19.258226458105163
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "3/06/2024 01:07 pm"
    },
    {
      "dateTime": "3/06/2024 12:00 am"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-06-08",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-06-08",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "Country - India",
```

```
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Dahisar ",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "1",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban ",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
```

```
"name": "Taluka",
"key": "taluka",
"value": "Borivali ",
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Omkareshwar",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Kandarpada",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Link Road ",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
}
```



```
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "134, 150/A, 150/B & others ",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
```

```
"key": "blockNo",
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "103",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
}
```

```
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 068",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Dahisar (West)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_/_Glass_Door",
    "label": "Teak Wood / Glass Door"
  },
  "windows": {
    "value": "Wooden_frame_openable_widow_with_M._S._Grill",
    "label": "Wooden frame openable widow with M. S. Grill"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering_+_POP_Finish",
```

```
    "label": "Cement Plastering + POP Finish"
  }
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MCGM",
    "label": "Municipal Corporation of Greater Mumbai (MCGM)"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "CS Link Road / Kandarpada Road ",
    "west": "Open Plot",
    "south": "Chawls ",
    "east": "Laxman Mhatre Road "
  },
  "asPerDocumentAgreement": {
    "north": "By CTS No. 159",
    "west": "By CTS No. 168",
    "south": "By CTS No. 148, 147",
    "east": "By CTS No. 155, 153"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "",
      "west": "",
      "south": "",
      "east": ""
    },
    "asPerDocument": {
      "north": "",
      "west": "",

```

```

    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "The Composition of Commercial Office is 3 Cabin +
Reception + Pantry + Passage + Toilet.",
"dateOfIssusApprovePlan": "Copy of Approved Building plans were not provided and
not verified.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A.",
"unauthorizedConstruction": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "i) As per Site Inspection, Actual Total Carpet area 574.00 Sq. Ft. is more
than Built Up area 558.00 Sq. Ft. mentioned in the documents provided to us. We have
considered area mentioned in the documents for valuation.<br />ii) At the time of site
visit, internal office renovation work is in progress.\n",
  "depreciationPercentage": "21",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "20412",
  "depreciatedBuildingRate": "2212"
},
"igrRate": {
  "propertyName": "Office",
  "rate": "156510",

```

```
"landRate": "60250",
"igrImage": "cases/665d60d259496f15880e8553/igr_1717847248022_Image.png",
"squareMeterGuideLineRate": "156510.00",
"squareFeetGuideLineRate": "14540.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "86",
  "rate": "13288.00",
  "squareFeetGuideLineRate": "13288.00",
  "squareMeterGuideLineRate": "143034.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Commercial_use",
    "label": "Commercial use"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "N.A.",
  "assessmentNo": "Details not available ",
  "taxPaidHolderName": "Details not available ",
  "taxAmount": "Details not available ",
  "electricityServiceConnectionNo": "Details not available ",
  "meterCardHolderName": "Details not available ",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available ",
  "floorSpaceIndex": "Details not available ",
  "tenantName": "",
  "maintenanceOfFlat": "Good "
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
```

```
"value": "rcc_Slab",
"label": "R. C. C. Slab"
},
"partitions": {
"value": "6\"_Thk._Brick_Masonry",
"label": "6\" Thk. Brick Masonery"
},
"waterTank": {
"value": "MunicipalWaterSupply",
"label": "Municipal Water Supply"
},
"pavementLaid": {
"value": "Yes",
"label": "Yes"
},
"carParking": "Stilt Car Parking Space ",
"constructionWorkStatus": {
"value": "Completed",
"label": "Completed"
},
"asthetikLook": {
"value": "Plain_Looking",
"label": "Plain Looking"
},
"dateOfConstruction": {
"date": "1",
"month": "1",
"year": "2010",
"fullDate": "1/1/2010"
},
"planningArea": {
"value": "Residential_cum_Commercial",
"label": "Residential cum Commercial"
},
"typeOfStructure": {
"value": "R.C.C._Framed_Structure",
"label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
"value": "rcc",
"label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
"value": "Good",
"label": "Good"
},
}
```

```
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenancelssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
```



```
"label": "Yes"
},
"groundStilt": {
  "value": "Part_Ground_and_Part_Stilt",
  "label": "Part Ground + Part Stilt"
},
"yearOfConstructionAsPer": {
  "value": "As_Per_Previous_valuation_Report",
  "label": "As Per Previous valuation Report"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "46",
"ageOfBuilding": "14",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "7",
"flatFloorNo": "1",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "3"
},
"finalPlinthArea": {
  "area": "558.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Article of Agreement"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Metro_Station",
      "label": "Metro Station"
    }
  },
  "routeMapImg": "cases/665d60d259496f15880e8553/
routeMap_1718012661862_Image.png",
  "routeLat": "19.257957",
  "routeLng": "72.853477",
  "stationName": "Kandarpada ",
  "routeDistance": "400 Mtrs. "
},
"finalLatLng": {
  "coordinates": [
    null,
    null
  ]
},
]
```

```
"type": "Point"
},
"showLocation": {
  "latlng": true,
  "finallatlng": true
},
"locationMapImg": [
  {
    "id": "a5ru4l",
    "name": "a5ru4l",
    "image": "cases/665d60d259496f15880e8553/
routeMap_1718012587565_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "11389896.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
```

```
"bookValue": "0",
"finalValue": "11389896.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Mon Jun 10 2024 15:51:43 GMT+0530 (India Standard Time)",
  "number": "2306660",
  "dayCount": "11",
  "monthCount": "104",
  "generatedBy": "64dc7184ccaf1e7b7f637f47"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "7414704.00",
```

```
"selectedBuildUpValue": "558.00",
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "66642fa0ae3a5a1dc46aaf16",
      "name":
"externallmg_1717841824467_WhatsApp_Image_20240608_at_141800_1.jpeg",
      "path": "cases/665d60d259496f15880e8553/
externallmg_1717841824467_WhatsApp_Image_20240608_at_141800_1.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "66642fa0ae3a5a1dc46aaf16",
      "name":
"externallmg_1717841824467_WhatsApp_Image_20240608_at_141800_1.jpeg",
      "path": "cases/665d60d259496f15880e8553/
externallmg_1717841824467_WhatsApp_Image_20240608_at_141800_1.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "66642fa0ae3a5a1dc46aaf14",
      "name":
"externallmg_1717841824462_WhatsApp_Image_20240608_at_141759_2.jpeg",
      "path": "cases/665d60d259496f15880e8553/
externallmg_1717841824462_WhatsApp_Image_20240608_at_141759_2.jpeg",
      "orientation": "landscape"
    },
    {
      "status": false,
      "_id": "66642fa0ae3a5a1dc46aaf15",
      "name":
"externallmg_1717841824465_WhatsApp_Image_20240608_at_141759.jpeg",
      "path": "cases/665d60d259496f15880e8553/
externallmg_1717841824465_WhatsApp_Image_20240608_at_141759.jpeg",
      "orientation": "landscape"
    },
    {
      "status": false,
```

```
    "_id": "66642fa0ae3a5a1dc46aaf19",
    "name":
"externallmg_1717841824477_WhatsApp_Image_20240608_at_141801_1.jpeg",
    "path": "cases/665d60d259496f15880e8553/
externallmg_1717841824477_WhatsApp_Image_20240608_at_141801_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66642fa0ae3a5a1dc46aaf1e",
    "name":
"externallmg_1717841824492_WhatsApp_Image_20240608_at_141802.jpeg",
    "path": "cases/665d60d259496f15880e8553/
externallmg_1717841824492_WhatsApp_Image_20240608_at_141802.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66642fa0ae3a5a1dc46aaf20",
    "name":
"externallmg_1717841824497_WhatsApp_Image_20240608_at_141803_2.jpeg",
    "path": "cases/665d60d259496f15880e8553/
externallmg_1717841824497_WhatsApp_Image_20240608_at_141803_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66642fa0ae3a5a1dc46aaf1f",
    "name":
"externallmg_1717841824494_WhatsApp_Image_20240608_at_141803_1.jpeg",
    "path": "cases/665d60d259496f15880e8553/
externallmg_1717841824494_WhatsApp_Image_20240608_at_141803_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66642fa0ae3a5a1dc46aaf24",
    "name":
"externallmg_1717841824509_WhatsApp_Image_20240608_at_141804.jpeg",
    "path": "cases/665d60d259496f15880e8553/
externallmg_1717841824509_WhatsApp_Image_20240608_at_141804.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66642f90ae3a5a1dc46aaedf",
```

```
    "name":
"externallmg_1717841807854_WhatsApp_Image_20240608_at_141758_1.jpeg",
  "path": "cases/665d60d259496f15880e8553/
externallmg_1717841807854_WhatsApp_Image_20240608_at_141758_1.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "66642f90ae3a5a1dc46aaee0",
  "name":
"externallmg_1717841807859_WhatsApp_Image_20240608_at_141758.jpeg",
  "path": "cases/665d60d259496f15880e8553/
externallmg_1717841807859_WhatsApp_Image_20240608_at_141758.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "66642fa0ae3a5a1dc46aaf1d",
  "name":
"externallmg_1717841824489_WhatsApp_Image_20240608_at_141802_2.jpeg",
  "path": "cases/665d60d259496f15880e8553/
externallmg_1717841824489_WhatsApp_Image_20240608_at_141802_2.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "66642fa0ae3a5a1dc46aaf1c",
  "name":
"externallmg_1717841824486_WhatsApp_Image_20240608_at_141802_1.jpeg",
  "path": "cases/665d60d259496f15880e8553/
externallmg_1717841824486_WhatsApp_Image_20240608_at_141802_1.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "66642fa0ae3a5a1dc46aaf1b",
  "name":
"externallmg_1717841824482_WhatsApp_Image_20240608_at_141801.jpeg",
  "path": "cases/665d60d259496f15880e8553/
externallmg_1717841824482_WhatsApp_Image_20240608_at_141801.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "66642fa0ae3a5a1dc46aaf22",
  "name":
"externallmg_1717841824504_WhatsApp_Image_20240608_at_141804_1.jpeg",
```



```
    "path": "cases/665d60d259496f15880e8553/
externallmg_1717841824504_WhatsApp_Image_20240608_at_141804_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66642fa0ae3a5a1dc46aaf23",
    "name":
"externallmg_1717841824507_WhatsApp_Image_20240608_at_141804_2.jpeg",
    "path": "cases/665d60d259496f15880e8553/
externallmg_1717841824507_WhatsApp_Image_20240608_at_141804_2.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "24921.00",
    "max": "32143.00"
  },
  "builtUpRateRange": {
    "min": "20768.00",
    "max": "26786.00"
  },
  "saleableRateRange": {
    "min": "17306.00",
    "max": "22322.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
```

```
"label": "Lead",
"value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "558.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentIds": [],
"_id": "665d60d259496f15880e8553",
"ownerName": "Mr. Laxmikant Ramchandra Sawant",
"ownerPhoneNo": "8652458973",
"appAddress": "Office no 103 1 St floor Omkareshwar Kandarpada Link Road Dahisar
West Mumbai 400068",
"remark": "Contact person Neam-Datta Sawant ",
"documents": [
  {
    "documentType": {
      "value": "60ae124faa6d152c1801b30f",
      "label": "Article of Agreement"
    },
    "inputs": {
      "documentDate": "13/12/2013",
      "from": {
        "value": "Developers",
        "label": "Developers"
      },
      "Developers": "M/s. Vishwambhar Construction ",
      "to": {
        "value": "Purchaser",
        "label": "Purchaser"
      },
      "Purchaser": "Mr. Laxmikant Ramchandra Sawant"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1718009109611_Sawant_Construction_Office_no_103.pdf",
    "path": "cases/665d60d259496f15880e8553/
document_1718009109611_Sawant_Construction_Office_no_103.pdf",
    "id": "344508",
    "uploadedBy": "62fe044a48a26047e6552796",
```

```
"createdAt": "Mon Jun 10 2024 14:15:10 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "04/05/2006",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_of_Greater_Mumbai",
      "label": "Municipal Corporation of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "CHE / A - 3866 / BP(WS) / AP / AR"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1718009156751_Sawant_Construction_Office_no_103.pdf",
"path": "cases/665d60d259496f15880e8553/
document_1718009156751_Sawant_Construction_Office_no_103.pdf",
"id": "373642",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Mon Jun 10 2024 14:15:57 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1248aa6d152c1801b2ee",
    "label": "Previous Valuation Report"
  },
  "inputs": {
    "documentDate": "27/07/2020",
    "remark": " in the name of Mr. Laxmikant Ramchandra Sawant issued by Vastukala
Consultants Pvt. Ltd"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1718009237628_Previous_Valuation_report.pdf",
  "path": "cases/665d60d259496f15880e8553/
document_1718009237628_Previous_Valuation_report.pdf",
  "id": "455399",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Mon Jun 10 2024 14:17:18 GMT+0530 (India Standard Time)"
}
```

```
}
],
"caseNumber": "009050",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "790330",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Jun 03 2024 11:51:06 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Laxmikant Ramchandra Sawant",
    "phone": "8652458973",
    "ownershipShare": "",
    "email": "",
    "id": "699104"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "623132",
    "name": "Cabin",
    "length": "94.00",
    "length1": "94",
    "length2": "00",
    "width": "1.00",
    "width1": "1",
    "width2": "00",
    "totalArea": "94.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "94.00"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    }
  }
]
```

```
},
  "id": "1",
  "name": "Cabin",
  "length": "108.00",
  "length1": "108",
  "length2": "00",
  "width": "1.00",
  "width1": "1",
  "width2": "00",
  "totalArea": "108.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "108.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Cabin",
  "length": "123.00",
  "length1": "123",
  "length2": "00",
  "width": "1.00",
  "width1": "1",
  "width2": "00",
  "totalArea": "123.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "123.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Reception",
  "length": "143.00",
  "length1": "143",
  "length2": "00",
  "width": "1.00",
  "width1": "1",
  "width2": "00",
  "totalArea": "143.00",
```

```
"images": [],
"extraAreas": [],
"finalArea": "143.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Pantry",
  "length": "27.00",
  "length1": "27",
  "length2": "00",
  "width": "1.00",
  "width1": "1",
  "width2": "00",
  "totalArea": "27.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "27.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Passage",
  "length": "43.00",
  "length1": "43",
  "length2": "00",
  "width": "1.00",
  "width1": "1",
  "width2": "00",
  "totalArea": "43.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "43.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
```



```
"name": "Toilet",
"length": "36.00",
"length1": "36",
"length2": "00",
"width": "1.00",
"width1": "1",
"width2": "00",
"totalArea": "36.00",
"images": [],
"extraAreas": [],
"finalArea": "36.00"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
"typeofDocument": {
"value": "60ae124faa6d152c1801b30f",
"label": "Article of Agreement"
},
"docMeasurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"docFinalBuiltUp": "0.00",
"docFinalBuiltUpSquareMeter": "0.00",
"docBuiltupPercentage": "",
"docSaleablePercentage": "0",
"docFinalSaleable": "0",
"docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
"carpetArea": {
"area": "315.00",
"squareMeterArea": "29.26",
"expectedRate": "24920.63",
"percentage": ""
}
},
]
```

```
"builtUpArea": {
  "area": "378.00",
  "squareMeterArea": "35.12",
  "expectedRate": "20767.20",
  "percentage": "20"
},
"saleableArea": {
  "area": "453.60",
  "squareMeterArea": "42.14",
  "expectedRate": "17306.00",
  "percentage": "20"
},
"printInReport": true,
"_id": "666444dd46c7a930aad41501",
"property": "Office",
"area": "378",
"builtUpPercentage": "20",
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"floor": "",
"source": "Nobroker.com",
"expectedPrice": "7850000",
"expectedRate": "24920.63",
"builtUpExpectedRate": "7850000",
"image": "cases/665d60d259496f15880e8553/
indicator_1717847099849_Image.png",
"squareMeter": "35.12",
"id": "160310"
},
{
  "carpetArea": {
    "area": "280.00",
    "squareMeterArea": "26.01",
    "expectedRate": "32142.86",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "336.00",
    "squareMeterArea": "31.22",
    "expectedRate": "26785.71",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "403.20",
    "squareMeterArea": "37.46",
```

```
    "expectedRate": "22321.43",
    "percentage": "20"
  },
  "printlnReport": true,
  "_id": "666444dd46c7a930aad41502",
  "property": "Office",
  "area": "280",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "Nobroker.com",
  "expectedPrice": "9000000",
  "expectedRate": "32142.86",
  "builtUpExpectedRate": "26785.71",
  "image": "cases/665d60d259496f15880e8553/
indicator_1717847158297_Image.png",
  "squareMeter": "26.01",
  "id": "964765"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66642f90ae3a5a1dc46aaedd",
    "name":
"externalImg_1717841807844_WhatsApp_Image_20240608_at_141754.jpeg",
    "path": "cases/665d60d259496f15880e8553/
externalImg_1717841807844_WhatsApp_Image_20240608_at_141754.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66642f90ae3a5a1dc46aaede",
    "name":
"externalImg_1717841807848_WhatsApp_Image_20240608_at_141755.jpeg",
    "path": "cases/665d60d259496f15880e8553/
externalImg_1717841807848_WhatsApp_Image_20240608_at_141755.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "66642f90ae3a5a1dc46aaedf",
    "name":
"externallmg_1717841807854_WhatsApp_Image_20240608_at_141758_1.jpeg",
    "path": "cases/665d60d259496f15880e8553/
externallmg_1717841807854_WhatsApp_Image_20240608_at_141758_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66642f90ae3a5a1dc46aaee0",
    "name":
"externallmg_1717841807859_WhatsApp_Image_20240608_at_141758.jpeg",
    "path": "cases/665d60d259496f15880e8553/
externallmg_1717841807859_WhatsApp_Image_20240608_at_141758.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66642fa0ae3a5a1dc46aaf13",
    "name":
"externallmg_1717841824458_WhatsApp_Image_20240608_at_141759_1.jpeg",
    "path": "cases/665d60d259496f15880e8553/
externallmg_1717841824458_WhatsApp_Image_20240608_at_141759_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66642fa0ae3a5a1dc46aaf14",
    "name":
"externallmg_1717841824462_WhatsApp_Image_20240608_at_141759_2.jpeg",
    "path": "cases/665d60d259496f15880e8553/
externallmg_1717841824462_WhatsApp_Image_20240608_at_141759_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66642fa0ae3a5a1dc46aaf15",
    "name":
"externallmg_1717841824465_WhatsApp_Image_20240608_at_141759.jpeg",
    "path": "cases/665d60d259496f15880e8553/
externallmg_1717841824465_WhatsApp_Image_20240608_at_141759.jpeg",
    "orientation": "landscape"
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66642fa0ae3a5a1dc46aaf16",
      "name":
"externallmg_1717841824467_WhatsApp_Image_20240608_at_141800_1.jpeg",
      "path": "cases/665d60d259496f15880e8553/
externallmg_1717841824467_WhatsApp_Image_20240608_at_141800_1.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66642fa0ae3a5a1dc46aaf17",
      "name":
"externallmg_1717841824472_WhatsApp_Image_20240608_at_141800_2.jpeg",
      "path": "cases/665d60d259496f15880e8553/
externallmg_1717841824472_WhatsApp_Image_20240608_at_141800_2.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66642fa0ae3a5a1dc46aaf18",
      "name":
"externallmg_1717841824474_WhatsApp_Image_20240608_at_141800.jpeg",
      "path": "cases/665d60d259496f15880e8553/
externallmg_1717841824474_WhatsApp_Image_20240608_at_141800.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66642fa0ae3a5a1dc46aaf19",
      "name":
"externallmg_1717841824477_WhatsApp_Image_20240608_at_141801_1.jpeg",
      "path": "cases/665d60d259496f15880e8553/
externallmg_1717841824477_WhatsApp_Image_20240608_at_141801_1.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66642fa0ae3a5a1dc46aaf1a",
      "name":
"externallmg_1717841824479_WhatsApp_Image_20240608_at_141801_2.jpeg",
```

```
    "path": "cases/665d60d259496f15880e8553/
externallmg_1717841824479_WhatsApp_Image_20240608_at_141801_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66642fa0ae3a5a1dc46aaf1b",
    "name":
"externallmg_1717841824482_WhatsApp_Image_20240608_at_141801.jpeg",
    "path": "cases/665d60d259496f15880e8553/
externallmg_1717841824482_WhatsApp_Image_20240608_at_141801.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66642fa0ae3a5a1dc46aaf1c",
    "name":
"externallmg_1717841824486_WhatsApp_Image_20240608_at_141802_1.jpeg",
    "path": "cases/665d60d259496f15880e8553/
externallmg_1717841824486_WhatsApp_Image_20240608_at_141802_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66642fa0ae3a5a1dc46aaf1d",
    "name":
"externallmg_1717841824489_WhatsApp_Image_20240608_at_141802_2.jpeg",
    "path": "cases/665d60d259496f15880e8553/
externallmg_1717841824489_WhatsApp_Image_20240608_at_141802_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66642fa0ae3a5a1dc46aaf1e",
    "name":
"externallmg_1717841824492_WhatsApp_Image_20240608_at_141802.jpeg",
    "path": "cases/665d60d259496f15880e8553/
externallmg_1717841824492_WhatsApp_Image_20240608_at_141802.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "66642fa0ae3a5a1dc46aaf1f",
  "name":
"externallmg_1717841824494_WhatsApp_Image_20240608_at_141803_1.jpeg",
  "path": "cases/665d60d259496f15880e8553/
externallmg_1717841824494_WhatsApp_Image_20240608_at_141803_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66642fa0ae3a5a1dc46aaf20",
  "name":
"externallmg_1717841824497_WhatsApp_Image_20240608_at_141803_2.jpeg",
  "path": "cases/665d60d259496f15880e8553/
externallmg_1717841824497_WhatsApp_Image_20240608_at_141803_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66642fa0ae3a5a1dc46aaf21",
  "name":
"externallmg_1717841824501_WhatsApp_Image_20240608_at_141803.jpeg",
  "path": "cases/665d60d259496f15880e8553/
externallmg_1717841824501_WhatsApp_Image_20240608_at_141803.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66642fa0ae3a5a1dc46aaf22",
  "name":
"externallmg_1717841824504_WhatsApp_Image_20240608_at_141804_1.jpeg",
  "path": "cases/665d60d259496f15880e8553/
externallmg_1717841824504_WhatsApp_Image_20240608_at_141804_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66642fa0ae3a5a1dc46aaf23",
  "name":
"externallmg_1717841824507_WhatsApp_Image_20240608_at_141804_2.jpeg",
  "path": "cases/665d60d259496f15880e8553/
externallmg_1717841824507_WhatsApp_Image_20240608_at_141804_2.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66642fa0ae3a5a1dc46aaf24",
  "name":
"externallmg_1717841824509_WhatsApp_Image_20240608_at_141804.jpeg",
  "path": "cases/665d60d259496f15880e8553/
externallmg_1717841824509_WhatsApp_Image_20240608_at_141804.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
{
  "originalname": "LAXMIKANT RAMCHANDRA SAWANT - Office No. 103 - State
Bank Of India ( S.V. Road Borivali West Branch ( 15781 S M E Branch).xlsx",
  "filename": "1717848444282_LAXMIKANT_RAMCHANDRA_SAWANT__Office_N
o_103__State_Bank_Of_India__SV_Road_Borivali_West_Branch__15781_S_M_E_Bra
nch.xlsx",
  "path": "cases/665d60d259496f15880e8553/processingDocuments/1717848444282
_LAXMIKANT_RAMCHANDRA_SAWANT__Office_No_103__State_Bank_Of_India__
SV_Road_Borivali_West_Branch__15781_S_M_E_Branch.xlsx",
  "size": "2367003",
  "createdAt": "Sat Jun 08 2024 17:37:24 GMT+0530 (India Standard Time)",
  "uploadedBy": "64dc7184ccaf1e7b7f637f47"
},
{
  "originalname": "Sawant Construction Office no 103.pdf",
  "filename": "1718013092310_Sawant_Construction_Office_no_103.pdf",
  "path": "cases/665d60d259496f15880e8553/
processingDocuments/1718013092310_Sawant_Construction_Office_no_103.pdf",
  "size": "12766364",
  "createdAt": "Mon Jun 10 2024 15:21:32 GMT+0530 (India Standard Time)",
  "uploadedBy": "62fe044a48a26047e6552796"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
{
  "createdBy": {
    "_id": "64dc7184ccaf1e7b7f637f47",
    "role": "FRONTDESK",
    "firstName": "Binumon",
```



```
    "lastName": "Moozhickal",
    "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "66643b94ae3a5a1dc46abcee",
  "note": "Value Given for Confirmation",
  "taskId": "665d734759496f15880e97c6",
  "createdAt": "2024-06-08T11:08:04.445Z"
}
],
"createdAt": "2024-06-03T06:21:06.513Z",
"updatedAt": "2024-06-10T10:32:42.726Z",
"__v": 0,
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"fullAddress": "Commercial Office No. 103, 1st Floor, Omkareshwar, CTS No. 134, 150/
A, 150/B & others , Kandarpada, Link Road , Village - Dahisar , Dahisar (West), Taluka
- Borivali , District - Mumbai Suburban , PIN - 400 068, State - Maharashtra, Country -
India",
"updatedBy": "64dc7184ccaf1e7b7f637f47",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Mr. Niraj Pandey ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner's Employee ",
"siteVisitContactNo": "8652458973",
"buildingServicesRate": "2800",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Article of Agreement",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 558.00",
"flatRate": "21000",
"landOtherRate": "18200",
"shopDetails": {
```

```

"typeOfShops": null,
"roadFacing": false,
"mall": false
},
"builtupPercentage": "10",
"carpetTotal": "574.00",
"extendOfSiteRemark": "",
"finalBuiltupArea": "631.40",
"finalCarpetArea": "574.00",
"finalSalableArea": "694.54",
"otherCarpetTotal": "0.00",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"briefDescOfProperty": "3 Cabin + Reception + Pantry + Passage + Toilet",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
  "leaseTo": "",
  "remainingLeasePeriod": 0,
  "leaseDate": ""
}
},
"reportGeneratedDate": "Mon Jun 10 2024 14:18:22 GMT+0530 (India Standard Time)",
"siteVisitDate": "2024-06-08"
}

```

Name	Length	Width	Total
Composition :			
Cabin	94'00"	1'00"	94.00
Cabin	108'00"	1'00"	108.00
Cabin	123'00"	1'00"	123.00

Reception	143'00"	1'00"	143.00
Pantry	27'00"	1'00"	27.00
Passage	43'00"	1'00"	43.00
Toilet	36'00"	1'00"	36.00
Other Composition :			