### PROFORMA INVOICE

		_
1	and the same	. 0
		7
	W	
VAS	STUK	ΔΙΔ

Vastukala Consultants (I) Pvt Ltd B1-001, U/B FLOOR, BOOMERANG, CHANDIVALI FARM ROAD.

ANDHERI-EAST, MUMBAI - 400072 GSTIN/UIN: 27AADCV4303R1ZX State Name: Maharashtra, Code: 27

E-Mail: accounts@vastukala.co.in

Buyer (Bill to)

STATE BANK OF INDIA - THANE RACPC RACPC THANE BRANCH

Retail Assets Centralized, Processing Centre, Dosti Pinnacle, Plot No E7, Near New Passport Office, Gate No-3, Road No 22, Panchpakhadi Village Wagle Indl Estate. Thane- 400604

GSTIN/UIN

: 27AAACS8577K2ZO State Name : Maharashtra, Code : 27

Dated
25-Jun-24
Mode/Terms of Payment
<b>AGAINST REPORT</b>
Other References
Dated
Delivery Note Date
naces ones were sent
Destination

Terms of Delivery

SI No.	Particulars	HSN/S/	AC GST Rate	Amount
1		997224 GST GGST	18 %	1,500.00 135.00 135.00
	e er for oan oar for moret manne (beset) en er 100e - er er er er er er er beg	Total		1,770.00

Amount Chargeable (in words)

E. & O.E

#### Indian Rupee One Thousand Seven Hundred Seventy Only

HSN/SAC	Taxable Cer		tral Tax	State Tax		Total
	Value	Rate	Amount	Rate	Amount	Tax Amount
997224	1,500.00	9%	135.00	9%	135.00	270.00
Total	1,500.00		135.00		135.00	270.00

Tax Amount (in words): Indian Rupee Two Hundred Seventy Only

Mrs. Aparna Ankush Shelar - Residential Flat No. 1503, 15th Floor, Building No 39, "Avon Co-Op. Hsg. Soc. Ltd.", Hiranandani Estate, Patlipada, off. Ghodbunder Road, Village - Kolshet, Thane ( West), Taluka - Thane, District - Thane, PIN - 400 607, State - Maharashtra, Country - India

Company's PAN

: AADCV4303R

Declaration
NOTE – AS PER MSME RULES INVOICE NEED TO BE CLEARED WITHIN 45 DAYS OR INTEREST CHARGES APPLICABLE AS PER

THE RULE.

MSME Registration No. - 27222201137

Customer's Seal and Signature

Company's Bank Details

Bank Name : ICICI BANK LTD

340505000531 A/c No.

Branch & IFS Code: THANE CHARAI & ICIC0003405



**UPI** Virtual ID VASTUKALATHANE@icici

for Vastukala Consultants (I) Pvt Ltd

ASMITA JAYSING RATHOD Digitally signed on 25-86-2024 11:19:46

**Authorised Signatory** 



MSME Reg No: UDYAM-MH-18-0083617 An ISO 9001: 2015 Certified Company CIN: U74120MH2010PTC207869

# Vastukala Consultants (I) Pvt. Ltd.

Structural Stability Report Prepared for SBI / RACPC Thane/ Dinesh Ramesh Naik (009493/2306881)

Page 1 of 3

www.vastukala.co.in

Vastu/Thane/06/2024/009493/2306881 25/1-325-PRRJ Date: 25.06.2024

## Structural Stability Report

Structural Observation Report of Residential Flat No. 1503, 15th Floor, Building No 39, "Avon Co-Op. Hsg. Soc. Ltd. ", Hiranandani Estate, Patlipada, off. Ghodbunder Road, Village - Kolshet, Thane (West), Taluka - Thane, District - Thane, PIN - 400 607, State - Maharashtra, Country - India.

Name of Owner: Mr. Dinesh Ramesh Naik & Mrs. Aparna Ankush Shelar

This is to certify that on visual inspection, it appears that the structure of the at "Avon Co-Op. Hsg. Soc. Ltd.", is in normal condition and the future life can be reasonably taken under good condition and with proper periodic repairs & maintenance is about 40 years.

### General Information:

A.	000 - 81 1/2 4388	Introduction		
1	Name of Building	"Avon Co-Op. Hsg. Soc. Ltd."		
2	Property Address	Residential Flat No. 1503, 15th Floor, Building No 39, "Avon Co-Op. Hsg. Soc. Ltd. ", Hiranandani Estate, Patlipada, off. Ghodbunder Road, Village - Kolshet, Thane (West), Taluka - Thane, District - Thane, PIN - 400 607, State - Maharashtra, Country - India.		
3	Type of Building	Residential used		
4	No. of Floors	Ground + 16th Upper Floors		
5	Whether stilt / podium / open parking provided	Along with One Open Car Parking Space No. 13		
6	Type of Construction	R.C.C. Framed Structure		
7	Type of Foundation	R.C.C. Footing		
8	Thickness of the External Walls	9" thick brick walls both sides plastered		
9	Type of Compound	Brick Masonry Walls		
10	Year of Construction	2004 (As per Occupancy Certificate)		
11	Present age of building	20 years		
12	Residual age of the building	40 years Subject to proper, preventive periodic maintenance & structural repairs.		
13	No. of flats (Per Floor)	06 Flats on 15th Floor		
14	Methodology adopted	As per visual site inspection		

B.	External Observation of the Building			
1	Plaster	Normal Condition		
2	Chajjas	Normal Condition		
3	Plumbing	Normal Condition		
4	Cracks on the external walls	Not Found		
5	Filling cracks on the external walls	Not Found		
6	Cracks on columns & beams	Not Found		
7	Vegetation	Not Found		

Thane: 101, 1st Floor, Beth Shalom, Near Civil Hospital, Thane (W) - 400601, (M.S),INDIA Email:thane@vastukala.co.in | Tel: 80978 82976 / 90216 05621

Our Pan India Presence at:

Aurangabad
Pune

Mumbai Nashik Rajkot

Raipur 

Regd. Office

B1-001, U/B Floor, BOOMERANG, Chandivali Farm Road, Powai, Andheri East, Mumbai: -400072, (M.S), India





