

```
{
  "typeOfReport": {
    "label": "Office",
    "value": "Office"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64cb4e070faf29427aca4671"
    },
    "firstName": "Neha",
    "type": "CREDITOFFICER",
    "_id": "65d6e4d5cf7ad63a0afa958a",
    "lastName": "Khankal",
    "mobileNo": "",
    "workMobileNo": "7709307753",
    "email": "mcc813400@gmail.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "980213400",
    "discussWithPerson": "Neha",
    "expectedFees": 490106.7,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1812",
  "type": "BANK",
  "name": "Punjab National Bank",
  "displayName": "Punjab National Bank",
  "initial": "PNB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "64cb4e070faf29427aca4671",
  "name": "MCC MW 2 Goregaon\t",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "mcc8134@pnb.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Rajnigandha Shopping Centre, 1st Floor, Krishna Vatika Marg, Opp.
Gokuldham Temple, Goregaon (E), Mumbai 400063"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f7fcadf3dd69653a58d9d7",
  "zoneName": "Mumbai Zone (Maharashtra)"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
  "_id": "60af6ae22ffdf65bcd65861d",
  "role": "PICKUPPERSON",
  "firstName": "Sunil",
  "email": "misalsunil87@gmail.com",
  "lastName": "Misal",
  "mobileNo": "8422982721",
  "shortName": "SM",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60af6ae22ffdf65bcd65861d\\
\\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62691c48afd7d55eddecfda3",
  "role": "ADMIN",
  "firstName": "Bhavika",
  "email": "bhavikachavan0102@gmail.com",
  "lastName": "chavan",
  "mobileNo": "8390804382",
  "designation": "Site Engineer",
  "shortName": "BH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
},
"rateVerifier": null,
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "[N]C.C.I.T/I -14/52/2008-09",
        "label": "Wealth Tax"
      }
    ]
  },
  "type": "EMPLOYEE",
  "_id": "6084131a13f01f158c6ea1f3",
  "PANNo": "AEAPC7114Q",
  "role": "VALUER",
  "firstName": "Sharadkumar",
  "fatherName": "Baburao",
  "email": "cmd@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9422171100",
  "designation": "CMD",
```

```
"registrationNo": [
  {
    "title": {
      "value": "Wealth_Tax",
      "label": "Wealth Tax"
    },
    "_id": "6084131a13f01f158c6ea1f4",
    "number": "[N]C.C.I.T/I -14/52/2008-09"
  }
],
"shortName": "SBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
],
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.10566952195483",
  "longitude": "72.86302250516181"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.86302250516181,
    19.10566952195483
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "23/07/2024 03:38 pm"
    }
  ]
},
"visitedDate": [],
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
```

```
"finalMeasurementType": "Sq. Ft.",
"underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
    "value": "",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "1",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": false,
    "name": "District",
    "key": "district",
    "value": "",
    "label": true
  },
}
```

```
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "KARISHMA CHAMBER",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
```

```
"value": "NEAR BOMBAY CAMBRIDGE SCHOOL",
"label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "OFF SAHAR ROAD J B NAGAR",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
```

```
"status": false,
"name": "Hissa No.",
"key": "hissaNo",
"value": "",
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "101-102-103-104-105-106",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
```



```
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400069",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "ANDHERI EAST",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    }
  },
}
```

```
"taxies": {
  "title": "Taxies"
},
"auto": {
  "title": "Auto"
},
"privateCars": {
  "title": "Private Cars"
}
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
```

```
"status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
```

```
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTillingKitchenPlatform": {
"label": "Flooring, Tilling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
```

```
"min": "0.00",
"max": "0.00"
},
"builtUpRateRange": {
  "min": "0.00",
  "max": "0.00"
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
```

```
"title": "Superfine finish",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": true,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "669f7ed0522e015687d410d8",
"ownerName": "M/s Landmark Vista Hotels & Resorts Pvt Ltd ",
"ownerPhoneNo": "9879905200",
"appAddress": "Office no 101 ,102 ,103 ,104,105,106 First 1 Floor Karishma
Chambers GTB Nagar Sahar road Near Bombay Cambridge school Andheri East
Mumbai 400069",
```



```
"remark": "",
"documents": [
  {
    "documentType": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/669f7ed0522e015687d410d8/document_1721728067642_17217279
60756_101_Draft_Agreement_Karishma_Chambers.pdf",
    "fileName": "document_1721728067642_1721727960756_101_Draft_Agreement_K
arishma_Chambers.pdf",
    "id": "427222",
    "uploadedBy": "60af6ae22ffdf65bcd65861d",
    "createdAt": "Tue Jul 23 2024 15:28:40 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/669f7ed0522e015687d410d8/document_1721728083299_17217279
77686_102_Draft_Agreement_Karishma_Chambers.pdf",
    "fileName": "document_1721728083299_1721727977686_102_Draft_Agreement_K
arishma_Chambers.pdf",
    "id": "652736",
    "uploadedBy": "60af6ae22ffdf65bcd65861d",
    "createdAt": "Tue Jul 23 2024 15:28:40 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/669f7ed0522e015687d410d8/document_1721728107870_17217279
88175_103_Draft_Agreement_Karishma_Chambers.pdf",
    "fileName": "document_1721728107870_1721727988175_103_Draft_Agreement_K
arishma_Chambers.pdf",
    "id": "338261",
    "uploadedBy": "60af6ae22ffdf65bcd65861d",
    "createdAt": "Tue Jul 23 2024 15:28:40 GMT+0530 (India Standard Time)"
  }
]
```

```
},
{
  "documentType": {
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/669f7ed0522e015687d410d8/document_1721728120667_1721728015264_104_Draft_Agreement_Karishma_Chambers.pdf",
  "fileName": "document_1721728120667_1721728015264_104_Draft_Agreement_Karishma_Chambers.pdf",
  "id": "794299",
  "uploadedBy": "60af6ae22ffdf65bcd65861d",
  "createdAt": "Tue Jul 23 2024 15:28:40 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/669f7ed0522e015687d410d8/document_1721728133469_1721728027124_105_Draft_Agreement_Karishma_Chambers.pdf",
  "fileName": "document_1721728133469_1721728027124_105_Draft_Agreement_Karishma_Chambers.pdf",
  "id": "778419",
  "uploadedBy": "60af6ae22ffdf65bcd65861d",
  "createdAt": "Tue Jul 23 2024 15:28:40 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/669f7ed0522e015687d410d8/document_1721728144669_1721728038514_106_Draft_Agreement_Karishma_Chambers.pdf",
  "fileName": "document_1721728144669_1721728038514_106_Draft_Agreement_Karishma_Chambers.pdf",
  "id": "796777",
  "uploadedBy": "60af6ae22ffdf65bcd65861d",
  "createdAt": "Tue Jul 23 2024 15:28:40 GMT+0530 (India Standard Time)"
},
}
```

```
{
  "documentType": {
    "label": "Any Other Document",
    "value": "60ae124aaa6d152c1801b2f7"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/669f7ed0522e015687d410d8/
document_1721728164572_1721728057974_CC.pdf",
  "fileName": "document_1721728164572_1721728057974_CC.pdf",
  "id": "208723",
  "uploadedBy": "60af6ae22ffdf65bcd65861d",
  "createdAt": "Tue Jul 23 2024 15:28:40 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": "Approved Building Plan",
    "value": "60ae1277aa6d152c1801b3cc"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/669f7ed0522e015687d410d8/document_1721728188348_17217280
82202_BUILDING_APPROVE_PLAN_KARISHMA_LAND.pdf",
  "fileName": "document_1721728188348_1721728082202_BUILDING_APPROVE_P
LAN_KARISHMA_LAND.pdf",
  "id": "314980",
  "uploadedBy": "60af6ae22ffdf65bcd65861d",
  "createdAt": "Tue Jul 23 2024 15:28:40 GMT+0530 (India Standard Time)"
}
],
"gstNo": "",
"caseNumber": "010107",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "692619",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Jul 23 2024 15:28:40 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "M/s Landmark Vista Hotels & Resorts Pvt Ltd ",
    "phone": "9879905200",
    "ownershipShare": ""
  }
]
```

```
    "email": "",
    "id": "553122"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a0dca973ce9d724ff9cedd",
    "name": "externallmg_1721818209119_1721818103685_image_0.jpeg",
    "path": "cases/669f7ed0522e015687d410d8/
externallmg_1721818209119_1721818103685_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a0dca973ce9d724ff9cede",
    "name": "externallmg_1721818254015_1721818103685_image_1.jpeg",
    "path": "cases/669f7ed0522e015687d410d8/
externallmg_1721818254015_1721818103685_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a0dca973ce9d724ff9cedf",
    "name": "externallmg_1721818267602_1721818103685_image_2.jpeg",
    "path": "cases/669f7ed0522e015687d410d8/
externallmg_1721818267602_1721818103685_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a0dca973ce9d724ff9cee0",
    "name": "externallmg_1721818269655_1721818103686_image_3.jpeg",
    "path": "cases/669f7ed0522e015687d410d8/
externallmg_1721818269655_1721818103686_image_3.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a0dca973ce9d724ff9cee1",
  "name": "externallmg_1721818271586_1721818103686_image_4.jpeg",
  "path": "cases/669f7ed0522e015687d410d8/
externallmg_1721818271586_1721818103686_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a0dca973ce9d724ff9cee2",
  "name": "externallmg_1721818272402_1721818103686_image_5.jpeg",
  "path": "cases/669f7ed0522e015687d410d8/
externallmg_1721818272402_1721818103686_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a0dca973ce9d724ff9cee3",
  "name": "externallmg_1721818274012_1721818103686_image_6.jpeg",
  "path": "cases/669f7ed0522e015687d410d8/
externallmg_1721818274012_1721818103686_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a0dca973ce9d724ff9cee4",
  "name": "externallmg_1721818275458_1721818103686_image_7.jpeg",
  "path": "cases/669f7ed0522e015687d410d8/
externallmg_1721818275458_1721818103686_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a0dca973ce9d724ff9cee5",
  "name": "externallmg_1721818276865_1721818103686_image_8.jpeg",
  "path": "cases/669f7ed0522e015687d410d8/
externallmg_1721818276865_1721818103686_image_8.jpeg",
  "orientation": "landscape"
}
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a0dca973ce9d724ff9cee6",
    "name": "externallmg_1721818278255_1721818103686_image_9.jpeg",
    "path": "cases/669f7ed0522e015687d410d8/
externallmg_1721818278255_1721818103686_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66a0dcb320bf0172211c01d3",
    "name": "externallmg_1721818195259_1721818069413_image_0.jpeg",
    "path": "cases/669f7ed0522e015687d410d8/
externallmg_1721818195259_1721818069413_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66a0dcb320bf0172211c01d4",
    "name": "externallmg_1721818197840_1721818069416_image_1.jpeg",
    "path": "cases/669f7ed0522e015687d410d8/
externallmg_1721818197840_1721818069416_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66a0dcb320bf0172211c01d5",
    "name": "externallmg_1721818203659_1721818069416_image_2.jpeg",
    "path": "cases/669f7ed0522e015687d410d8/
externallmg_1721818203659_1721818069416_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66a0dcb320bf0172211c01d6",
    "name": "externallmg_1721818215571_1721818069416_image_3.jpeg",
    "path": "cases/669f7ed0522e015687d410d8/
externallmg_1721818215571_1721818069416_image_3.jpeg",
    "orientation": "portrait"
  },
}
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66a0dcb320bf0172211c01d7",
  "name": "externallmg_1721818267799_1721818069416_image_4.jpeg",
  "path": "cases/669f7ed0522e015687d410d8/
externallmg_1721818267799_1721818069416_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66a0dcb320bf0172211c01d8",
  "name": "externallmg_1721818272493_1721818069416_image_5.jpeg",
  "path": "cases/669f7ed0522e015687d410d8/
externallmg_1721818272493_1721818069416_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66a0dcb320bf0172211c01d9",
  "name": "externallmg_1721818276768_1721818069416_image_6.jpeg",
  "path": "cases/669f7ed0522e015687d410d8/
externallmg_1721818276768_1721818069416_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66a0dcb320bf0172211c01da",
  "name": "externallmg_1721818279845_1721818069416_image_7.jpeg",
  "path": "cases/669f7ed0522e015687d410d8/
externallmg_1721818279845_1721818069416_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66a0dcb320bf0172211c01db",
  "name": "externallmg_1721818279879_1721818069416_image_8.jpeg",
  "path": "cases/669f7ed0522e015687d410d8/
externallmg_1721818279879_1721818069416_image_8.jpeg",
  "orientation": "portrait"
},
{
```

```
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "66a0dcb320bf0172211c01dc",
"name": "externallmg_1721818280750_1721818069416_image_9.jpeg",
"path": "cases/669f7ed0522e015687d410d8/
externallmg_1721818280750_1721818069416_image_9.jpeg",
"orientation": "portrait"
},
{
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "66a0dcb320bf0172211c01dd",
"name": "externallmg_1721818281083_1721818069416_image_10.jpeg",
"path": "cases/669f7ed0522e015687d410d8/
externallmg_1721818281083_1721818069416_image_10.jpeg",
"orientation": "portrait"
},
{
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "66a0dcb320bf0172211c01de",
"name": "externallmg_1721818281518_1721818069416_image_11.jpeg",
"path": "cases/669f7ed0522e015687d410d8/
externallmg_1721818281518_1721818069416_image_11.jpeg",
"orientation": "portrait"
},
{
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "66a0dcb320bf0172211c01df",
"name": "externallmg_1721818281987_1721818069416_image_12.jpeg",
"path": "cases/669f7ed0522e015687d410d8/
externallmg_1721818281987_1721818069416_image_12.jpeg",
"orientation": "portrait"
},
{
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "66a0dcb320bf0172211c01e0",
"name": "externallmg_1721818282490_1721818069416_image_13.jpeg",
"path": "cases/669f7ed0522e015687d410d8/
externallmg_1721818282490_1721818069416_image_13.jpeg",
"orientation": "portrait"
},
{
"type": "MEASUREMENT_IMAGE",
```



```
"status": false,
  "_id": "66a0dcb320bf0172211c01e1",
  "name": "externallmg_1721818283549_1721818069416_image_14.jpeg",
  "path": "cases/669f7ed0522e015687d410d8/
externallmg_1721818283549_1721818069416_image_14.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66a0dcb320bf0172211c01e2",
  "name": "externallmg_1721818284222_1721818069416_image_15.jpeg",
  "path": "cases/669f7ed0522e015687d410d8/
externallmg_1721818284222_1721818069416_image_15.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66a0dcb320bf0172211c01e3",
  "name": "externallmg_1721818284844_1721818069416_image_16.jpeg",
  "path": "cases/669f7ed0522e015687d410d8/
externallmg_1721818284844_1721818069416_image_16.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66a0dcb320bf0172211c01e4",
  "name": "externallmg_1721818286430_1721818069416_image_17.jpeg",
  "path": "cases/669f7ed0522e015687d410d8/
externallmg_1721818286430_1721818069416_image_17.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66a0dcb320bf0172211c01e5",
  "name": "externallmg_1721818288099_1721818069416_image_18.jpeg",
  "path": "cases/669f7ed0522e015687d410d8/
externallmg_1721818288099_1721818069416_image_18.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
```

```

    "_id": "66a0dcb320bf0172211c01e6",
    "name": "externalImg_1721818289711_1721818069416_image_19.jpeg",
    "path": "cases/669f7ed0522e015687d410d8/
externalImg_1721818289711_1721818069416_image_19.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-07-23T09:58:40.961Z",
"updatedAt": "2024-07-24T10:51:31.615Z",
"__v": 0,
"uniqueNo": "",
"updatedBy": "62691c48afd7d55eddecfda3",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Office No. 101-102-103-104-105-106, 1st Floor,
KARISHMA CHAMBER, NEAR BOMBAY CAMBRIDGE SCHOOL, OFF SAHAR ROAD
J B NAGAR, ANDHERI EAST, Mumbai, 400069",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "M/s Landmark Vista Hotels & Resorts Pvt Ltd ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9879905200"
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			