

```
{
  "typeOfReport": {
    "label": "Land and Building",
    "value": "Land_and_Building"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856badb"
    },
    "firstName": "Akhilesh",
    "type": "CREDITOFFICER",
    "_id": "65cb37dad93fe4510d4dc357",
    "lastName": "Mishra",
    "mobileNo": "",
    "workMobileNo": "7045878520",
    "email": "abhishek.mishra1@unionbankofindia.bank"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "8500000",
    "discussWithPerson": "Akhilesh",
    "expectedFees": 4250,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856badb",
  "branchCode": "000033",
  "type": "BRANCH",
  "name": "Bhat Bazar Branch",
  "email": "ubin0531596@unionbankofindia.bank",
  "mobileNo": "02223752321",
  "alternateMobileNo": "",
  "address": "Anant Deep Chambers,273/277,Narshi Natha Street,Mumbai-400009",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f93be845132d6a6bdda676",
  "zoneName": "MUMBAI SOUTH"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "62727444afd7d55eddee092c",
"role": "PICKUPPERSON",
"firstName": "Shantilal",
"email": "shantilal@vastukala.org",
"lastName": "Patel",
"mobileNo": "9969039853",
"shortName": "SHP",
"workWithDocumentMaker": "",
"profilePhoto": "users/62727444afd7d55eddee092c/
profilePhoto_1668057663775_WhatsApp_Image_20221110_at_104853_AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "63fc4680ce84bf289ba9c7fc",
"role": "SITEENGINEER",
"firstName": "Nikhil ",
"email": "valtechnical2022@gmail.com",
"lastName": "Sonawane",
"mobileNo": "9819470709",
"designation": "",
"shortName": "NS",
"workWithDocumentMaker": "6006d4ce5080a310ac1fdcf2",
"profilePhoto": "users/63fc4680ce84bf289ba9c7fc/
profilePhoto_1720806809901_image.jpg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"maker": {
"type": "EMPLOYEE",
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
```

```
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"checker": {
"type": "EMPLOYEE",
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
}
],
{
```

```
"title": {
  "value": "FIIV",
  "label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.211898242404814",
  "longitude": "73.10382568550368"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.10382568550368,
    19.211898242404814
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "20/08/2024 01:05 pm"
    },
    {
      "dateTime": "20/08/2024 12:00 am"
    },
    {
      "dateTime": "20/08/2024 12:00 am"
    }
  ],
  "visitedDate": [],
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Asde Golivali",
    "label": true
  }
}
```

```
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Ground",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Dombivali",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
```

```
"key": "plotNo",
"value": "A 143",
"label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Dombivali Industrial Area Phase 1",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Off Kalyan Shilphata Road",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
}
```



```
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
```

```
"value": "",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
```

```
"status": true,
"name": "Postal Code",
"key": "postalCode",
"value": "421204",
"label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Dombivali east",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
}
```

```
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
}
```

```
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
```

```
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "0",
"selectedBuildUpValue": "0",
"selectedBuildUpMeasurementType": ""
},
"reportImages": {
"frontPageImages": [],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
"carpetRateRange": {
"min": "0.00",
"max": "0.00"
},
"builtUpRateRange": {
"min": "0.00",
"max": "0.00"
},
"saleableRateRange": {
"min": "0.00",
"max": "0.00"
}
},
"detailsOfValuation": {
"presentValueOfFlat": {
"title": "Present value of the flat (incl. car parking, if provided)",
"quantity": "0.00",
"ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
```



```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
```

```
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66c362eb0f117327db7239ed",
"ownerName": "Ms Bi Chem (India)Pvt Ltd (prabhat trading co)",
"ownerPhoneNo": "9892894067",
"appAddress": "A -143 \n1000 sq meters \nMIDC Dombivali \n",
"remark": "All Documents given \nvisit time \n\nurgent \n",
"documents": [
  {
    "documentType": {
      "label": "Any Other Document",
      "value": "60ae124aaa6d152c1801b2f7"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/66c362eb0f117327db7239ed/
document_1724080860792_1724080857684_Blchem_India_Pvt_Ltd_Pending.doc",
    "fileName":
"document_1724080860792_1724080857684_Blchem_India_Pvt_Ltd_Pending.doc",
    "id": "344291",
    "uploadedBy": "62727444afd7d55eddee092c",
    "createdAt": "Mon Aug 19 2024 20:51:14 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
```

```
    "label": "Agreement To Lease",
    "value": "60ae1278aa6d152c1801b3d1"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/66c362eb0f117327db7239ed/
document_1724135324326_1724135321947_Lease_Agreement_Bichem.pdf",
  "fileName":
"document_1724135324326_1724135321947_Lease_Agreement_Bichem.pdf",
  "id": "718051",
  "uploadedBy": "62727444afd7d55eddee092c",
  "createdAt": "Tue Aug 20 2024 11:58:56 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": "Full Occupancy Certificate",
    "value": "60ae127eaa6d152c1801b3ee"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/66c362eb0f117327db7239ed/document_1724135723047_17241355
50160_Bichem_Occupany_Certificate_prabhat_Trading.pdf",
  "fileName": "document_1724135723047_1724135550160_Bichem_Occupany_Certi
ficate_prabhat_Trading.pdf",
  "id": "801701",
  "uploadedBy": "62727444afd7d55eddee092c",
  "createdAt": "Tue Aug 20 2024 12:05:42 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1724139978558_Bichem__Dombivli_office_valuation_report
_held_in_25th_Nov_2023_1.pdf",
  "path": "cases/66c362eb0f117327db7239ed/document_1724139978558_Bichem__
Dombivli_office_valuation_report_held_in_25th_Nov_2023_1.pdf",
  "id": "608859",
  "uploadedBy": "6006d4ce5080a310ac1fdfc2",
  "createdAt": "Tue Aug 20 2024 13:17:00 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
```

```
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1724139993607_Agreement_Prabhat_Trading.pdf",
  "path": "cases/66c362eb0f117327db7239ed/
document_1724139993607_Agreement_Prabhat_Trading.pdf",
  "id": "901113",
  "uploadedBy": "6006d4ce5080a310ac1fd2",
  "createdAt": "Tue Aug 20 2024 13:17:00 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1724140006446_Certificate_of_Incorporation.pdf",
  "path": "cases/66c362eb0f117327db7239ed/
document_1724140006446_Certificate_of_Incorporation.pdf",
  "id": "204349",
  "uploadedBy": "6006d4ce5080a310ac1fd2",
  "createdAt": "Tue Aug 20 2024 13:17:00 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1724140018879_Lease_Agreement_Bichem.pdf",
  "path": "cases/66c362eb0f117327db7239ed/
document_1724140018879_Lease_Agreement_Bichem.pdf",
  "id": "227677",
  "uploadedBy": "6006d4ce5080a310ac1fd2",
  "createdAt": "Tue Aug 20 2024 13:17:00 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
```

```
"fileName": "document_1724155012976_Bichem_building_plan.pdf",
"path": "cases/66c362eb0f117327db7239ed/
document_1724155012976_Bichem_building_plan.pdf",
"id": "832404",
"uploadedBy": "6006d4ce5080a310ac1fd2",
"createdAt": "Tue Aug 20 2024 17:34:40 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1724155035532_Lease_Agreement_Bichem_1.pdf",
  "path": "cases/66c362eb0f117327db7239ed/
document_1724155035532_Lease_Agreement_Bichem_1.pdf",
  "id": "297285",
  "uploadedBy": "6006d4ce5080a310ac1fd2",
  "createdAt": "Tue Aug 20 2024 17:34:40 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1724155044547_A_V_Shetty__Valuation_Report_2.pdf",
  "path": "cases/66c362eb0f117327db7239ed/
document_1724155044547_A_V_Shetty__Valuation_Report_2.pdf",
  "id": "797172",
  "uploadedBy": "6006d4ce5080a310ac1fd2",
  "createdAt": "Tue Aug 20 2024 17:34:40 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1724155054380_Agreement_Prabhat_Trading.pdf",
  "path": "cases/66c362eb0f117327db7239ed/
document_1724155054380_Agreement_Prabhat_Trading.pdf",
  "id": "525914",
```

```
"uploadedBy": "6006d4ce5080a310ac1fdcf2",
"createdAt": "Tue Aug 20 2024 17:34:40 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1724155080534_Bichem__Dombivli_office_valuation_report_held_in_25th_Nov_2023_1_1.pdf",
  "path": "cases/66c362eb0f117327db7239ed/document_1724155080534_Bichem__Dombivli_office_valuation_report_held_in_25th_Nov_2023_1_1.pdf",
  "id": "560476",
  "uploadedBy": "6006d4ce5080a310ac1fdcf2",
  "createdAt": "Tue Aug 20 2024 17:34:40 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1724155095500_Bichem__Dombivli_office_valuation_report_held_in_25th_Nov_2023_1.pdf",
  "path": "cases/66c362eb0f117327db7239ed/document_1724155095500_Bichem__Dombivli_office_valuation_report_held_in_25th_Nov_2023_1.pdf",
  "id": "155754",
  "uploadedBy": "6006d4ce5080a310ac1fdcf2",
  "createdAt": "Tue Aug 20 2024 17:34:40 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1724155107824_Bichem__Dombivli_office_valuation_report_held_in_25th_Nov_2023_1.pdf",
  "path": "cases/66c362eb0f117327db7239ed/document_1724155107824_Bichem__Dombivli_office_valuation_report_held_in_25th_Nov_2023_1.pdf",
  "id": "172217",
  "uploadedBy": "6006d4ce5080a310ac1fdcf2",
```

```
"createdAt": "Tue Aug 20 2024 17:34:40 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName":
"document_1724155118986_Bichem_Occupany_Certificate_prabhat_Trading.pdf",
  "path": "cases/66c362eb0f117327db7239ed/
document_1724155118986_Bichem_Occupany_Certificate_prabhat_Trading.pdf",
  "id": "415565",
  "uploadedBy": "6006d4ce5080a310ac1fd2",
  "createdAt": "Tue Aug 20 2024 17:34:40 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName":
"document_1724155130574_Bichem_Occupany_Certificate_prabhat_Trading.pdf",
  "path": "cases/66c362eb0f117327db7239ed/
document_1724155130574_Bichem_Occupany_Certificate_prabhat_Trading.pdf",
  "id": "333763",
  "uploadedBy": "6006d4ce5080a310ac1fd2",
  "createdAt": "Tue Aug 20 2024 17:34:40 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1724155140805_Certificate_of_Incorporation.pdf",
  "path": "cases/66c362eb0f117327db7239ed/
document_1724155140805_Certificate_of_Incorporation.pdf",
  "id": "832339",
  "uploadedBy": "6006d4ce5080a310ac1fd2",
  "createdAt": "Tue Aug 20 2024 17:34:40 GMT+0530 (India Standard Time)"
},
}
```

```
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1724155150784_Electricity_Bill.pdf",
  "path": "cases/66c362eb0f117327db7239ed/
document_1724155150784_Electricity_Bill.pdf",
  "id": "963280",
  "uploadedBy": "6006d4ce5080a310ac1fdcf2",
  "createdAt": "Tue Aug 20 2024 17:34:40 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1724155161188_Lease_Agreement_Bichem.pdf",
  "path": "cases/66c362eb0f117327db7239ed/
document_1724155161188_Lease_Agreement_Bichem.pdf",
  "id": "295723",
  "uploadedBy": "6006d4ce5080a310ac1fdcf2",
  "createdAt": "Tue Aug 20 2024 17:34:40 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "010676",
"createdBy": "62727444afd7d55eddee092c",
"caseHistory": [
  {
    "id": "790646",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Aug 19 2024 20:51:15 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Ms Bi Chem (India)Pvt Ltd (prabhat trading co)",
    "phone": "9892894067",
    "ownershipShare": "",
    "email": "",
    "id": "228651"
  }
]
```



```
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66c59580c884d112334d45e7",
    "name": "externalImg_r_1724224891765_1724224890928_image_0.jpg",
    "path": "cases/66c362eb0f117327db7239ed/
externalImg_r_1724224891765_1724224890928_image_0.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c596dfc884d112334d4a0b",
    "name": "externalImg_1724225157365_1724225150701_image_0.png",
    "path": "cases/66c362eb0f117327db7239ed/
externalImg_1724225157365_1724225150701_image_0.png",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c596dfc884d112334d4a0c",
    "name": "externalImg_r_1724225173160_1724225150701_image_3.jpg",
    "path": "cases/66c362eb0f117327db7239ed/
externalImg_r_1724225173160_1724225150701_image_3.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c596dfc884d112334d4a0d",
    "name": "externalImg_r_1724225163419_1724225150701_image_1.jpg",
    "path": "cases/66c362eb0f117327db7239ed/
externalImg_r_1724225163419_1724225150701_image_1.jpg",
    "orientation": "portrait"
  }
]
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66c596dfc884d112334d4a0e",
  "name": "externallmg_r_1724225177561_1724225150701_image_4.jpg",
  "path": "cases/66c362eb0f117327db7239ed/
externallmg_r_1724225177561_1724225150701_image_4.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66c596dfc884d112334d4a0f",
  "name": "externallmg_r_1724225168160_1724225150701_image_2.jpg",
  "path": "cases/66c362eb0f117327db7239ed/
externallmg_r_1724225168160_1724225150701_image_2.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66c596dfc884d112334d4a10",
  "name": "externallmg_r_1724225180605_1724225150701_image_5.jpg",
  "path": "cases/66c362eb0f117327db7239ed/
externallmg_r_1724225180605_1724225150701_image_5.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66c596dfc884d112334d4a11",
  "name": "externallmg_r_1724225183950_1724225150701_image_6.jpg",
  "path": "cases/66c362eb0f117327db7239ed/
externallmg_r_1724225183950_1724225150701_image_6.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66c596dfc884d112334d4a12",
  "name": "externallmg_r_1724225187390_1724225150701_image_7.jpg",
  "path": "cases/66c362eb0f117327db7239ed/
externallmg_r_1724225187390_1724225150701_image_7.jpg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66c596dfc884d112334d4a13",
  "name": "externallmg_r_1724225193965_1724225150701_image_8.jpg",
  "path": "cases/66c362eb0f117327db7239ed/
externallmg_r_1724225193965_1724225150701_image_8.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66c596dfc884d112334d4a14",
  "name": "externallmg_r_1724225198055_1724225150701_image_9.jpg",
  "path": "cases/66c362eb0f117327db7239ed/
externallmg_r_1724225198055_1724225150701_image_9.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66c596dfc884d112334d4a15",
  "name": "externallmg_r_1724225211290_1724225150701_image_11.jpg",
  "path": "cases/66c362eb0f117327db7239ed/
externallmg_r_1724225211290_1724225150701_image_11.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66c596dfc884d112334d4a16",
  "name": "externallmg_r_1724225214264_1724225150701_image_12.jpg",
  "path": "cases/66c362eb0f117327db7239ed/
externallmg_r_1724225214264_1724225150701_image_12.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66c596dfc884d112334d4a17",
  "name": "externallmg_r_1724225204940_1724225150701_image_10.jpg",
  "path": "cases/66c362eb0f117327db7239ed/
externallmg_r_1724225204940_1724225150701_image_10.jpg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c596dfc884d112334d4a18",
    "name": "externallmg_r_1724225219589_1724225150701_image_13.jpg",
    "path": "cases/66c362eb0f117327db7239ed/
externallmg_r_1724225219589_1724225150701_image_13.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c596dfc884d112334d4a19",
    "name": "externallmg_r_1724225224709_1724225150701_image_14.jpg",
    "path": "cases/66c362eb0f117327db7239ed/
externallmg_r_1724225224709_1724225150701_image_14.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c596dfc884d112334d4a1a",
    "name": "externallmg_r_1724225232280_1724225150701_image_16.jpg",
    "path": "cases/66c362eb0f117327db7239ed/
externallmg_r_1724225232280_1724225150701_image_16.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c596dfc884d112334d4a1b",
    "name": "externallmg_r_1724225228979_1724225150701_image_15.jpg",
    "path": "cases/66c362eb0f117327db7239ed/
externallmg_r_1724225228979_1724225150701_image_15.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c596dfc884d112334d4a1c",
    "name": "externallmg_r_1724225235015_1724225150701_image_17.jpg",
    "path": "cases/66c362eb0f117327db7239ed/
externallmg_r_1724225235015_1724225150701_image_17.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "66c596dfc884d112334d4a1d",
    "name": "externalimg_r_1724225238320_1724225150701_image_18.jpg",
    "path": "cases/66c362eb0f117327db7239ed/
externalimg_r_1724225238320_1724225150701_image_18.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c596dfc884d112334d4a1e",
    "name": "externalimg_r_1724225241766_1724225150701_image_19.jpg",
    "path": "cases/66c362eb0f117327db7239ed/
externalimg_r_1724225241766_1724225150701_image_19.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c59740da840b1214ca53f3",
    "name": "externalimg_r_1724225287854_1724225276963_image_2.jpg",
    "path": "cases/66c362eb0f117327db7239ed/
externalimg_r_1724225287854_1724225276963_image_2.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c59740da840b1214ca53f4",
    "name": "externalimg_r_1724225289380_1724225276963_image_3.jpg",
    "path": "cases/66c362eb0f117327db7239ed/
externalimg_r_1724225289380_1724225276963_image_3.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c59740da840b1214ca53f5",
    "name": "externalimg_r_1724225281389_1724225276963_image_0.jpg",
    "path": "cases/66c362eb0f117327db7239ed/
externalimg_r_1724225281389_1724225276963_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "66c59740da840b1214ca53f6",
    "name": "externallmg_r_1724225285080_1724225276963_image_1.jpg",
    "path": "cases/66c362eb0f117327db7239ed/
externallmg_r_1724225285080_1724225276963_image_1.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c59740da840b1214ca53f7",
    "name": "externallmg_r_1724225292234_1724225276963_image_4.jpg",
    "path": "cases/66c362eb0f117327db7239ed/
externallmg_r_1724225292234_1724225276963_image_4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c59740da840b1214ca53f8",
    "name": "externallmg_r_1724225299270_1724225276963_image_6.jpg",
    "path": "cases/66c362eb0f117327db7239ed/
externallmg_r_1724225299270_1724225276963_image_6.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c59740da840b1214ca53f9",
    "name": "externallmg_r_1724225302144_1724225276963_image_7.jpg",
    "path": "cases/66c362eb0f117327db7239ed/
externallmg_r_1724225302144_1724225276963_image_7.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c59740da840b1214ca53fa",
    "name": "externallmg_r_1724225295534_1724225276963_image_5.jpg",
    "path": "cases/66c362eb0f117327db7239ed/
externallmg_r_1724225295534_1724225276963_image_5.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c59740da840b1214ca53fb",
```

```
    "name": "externalImg_r_1724225312900_1724225276963_image_9.jpg",
    "path": "cases/66c362eb0f117327db7239ed/
externalImg_r_1724225312900_1724225276963_image_9.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c59740da840b1214ca53fc",
    "name": "externalImg_r_1724225316710_1724225276963_image_10.jpg",
    "path": "cases/66c362eb0f117327db7239ed/
externalImg_r_1724225316710_1724225276963_image_10.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c59740da840b1214ca53fd",
    "name": "externalImg_r_1724225320805_1724225276963_image_11.jpg",
    "path": "cases/66c362eb0f117327db7239ed/
externalImg_r_1724225320805_1724225276963_image_11.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c59740da840b1214ca53fe",
    "name": "externalImg_r_1724225305504_1724225276963_image_8.jpg",
    "path": "cases/66c362eb0f117327db7239ed/
externalImg_r_1724225305504_1724225276963_image_8.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c59740da840b1214ca53ff",
    "name": "externalImg_r_1724225329120_1724225276963_image_12.jpg",
    "path": "cases/66c362eb0f117327db7239ed/
externalImg_r_1724225329120_1724225276963_image_12.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
```

```

"remarks": [],
"createdAt": "2024-08-19T15:21:15.034Z",
"updatedAt": "2024-08-21T07:29:04.137Z",
"__v": 0,
"uniqueNo": "",
"updatedBy": "63fc4680ce84bf289ba9c7fc",
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"fullAddress": "Residential Land and Building No. Ground Floor, Plot No. A 143,
Dombivali Industrial Area Phase 1, Off Kalyan Shilphata Road, Village - Asde Golivali,
Dombivali east, Dombivali, 421204, State - Maharashtra, India",
"addressForMap": "",
"caseReferredBy": "62727444afd7d55eddee092c",
"contactPersonName": "Ms Bi Chem (India)Pvt Ltd (prabhat trading co)",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9892894067"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			