## SLUM REHABILITATION AUTHORITY

No.SRA/Eng/ MC/サ3/Sロコノキュノロー V Floor, Griha Nirman Bhavan, Bandra (East), Mumbai 400 051.

Date :

L 6 JUL 1999.

To,

Shri Madhav R. Parpudi Architect 19/301, Miranda Bldg., N.C.Kelkar Road, Dadar, Mumbai-400 028.

Sub: Occupation Certificate for Rehab. Bldg. 'B' under SRD on plot bearing CS No.2/158, Lower Parel Division at Sitaram Jadhav Marg, Lower Parel, G/South Ward.

Ref: Your letter dtd. 2nd July 1999.

Sir,

With reference to the above, the BCC submitted by you, I have to inform you that the same is rejected for the following reasons.

- Site is not cleared, debris/ building material is not removed.
- Work is not completed in all respects.
- Some of the IOD conditions are not complied with.
- Some of the LOI conditions are not yet complied with.
- Final canvas plan is not submitted.

Yours faithfully,

Executive Engineer (SRA)IV

Eng4/raj/sept99/occparpudi/1

CERTIFIED THUE COPY

(MADHAY PARPUDI)

REG. NO. CA/77/3418