

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "646869f246e69b7878e9c07a"
    },
    "firstName": "Mr. Satish",
    "type": "CREDITOFFICER",
    "_id": "646869f246e69b7878e9c07c",
    "lastName": "Sir",
    "mobileNo": "",
    "workMobileNo": "9769699931",
    "email": "satish.sambare@siemens.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "646867a446e69b7878e9b892",
  "type": "INSTITUTION",
  "name": "Siemens Financial Services Private Limited",
  "displayName": "",
  "initial": "SFS"
},
"branch": {
  "_id": "646869f246e69b7878e9c07a",
  "name": "SFS COF E RU-IN RM AM",
  "branchCode": "",
  "mobileNo": "9769699930",
  "alternateMobileNo": "",
  "email": "satish.sambare@siemens.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Thane Belapur Road\n400708 Thane, India"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "6468691f46e69b7878e9be2e",
  "zoneName": "Pan India"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "656aa949cebbe1714411d21b",
    "role": "FRONTDESK",
```

```
"firstName": "Priyanka",
"email": "thane@vastukala.org",
"lastName": "Pawar",
"mobileNo": "8928414480",
"shortName": "PCP",
"workWithDocumentMaker": "627222afafd7d55eddeddd82"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62720b21afd7d55eddeddc545",
  "role": "MAKER+CHECKER",
  "firstName": "Avinash",
  "email": "avinash.pandey@vastukala.org",
  "lastName": "Pandey",
  "mobileNo": "9021605621",
  "designation": "",
  "shortName": "AV",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64dc7184ccaf1e7b7f637f47",
  "role": "FRONTDESK",
  "firstName": "Binumon",
  "email": "binu@vastukala.org",
  "lastName": "Moozhickal",
  "mobileNo": "9930252906",
  "designation": "Back Office Team Leader",
  "shortName": "BS",
  "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
  "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"maker": null,
"checker": null,
"valuers": []
},
"clientType": {
  "value": "INSTITUTION",
  "label": "INSTITUTION"
},
"location": {
  "latitude": "17.39951408387849",
  "longitude": "78.45371164853178"
},
"geo": {
```

```
"type": "Point",
"coordinates": [
  0,
  0
]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
    "value": "",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "3",
```

```
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Hyderabad",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
```

```
"name": "Building Name",
"key": "buildingName",
"value": "Siena Grand ",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Telangana",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Shantinagar, Mallepally",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
}
```

```
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "302",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
```

```
"key": "municipalityWardNo",
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "500 057",
  "label": false
},
}
```



```
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
```

```
"routeLat": "",
"routeLng": "",
"stationName": "",
"routeDistance": ""
},
"finalLatLng": {
  "coordinates": []
},
"locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```

```
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
```

```
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66dfeebd82c5810dfb19f692",
"ownerName": "Sri. Nalla Narayana Rao & S/o. Late Nalla Jagannadham",
"ownerPhoneNo": "0000000000",
"fullAddress": "Residential Flat No. 302, 3rd Floor, Siena Grand , Shantinagar,
Mallepally, Telangana, District - Hyderabad, 500 057",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae1245aa6d152c1801b2e3",
      "label": "Sale Deed"
    },
    "inputs": {
      "documentDate": "20/09/2021",
      "from": {
        "value": "Vendor",
        "label": "Vendor"
      },
      "Vendor": "Smt. A. Uma Rani & Sri. D. Mahender Rao",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      },
      "purchaser": "Sri. Nalla Narayana Rao & S/o. Late Nalla Jagannadham",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "0000"
```



```
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1725951620496_MAIN_PROPERTY_DOCUMENT.pdf",
    "path": "cases/66dfeebd82c5810dfb19f692/
document_1725951620496_MAIN_PROPERTY_DOCUMENT.pdf",
    "id": "548711",
    "uploadedBy": "656aa949cebbe1714411d21b",
    "createdAt": "Tue Sep 10 2024 12:31:17 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "inputs": {
      "number": {
        "value": "Document_No",
        "label": "Document No"
      }
    }
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1725951635754_link_document_JUNE19654.pdf",
  "path": "cases/66dfeebd82c5810dfb19f692/
document_1725951635754_link_document_JUNE19654.pdf",
  "id": "969654",
  "uploadedBy": "656aa949cebbe1714411d21b",
  "createdAt": "Tue Sep 10 2024 12:31:17 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1725951647552_link_DOCUMENT_JUNE20082.pdf",
  "path": "cases/66dfeebd82c5810dfb19f692/
document_1725951647552_link_DOCUMENT_JUNE20082.pdf",
  "id": "425163",
  "uploadedBy": "656aa949cebbe1714411d21b",
  "createdAt": "Tue Sep 10 2024 12:31:17 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
```

```
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1725951660972_LINK_DOUCMENT1.pdf",
  "path": "cases/66dfeebd82c5810dfb19f692/
document_1725951660972_LINK_DOUCMENT1.pdf",
  "id": "562076",
  "uploadedBy": "656aa949cebbe1714411d21b",
  "createdAt": "Tue Sep 10 2024 12:31:17 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1725951671149_link_document_3.pdf",
  "path": "cases/66dfeebd82c5810dfb19f692/
document_1725951671149_link_document_3.pdf",
  "id": "318930",
  "uploadedBy": "656aa949cebbe1714411d21b",
  "createdAt": "Tue Sep 10 2024 12:31:17 GMT+0530 (India Standard Time)"
}
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "011118",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
  {
    "id": "277335",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Sep 10 2024 12:31:17 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Sri. Nalla Narayana Rao & S/o. Late Nalla Jagannadham",
    "phone": "0000000000",
    "ownershipShare": ""
  }
]
```

```
    "email": "",
    "id": "252853"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e13d2654df030e57a49e96",
    "name":
"externalImg_1726037285831_WhatsApp_Image_20240911_at_120407_PM_1.jpeg",
    "path": "cases/66dfeebd82c5810dfb19f692/
externalImg_1726037285831_WhatsApp_Image_20240911_at_120407_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e13d2654df030e57a49e97",
    "name":
"externalImg_1726037285846_WhatsApp_Image_20240911_at_120407_PM.jpeg",
    "path": "cases/66dfeebd82c5810dfb19f692/
externalImg_1726037285846_WhatsApp_Image_20240911_at_120407_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e13d2654df030e57a49e98",
    "name":
"externalImg_1726037285857_WhatsApp_Image_20240911_at_120408_PM_1.jpeg",
    "path": "cases/66dfeebd82c5810dfb19f692/
externalImg_1726037285857_WhatsApp_Image_20240911_at_120408_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "66e13d2654df030e57a49e99",
    "name":
"externallmg_1726037285863_WhatsApp_Image_20240911_at_120408_PM_2.jpeg",
    "path": "cases/66dfeebd82c5810dfb19f692/
externallmg_1726037285863_WhatsApp_Image_20240911_at_120408_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e13d2654df030e57a49e9a",
    "name":
"externallmg_1726037285873_WhatsApp_Image_20240911_at_120408_PM.jpeg",
    "path": "cases/66dfeebd82c5810dfb19f692/
externallmg_1726037285873_WhatsApp_Image_20240911_at_120408_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e13d2654df030e57a49e9b",
    "name":
"externallmg_1726037285886_WhatsApp_Image_20240911_at_120409_PM_1.jpeg",
    "path": "cases/66dfeebd82c5810dfb19f692/
externallmg_1726037285886_WhatsApp_Image_20240911_at_120409_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e13d2654df030e57a49e9c",
    "name":
"externallmg_1726037285890_WhatsApp_Image_20240911_at_120409_PM_2.jpeg",
    "path": "cases/66dfeebd82c5810dfb19f692/
externallmg_1726037285890_WhatsApp_Image_20240911_at_120409_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e13d2654df030e57a49e9d",
    "name":
"externallmg_1726037285897_WhatsApp_Image_20240911_at_120409_PM.jpeg",
    "path": "cases/66dfeebd82c5810dfb19f692/
externallmg_1726037285897_WhatsApp_Image_20240911_at_120409_PM.jpeg",
    "orientation": "portrait"
  }
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66e13d2654df030e57a49e9e",
  "name":
"externallmg_1726037285900_WhatsApp_Image_20240911_at_120410_PM_1.jpeg",
  "path": "cases/66dfeebd82c5810dfb19f692/
externallmg_1726037285900_WhatsApp_Image_20240911_at_120410_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66e13d2654df030e57a49e9f",
  "name":
"externallmg_1726037285909_WhatsApp_Image_20240911_at_120410_PM_2.jpeg",
  "path": "cases/66dfeebd82c5810dfb19f692/
externallmg_1726037285909_WhatsApp_Image_20240911_at_120410_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66e13d2654df030e57a49ea0",
  "name":
"externallmg_1726037285915_WhatsApp_Image_20240911_at_120410_PM.jpeg",
  "path": "cases/66dfeebd82c5810dfb19f692/
externallmg_1726037285915_WhatsApp_Image_20240911_at_120410_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66e13d2654df030e57a49ea1",
  "name":
"externallmg_1726037285923_WhatsApp_Image_20240911_at_120411_PM_1.jpeg",
  "path": "cases/66dfeebd82c5810dfb19f692/
externallmg_1726037285923_WhatsApp_Image_20240911_at_120411_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66e13d2654df030e57a49ea2",
  "name":
"externallmg_1726037285929_WhatsApp_Image_20240911_at_120411_PM_2.jpeg",
```

```
    "path": "cases/66dfeebd82c5810dfb19f692/
externallmg_1726037285929_WhatsApp_Image_20240911_at_120411_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e13d2654df030e57a49ea3",
    "name":
"externallmg_1726037285936_WhatsApp_Image_20240911_at_120411_PM.jpeg",
    "path": "cases/66dfeebd82c5810dfb19f692/
externallmg_1726037285936_WhatsApp_Image_20240911_at_120411_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e13d2654df030e57a49ea4",
    "name":
"externallmg_1726037285941_WhatsApp_Image_20240911_at_120412_PM_1.jpeg",
    "path": "cases/66dfeebd82c5810dfb19f692/
externallmg_1726037285941_WhatsApp_Image_20240911_at_120412_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e13d2654df030e57a49ea5",
    "name":
"externallmg_1726037285948_WhatsApp_Image_20240911_at_120412_PM_2.jpeg",
    "path": "cases/66dfeebd82c5810dfb19f692/
externallmg_1726037285948_WhatsApp_Image_20240911_at_120412_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e13d2654df030e57a49ea6",
    "name":
"externallmg_1726037285954_WhatsApp_Image_20240911_at_120412_PM_3.jpeg",
    "path": "cases/66dfeebd82c5810dfb19f692/
externallmg_1726037285954_WhatsApp_Image_20240911_at_120412_PM_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "66e13d2654df030e57a49ea7",
  "name":
"externalImg_1726037285963_WhatsApp_Image_20240911_at_120412_PM.jpeg",
  "path": "cases/66dfeebd82c5810dfb19f692/
externalImg_1726037285963_WhatsApp_Image_20240911_at_120412_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66e13d2654df030e57a49ea8",
  "name":
"externalImg_1726037285987_WhatsApp_Image_20240911_at_120413_PM_1.jpeg",
  "path": "cases/66dfeebd82c5810dfb19f692/
externalImg_1726037285987_WhatsApp_Image_20240911_at_120413_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66e13d2654df030e57a49ea9",
  "name":
"externalImg_1726037286004_WhatsApp_Image_20240911_at_120413_PM.jpeg",
  "path": "cases/66dfeebd82c5810dfb19f692/
externalImg_1726037286004_WhatsApp_Image_20240911_at_120413_PM.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-09-10T07:01:17.115Z",
"updatedAt": "2024-09-11T06:48:06.068Z",
"__v": 0,
"updatedBy": "656aa949cebbe1714411d21b",
"addressForMap": "",
"caseReferredBy": "62720b21afd7d55eddedc545",
"contactPersonName": "Sri. Nalla Narayana Rao & S/o. Late Nalla Jagannadham",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": ""
```

"purchaseValueAsPerDocument": "",  
"relationWithOwner": "self",  
"siteVisitContactNo": "0000000000"

}

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			