

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "66ee8bd1ada7094de494702e"
    },
    "firstName": "Saumya",
    "type": "CREDITOFFICER",
    "_id": "66ee8bf5364a0f4dac139a2c",
    "email": "ubin0813915@unionbankofindia.bank",
    "lastName": "Raj",
    "mobileNo": "",
    "workMobileNo": "9891938461"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "66ee8bd1ada7094de494702e",
  "name": "Seawoods Sector 42 West Branch",
  "branchCode": "",
  "mobileNo": "02227719157",
  "alternateMobileNo": "",
  "email": "ubin0813915@unionbankofindia.bank",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Shelter Arcade, First Floor, Opp D mart, Seawoods Sector 42\nNavi
Mumbai 400706"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f93be845132d6a6bdda676",
  "zoneName": "MUMBAI SOUTH"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60b7189d2ffdf65bcd65882b",
```

```
"role": "PICKUPPERSON",
"firstName": "Ravindra",
"email": "ravindrakasare186@gmail.com",
"lastName": "Kasare",
"mobileNo": "9167204055",
"shortName": "RBK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60b7189d2ffdf65bcd65882b\
\profilePhoto_1622701555488_WhatsApp Image 2021-06-03 at 11.46.40 AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "60f9343b45132d6a6bdd96e8",
"role": "SITEENGINEER",
"firstName": "Rajesh",
"email": "rajeshb.ghadi@gmail.com",
"lastName": "Ghadi",
"mobileNo": "8652092666",
"designation": "",
"shortName": "RHG",
"workWithDocumentMaker": ""
},
"rateVerifier": null,
"maker": null,
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
},
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
}
},
}
```

```
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.043382562309027",
  "longitude": "73.01519089745486"
},
"geo": {
```

```
"type": "Point",
"coordinates": [
  73.01519089745486,
  19.043382562309027
]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "21/09/2024 04:59 pm"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Nerul",
    "label": true
  },
  "floorNo": {
```

```
"status": true,
"name": "Floor No",
"key": "floorNo",
"value": "2",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Navi Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "B 38",
```

```
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Thakur Paradise CHSL",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "20",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
```

```
"name": "Project Name",
"key": "projectName",
"value": "",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "204",
  "label": false
}
```



```
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
```

```
"key": "postalCode",
"value": "400706",
"label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
```

```
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```

```
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
```



```
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Approximate Rate Lead",
  "value": "APPROXIMATE_LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66ee956f364a0f4dac13a8ca",
"ownerName": "Abdul Rehman Usman Shaikh & Masooda Abdul Rehman Shaikh",
"ownerPhoneNo": "9820818365",
"appAddress": "flat no 204 2 nd floor plot no 38 /1 thakur paradise co.op Hsg Ltd
sector no 20 Nerul ",
"remark": "bankar chandan kumar sir suryakant sonnada",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/66ee956f364a0f4dac13a8ca/document_1726911731364_172691131
9790_Abdul_Shaikh_Union_Bank_seawoods.pdf",
    "fileName": "document_1726911731364_1726911319790_Abdul_Shaikh_Union_Ba
nk_seawoods.pdf",
    "id": "684219",
    "uploadedBy": "60b7189d2ffdf65bcd65882b",
    "createdAt": "Sat Sep 21 2024 15:14:15 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "011379",
"createdBy": "60b7189d2ffdf65bcd65882b",
```

```
"caseHistory": [
  {
    "id": "586435",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Sep 21 2024 15:14:15 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Abdul Rehman Usman Shaikh & Masooda Abdul Rehman Shaikh",
    "phone": "9820818365",
    "ownershipShare": "",
    "email": "",
    "id": "817769"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f23aa1ba8a41d153afab3e",
    "name": "externalImg_1727150753771_IMG_20240924_084110.jpg",
    "path": "cases/66ee956f364a0f4dac13a8ca/
externalImg_1727150753771_IMG_20240924_084110.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f23aa1ba8a41d153afab3f",
    "name": "externalImg_1727150753780_IMG_20240924_084117.jpg",
    "path": "cases/66ee956f364a0f4dac13a8ca/
externalImg_1727150753780_IMG_20240924_084117.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "66f23aa1ba8a41d153afab40",
  "name": "externallmg_1727150753783_IMG_20240924_084115.jpg",
  "path": "cases/66ee956f364a0f4dac13a8ca/
externallmg_1727150753783_IMG_20240924_084115.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f23aa1ba8a41d153afab41",
  "name": "externallmg_1727150753792_IMG_20240923_182547.jpg",
  "path": "cases/66ee956f364a0f4dac13a8ca/
externallmg_1727150753792_IMG_20240923_182547.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f23aa1ba8a41d153afab42",
  "name": "externallmg_1727150753797_Screenshot_20240924_084053.jpg",
  "path": "cases/66ee956f364a0f4dac13a8ca/
externallmg_1727150753797_Screenshot_20240924_084053.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f23b10ba8a41d153afab92",
  "name": "externallmg_1727150863979_IMG_20240923_202853.jpg",
  "path": "cases/66ee956f364a0f4dac13a8ca/
externallmg_1727150863979_IMG_20240923_202853.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f23b10ba8a41d153afab93",
  "name": "externallmg_1727150863983_IMG_20240923_182543.jpg",
  "path": "cases/66ee956f364a0f4dac13a8ca/
externallmg_1727150863983_IMG_20240923_182543.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "66f23b10ba8a41d153afab94",
    "name": "externallmg_1727150863991_IMG_20240923_181735.jpg",
    "path": "cases/66ee956f364a0f4dac13a8ca/
externallmg_1727150863991_IMG_20240923_181735.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f23b10ba8a41d153afab95",
    "name": "externallmg_1727150863998_Screenshot_20240923_183948.jpg",
    "path": "cases/66ee956f364a0f4dac13a8ca/
externallmg_1727150863998_Screenshot_20240923_183948.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f23b10ba8a41d153afab96",
    "name": "externallmg_r_1727150864009_TimePhoto_20240923_181703.jpg",
    "path": "cases/66ee956f364a0f4dac13a8ca/
externallmg_r_1727150864009_TimePhoto_20240923_181703.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f23b10ba8a41d153afab97",
    "name": "externallmg_r_1727150864011_TimePhoto_20240923_181710.jpg",
    "path": "cases/66ee956f364a0f4dac13a8ca/
externallmg_r_1727150864011_TimePhoto_20240923_181710.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f23b10ba8a41d153afab98",
    "name": "externallmg_r_1727150864010_TimePhoto_20240923_181704.jpg",
    "path": "cases/66ee956f364a0f4dac13a8ca/
externallmg_r_1727150864010_TimePhoto_20240923_181704.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f23b10ba8a41d153afab99",
```

```
    "name": "externallmg_r_1727150864008_TimePhoto_20240923_181657.jpg",
    "path": "cases/66ee956f364a0f4dac13a8ca/
externallmg_r_1727150864008_TimePhoto_20240923_181657.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f23b10ba8a41d153afab9a",
    "name": "externallmg_r_1727150864012_TimePhoto_20240923_181843.jpg",
    "path": "cases/66ee956f364a0f4dac13a8ca/
externallmg_r_1727150864012_TimePhoto_20240923_181843.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f23b10ba8a41d153afab9b",
    "name": "externallmg_r_1727150864011_TimePhoto_20240923_181816.jpg",
    "path": "cases/66ee956f364a0f4dac13a8ca/
externallmg_r_1727150864011_TimePhoto_20240923_181816.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f23b1d2d094ed13709ef68",
    "name": "externallmg_r_1727150877068_TimePhoto_20240923_182243.jpg",
    "path": "cases/66ee956f364a0f4dac13a8ca/
externallmg_r_1727150877068_TimePhoto_20240923_182243.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f23b1d2d094ed13709ef69",
    "name": "externallmg_r_1727150877069_TimePhoto_20240923_182246.jpg",
    "path": "cases/66ee956f364a0f4dac13a8ca/
externallmg_r_1727150877069_TimePhoto_20240923_182246.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f23b1d2d094ed13709ef6a",
    "name": "externallmg_r_1727150877069_TimePhoto_20240923_182247.jpg",
```

```
    "path": "cases/66ee956f364a0f4dac13a8ca/
externallmg_r_1727150877069_TimePhoto_20240923_182247.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f23b1d2d094ed13709ef6b",
    "name": "externallmg_r_1727150877068_TimePhoto_20240923_182244.jpg",
    "path": "cases/66ee956f364a0f4dac13a8ca/
externallmg_r_1727150877068_TimePhoto_20240923_182244.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f23b1d2d094ed13709ef6c",
    "name": "externallmg_r_1727150877070_TimePhoto_20240923_182251.jpg",
    "path": "cases/66ee956f364a0f4dac13a8ca/
externallmg_r_1727150877070_TimePhoto_20240923_182251.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f23b1d2d094ed13709ef6d",
    "name": "externallmg_r_1727150877071_TimePhoto_20240923_182252.jpg",
    "path": "cases/66ee956f364a0f4dac13a8ca/
externallmg_r_1727150877071_TimePhoto_20240923_182252.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f23b1d2d094ed13709ef6e",
    "name": "externallmg_r_1727150877072_TimePhoto_20240923_182304.jpg",
    "path": "cases/66ee956f364a0f4dac13a8ca/
externallmg_r_1727150877072_TimePhoto_20240923_182304.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f23b1d2d094ed13709ef6f",
    "name": "externallmg_r_1727150877070_TimePhoto_20240923_182250.jpg",
    "path": "cases/66ee956f364a0f4dac13a8ca/
externallmg_r_1727150877070_TimePhoto_20240923_182250.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f23b1d2d094ed13709ef70",
  "name": "externallmg_r_1727150877073_TimePhoto_20240923_182305.jpg",
  "path": "cases/66ee956f364a0f4dac13a8ca/
externallmg_r_1727150877073_TimePhoto_20240923_182305.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f23b1d2d094ed13709ef71",
  "name": "externallmg_r_1727150877073_TimePhoto_20240923_182306.jpg",
  "path": "cases/66ee956f364a0f4dac13a8ca/
externallmg_r_1727150877073_TimePhoto_20240923_182306.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f23b1d2d094ed13709ef72",
  "name": "externallmg_r_1727150877074_TimePhoto_20240923_182307.jpg",
  "path": "cases/66ee956f364a0f4dac13a8ca/
externallmg_r_1727150877074_TimePhoto_20240923_182307.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f23b1d2d094ed13709ef73",
  "name": "externallmg_r_1727150877074_TimePhoto_20240923_182506.jpg",
  "path": "cases/66ee956f364a0f4dac13a8ca/
externallmg_r_1727150877074_TimePhoto_20240923_182506.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f23b1d2d094ed13709ef74",
  "name": "externallmg_r_1727150877075_TimePhoto_20240923_182831.jpg",
  "path": "cases/66ee956f364a0f4dac13a8ca/
externallmg_r_1727150877075_TimePhoto_20240923_182831.jpg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66f23b1d2d094ed13709ef75",
      "name": "externallmg_r_1727150877077_TimePhoto_20240923_182832.jpg",
      "path": "cases/66ee956f364a0f4dac13a8ca/
externallmg_r_1727150877077_TimePhoto_20240923_182832.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66f23b1d2d094ed13709ef76",
      "name": "externallmg_r_1727150877080_TimePhoto_20240923_182833.jpg",
      "path": "cases/66ee956f364a0f4dac13a8ca/
externallmg_r_1727150877080_TimePhoto_20240923_182833.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66f23b1d2d094ed13709ef77",
      "name": "externallmg_r_1727150877081_TimePhoto_20240923_182834.jpg",
      "path": "cases/66ee956f364a0f4dac13a8ca/
externallmg_r_1727150877081_TimePhoto_20240923_182834.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66f23b1d2d094ed13709ef78",
      "name": "externallmg_r_1727150877082_TimePhoto_20240923_182847.jpg",
      "path": "cases/66ee956f364a0f4dac13a8ca/
externallmg_r_1727150877082_TimePhoto_20240923_182847.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66f23b1d2d094ed13709ef79",
      "name": "externallmg_r_1727150877082_TimePhoto_20240923_182848.jpg",
      "path": "cases/66ee956f364a0f4dac13a8ca/
externallmg_r_1727150877082_TimePhoto_20240923_182848.jpg",
      "orientation": "portrait"
    }
  }
```



```
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "60f915d3f3dd69653a592199",
      "role": "MAKER + RATE VERIFIER + CHEAKER",
      "firstName": "Shobha",
      "lastName": "Kuperkar",
      "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "66eea12bada7094de4949359",
    "note": "80 Lakh approx.",
    "taskId": "66ee9570ada7094de4947feb",
    "createdAt": "2024-09-21T10:34:19.358Z"
  }
],
"createdAt": "2024-09-21T09:44:15.791Z",
"updatedAt": "2024-09-24T04:07:57.202Z",
"__v": 0,
"updatedBy": "6006d4ce5080a310ac1fdfc2",
"uniqueNo": "",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 204, 2nd Floor, Thakur Paradise CHSL, Plot No. B
38, Sector 20, Village - Nerul, Navi Mumbai, 400706",
"addressForMap": "",
"caseReferredBy": "60b7189d2ffdf65bcd65882b",
"contactPersonName": "Abdul Rehman Usman Shaikh & Masooda Abdul Rehman
Shaikh",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
```

"siteVisitContactNo": "9820818365"

}

Name	Length	Width	Total
-------------	---------------	--------------	--------------

Composition :

Other

Composition :
