

```
{
  "typeOfReport": {
    "label": "Row House",
    "value": "Row_House"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63b666c8191f7b344b00e421"
    },
    "firstName": "Bijendra ",
    "type": "CREDITOFFICER",
    "_id": "6544a09d99e3743444bdf144",
    "lastName": "Chauhan",
    "mobileNo": "",
    "workMobileNo": "7906367297",
    "email": "rbc.cbdbelapur@bankofindia.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "110000000",
    "discussWithPerson": "Bijendra ",
    "expectedFees": 55000,
    "quotedAmount": "10000"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180a",
  "type": "BANK",
  "name": "Bank of India",
  "displayName": "Bank of India",
  "initial": "BOI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63b666c8191f7b344b00e421",
  "name": "RBC Belapur",
  "branchCode": "",
  "mobileNo": "2227570151",
  "alternateMobileNo": "",
  "email": "rbc.cbdbelapur@bankofindia.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Bank Of India RBC Cbd Belapur, Bank Of India Building Ground Floor ,
Sector 11, Plot no 11 C B D Belapur, Navi Mumbai - 400614\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e2f4b16576061dae469446",
  "zoneName": "Navi Mumbai Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
  "_id": "60af3d172ffdf65bcd6585cd",
  "role": "PICKUPPERSON",
  "firstName": "Sachin",
  "email": "sachin.joshi@vastukala.org",
  "lastName": "Joshi",
  "mobileNo": "9167204063",
  "shortName": "SJ",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60af3d172ffdf65bcd6585cd\\
\\profilePhoto_1622372567671_Sachin Joshi Photo 3 (2).jpg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62691c48afd7d55eddecfda3",
  "role": "MAKER",
  "firstName": "Bhavika",
  "email": "bhavikachavan0102@gmail.com",
  "lastName": "chavan",
  "mobileNo": "8390804382",
  "designation": "Site Engineer",
  "shortName": "BH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
},
"rateVerifier": null,
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  "type": "EMPLOYEE",
  "_id": "5ffe92d27737ca4d986b6453",
  "role": "VALUER",
  "firstName": "Manoj",
  "email": "manoj@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9819597579",
  "designation": "Registered Valuer",
  "registrationNo": [
    {
```

```
"title": {
  "label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.241775976643915",
```

```
"longitude": "72.84599519513313"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.84599519513313,
    19.241775976643915
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "3/10/2024 05:20 pm"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Eksar",
```

```
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Ground",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
```

```
"name": "Plot No.",
"key": "plotNo",
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shree Tilak Complex CHSL",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Near Devki Nagar ",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
}
```

```
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
```



```
"key": "selectNo",
"value": "2",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
}
```

```
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400103",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Borivali West",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
}
```

```
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
```

```
"title": "Electricity deposits / electrical fittings, etc",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
```



```
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66fe5f52f667804969b52c5d",
"ownerName": "Hemlata Damji Dedhia ",
"ownerPhoneNo": "0000000000",
"appAddress": "Row House no 2,Street Tilak Complex,Link Road &Davidas Road
Eksar Village Borivali West ",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/66fe5f52f667804969b52c5d/document_1727946260168_172794625
6735_Gift_Deed_Bungalow_No_227122001.pdf",
    "fileName": "document_1727946260168_1727946256735_Gift_Deed_Bungalow_No_
227122001.pdf",
    "id": "600761",
    "uploadedBy": "60af3d172ffdf65bcd6585cd",
    "createdAt": "Thu Oct 03 2024 14:39:38 GMT+0530 (India Standard Time)"
  },

```

```
{
  "documentType": {
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/66fe5f52f667804969b52c5d/document_1727946276514_1727946273800_Release_Deed_Bungalow_no_217062009.pdf",
  "fileName": "document_1727946276514_1727946273800_Release_Deed_Bungalow_no_217062009.pdf",
  "id": "854511",
  "uploadedBy": "60af3d172ffdf65bcd6585cd",
  "createdAt": "Thu Oct 03 2024 14:39:38 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": "Any Other Document",
    "value": "60ae124aaa6d152c1801b2f7"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/66fe5f52f667804969b52c5d/document_1727946328368_1727946325866_Tilak_Architech_Letter_1.pdf",
  "fileName": "document_1727946328368_1727946325866_Tilak_Architech_Letter_1.pdf",
  "id": "510202",
  "uploadedBy": "60af3d172ffdf65bcd6585cd",
  "createdAt": "Thu Oct 03 2024 14:39:38 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": "Other",
    "value": "60ae124eaa6d152c1801b30b"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/66fe5f52f667804969b52c5d/document_1727946342086_1727946339688_Tilak_Elct_Bill__July_2022.pdf",
  "fileName": "document_1727946342086_1727946339688_Tilak_Elct_Bill__July_2022.pdf",
  "id": "177337",
  "uploadedBy": "60af3d172ffdf65bcd6585cd",
  "createdAt": "Thu Oct 03 2024 14:39:38 GMT+0530 (India Standard Time)"
},
{
```

```
"documentType": {
  "label": "Other",
  "value": "60ae124eaa6d152c1801b30b"
},
"isHardCopy": false,
"displayStatus": false,
"path": "cases/66fe5f52f667804969b52c5d/
document_1727946357994_1727946355632_80_100_9_Satbara.pdf",
"fileName": "document_1727946357994_1727946355632_80_100_9_Satbara.pdf",
"id": "909967",
"uploadedBy": "60af3d172ffdf65bcd6585cd",
"createdAt": "Thu Oct 03 2024 14:39:38 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": "Other",
    "value": "60ae124eaa6d152c1801b30b"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/66fe5f52f667804969b52c5d/
document_1727946369699_1727946367430_Tilak_Architech_Letter.pdf",
  "fileName":
"document_1727946369699_1727946367430_Tilak_Architech_Letter.pdf",
  "id": "511450",
  "uploadedBy": "60af3d172ffdf65bcd6585cd",
  "createdAt": "Thu Oct 03 2024 14:39:38 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": "Other",
    "value": "60ae124eaa6d152c1801b30b"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/66fe5f52f667804969b52c5d/document_1727946382307_172794637
9907_TILAK_BUNGLOW_SEVEN_TWELVE_EXTRACT_0001.pdf",
  "fileName": "document_1727946382307_1727946379907_TILAK_BUNGLOW_SEV
EN_TWELVE_EXTRACT_0001.pdf",
  "id": "643895",
  "uploadedBy": "60af3d172ffdf65bcd6585cd",
  "createdAt": "Thu Oct 03 2024 14:39:38 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": "Occupancy Certificate",
```

```
    "value": "60ae124baa6d152c1801b2fd"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/66fe5f52f667804969b52c5d/
document_1727946414041_1727946411661_OC_Tilak_Bungalow.pdf",
  "fileName": "document_1727946414041_1727946411661_OC_Tilak_Bungalow.pdf",
  "id": "498487",
  "uploadedBy": "60af3d172ffdf65bcd6585cd",
  "createdAt": "Thu Oct 03 2024 14:39:38 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": "Architect Plan",
    "value": "60ae124eaa6d152c1801b30c"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/66fe5f52f667804969b52c5d/
document_1727946429896_1727946427576_Ground.pdf",
  "fileName": "document_1727946429896_1727946427576_Ground.pdf",
  "id": "622390",
  "uploadedBy": "60af3d172ffdf65bcd6585cd",
  "createdAt": "Thu Oct 03 2024 14:39:38 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": "Architect Plan",
    "value": "60ae124eaa6d152c1801b30c"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/66fe5f52f667804969b52c5d/
document_1727946444546_1727946442243_Basment.pdf",
  "fileName": "document_1727946444546_1727946442243_Basment.pdf",
  "id": "904412",
  "uploadedBy": "60af3d172ffdf65bcd6585cd",
  "createdAt": "Thu Oct 03 2024 14:39:38 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": "Property Tax Bill",
    "value": "60ae126aaa6d152c1801b38b"
  },
  "isHardCopy": false,
  "displayStatus": false,
```

```
    "path": "cases/66fe5f52f667804969b52c5d/
document_1727946467707_1727946465339_Property_Card_Tilak_0001.pdf",
    "fileName":
"document_1727946467707_1727946465339_Property_Card_Tilak_0001.pdf",
    "id": "488577",
    "uploadedBy": "60af3d172ffdf65bcd6585cd",
    "createdAt": "Thu Oct 03 2024 14:39:38 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": "NA Order Cum Commencement Certificate",
      "value": "65ea9becf9222577acfb285"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/66fe5f52f667804969b52c5d/
document_1727946495886_1727946480762_19981017_Tilak_NA_Order.pdf",
    "fileName":
"document_1727946495886_1727946480762_19981017_Tilak_NA_Order.pdf",
    "id": "355625",
    "uploadedBy": "60af3d172ffdf65bcd6585cd",
    "createdAt": "Thu Oct 03 2024 14:39:38 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": "Architect Plan",
      "value": "60ae124eaa6d152c1801b30c"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/66fe5f52f667804969b52c5d/
document_1727946537098_1727946527378_Basment.pdf",
    "fileName": "document_1727946537098_1727946527378_Basment.pdf",
    "id": "295272",
    "uploadedBy": "60af3d172ffdf65bcd6585cd",
    "createdAt": "Thu Oct 03 2024 14:39:38 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": "Architect Plan",
      "value": "60ae124eaa6d152c1801b30c"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/66fe5f52f667804969b52c5d/
document_1727946554072_1727946551535_1St_Floor.pdf",
```

```
"fileName": "document_1727946554072_1727946551535_1St_Floor.pdf",
"id": "292333",
"uploadedBy": "60af3d172ffdf65bcd6585cd",
"createdAt": "Thu Oct 03 2024 14:39:38 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/66fe5f52f667804969b52c5d/
document_1727946612695_1727946610238_Tilak__Certified_Conveyance_Deed.pdf",
  "fileName": "document_1727946612695_1727946610238_Tilak__Certified_Convey
ance_Deed.pdf",
  "id": "816210",
  "uploadedBy": "60af3d172ffdf65bcd6585cd",
  "createdAt": "Thu Oct 03 2024 14:41:30 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "011588",
"createdBy": "60af3d172ffdf65bcd6585cd",
"caseHistory": [
  {
    "id": "684130",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Oct 03 2024 14:39:38 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Hemlata Damji Dedhia ",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "592766"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
```

```
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6703b6baba5e64b24a30884d",
    "name": "externallmg_1728296628196_1728296623466_image_0.jpeg",
    "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296628196_1728296623466_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6703b6baba5e64b24a30884e",
    "name": "externallmg_1728296628359_1728296623466_image_1.jpeg",
    "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296628359_1728296623466_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6703b6baba5e64b24a30884f",
    "name": "externallmg_1728296628762_1728296623466_image_2.jpeg",
    "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296628762_1728296623466_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6703b6baba5e64b24a308850",
    "name": "externallmg_1728296629054_1728296623466_image_3.jpeg",
    "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296629054_1728296623466_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6703b6baba5e64b24a308851",
    "name": "externallmg_1728296629280_1728296623466_image_4.jpeg",
    "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296629280_1728296623466_image_4.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6703b6baba5e64b24a308852",
  "name": "externallmg_1728296629612_1728296623466_image_5.jpeg",
  "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296629612_1728296623466_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6703b6baba5e64b24a308853",
  "name": "externallmg_1728296629829_1728296623466_image_6.jpeg",
  "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296629829_1728296623466_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6703b6baba5e64b24a308854",
  "name": "externallmg_1728296629996_1728296623466_image_7.jpeg",
  "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296629996_1728296623466_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6703b6baba5e64b24a308855",
  "name": "externallmg_1728296630088_1728296623466_image_8.jpeg",
  "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296630088_1728296623466_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6703b6baba5e64b24a308856",
  "name": "externallmg_1728296630280_1728296623466_image_9.jpeg",
  "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296630280_1728296623466_image_9.jpeg",
  "orientation": "portrait"
}
```



```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6703b6baba5e64b24a308857",
      "name": "externallmg_1728296630454_1728296623466_image_10.jpeg",
      "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296630454_1728296623466_image_10.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6703b6baba5e64b24a308858",
      "name": "externallmg_1728296630671_1728296623466_image_11.jpeg",
      "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296630671_1728296623466_image_11.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6703b6baba5e64b24a308859",
      "name": "externallmg_1728296630835_1728296623466_image_12.jpeg",
      "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296630835_1728296623466_image_12.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6703b6baba5e64b24a30885a",
      "name": "externallmg_1728296631250_1728296623466_image_13.jpeg",
      "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296631250_1728296623466_image_13.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6703b6baba5e64b24a30885b",
      "name": "externallmg_1728296631630_1728296623466_image_14.jpeg",
      "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296631630_1728296623466_image_14.jpeg",
      "orientation": "portrait"
    },
  ],
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6703b6baba5e64b24a30885c",
  "name": "externallmg_1728296631996_1728296623466_image_15.jpeg",
  "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296631996_1728296623466_image_15.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6703b6baba5e64b24a30885d",
  "name": "externallmg_1728296632243_1728296623466_image_16.jpeg",
  "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296632243_1728296623466_image_16.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6703b6baba5e64b24a30885e",
  "name": "externallmg_1728296632473_1728296623466_image_17.jpeg",
  "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296632473_1728296623466_image_17.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6703b6baba5e64b24a30885f",
  "name": "externallmg_1728296632585_1728296623466_image_18.jpeg",
  "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296632585_1728296623466_image_18.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6703b6baba5e64b24a308860",
  "name": "externallmg_1728296632875_1728296623466_image_19.jpeg",
  "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296632875_1728296623466_image_19.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6703b69b6d5ad2b22309c17a",
    "name": "externallmg_1728296598751_1728296560437_image_0.jpeg",
    "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296598751_1728296560437_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6703b69b6d5ad2b22309c17b",
    "name": "externallmg_1728296598901_1728296560438_image_1.jpeg",
    "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296598901_1728296560438_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6703b69b6d5ad2b22309c17c",
    "name": "externallmg_1728296599035_1728296560438_image_2.jpeg",
    "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296599035_1728296560438_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6703b69b6d5ad2b22309c17d",
    "name": "externallmg_1728296599168_1728296560438_image_3.jpeg",
    "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296599168_1728296560438_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6703b69b6d5ad2b22309c17e",
    "name": "externallmg_1728296599344_1728296560438_image_4.jpeg",
    "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296599344_1728296560438_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
```

```
    "status": false,
    "_id": "6703b69b6d5ad2b22309c17f",
    "name": "externallmg_1728296599580_1728296560438_image_5.jpeg",
    "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296599580_1728296560438_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6703b69b6d5ad2b22309c180",
    "name": "externallmg_1728296599639_1728296560438_image_6.jpeg",
    "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296599639_1728296560438_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6703b69b6d5ad2b22309c181",
    "name": "externallmg_1728296600013_1728296560438_image_7.jpeg",
    "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296600013_1728296560438_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6703b69b6d5ad2b22309c182",
    "name": "externallmg_1728296600373_1728296560438_image_8.jpeg",
    "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296600373_1728296560438_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6703b69b6d5ad2b22309c183",
    "name": "externallmg_1728296600826_1728296560438_image_9.jpeg",
    "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296600826_1728296560438_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
```

```
    "_id": "6703b69b6d5ad2b22309c184",
    "name": "externallmg_1728296601138_1728296560438_image_10.jpeg",
    "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296601138_1728296560438_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6703b69b6d5ad2b22309c185",
    "name": "externallmg_1728296601325_1728296560438_image_11.jpeg",
    "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296601325_1728296560438_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6703b69b6d5ad2b22309c186",
    "name": "externallmg_1728296601444_1728296560439_image_12.jpeg",
    "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296601444_1728296560439_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6703b69b6d5ad2b22309c187",
    "name": "externallmg_1728296601718_1728296560439_image_13.jpeg",
    "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296601718_1728296560439_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6703b69b6d5ad2b22309c188",
    "name": "externallmg_1728296601917_1728296560439_image_14.jpeg",
    "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296601917_1728296560439_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6703b69b6d5ad2b22309c189",
```

```
    "name": "externallmg_1728296602073_1728296560439_image_15.jpeg",
    "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296602073_1728296560439_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6703b69b6d5ad2b22309c18a",
    "name": "externallmg_1728296602272_1728296560439_image_16.jpeg",
    "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296602272_1728296560439_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6703b69b6d5ad2b22309c18b",
    "name": "externallmg_1728296602752_1728296560439_image_17.jpeg",
    "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296602752_1728296560439_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6703b69b6d5ad2b22309c18c",
    "name": "externallmg_1728296602940_1728296560439_image_18.jpeg",
    "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296602940_1728296560439_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6703b69b6d5ad2b22309c18d",
    "name": "externallmg_1728296603347_1728296560439_image_19.jpeg",
    "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296603347_1728296560439_image_19.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6703b6eec691adb224f719f3",
    "name": "externallmg_1728296683410_1728296678406_image_0.jpeg",
```

```
    "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296683410_1728296678406_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6703b6eec691adb224f719f4",
    "name": "externallmg_1728296684052_1728296678407_image_1.jpeg",
    "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296684052_1728296678407_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6703b6eec691adb224f719f5",
    "name": "externallmg_1728296684191_1728296678407_image_2.jpeg",
    "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296684191_1728296678407_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6703b6eec691adb224f719f6",
    "name": "externallmg_1728296684569_1728296678407_image_3.jpeg",
    "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296684569_1728296678407_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6703b6eec691adb224f719f7",
    "name": "externallmg_1728296684826_1728296678407_image_4.jpeg",
    "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296684826_1728296678407_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6703b6eec691adb224f719f8",
    "name": "externallmg_1728296684949_1728296678407_image_5.jpeg",
    "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296684949_1728296678407_image_5.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6703b6eec691adb224f719f9",
  "name": "externallmg_1728296685334_1728296678407_image_6.jpeg",
  "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296685334_1728296678407_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6703b6eec691adb224f719fa",
  "name": "externallmg_1728296685613_1728296678407_image_7.jpeg",
  "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296685613_1728296678407_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6703b6eec691adb224f719fb",
  "name": "externallmg_1728296685790_1728296678407_image_8.jpeg",
  "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296685790_1728296678407_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6703b6eec691adb224f719fc",
  "name": "externallmg_1728296686104_1728296678407_image_9.jpeg",
  "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296686104_1728296678407_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6703b6eec691adb224f719fd",
  "name": "externallmg_1728296686344_1728296678407_image_10.jpeg",
  "path": "cases/66fe5f52f667804969b52c5d/
externallmg_1728296686344_1728296678407_image_10.jpeg",
  "orientation": "portrait"
}
```



```

    }
  ],
  "externalDocuments": [],
  "processingDocuments": [],
  "leadRemarks": [],
  "audioRemarks": [],
  "remarks": [],
  "createdAt": "2024-10-03T09:09:38.164Z",
  "updatedAt": "2024-10-07T10:24:46.781Z",
  "__v": 0,
  "uniqueNo": "",
  "updatedBy": "62691c48afd7d55eddecfda3",
  "assignmentType": {
    "value": "Retail",
    "label": "Retail"
  },
  },
  "fullAddress": "Residential Row House No. 2, Ground Floor, Shree Tilak Complex
CHSL, Near Devki Nagar , Village - Eksar, Borivali West, Mumbai, 400103",
  "addressForMap": "",
  "caseReferredBy": "60af3d172ffdf65bcd6585cd",
  "contactPersonName": "Ms NIdhi",
  "email": "",
  "isExternal": "false",
  "isUrgent": "false",
  "ownershipShare": "",
  "proposePurchaserName": "",
  "purchaseValueAsPerDocument": "",
  "relationWithOwner": "Contact Person",
  "siteVisitContactNo": "8591118966"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			