

```
{
  "typeOfReport": {
    "value": "Cost_Vetting",
    "label": "Cost Vetting"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Vetting_Of_Estimates",
    "label": "Vetting Of Estimates"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "632ee4c4e2561b46f656d584"
    },
    "firstName": "testadgaon",
    "type": "CREDITOFFICER",
    "_id": "635f7a01e363ef22db2f2417",
    "lastName": "adgaon",
    "mobileNo": "",
    "email": "adgaon@vastukala.org",
    "workMobileNo": "0000000000"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "1180"
  },
}
```

```
"organization": {
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Madhusa Elite, Vrundavan Nagar, Jatra - Nandur Naka Link
Road, Adgaon, Nashik - 422003",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "632ee4c4e2561b46f656d584",
  "name": "RACPC Adgaon,",
  "branchCode": "14",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "me@me.sbi",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "RACPC Adgaon, Nashik Branch,Nshik, Maharashtra State –
Maharashtra, Country – India."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "63f9ed37ce84bf289ba991ac",
"role": "FRONTDESK",
"firstName": "Rushikesh",
"email": "rushingle2201@gmail.com",
"lastName": "Pingle",
"mobileNo": "8788210361",
"shortName": "RUP",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "636a1ad14d42487767af3f91",
"role": "MAKER + RATE VERIFIER",
"firstName": "Chintamani",
"email": "chintamanichaudhari099@gmail.com",
"lastName": "Chaudhari",
"mobileNo": "8007230780",
"designation": "",
"shortName": "cc",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "63f9ed37ce84bf289ba991ac",
"role": "FRONTDESK",
"firstName": "Rushikesh",
"email": "rushingle2201@gmail.com",
"lastName": "Pingle",
"mobileNo": "8788210361",
"designation": "",
"shortName": "RUP",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "63f9ed37ce84bf289ba991ac",
"role": "FRONTDESK",
"firstName": "Rushikesh",
"email": "rushingle2201@gmail.com",
"lastName": "Pingle",
```

```
"mobileNo": "8788210361",
"designation": "",
"shortName": "RUP",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "64dc7184ccaf1e7b7f637f47",
  "role": "FRONTDESK",
  "firstName": "Binumon",
  "email": "binu@vastukala.org",
  "lastName": "Moozhickal",
  "mobileNo": "9930252906",
  "designation": "Back Office Team Leader",
  "shortName": "BS",
  "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
  "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  "type": "EMPLOYEE",
  "_id": "5ffe92d27737ca4d986b6453",
  "role": "VALUER",
  "firstName": "Manoj",
  "email": "manoj@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9819597579",
  "designation": "Registered Valuer",
  "registrationNo": [
    {
      "title": {
        "label": "IBBI"
      },
      "_id": "60af80072ffdf65bcd658651",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  {
```

```
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "20.003694042319573",
  "longitude": "73.8315548114407"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "26/10/2024 12:00 am"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Dasak Shiwar",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "12",
```

```
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Nashik",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": " 1+2",
  "label": true
},
"buildingName": {
  "status": false,
```

```
"name": "Building Name",
"key": "buildingName",
"value": "",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Sambhaji Nagar Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Near Dalimb Market, Kailash Nagar",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
}
```



```
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1201",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
```

```
"key": "municipalityWardNo",
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422 003",
  "label": false
},
}
```

```
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
}
```

```
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```

```
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```



```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
```

```
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "671c770cfd14bf9350ac7c52",
"ownerName": " Vikram Pagare",
"ownerPhoneNo": "9373901547",
"fullAddress": "Residential Cost Vetting No. 1201, 12th Floor, Near Dalimb Market,
Kailash Nagar, Plot No. 1+2, Sambhaji Nagar Road, Village - Dasak Shiwar, Taluka -
Nashik, District - Nashik, Nashik, 422 003",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae128aaa6d152c1801b41f",
      "label": "Vetting Documents"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1729918714223_New_Doc_10252024_1856.pdf",
    "path": "cases/671c770cfd14bf9350ac7c52/
document_1729918714223_New_Doc_10252024_1856.pdf",
    "id": "572855",
    "uploadedBy": "63f9ed37ce84bf289ba991ac",
    "createdAt": "Sat Oct 26 2024 04:58:52 GMT+0000 (Coordinated Universal Time)"
  }
],
"assignmentType": {
  "value": "Retail",
```

```
"label": "Retail"
},
"caseNumber": "012102",
"createdBy": "63f9ed37ce84bf289ba991ac",
"caseHistory": [
  {
    "id": "986453",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Oct 26 2024 04:58:52 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": " Vikram Pagare",
    "phone": "9373901547",
    "ownershipShare": "",
    "email": "",
    "id": "568462"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671c7751fd14bf9350ac7d2c",
    "name":
"externalImg_1729918799840_WhatsApp_Image_20241024_at_53343_PM.jpeg",
    "path": "cases/671c770cfd14bf9350ac7c52/
externalImg_1729918799840_WhatsApp_Image_20241024_at_53343_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671c7751fd14bf9350ac7d2d",
    "name":
"externalImg_1729918800016_WhatsApp_Image_20241024_at_53344_PM_1.jpeg",
```

```
    "path": "cases/671c770cfd14bf9350ac7c52/
externallmg_1729918800016_WhatsApp_Image_20241024_at_53344_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671c7751fd14bf9350ac7d2e",
    "name":
"externallmg_1729918800096_WhatsApp_Image_20241024_at_53344_PM.jpeg",
    "path": "cases/671c770cfd14bf9350ac7c52/
externallmg_1729918800096_WhatsApp_Image_20241024_at_53344_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671c7751fd14bf9350ac7d2f",
    "name":
"externallmg_1729918800137_WhatsApp_Image_20241024_at_53345_PM_1.jpeg",
    "path": "cases/671c770cfd14bf9350ac7c52/
externallmg_1729918800137_WhatsApp_Image_20241024_at_53345_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671c7751fd14bf9350ac7d30",
    "name":
"externallmg_1729918800145_WhatsApp_Image_20241024_at_53345_PM.jpeg",
    "path": "cases/671c770cfd14bf9350ac7c52/
externallmg_1729918800145_WhatsApp_Image_20241024_at_53345_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671c7751fd14bf9350ac7d31",
    "name":
"externallmg_1729918800189_WhatsApp_Image_20241024_at_53346_PM.jpeg",
    "path": "cases/671c770cfd14bf9350ac7c52/
externallmg_1729918800189_WhatsApp_Image_20241024_at_53346_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "671c7751fd14bf9350ac7d32",
    "name":
"externallmg_1729918800214_WhatsApp_Image_20241024_at_53347_PM.jpeg",
    "path": "cases/671c770cfd14bf9350ac7c52/
externallmg_1729918800214_WhatsApp_Image_20241024_at_53347_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671c7751fd14bf9350ac7d33",
    "name":
"externallmg_1729918800235_WhatsApp_Image_20241024_at_53348_PM_1.jpeg",
    "path": "cases/671c770cfd14bf9350ac7c52/
externallmg_1729918800235_WhatsApp_Image_20241024_at_53348_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671c7751fd14bf9350ac7d34",
    "name":
"externallmg_1729918800266_WhatsApp_Image_20241024_at_53348_PM_2.jpeg",
    "path": "cases/671c770cfd14bf9350ac7c52/
externallmg_1729918800266_WhatsApp_Image_20241024_at_53348_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671c7751fd14bf9350ac7d35",
    "name":
"externallmg_1729918800299_WhatsApp_Image_20241024_at_53348_PM.jpeg",
    "path": "cases/671c770cfd14bf9350ac7c52/
externallmg_1729918800299_WhatsApp_Image_20241024_at_53348_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671c7751fd14bf9350ac7d36",
    "name":
"externallmg_1729918800306_WhatsApp_Image_20241024_at_53349_PM_1.jpeg",
    "path": "cases/671c770cfd14bf9350ac7c52/
externallmg_1729918800306_WhatsApp_Image_20241024_at_53349_PM_1.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671c7751fd14bf9350ac7d37",
  "name":
"externallmg_1729918800345_WhatsApp_Image_20241024_at_53349_PM_2.jpeg",
  "path": "cases/671c770cfd14bf9350ac7c52/
externallmg_1729918800345_WhatsApp_Image_20241024_at_53349_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671c7751fd14bf9350ac7d38",
  "name":
"externallmg_1729918800372_WhatsApp_Image_20241024_at_53349_PM.jpeg",
  "path": "cases/671c770cfd14bf9350ac7c52/
externallmg_1729918800372_WhatsApp_Image_20241024_at_53349_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671c7751fd14bf9350ac7d39",
  "name":
"externallmg_1729918800377_WhatsApp_Image_20241024_at_53350_PM_1.jpeg",
  "path": "cases/671c770cfd14bf9350ac7c52/
externallmg_1729918800377_WhatsApp_Image_20241024_at_53350_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671c7751fd14bf9350ac7d3a",
  "name":
"externallmg_1729918800712_WhatsApp_Image_20241024_at_53350_PM.jpeg",
  "path": "cases/671c770cfd14bf9350ac7c52/
externallmg_1729918800712_WhatsApp_Image_20241024_at_53350_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671c7751fd14bf9350ac7d3b",
```

```
    "name":
"externallmg_1729918800747_WhatsApp_Image_20241024_at_53351_PM_1.jpeg",
  "path": "cases/671c770cfd14bf9350ac7c52/
externallmg_1729918800747_WhatsApp_Image_20241024_at_53351_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671c7751fd14bf9350ac7d3c",
  "name":
"externallmg_1729918800757_WhatsApp_Image_20241024_at_53351_PM_2.jpeg",
  "path": "cases/671c770cfd14bf9350ac7c52/
externallmg_1729918800757_WhatsApp_Image_20241024_at_53351_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671c7751fd14bf9350ac7d3d",
  "name":
"externallmg_1729918800802_WhatsApp_Image_20241024_at_53351_PM.jpeg",
  "path": "cases/671c770cfd14bf9350ac7c52/
externallmg_1729918800802_WhatsApp_Image_20241024_at_53351_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671c7751fd14bf9350ac7d3e",
  "name":
"externallmg_1729918800809_WhatsApp_Image_20241024_at_53352_PM_1.jpeg",
  "path": "cases/671c770cfd14bf9350ac7c52/
externallmg_1729918800809_WhatsApp_Image_20241024_at_53352_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671c7751fd14bf9350ac7d3f",
  "name":
"externallmg_1729918800858_WhatsApp_Image_20241024_at_53352_PM_2.jpeg",
  "path": "cases/671c770cfd14bf9350ac7c52/
externallmg_1729918800858_WhatsApp_Image_20241024_at_53352_PM_2.jpeg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671c775c038561936233e62b",
  "name":
"externallmg_1729918811887_WhatsApp_Image_20241024_at_53352_PM.jpeg",
  "path": "cases/671c770cfd14bf9350ac7c52/
externallmg_1729918811887_WhatsApp_Image_20241024_at_53352_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671c775c038561936233e62c",
  "name":
"externallmg_1729918812008_WhatsApp_Image_20241024_at_53353_PM_1.jpeg",
  "path": "cases/671c770cfd14bf9350ac7c52/
externallmg_1729918812008_WhatsApp_Image_20241024_at_53353_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671c775c038561936233e62d",
  "name":
"externallmg_1729918812026_WhatsApp_Image_20241024_at_53353_PM_2.jpeg",
  "path": "cases/671c770cfd14bf9350ac7c52/
externallmg_1729918812026_WhatsApp_Image_20241024_at_53353_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671c775c038561936233e62e",
  "name":
"externallmg_1729918812058_WhatsApp_Image_20241024_at_53353_PM.jpeg",
  "path": "cases/671c770cfd14bf9350ac7c52/
externallmg_1729918812058_WhatsApp_Image_20241024_at_53353_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671c775c038561936233e62f",
  "name":
"externallmg_1729918812067_WhatsApp_Image_20241024_at_53354_PM_1.jpeg",
```



```
    "path": "cases/671c770cfd14bf9350ac7c52/
externallmg_1729918812067_WhatsApp_Image_20241024_at_53354_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671c775c038561936233e630",
    "name":
"externallmg_1729918812106_WhatsApp_Image_20241024_at_53354_PM_2.jpeg",
    "path": "cases/671c770cfd14bf9350ac7c52/
externallmg_1729918812106_WhatsApp_Image_20241024_at_53354_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671c775c038561936233e631",
    "name":
"externallmg_1729918812113_WhatsApp_Image_20241024_at_53354_PM.jpeg",
    "path": "cases/671c770cfd14bf9350ac7c52/
externallmg_1729918812113_WhatsApp_Image_20241024_at_53354_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671c775c038561936233e632",
    "name":
"externallmg_1729918812149_WhatsApp_Image_20241024_at_53355_PM_1.jpeg",
    "path": "cases/671c770cfd14bf9350ac7c52/
externallmg_1729918812149_WhatsApp_Image_20241024_at_53355_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671c775c038561936233e633",
    "name":
"externallmg_1729918812159_WhatsApp_Image_20241024_at_53355_PM.jpeg",
    "path": "cases/671c770cfd14bf9350ac7c52/
externallmg_1729918812159_WhatsApp_Image_20241024_at_53355_PM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
```

```

"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-10-26T04:58:52.302Z",
"updatedAt": "2024-10-26T05:00:12.447Z",
"__v": 0,
"updatedBy": "63f9ed37ce84bf289ba991ac",
"addressForMap": "",
"caseReferredBy": "62724142afd7d55eddede405",
"contactPersonName": "Vikram Pagare",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"reald": "",
"siteVisitContactNo": "9373901547"

```

}

Name	Length	Width	Total
Composition :			
Other			
Composition :			