



A/12, Kamdar Park, Off Gokhale Road (South), Dadar, Mumbai 400 028.

A/12, Kamdar Park, Off Gokhale Road (South), Dadar, Mumbai 400 028.

Tel.: 2437 7945, 2422 0717 • Email: miltec@mtnl.net.in • miltec.con@gmail.com

May 20, 2015

Branch Manager, Cosmos Bank, Goregaon E Branch, Mumbai

Dear Sir,

#### Valuation Report: Flat No. 517 Wing B, Sai Prasad CHS, MIDC, Andheri E, Mumbai 400093

As desired by you we enclose Valuation Report No. 045/2015-16 of Valuation of Flat No. 517 Wing B, Sai Prasad CHS, MIDC, Andheri E, Mumbai 400093, belonging to Anil B. Kharate.

Photographs of the property are attached to the Report.

In case you need any clarifications we shall be glad to provide the same.

Yours truly,

Milind V. Joshi.

Encl: As above.

# Valuation Report No. 045/2015-16

#### VALUATION REPORT

May 20, 2015

Sub: Valuation of Flat 517 Wing B, Sai Prasad CHS, MIDC, Andheri E, Mumbai 400093.

gaon E
tion
ti Trade
, Tal
igher and
ery of
/ <b>.</b>
and West
01/05/2002
ig

NA

Approvals of authorities/ULC 1.18 clearance/FSI available And balance for occupation certificate Future use/FSI from TDR

Presumed to have been obtained. O/c dated 21/05/2003 from MIDC.

Name of the Co-Operative Society 1.19 Registration No. of the Society. No. of shares held and certificate No.

Sai Prasad CHS MUM/WK(East)/HSG/TC/12974/05-06 dt 31/05/2005 Share Certificate no. 107, 5 shares of Rs 50 each Distinctive no. 531 to 535

Outgoings per year



## Valuation Report No. 045/2015-16

## miltec

<u>2.0</u>	Details of Structure and Specifications	:	
2.1	Year of construction of Building	:	2001
2.2	Age of the Building and anticipated future life	:	Age 14 yrs; Balance life 36 yrs. (Building life assumed as 50 yrs since it Slum Rehabilitation Low Cost Housing Project)
2.3	Present Condition of the building And any last repairs done and painting done, immediate repairs require and cost of the same	:	Visibly satisfactory
2.4	Type of construction	:	RCC framed structure
2.5	No. of floors and flats on each floor	:	Ground + 7 floors.
2.6	Wall plaster and painting	:	Masonry walls having sand face plaster with cement paint from outside; oil bound distemper from inside.
2.7	No. of Lifts Capacity and type	:	1 it was not operational
2.8	Type of underground, overhead tanks and pumps	:	RCC underground water tank and overhead tanks with pump room to distribute water to all flats
2.9	Flooring in open spaces and stilts and staircase	:	Ceramic flooring in staircase and passages.
2.10	Compound wall, gates and security	:	No Compound wall, gate or security.
2.11	Building elevation	:	Standard elevation.
2.12	Other amenities and special amenities and features	:	Not much of open space. No special amenities. No vehicle parking.
2.13	General comments on specifications	:	Mediocre.
<u>3.0</u>	Details of Flat under reference	:	
3.1	Doors and windows	:	Plywood board main door, and Bakelite board internal doors. Windows aluminium framed sliding type with MS grill.
3.2	Type of Flooring in rooms, skirting cladding	:	Hall and passage has ceramic tiles, kitchen has vitrified tiles.
3.3	Flooring in toilet, WC/ Bath Dado	:	Kota in bathroom, glazed in WC, both have glazed tiles dado of about 3 feet.
3.4	Kitchen Platform type and sink	:	Cuddapah platform with inbuilt sink.
3.5	Toilets plumbing lines concealed / open Type of plumbing and sanitary fittings Any special fittings, ceiling etc.	:	Open plumbing. Standard quality sanitary fittings.
3.6	Electrical installations open or concealed Wiring. Type of switches, telephone points, TV and cable points.	:	Concealed wiring.
3.7	No. of rooms for the Flat	:	Living room, kitchen, WC, bathroom.



## Valuation Report No. 045/2015-16

#### miltec

Balconies to rooms separate or merged 3.8 NA. No. of WC and Bath, whether attached or 3.9 1 WC (Indian) and bathroom; separate separate Built up Area 3.10 Carpet 225 sq. ft.; Built up 270 sq. ft. as per the Agreement. Assumptions, Data available and basis 4.0 for the purpose of Valuation : Drawings and approvals 4.1 Since it is MIDC building it is presumed that the structure is legal/authorized having all approvals Area considered for the purpose of 4.2 270 sq. ft. Valuation Present condition of gala/flat and 4.5 Visibly satisfactory. structure Govt. Ready Recknor Rate & Market 4.7 Govt. Ready Recknor Rate: Rs. 10,500/rates of the properties in the vicinity and Market rate: About Rs. 13,000/- to Rs. 15,000/- per sq.ft. surrounding area of built up area. We take Rs. 13,000/sq. ft. as the building in low cost construction. Conclusion and valuation of the 5.0 **Property:** In view of the data available and the basis for valuation, the valuation of the property under reference will be as under: Value of the new structure at the same 5.1 Rs. 35,10,000/location and having same specifications and having built up area of 270 sq. ft. @ Rs. 13,000 per sq. ft 5.2 Less: for depreciation of age of the Rs. 97,000/building and future life@ 20 % on Rs. 4,86,000(270 sq. ft. X Rs. 1,800 / sq. ft.) 5.3 Less for immediate repairs / painting/ Visibly NIL. structural repairs for the flat and building 5.4 Value of the property as on date Rs. 34,13,000/-(Rupees Thirty Four Lacs Thirteen Thousand only) 5.5 Distress sale value @ 85% of the above Rs. 29,01,000/-(Rupees Twenty Nine Lacs One Thousand only)

rior Milec Consultancy Services

Proprietos

Active Ac

## VALUATION REPORT NO. 045/2015-16 MR. ANIL KHARATE : ANDHERI





