

```
{
  "typeOfReport": {
    "value": "Land_and_Building",
    "label": "Land and Building"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Banking_Purpose",
    "label": "Banking Purpose"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "646dc536b05e530fb6c47b3b"
    },
    "firstName": "Pushpa",
    "type": "CREDITOFFICER",
    "_id": "64cb7e0add0a6d4cc439286c",
    "lastName": "Potinde",
    "mobileNo": "",
    "workMobileNo": "9403511861",
    "email": "cs.ho@bankofbaroda.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "2500"
  },
}
```

```
"organization": {
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Madhusa Elite, Vrundavan Nagar, Jatra - Nandur Naka Link
Road, Adgaon, Nashik - 422003",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180c",
  "type": "BANK",
  "name": "Bank Of Baroda",
  "displayName": "Bank Of Baroda",
  "initial": "BOB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "646dc536b05e530fb6c47b3b",
  "name": "RO Nashik\t",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "rlf.nashik@bankofbaroda.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "BSNL Building, Data Mandir Road, Nashik Road, Nashik 422101\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63fda060ce84bf289baace4c",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "63f9ed37ce84bf289ba991ac",
```

```
"role": "FRONTDESK",
"firstName": "Rushikesh",
"email": "rushipingle2201@gmail.com",
"lastName": "Pingle",
"mobileNo": "8788210361",
"shortName": "RUP",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "636a29b64d42487767af43ea",
"role": "NASHIK (LEAD + VISIT + RATE)",
"firstName": "Sachin",
"email": "sachinraundal9021@gmail.com",
"lastName": "Raundal",
"mobileNo": "9021337843",
"designation": "Site Engg",
"shortName": "Sachin",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/636a29b64d42487767af43ea/
profilePhoto_1688819202426_image.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "636a1ad14d42487767af3f91",
"role": "MAKER + RATE VERFIER",
"firstName": "Chintamani",
"email": "chintamanichaudhari099@gmail.com",
"lastName": "Chaudhari",
"mobileNo": "8007230780",
"designation": "",
"shortName": "cc",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "636a1ad14d42487767af3f91",
"role": "MAKER + RATE VERFIER",
"firstName": "Chintamani",
"email": "chintamanichaudhari099@gmail.com",
"lastName": "Chaudhari",
"mobileNo": "8007230780",
```

```
"designation": "",
"shortName": "cc",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordination",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
    {
      "title": {
```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.904612326556315",
  "longitude": "73.83122770396673"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "29/11/2024 12:00 am"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Sansari",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Basement",
    "label": false
  }
}
```

```
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Nashik",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "19",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
```

```
"key": "buildingName",
"value": "",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Howson Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Near BOB Deolali Bank",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
}
```



```
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "44/3",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
```

```
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422401",
  "label": false
},
"suburb": {
```

```
    "status": false,
    "name": "Suburb",
    "key": "suburb",
    "value": "",
    "label": false
  }
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
}
```

```
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": ""
  }
}
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": true,
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  }
}
```

```
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```



```
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
```

```
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67496054d1078a4ea7fc8592",
"ownerName": "Dr. Vijay Gangaram Mandale",
"ownerPhoneNo": "9823103435",
"fullAddress": "Residential Land and Building No. Basement Floor, Near BOB Deolali
Bank, Plot No. 19, New/Current Survey No. 44/3, Howson Road, Village - Sansari,
Taluka - Nashik, District - Nashik, Nashik, 422401",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae128eaa6d152c1801b430",
      "label": "Aadhaar Card"
    },
    "inputs": {
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "8554 2989 8284"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1732861858096_Aadhar_Downloadunlocked.pdf",
    "path": "cases/67496054d1078a4ea7fc8592/
document_1732861858096_Aadhar_Downloadunlocked.pdf",
    "id": "515309",
```

```
"uploadedBy": "63f9ed37ce84bf289ba991ac",
"createdAt": "Fri Nov 29 2024 06:33:56 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "inputs": {
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": ""
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1732861870311_Adobe_Scan_27Nov2024.pdf",
  "path": "cases/67496054d1078a4ea7fc8592/
document_1732861870311_Adobe_Scan_27Nov2024.pdf",
  "id": "499595",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Fri Nov 29 2024 06:33:56 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b308",
    "label": "Building Plan"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName":
"document_1732861888582_bulding_sanction_plan_of_Dr_Mandale.pdf",
  "path": "cases/67496054d1078a4ea7fc8592/
document_1732861888582_bulding_sanction_plan_of_Dr_Mandale.pdf",
  "id": "408214",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Fri Nov 29 2024 06:33:56 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
```

```
    "fileName": "document_1732861982401_Bungalow_sale_deed_of_dr_Mandale.pdf",
    "path": "cases/67496054d1078a4ea7fc8592/
document_1732861982401_Bungalow_sale_deed_of_dr_Mandale.pdf",
    "id": "310418",
    "uploadedBy": "63f9ed37ce84bf289ba991ac",
    "createdAt": "Fri Nov 29 2024 06:33:56 GMT+0000 (Coordinated Universal Time)"
  },
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1732861994441_composition_of_unauthorised_construction
_of_Mandale.pdf",
    "path": "cases/67496054d1078a4ea7fc8592/document_1732861994441_compositio
n_of_unauthorised_construction_of_Mandale.pdf",
    "id": "566467",
    "uploadedBy": "63f9ed37ce84bf289ba991ac",
    "createdAt": "Fri Nov 29 2024 06:33:56 GMT+0000 (Coordinated Universal Time)"
  },
  {
    "documentType": {
      "value": "60ae128eaa6d152c1801b431",
      "label": "Pan Card"
    },
    "inputs": {
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "CVAPMO373F"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1732862015161_PAN_Card.pdf",
    "path": "cases/67496054d1078a4ea7fc8592/
document_1732862015161_PAN_Card.pdf",
    "id": "904224",
    "uploadedBy": "63f9ed37ce84bf289ba991ac",
    "createdAt": "Fri Nov 29 2024 06:33:56 GMT+0000 (Coordinated Universal Time)"
  }
],
"assignmentType": {
  "value": "Retail",
```

```
"label": "Retail"
},
"caseNumber": "012674",
"createdBy": "63f9ed37ce84bf289ba991ac",
"caseHistory": [
  {
    "id": "823728",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Nov 29 2024 06:33:56 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Dr. Vijay Gangaram Mandale",
    "phone": "9823103435",
    "ownershipShare": "",
    "email": "",
    "id": "983513"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6749613e520246c6c063d192",
    "name":
"externalImg_1732862269353_WhatsApp_Image_20241129_at_102031_AM_1.jpeg",
    "path": "cases/67496054d1078a4ea7fc8592/
externalImg_1732862269353_WhatsApp_Image_20241129_at_102031_AM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6749613e520246c6c063d193",
    "name":
"externalImg_1732862269455_WhatsApp_Image_20241129_at_102031_AM_2.jpeg",
```

```
    "path": "cases/67496054d1078a4ea7fc8592/
externallmg_1732862269455_WhatsApp_Image_20241129_at_102031_AM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6749613e520246c6c063d194",
    "name":
"externallmg_1732862269477_WhatsApp_Image_20241129_at_102031_AM.jpeg",
    "path": "cases/67496054d1078a4ea7fc8592/
externallmg_1732862269477_WhatsApp_Image_20241129_at_102031_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6749613e520246c6c063d195",
    "name":
"externallmg_1732862269492_WhatsApp_Image_20241129_at_102032_AM_1.jpeg",
    "path": "cases/67496054d1078a4ea7fc8592/
externallmg_1732862269492_WhatsApp_Image_20241129_at_102032_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6749613e520246c6c063d196",
    "name":
"externallmg_1732862269527_WhatsApp_Image_20241129_at_102032_AM_2.jpeg",
    "path": "cases/67496054d1078a4ea7fc8592/
externallmg_1732862269527_WhatsApp_Image_20241129_at_102032_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6749613e520246c6c063d197",
    "name":
"externallmg_1732862269532_WhatsApp_Image_20241129_at_102032_AM.jpeg",
    "path": "cases/67496054d1078a4ea7fc8592/
externallmg_1732862269532_WhatsApp_Image_20241129_at_102032_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "6749613e520246c6c063d198",
  "name":
"externallmg_1732862269565_WhatsApp_Image_20241129_at_102033_AM_1.jpeg",
  "path": "cases/67496054d1078a4ea7fc8592/
externallmg_1732862269565_WhatsApp_Image_20241129_at_102033_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6749613e520246c6c063d199",
  "name":
"externallmg_1732862269595_WhatsApp_Image_20241129_at_102033_AM.jpeg",
  "path": "cases/67496054d1078a4ea7fc8592/
externallmg_1732862269595_WhatsApp_Image_20241129_at_102033_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6749613e520246c6c063d19a",
  "name":
"externallmg_1732862269599_WhatsApp_Image_20241129_at_102034_AM_1.jpeg",
  "path": "cases/67496054d1078a4ea7fc8592/
externallmg_1732862269599_WhatsApp_Image_20241129_at_102034_AM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6749613e520246c6c063d19b",
  "name":
"externallmg_1732862269627_WhatsApp_Image_20241129_at_102034_AM_2.jpeg",
  "path": "cases/67496054d1078a4ea7fc8592/
externallmg_1732862269627_WhatsApp_Image_20241129_at_102034_AM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6749613e520246c6c063d19c",
  "name":
"externallmg_1732862269630_WhatsApp_Image_20241129_at_102034_AM.jpeg",
  "path": "cases/67496054d1078a4ea7fc8592/
externallmg_1732862269630_WhatsApp_Image_20241129_at_102034_AM.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6749613e520246c6c063d19d",
    "name":
"externallmg_1732862269657_WhatsApp_Image_20241129_at_102035_AM_1.jpeg",
    "path": "cases/67496054d1078a4ea7fc8592/
externallmg_1732862269657_WhatsApp_Image_20241129_at_102035_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6749613e520246c6c063d19e",
    "name":
"externallmg_1732862269660_WhatsApp_Image_20241129_at_102035_AM.jpeg",
    "path": "cases/67496054d1078a4ea7fc8592/
externallmg_1732862269660_WhatsApp_Image_20241129_at_102035_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6749613e520246c6c063d19f",
    "name":
"externallmg_1732862269692_WhatsApp_Image_20241129_at_102036_AM_1.jpeg",
    "path": "cases/67496054d1078a4ea7fc8592/
externallmg_1732862269692_WhatsApp_Image_20241129_at_102036_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6749613e520246c6c063d1a0",
    "name":
"externallmg_1732862269714_WhatsApp_Image_20241129_at_102036_AM.jpeg",
    "path": "cases/67496054d1078a4ea7fc8592/
externallmg_1732862269714_WhatsApp_Image_20241129_at_102036_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6749613e520246c6c063d1a1",
```



```
    "name":
"externallmg_1732862269719_WhatsApp_Image_20241129_at_102037_AM_1.jpeg",
  "path": "cases/67496054d1078a4ea7fc8592/
externallmg_1732862269719_WhatsApp_Image_20241129_at_102037_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6749613e520246c6c063d1a2",
  "name":
"externallmg_1732862269741_WhatsApp_Image_20241129_at_102037_AM_2.jpeg",
  "path": "cases/67496054d1078a4ea7fc8592/
externallmg_1732862269741_WhatsApp_Image_20241129_at_102037_AM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6749613e520246c6c063d1a3",
  "name":
"externallmg_1732862269747_WhatsApp_Image_20241129_at_102037_AM.jpeg",
  "path": "cases/67496054d1078a4ea7fc8592/
externallmg_1732862269747_WhatsApp_Image_20241129_at_102037_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6749613e520246c6c063d1a4",
  "name":
"externallmg_1732862269772_WhatsApp_Image_20241129_at_102038_AM_1.jpeg",
  "path": "cases/67496054d1078a4ea7fc8592/
externallmg_1732862269772_WhatsApp_Image_20241129_at_102038_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6749613e520246c6c063d1a5",
  "name":
"externallmg_1732862269777_WhatsApp_Image_20241129_at_102038_AM.jpeg",
  "path": "cases/67496054d1078a4ea7fc8592/
externallmg_1732862269777_WhatsApp_Image_20241129_at_102038_AM.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67496147e077c54e532bebe5",
  "name":
"externallmg_1732862278897_WhatsApp_Image_20241129_at_102039_AM_1.jpeg",
  "path": "cases/67496054d1078a4ea7fc8592/
externallmg_1732862278897_WhatsApp_Image_20241129_at_102039_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67496147e077c54e532bebe6",
  "name":
"externallmg_1732862278960_WhatsApp_Image_20241129_at_102039_AM_2.jpeg",
  "path": "cases/67496054d1078a4ea7fc8592/
externallmg_1732862278960_WhatsApp_Image_20241129_at_102039_AM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67496147e077c54e532bebe7",
  "name":
"externallmg_1732862278984_WhatsApp_Image_20241129_at_102039_AM.jpeg",
  "path": "cases/67496054d1078a4ea7fc8592/
externallmg_1732862278984_WhatsApp_Image_20241129_at_102039_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67496147e077c54e532bebe8",
  "name":
"externallmg_1732862278995_WhatsApp_Image_20241129_at_102040_AM.jpeg",
  "path": "cases/67496054d1078a4ea7fc8592/
externallmg_1732862278995_WhatsApp_Image_20241129_at_102040_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67496147e077c54e532bebe9",
  "name":
"externallmg_1732862279019_WhatsApp_Image_20241129_at_102041_AM_1.jpeg",
```

```
    "path": "cases/67496054d1078a4ea7fc8592/
externallmg_1732862279019_WhatsApp_Image_20241129_at_102041_AM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67496147e077c54e532bebea",
    "name":
"externallmg_1732862279024_WhatsApp_Image_20241129_at_102041_AM.jpeg",
    "path": "cases/67496054d1078a4ea7fc8592/
externallmg_1732862279024_WhatsApp_Image_20241129_at_102041_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67496147e077c54e532bebeb",
    "name":
"externallmg_1732862279046_WhatsApp_Image_20241129_at_102042_AM_1.jpeg",
    "path": "cases/67496054d1078a4ea7fc8592/
externallmg_1732862279046_WhatsApp_Image_20241129_at_102042_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67496147e077c54e532bebec",
    "name":
"externallmg_1732862279049_WhatsApp_Image_20241129_at_102042_AM.jpeg",
    "path": "cases/67496054d1078a4ea7fc8592/
externallmg_1732862279049_WhatsApp_Image_20241129_at_102042_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67496147e077c54e532bebed",
    "name":
"externallmg_1732862279068_WhatsApp_Image_20241129_at_102043_AM_1.jpeg",
    "path": "cases/67496054d1078a4ea7fc8592/
externallmg_1732862279068_WhatsApp_Image_20241129_at_102043_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "67496147e077c54e532bebee",
  "name":
"externallmg_1732862279071_WhatsApp_Image_20241129_at_102043_AM_2.jpeg",
  "path": "cases/67496054d1078a4ea7fc8592/
externallmg_1732862279071_WhatsApp_Image_20241129_at_102043_AM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67496147e077c54e532bebef",
  "name":
"externallmg_1732862279095_WhatsApp_Image_20241129_at_102043_AM.jpeg",
  "path": "cases/67496054d1078a4ea7fc8592/
externallmg_1732862279095_WhatsApp_Image_20241129_at_102043_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67496147e077c54e532bebf0",
  "name":
"externallmg_1732862279099_WhatsApp_Image_20241129_at_102044_AM_1.jpeg",
  "path": "cases/67496054d1078a4ea7fc8592/
externallmg_1732862279099_WhatsApp_Image_20241129_at_102044_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67496147e077c54e532bebf1",
  "name":
"externallmg_1732862279140_WhatsApp_Image_20241129_at_102044_AM.jpeg",
  "path": "cases/67496054d1078a4ea7fc8592/
externallmg_1732862279140_WhatsApp_Image_20241129_at_102044_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67496147e077c54e532bebf2",
  "name":
"externallmg_1732862279148_WhatsApp_Image_20241129_at_102045_AM.jpeg",
  "path": "cases/67496054d1078a4ea7fc8592/
externallmg_1732862279148_WhatsApp_Image_20241129_at_102045_AM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67496147e077c54e532bebf3",
    "name":
"externallmg_1732862279199_WhatsApp_Image_20241129_at_103459_AM_1.jpeg",
    "path": "cases/67496054d1078a4ea7fc8592/
externallmg_1732862279199_WhatsApp_Image_20241129_at_103459_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67496147e077c54e532bebf4",
    "name":
"externallmg_1732862279205_WhatsApp_Image_20241129_at_103459_AM.jpeg",
    "path": "cases/67496054d1078a4ea7fc8592/
externallmg_1732862279205_WhatsApp_Image_20241129_at_103459_AM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-11-29T06:33:56.683Z",
"updatedAt": "2024-11-29T06:37:59.476Z",
"__v": 0,
"updatedBy": "63f9ed37ce84bf289ba991ac",
"addressForMap": "",
"caseReferredBy": "62724142afd7d55eddede405",
"contactPersonName": "Dr. Vijay Gangaram Mandale",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"reald": "",
"siteVisitContactNo": "9823103435"
}
```

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			